

THE TOWNSHIP OF NORTH DUNDAS



DRAFT BRIDGE MANAGEMENT STUDY REPORT 18 BRIDGES / 31 CULVERTS

March 2023

Report Submitted By:



HP Engineering Inc.

400-2039 Robertson Road, Ottawa, Ontario, K2H 8R2

Office: 613-695-3737 ~ Fax: 613-680-3636

TABLE OF CONTENTS

1.0	Introduction.....	3
2.0	Structure Inspections.....	3
3.0	Determination of Costs	3
3.1	Repair, Rehabilitation and Replacement.....	3
3.2	Engineering Investigation	7
4.0	Bridge Condition (BCI)	8
5.0	Routine Maintenance	9
6.0	Asset Management Strategy	10
7.0	Discussion.....	11

Appendices

Appendix A	Asset Management Summary
A-1	Bridges
A-2	Culverts
Appendix B	Summary of Recommended Works
B-1	Bridges
B-2	Culverts
Appendix C	Summary of Maintenance Needs
C-1	Bridges
C-2	Culverts
Appendix D	BCI Summary
Appendix E	10 Year Asset Management Plan

1.0 INTRODUCTION

The Township of North Dundas (herein referred to as the Township) has retained HP Engineering to perform inspections and develop a bridge management study for 49 structures owned and maintained by the Township.

Each structure in the Township's inventory was visually inspected using the Ministry of Transportation of Ontario's (MTO) Structure Inspection Manual. The data for each structure present visual observations, suggested rehabilitation, further required investigation and budget cost information. Refer to the appendices for individual inspection sheets for bridge and culvert type structures.

The following report summarizes the suggested rehabilitation / replacement costs, engineering investigation costs and replacement values for each structure based on benchmark budget costs.

Appendix A presents summary tables for all structures. The structures are listed in numerical order of structure number, and the rehabilitation / replacement costs (determined from benchmark budget costs) for each structure are based on priority (i.e. Within 1 year, 1-5 Years, 6-10 Years).

2.0 STRUCTURE INSPECTIONS

A total of 49 structures owned and maintained by the Township were visually inspected in accordance with the MTO Structure Inspection Manual. The inspections were performed during the spring and summer of 2021.

For each structure, components were screened for visual signs of deterioration. The components were then given a rating (in MDW) using the MTO extent and severity method, whereby the components are proportioned (in units of m², %, m, etc.) based on their observed conditions (excellent, good, fair, poor). This provides quantitative data as to the extent of the observed deterioration for each component. Explanatory statements accompany each of the components' ratings where deemed applicable by the inspector.

MDW entries also provide information regarding suggested engineering investigation and repairs and associated budgetary estimates of expected costs. Suggested engineering investigations are subdivided based on time of need. Repairs and associated budgetary estimates are subdivided based on time of need. The basis of selection for budget costs is further discussed in Section 3.0 of this report.

Photographs of each inspected structure are included with the inspection sheets including a minimum of 2 photographs for each structure (approach and elevation). Additional photographs depicting the details of the structure, observed defects or deterioration have also been included.

3.0 DETERMINATION OF COSTS

3.1 Repair, Rehabilitation and Replacement

Given the cursory information obtained during the visual inspections and without the benefit of detailed design information, it is impractical to develop detailed cost estimates for each structure. For these reasons, benchmark budget costs were developed for categories of repair, rehabilitation and replacement. Traditionally, benchmark costs do not necessarily provide accurate costs for individual repairs / replacement, but have proven to provide sufficient accuracy for global budgeting purposes when dealing with a large number of structures.

For the purpose of this study, benchmark costs for the rehabilitation and replacement of structures are based on maintaining the existing width, length and alignment of each structure. However, the costs to replace the existing structures with structures meeting current geometric standards are included for comparison. For this purpose, an overall roadway width of 10 metres was used for both bridge and culvert type structures. More accurate costs for each structure would be provided upon further engineering study and design based on exact repair, rehabilitation and replacement needs (including change in geometry). The following benchmark costs have been established for this study following the requirements of the inspection forms.

Bridge and Culvert Replacement Costs

Budget costs for the replacement of bridges are usually based on the deck surface area of individual structures (m²). Therefore, benchmark replacement costs for this study were determined using the following unit costs including approaches, administration and design costs, based on the spans of individual bridges and taking into account approach roadway costs (which do not vary with bridge span). In addition, the varying widths of bridges were taken into account to provide more realistic unit costs and to avoid large discrepancies in the replacement cost between bridges of different lengths, but similar surface areas.

Total Bridge Replacement Unit Costs		
Bridge Length (m)	Width (m)	Unit Replacement Cost (\$/m ²)
3-10	<10 m	\$10,000.00
	≥10 m	\$9,500.00
10-20	<10 m	\$9,500.00
	≥10 m	\$8,500.00
20-30	<10 m	\$8,500.00
	≥10 m	\$7,500.00
>30	<10 m	\$7,500.00
	≥10 m	\$6,500.00

In the case of culvert type structures, the plan area (or deck surface area) used in the calculation was ('length of spans' + 1 m) x ('width of roadway' + 1 m). The purpose of using the Total Bridge Replacement Unit Costs table for culvert type structures is to normalize the replacement cost figures. Although culverts are generally less expensive to construct than bridges, it is generally accepted that the expected life span is approximately 50% of a bridge. It is valid therefore, on a life cycle cost basis, to utilize the Total Bridge Replacement Unit Costs table for all structures, whether they are bridges or culverts.

Bridge Repair / Rehabilitation Costs

For budgeting purposes, costs for the rehabilitation of bridges are typically expressed as a percentage of the total replacement costs. Rehabilitation costs for this study are separated into four categories as presented in the table below (including administration and design costs).

Bridge Rehabilitation Costs		
Category		% of Replacement Cost
1.	Major Bridge Rehabilitation	50-60
2.	Minor Bridge Rehabilitation	25-50
3.	Major Item Repair	5-25
4.	Minor Item Repair	5 or less

Culvert Repair / Rehabilitation Costs

It is generally not practical to undertake major rehabilitation work to culvert crossings where significant deterioration or deficiencies exist in the metal liner (barrel). Culvert replacement is normally planned in these circumstances. Repair work identified generally included repairs to the inlet and outlet structures such as headwalls, cut-off walls, retaining walls, restoration of backfill, slope protection at the culvert ends and installation / upgrading of guiderail. In the case of concrete barrels, some repair work to the barrels may be included if the opening is large enough to permit construction access.

Approach Roadway Repair / Rehabilitation Costs

For this study, approaches are considered to be 30m of roadway from the centre of each individual culvert (60 m total per culvert) and 6m of roadway from the end of the deck for each individual bridge (12m total per bridge). Repair / rehabilitation costs for approach roadways have been separated into three categories as presented in the table below (including administration and design costs).

Separate costs for Approach Roadway Repair / Rehabilitation have been included for Bridge Rehabilitation. For structure replacement costs and repairs, the approach roadway repair / rehabilitation costs have been included in the recommended work costs if applicable.

Approach Roadway Repair/Rehabilitation Costs		
Category		Cost
1.	Capital Projects (Partial / Complete Paving, Guiderail)	\$40,000.00
2.	Minor Repairs / Maintenance (Crack Sealing, Surface Sealing, Guiderail Repairs)	\$15,000.00
3.	Crack Sealing Only	\$8,000.00

Construction Detour Costs

Several alternatives exist to maintain the flow of traffic when a bridge or culvert undergoes major rehabilitation or replacement. These include the construction of a detour structure adjacent to the existing structure, a detour route around (avoiding) the structure, and the staging of the construction to allow traffic on the structure during construction. The construction of a detour structure is the most costly option and is usually recommended only when the other options are not possible. The detour route is the least expensive option, but is often not practical due to the length of the detour route and the inconvenience to residents near the structure. The most frequently recommended option is the staging of rehabilitation work to allow the passage of traffic.

Since most bridge projects would consist of rehabilitation and not replacement, the staging of work would be the most frequently used option to maintain traffic during construction. Therefore, the benchmark costs for detours are based on staging of the work as per the following. These costs are based on additional costs incurred from staging of the work during construction (extra effort, time). Traffic control costs would be separate from detour costs and are presented later in this section.

Detour During Construction Costs		
Category		Cost
1.	Detour - Minor Rehabilitation / Major Rehabilitation of Bridges Less than 10m Long / Culvert Replacement	\$35,000.00
2.	Detour - Major Rehabilitation / Bridge Replacement	\$100,000.00

Traffic Control Costs

In addition to performing the work in stages to accommodate traffic, the safety of traffic passing on the bridge or over the culvert during construction must also be ensured. The costs of traffic control during staged projects would be as follows:

Traffic Control Costs		
Category		Cost
1.	Traffic Control- Minor Rehabilitation	\$35,000.00
2.	Traffic Control - Major Rehabilitation	\$60,000.00

Utilities / Right of Way Costs

Most bridge or culvert rehabilitation / replacement projects do not require substantial expenses for the installation or modification of existing utilities. Similarly, most of these projects do not require an increase in right of way. Therefore, specific benchmark budget costs for these items were not developed.

Environmental Study Costs

Since bridge or culvert replacements / rehabilitations typically do not involve a change in alignment or a reduction in clearances under the structure, these projects usually fall under the Schedule A or A+ Environmental Assessment for Ontario Highways. This type of environmental assessment does not require detailed environmental and mitigation plans, but typically requires written application with, and permission from, the appropriate environmental agencies (Ontario Ministry of Natural Resources, Ontario Ministry of the Environment, Local Conservation Authorities (Permit To Take Water)). Therefore, the benchmark budget cost for environmental study would be as follows (based on the requirement of Schedule A or A+ Environmental Assessment):

Environmental Study Costs		
	Category	Cost
1.	Bridge / Culvert Replacement, Minor and Major Rehabilitation	\$10,000.00

Other Costs

Any other costs not specified in the above (site specific requirements) are deemed to be covered in the total benchmark costs. Therefore, no specific amount for other work is specified in this report.

Contingency Costs

The benchmark costs used for budgeting purposes are based only on information obtained from visual inspections. Because of this, contingency allowances are already built into the benchmark costs. Therefore, specific amounts for contingencies will not be included in this report.

Recommended Replacement Costs

For the purposes of this report, when a structure (bridge or culvert) replacement has been recommended, all associated costs (approaches, detours, traffic control, utilities, right of way, environmental studies and contingency) have been included in the replacement cost provided in the 'Repair and Rehabilitation Required' table on the inspection forms.

3.2 Engineering Investigation

Further engineering investigation is recommended for several of the bridges and culverts as indicated on individual inspection forms. Benchmark budget costs for engineering investigation work are presented in the table below:

Engineering Investigation			
Category		Type of Structure	Cost
1.	Detailed Inspection / Rehabilitation Study - Full Bridge	Truss	\$25,000.00
		Others	\$20,000.00
		Traffic Barrier Only *	\$5,000.00
2.	Detailed Deck Condition Survey	Exposed Deck	\$10,000.00
		Asphalt Paved Deck	\$15,000.00
		Concrete Culvert with Height of Fill Less than 500 mm **	\$5,000.00
3.	Structure Evaluation	Truss	\$15,000.00
		Others	\$10,000.00
4.	Underwater Investigation	All Bridges	\$10,000.00

* Requirements for traffic barriers on bridges and culverts were determined using the Canadian Highway Bridge Design Code, MTO Standards and good engineering practice. The evaluation of existing traffic barriers was based on assumed values of AADT and good engineering practice. For structures with existing approach guiderail, a review of the required approach / leaving end length of guiderail and end treatments (as per the MTO's Roadside Safety Manual) was not carried out.

** Deck condition survey on concrete culvert includes cores with no corrosion potential survey. Deck condition surveys on concrete culverts with a height of fill greater than 500 mm are not practical.

The benchmark budget costs for a Structure Evaluation and Detailed Deck Condition Survey would be reduced to 50% of that shown in the table above when any one these are performed simultaneously with a Detailed Inspection / Rehabilitation Study.

Other investigations such as fatigue and seismic investigations would be included with the Detailed Inspection and Structure Evaluation (respectively), if deemed necessary by the engineer. Detailed coating condition surveys are typically only required where a failure of coating systems have occurred other than normal deterioration. A DART (Deck Assessment by Radar Technology) survey is not a commonly used investigation method. Detailed deck condition surveys are the most commonly used method of deck inspection. Therefore, individual costs for the various types of investigation described above are not provided.

4.0 BRIDGE CONDITION (BCI)

Bridge Condition Index (BCI) values were derived using MTO's standard methods as outlined in their document entitled '*Bridge Condition Index, an Overall Measure of Bridge Condition*' (July 2009). Based on this document, we utilize an excel spreadsheet (developed based on the parameters outlined in the

document) that, after inputting the inspection data for each element (condition ratings), automatically calculates the BCI value.

With the calculated BCI values for each structure, an *overall* picture of the general condition of the Township's structures inventory as a whole can then be presented by summarizing BCI ranges (good, fair, poor) and counting the overall percentage of structures in each category. This is the methodology that the MTO currently utilizes and it is generally an effective tool to determine where the Township stands in terms of the overall condition and maintenance needs for their structure inventory. This information can be used to compare the overall condition of various structures, to assist in prioritizing structures for future rehabilitation and assist in the funding application process.

The BCI ranges that are normally included in this summary table are as follows:

- Good (BCI Range 70-100); for this range, maintenance is not usually required with the next five years.
- Fair (BCI Range 60-70); for this range, maintenance work is usually required / scheduled within the next five years. Carrying out work within this timeframe (next five years) is typically considered the ideal time to get the most out of bridge spending.
- Poor (BCI Less than 60); for this range, maintenance work is usually required / schedule with the next year.

For the Township's inventory (20 structures total), the current summary of BCI ranges is presented as follows (individual structure BCI values are presented in the tables in *Appendix A* and *Appendix E*):

BCI Range	Number of Structures in Range	% of Structures in Range
70-100	14 (bridges), 15 (culverts) = 29 total	59.2
60-70	1 (bridges), 9 (culverts) = 10 total	20.4
Less than 60	2 (bridges), 6 (culverts) = 8 total	16.3
Not Inspected	1 (bridge), 1 (culvert) = 2 total	4.1

5.0 ROUTINE MAINTENANCE

As part of the Township's overall bridge management program, a program of routine maintenance should be implemented and up-kept for all structures. Maintaining this program will assist in minimizing the potential for premature deterioration of structural elements; and, when combined with a program of bridge rehabilitation, will assist in maximizing the useful service life of the Township's structure inventory.

Overall routine maintenance needs will vary depending on the type of structure, location, traffic volumes, winter maintenance procedures (sanding vs. salting, etc.), size of the structure, vintage and previous maintenance / rehabilitation carried out on the structure in the past. The following presents a general summary of routine maintenance operations that are considered applicable for the structures present within the Township's inventory:

- Periodic bridge cleaning; this would include power-washing of all components exposed to roadway traffic and areas where debris accumulation is prevalent. This would include asphalt wearing surfaces, expansion joint gaps, edges of roadway, bearing seats, truss bottom chords, etc. Typically this operation would be carried out on an annual basis, most likely each spring after winter sanding / salting operations have ceased; however, in some cases (i.e. gravel approach roadways, etc.), an increase in the number of cleanings per year may be required.

- Concrete spot repairs; this would generally include localized patching of small concrete spalls and delaminations located in areas within the roadway splash zones (top of deck, curbs, expansion joint block-outs, etc.). Completing these repairs will assist in preventing accelerated deterioration of concrete in these areas by reducing the ingress of chlorides, etc. There is no specific timing for these types of repairs and they are generally performed on an as-needed basis.
- Steel spot repairs / spot coating; this would generally include localized touch-ups to steel coatings located in areas within the roadway splash zones (truss bottom chords, exterior floor beams / stringers, etc.) as well as localized spot repairs in areas of appreciable section loss / corrosion. There is no specific timing for these types of repairs and they are generally performed on an as-needed basis.
- Clearing of debris in waterway; this would include clearing of trapped debris in the vicinity of the structure (upstream / downstream). This operation would typically be carried out on an annual basis, after the spring run-off period.
- Asphalt surface repairs / rout and seal; this would include cold patch asphalt repairs, routing and sealing of wide cracks in asphalt. This operation would typically be carried out on an annual basis, after winter clearing operations have ceased.
- Re-grading of approach roadways (gravel roadway surfaces); this would include placing and grading fresh granular material on roadway surfaces. The timing of this work would depend on the overall volume and type of traffic typically traversing the roadway (truck haul route, summer cottage traffic route, etc.). Typically this work would be carried out on an annual or bi-annual basis.
- Bridge deck drainage; this would include maintaining existing deck drains free of debris and maintaining them in an un-plugged condition. This operation would typically be carried out on an annual basis, after winter clearing operations have ceased.
- Clearing of debris / vegetation from approach guiderail; this would involve removing debris and vegetation from in front of approach guiderail. Although this is mainly a safety measure (to ensure proper performance of the guiderail), it also assists in prolonging the lifespan of the guiderail (accumulation of debris can accelerate rot on wooden posts, corrosion on steel guiderail, etc.).
- Surface sealing of exposed concrete surfaces; this would include cleaning and applying a concrete sealer on concrete surfaces exposed within the splash zone (exposed concrete decks, curbs, sidewalks and barrier walls); this operation is not typically required on an annual basis and would typically be completed in 3-5 year intervals. Sealing concrete surfaces periodically assists in minimizing the migration of chlorides into the concrete.

6.0 ASSET MANAGEMENT STRATEGY

As previously mentioned, all structures were visited and inspected in conformance with the requirements of the Ontario Structure Inspection Manual (2020 Revision). Based on the results of the inspections, repair / rehabilitation needs and budgetary costs for these were identified. In addition, additional engineering inspections and studies were also recommended.

Although OSIM inspections (generally performed every 2 years) are a useful screening tool to identify upcoming bridge maintenance needs and costs, these inspections solely rely on visual evidence of

deterioration and do not take into account the age (life cycles) of individual structures, nor do they take into account the potential for hidden deterioration (which could be revealed with further investigations such as detailed bridge condition surveys, rehabilitation studies, etc.).

In order to provide the Township with a more useful planning tool for structure rehabilitation / replacement, all of the information gathered from the OSIM inspections was summarized in an asset information summary table. The information presented in the tables is described in the following section, the information for bridges and culverts are presented separately.

Asset Management Summary

This set of tables presents basic asset information for the structures such as structure name, type of structure and basic geometry. The replacement value for each structure (based on current and widened geometry, in the case where the width of the existing structures are deficient) is also provided. These values are presented in 2022 dollars. The BCI calculated by HP Engineering for each structure is also provided.

A 10-year asset management plan for the structures was also developed as part of this assignment. The year-by-year plan takes into consideration the age of the structure and its known (major) rehabilitation history. The plan assumes a distribution of the replacements and major/minor rehabilitations per year over the next 10 years. For this plan it has been assumed, for smaller structures, that additional work (i.e., joint replacements, paving, overlays, barrier upgrades etc.) would be completed in addition to defects noted in the OSIM inspection. The costs given are shown in 2022 dollars and have not been adjusted for inflation. It should be noted that cost estimates prepared for the Township are opinions of probable costs attained for the expected construction work. It is not a prediction of the lowest tender price. Tender prices will be influenced by many factors such as the tenders' method of pricing and/or interpretation of their probable level of effort, current and pending projects by others and level of competitiveness in the market at the time of tender, availability of labour and materials, etc., which are not within our control, knowledge, and/or ability to predict. This schedule should be reviewed and adjusted as required by the Township based on budget availability. This schedule may also be adjusted or augmented based on the results of further Engineering Investigations (detailed condition surveys, rehabilitation studies, etc.) and future OSIM inspections.

It is noted that the asset management information as discussed above (and presented in **Appendix A**) was developed based on the current information available for the structures, the current (2022) OSIM inspections and based on the overall assumptions presented above.

7.0 DISCUSSION

This Bridge Management Asset Study was developed to provide the Township of North Dundas with the necessary information required to budget projects and set priorities for future bridge and culvert rehabilitation / replacement programs.

Replacement, rehabilitation and engineering investigation budget costs were provided for 49 of the Township's structure based on visual biennial inspections performed by HP Engineering (during the spring and summer of 2022).

The costs for individual structures are presented in the Bridge and Culvert OSIM Inspection Reports, these cost values were based on benchmark costs developed for this study. These should be used for

budgeting purposes only. More accurate cost estimates for each structure's needs would be provided based on more detailed scopes of work developed during the design engineering stages.


The estimated replacement value of the Township's bridge and culvert inventory (based on 49 structures in the inventory) is approximately **38.79 million dollars**. The estimated value of all the bridges and culverts (based on 49 structures in the inventory) if reconstructed to current geometric standards would be approximately **45.96 million dollars**.

Immediate repair / rehabilitation costs for the 49 structures inspected are estimated to be a total of approximately **611 thousand dollars** broken down as **48** and **563 thousand dollars** for bridges and culverts respectively. Similarly, the longer-term repair / rehabilitation costs (1-5 years) for the 49 structures inspected are estimated to be a total of approximately **5.58 million dollars** broken down as **1.62** and **3.96 million dollars** for bridges and culverts, respectively. The longer-term repair / rehabilitation costs in the 6-10 year range for the 49 structures inspected are estimated to be a total of approximately **0.881 million dollars** broken down as **225** and **655 thousand dollars** for bridges and culverts, respectively.

The costs associated with recommended further Engineering Investigations for the 49 structures inspected was estimated to be a total of approximately **545 thousand dollars** broken down as **235** and **310 thousand dollars** for bridges and culverts respectively.

Respectfully Submitted,

April 17th, 2023



Tashi Dwivedi, P.Eng.
Principal

APPENDIX A

ASSET MANAGEMENT SUMMARY

APPENDIX A-1

BRIDGES
(18 STRUCTURES)

Appendix A-1 : Asset Information Summary - Bridges

Site No	Bridge Name	Inspected By	Inspection Year	Northing	Easting	Location	Bridge Type	Year Built (Age)	Year of Last Rehab	Number of Spans	Total Length (Parallel to Roadway) (m)	Width (Perpendicular to roadway) (m)	Roadway Width (m)	Existing Surface Area (m²)	Replacement Cost - Existing Geometry (\$000)	Replacement Cost - Current Geometric Standards (\$000)	BCI	Benchmark Budget Costs			
																		Rehabilitation Costs (\$000)			Engineering Investigation Costs (\$000)
																		< 1 year	1-5 Years	6-10 Years	Normal
BRH001	Belmeade Rd & South Castor Creek Bridge	HP Engineering Inc	2022	45.1253948	-75.4990661	5.0km West of County Rd 31	Slab on Concrete Box Girders	1981	N/A	1	12.20	10.50	7.00	128	1,089	1,400	70		70		15
BRH002	Belmeade Rd & South Castor Creek Bridge	HP Engineering Inc	2022	45.1366902	-75.4657242	2.1km West of County Rd 31	Slab on Concrete Box Girders	1981	2018	1	17.40	10.50	7.30	183	1,553	1,952	73		70		15
BRH003	Ormond Bridge	HP Engineering Inc	2022	45.1653584	-75.3556303	0.2km West of Bisson Road	Reinforced Concrete Solid Slab	1979	N/A	3	32.30	9.10	7.50	294	2,204	2,435	73		36		15
BRH004	Cayer Rd & Annable Creek MD Bridge (Active Co	HP Engineering Inc	2022						2005												
BRH005	Liscumb Rd & Annable MD Bridge	HP Engineering Inc	2022	45.10424	-75.3622	0.35km West of County Rd 3	Concrete Rigid Frame		2001	1	5.30	6.40	4.60	34	339	594	65		135		
BRH006	Development Rd & North Branch of South Nation R	HP Engineering Inc	2022	45.044685	-75.449811	1.2km North of Van Camp Road	Slab on Steel I-Girders		2003	1	25.90	9.60	8.00	249	2,113	2,253	71			226	20
BRH007	Levere Rd & North Branch South Nation River Brid	HP Engineering Inc	2022	45.0456626	-75.4447956	0.4 km East of Development Road	Slab on Concrete Box Girders		2021	1	14.70	8.50	7.00	125	1,187	1,437	73		21		15
BRH008	Van Camp Rd & North Branch South Nation River	HP Engineering Inc	2022	45.03686	-75.4361	0.5km east of Development Road	Slab on Concrete Box Girders	1979	1990	1	14.70	9.00	6.00	132	1,257	1,624	73				15
BRH009	Cameron Rd & Near Boundary Rd Bridge	HP Engineering Inc	2022	44.995	-75.51611	50m East of Boundary Rd	Slab on Steel I-Girders		2018	1	11.50	6.00	10.40	69	656	656	58		479		35
BRH010	Cameron Rd & North Branch South Nation River M	HP Engineering Inc	2022	45.03032	-75.41273	1.5km West of County Road 3	Slab on CPCI Girders		N/A	1	18.30	9.00	7.30	165	1,565	1,820	75				
BRH011	Nation Valley Rd & South Nation River Bridge	HP Engineering Inc	2022	45.0681762	-75.2806069	70m South of River Rd	Slab on CPCI Girders	1980	N/A	3	69.10	9.20	7.30	636	4,768	5,345	73		114		20
BRH012	Nation Valley Rd & Barkley Creek Bridge	HP Engineering Inc	2022	45.0666325	-75.2830706	5.0 km West of County Rd 43	Concrete Rigid Frame CIP T-Beam		N/A	1	7.00	6.00	4.80	42	420	745	41		560		20
BRH013	Timmins Rd & North Branch South Nation river Bri	HP Engineering Inc	2022	45.02092	-75.38608	0.8km South of County Rd 3	Slab on Concrete Box Girders	1987	2006	1	20.80	10.10	9.00	210	1,576	1,799	72		43		15
BRH014	Bridge St & South Nation River Bridge	HP Engineering Inc	2022	44.98924	-75.45054	0.3km North of Sandt Road Road	Slab on Concrete Box Girders	1977	N/A	1	30.20	7.00	4.90	211	1,586	2,231	73		84		15
BRH015	Limerick Rd & McMillan Rd Bridge	HP Engineering Inc	2022	45.0798707	-75.2027987	0.8km East of County Rd 8	Concrete Rigid Frame - Arch		N/A	1	14.00	8.50	7.00	119	1,131	1,369	71	48			5
BRH016	West Bridge	HP Engineering Inc	2022	44.95978	-75.47725	0.1km South of Nation River Road	Slab on CPCI Girders	1981	2017	1	32.20	9.70	8.50	312	2,343	2,344	75				15
BRH017	Bigford Bridge	HP Engineering Inc	2022	45.00415	-75.36276	0.2km North of County Road 5	Solid Slab	1983	N/A	1	12.20	10.50	7.00	128	1,089	1,400	74		9		15
BRT001	Chesterville Dam Structure Pedestrian Bridge	HP Engineering Inc	2022	45.1012649	-75.2259991	30m South of Water St.	Pedestrian bridge (Solid Concrete Slab)		N/A	6	42.00	4.00	4.00	168	1,260	2,730	75				
TOTALS															26,134	32,133		48	1,618	226	235

	NOTES:
	1. BCI as calculated by HP Engineering.

APPENDIX A-2

CULVERTS
(31 STRUCTURES)

Appendix A-2 : Asset Information Summary - Culverts

Township of North Dundas

2022 BIENNIAL INSPECTIONS

Culvert No.	Culvert Name	Inspected By	Inspection Year	Northing	Easting	Location	Culvert Type	Year Built (Age)	Year of Last Rehab	Number of Barrels	Total Length (Parallel to Roadway) (m)	Width (Perpendicular to roadway) (m)	Roadway Width (m)	Existing Surface Area (m ²)	Replacement Cost - Existing Geometry (\$000)	Replacement Cost - Current Geometric Standards (\$000)	BCI	Benchmark Budget Costs			
																		Rehabilitation Costs (\$000)			Engineering Investigation Costs (\$000)
																		< 1 Year	1-5 Years	6-10 Years	Normal
CUC001	Cayer Rd & McLean MD Culvert	HP Engineering Inc.	2022	45.13701	-75.378067	0.5km South of County Rd 13	Precast Concrete Box Culvert			1	3.00	11.70	6.40	35	281	330	70		85		
CUC002	Cayer Rd & Cinnamon MD Culvert	HP Engineering Inc.	2022	45.12935	-75.37231	1.3km South of County Rd 13	Concrete Rigid Frame (Open Footing)			1	6.10	19.50	6.00	119	952	586	74				
CUC003	Thompson Rd & Black Creek MD Culvert	HP Engineering Inc.	2022	45.15021	-75.31702	Intersection of Thompson Rd and Steen Rd	Precast Concrete Box Culvert			1	3.60	15.90	6.00	57	458	380	74		48		5.0
CUC004	Cayer Rd & Castor Extension MD Culvert	HP Engineering Inc.	2022	45.1211	-75.36599	2.4km South of County Rd 13	2-Cell Precast Concrete Box Culvert			2	8.50	18.00	6.00	153	1,224	784	74				
CUC005	Kerrs Ridge Rd & Castor Extension MD Culvert	HP Engineering Inc.	2022	45.08721	-75.4293937	0.6km North of Spruit Rd	Precast Concrete Box Culvert			1	3.40	14.50	4.50	49	394	363	71		10		
CUC006	Winchester Main St & Henderson Creek MD Culvert	HP Engineering Inc.	2022	45.09537	-75.3471575	0.3km East of Ottawa St.	Concrete Rigid Frame (Open Footing)			1	15.30	15.30	9.80	234	1,522	1,165	59	83	28		5.0
CUC007	Guy Rd & East Justus MD Culvert	HP Engineering Inc.	2022	45.05029	-75.35644	2.5km West of County Rd 31	Cast-in-place Concrete box culvert			1	4.20	12.80	6.00	54	430	429	74	48			???
CUC008	Nation Valley Rd & Servage MD Culvert	HP Engineering Inc.	2022	45.07586	-75.26137	60m West of Forward Rd	Concrete Rigid Frame (Open Footing)			1	3.50	7.50	4.60	26	210	371	43		295		20.0
CUC009	Nation River Rd & Eager MD Culvert	HP Engineering Inc.	2022	44.96921	-75.47351	1.0 km East of Wallace Road	Precast Concrete Box Culvert			1	3.00	17.40	5.80	52	418	330	74	48		5	5.0
CUS001	Marionville Rd & Lough MD Culvert	HP Engineering Inc.	2022	45.16386	-75.396942	0.4km East of Rodney Ln	CSP Arch Culvert			1	3.20	28.70	6.00	92	551	347	75	48			5.0
CUS002	Carruthers Rd & Muffat Creek MD Culvert	HP Engineering Inc.	2022	45.19173	-75.2836435	0.85km East of County Rd 7	SPCSP Arch Culvert			1	3.70	15.30	5.80	57	226	388	67	48			5.0
CUS003	Allen Rd & Allen Creek MD Culvert	HP Engineering Inc.	2022	45.08615	-75.55013	0.5km South of French Settlement Road	Corrugated Steel Pipe Arch Culvert			1	3.10	18.30	5.50	57	227	338	75	48			5.0
CUS004	Jennings Rd & Castor Extension MD Culvert	HP Engineering Inc.	2022	45.1004	-75.42241	2.2km North of Spruit Rd	SPCSP Arch Culvert			1	4.60	13.70	5.70	63	252	462	66		337		22.5
CUS005	Kerrs Ridge Rd Allowance & Castor Extension MD Culvert	HP Engineering Inc.	2022	45.09437	-75.42706	0.6km Wset of Jennings Road	SPCSP Arch Culvert			1	4.00	15.00	5.00	60	240	413	64			325	22.5
CUS006	Spruit Rd & Castor Extension MD Culvert	HP Engineering Inc.	2022	45.07952	-75.4313356	0.45km West of Riddell Rd	SPCSP Arch Culvert			1	3.00	13.70	4.00	41	206	330	59		291		20.0
CUS007	(Could not locate structure)																				
CUS008	Liscumb Rd & Tighe MD Culvert	HP Engineering Inc.	2022	45.10355	-75.3634268	0.6km West of County Rd 3	SPCSP Arch Culvert			1	4.50	15.30	10.00	69	241	454	70	48			5.0
CUS009	Boyne Rd & Kittle Creek MD Culvert	HP Engineering Inc.	2022	45.12667	-75.261989	1.2km East of Kittle Rd	2-Cell CSP Round Culvert			2	3.00	18.30	8.40	55	220	330	75	48			5.0
CUS010	Development Rd CPR Railway Culvert	HP Engineering Inc.	2022	45.04777	-75.45206	1.0km South of County Rd 43, South of CPR Rail tracks	3-Cell CSP Round Culvert			3	4.50	20.40	6.40	92	367	454	41		452		22.5
CUS011	Kittle Rd & Kittle Creek MD Culvert	HP Engineering Inc.	2022	45.11716	-75.25508	1.3km West of County Rd 7	2-Cell CSP Round Culvert			2	3.00	12.20	6.00	37	146	330	69	48			5.0
CUS012	Finch Winchester Boundary Rd & Stoney Creek MD Culvert	HP Engineering Inc.	2022	45.16392	-75.19492	0.4 km South of County Rd 9	CSP Round Culvert			1	3.00	18.30	4.60	55	220	330	64	48			5.0
CUS013	Van Camp Rd & North Branch South Nation River MD Culvert	HP Engineering Inc.	2022	45.01981	-75.48735	0.25km West of County Road 1	2-Cell SPCSP Culvert			2	12.60	23.50	6.40	296	1,036	972	73			18	2.5
CUS014	River Rd & Kittle Creek MD Culvert	HP Engineering Inc.	2022	45.10072	-75.250827	0.2km South of County Rd 43	CSP Horizontal Ellipse Culvert			1	3.90	25.30	6.00	99	395	404	62		452		22.5
CUS015	Guy Rd & Mullin MD Culvert	HP Engineering Inc.	2022	45.04362	-75.3733288	0.5km East of Browns Lane	SPCSP Arch Culvert			1	3.30	16.80	5.80	55	222	355	73			307	20.0
CUS016	Pemberton & Mulin Rd MD Culvert	HP Engineering Inc.	2022	45.04404	-75.3422	0.45km South of Hogaboam road	SPCSP Arch Culvert			1	4.80	17.50	5.80	84	336	479	63		421		20.0
CUS017	Nation Valley Rd & Dillabough Creek MD Culvert	HP Engineering Inc.	2022	45.08187	-75.2464547	2.4km West of County Rd 43	SPCSP Arch Culvert			1	3.30	17.40	6.40	57	230	355	75	48			5.0
CUS018	Webb Rd & Whittaker MD Culvert	HP Engineering Inc.	2022	45.05621	-75.2979	1.1 km North of Nesbitt Rd	4-Cell CSP Round Culvert			4	3.20	7.00	5.50	22	157	347	47		252		20.0
CUS019	Hollister Rd & Moffat Creek MD Culvert	HP Engineering Inc.	2022	45.04743	-75.31713	0.5 km South of River Rd	2-Cell CSP Culvert			2	3.00	26.50	10.70	80	278	330	60		363		20.0
CUS020	Hollister Rd Equalizer Culvert	HP Engineering Inc.	2022	45.04564	-75.3137318	0.9 km South of River Rd	2-Cell CSP Round Culvert			2	3.20	26.50	10.70	85	297	347	60		382		20.0
CUS021	Nesbitt Rd & Whittaker MD Culvert	HP Engineering Inc.	2022	45.04451	-75.2987	0.6 km East of County Rd 31	Super Cor Culvert			1	10.00	13.00	8.50	130	455	787	75				
CUS022	Nesbitt Rd & Barkley Creek MD Culvert	HP Engineering Inc.	2022	45.05131	-75.28076	0.3 km West of Shay Rd	SPCSP Arch Culvert			1	5.50	21.00	7.00	116	462	536	65		547		22.5
TOTALS															12,651	13,823		563	3,963	655	310.0

	NOTES:
	1. BCI as calculated by HP Engineering.

APPENDIX B-1

BRIDGES
(18 STRUCTURES)

Appendix B-1: Summary of Recommended Works - Bridges

Structure #	Structure Name	BCI	Timeframe	Recommended Work	Estimated Budget			Investigations	Cost
					Construction Cost	Associated Cost	Total Estimated Cost		
BRH001	Belmeade Rd & South Castor Creek Bridge	70	1-5 years	Replace Joint Amouring and Seals	\$70,000.00		\$70,000.00	Deck Condition Survey	\$15,000.00
BRH002	Belmeade Rd & South Castor Creek Bridge	73	1-5 years	Replace Joint Amouring and Seals	\$70,000.00		\$70,000.00	Deck Condition Survey	\$15,000.00
BRH003	Ormond Bridge	73	1-5 years	Concrete Repairs (Deck Top, Soffit)	\$35,500.00		\$35,500.00	Deck Condition Survey	\$15,000.00
BRH004	Cayer Rd & Annable Creek MD Bridge (Active Construction)						\$0.00		
BRH005	Liscumb Rd & Annable MD Bridge	65	1-5 years	Concrete Repairs (Soffit), Repave wearing surface	\$60,000.00	\$35,000.00	\$95,000.00		
BRH006	Development Rd & North Branch of South Nation River MD Bridge	71	6-10 years	Repave wearing surface, Replace joint seals and Barrier, Concrete Repairs (Abutment walls)	\$273,500.00	\$35,000.00	\$308,500.00	Rehabilitation/ Replacement study	\$20,000.00
BRH007	Levere Rd & North Branch South Nation River Bridge	73	1-5 years	Concrete Repairs (Deck top, Soffit)	\$21,000.00		\$21,000.00	Deck Condition Survey	\$15,000.00
BRH008	Van Camp Rd & North Branch South Nation River Bridge	73					\$0.00	Deck Condition Survey	\$15,000.00
BRH009	Cameron Rd & Near Boundary Rd Bridge	58	1-5 years	Major Rehabilitation	\$393,600.00	\$85,000.00	\$478,600.00	Rehabilitation/ Replacement study	\$20,000.00
BRH010	Cameron Rd & North Branch South Nation River MD Bridge	75							
BRH011	Nation Valley Rd & South Nation River Bridge	73	1-5 years	Concrete Repairs (Overhangs, Girders), Replacement of Joint selas	\$125,000.00	\$35,000.00	\$160,000.00	Rehabilitation/ Replacement study	\$20,000.00
BRH012	Nation Valley Rd & Barkley Creek Bridge	41	1-5 years	Structure Replacement	\$450,000.00	\$110,000.00	\$560,000.00	Rehabilitation/ Replacement study	\$20,000.00
BRH013	Timmins Rd & North Branch South Nation river Bridge	72	1-5 years	Concrete Repairs (Soffit, Wingwalls), Replace Joint seal	\$42,500.00		\$42,500.00	Deck Condition Survey	\$15,000.00
BRH014	Bridge St & South Nation River Bridge	73	1-5 years	Concrete Repairs (Barrier walls, Concrete curb, Abutment walls), Replace Joint seals	\$83,500.00		\$83,500.00	Deck Condition Survey	\$15,000.00
BRH015	Limerick Rd & McMillan Rd Bridge	71	<1 year	Install Code compliant approach barrier and end treatments	\$48,000.00		\$48,000.00	Rehabilitation/ Replacement study for Barrier Only	\$5,000.00
BRH016	West Bridge	75					\$0.00	Deck Condition Survey	\$15,000.00
BRH017	Bigford Bridge	74	1-5 years	Concrete Repairs (Deck Top)	\$8,500.00		\$8,500.00	Deck Condition Survey	\$15,000.00
BRT001	Chesterville Dam Structure Pedestrian Bridge	75					\$0.00		

APPENDIX B-2

CULVERTS
(31 STRUCTURES)

Appendix B-2: Summary of Recommended Works - Culverts

Structure #	Structure Name	BCI	Timeframe	Recommended Work	Estimated Budget			Investigations	Cost
					Construction Cost	Associated Cost	Total Estimated Cost		
CUC001	Cayer Rd & McLean MD Culvert	70	1-5 years	Repave and waterproofing of deck, Concrete Repairs	\$ 50,000.00	\$ 35,000.00	\$ 85,000.00		
CUC002	Cayer Rd & Cinnamon MD Culvert	74							
CUC003	Thompson Rd & Black Creek MD Culvert	74	<1 year	Install code compliant Barriers and End Treatments	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUC004	Cayer Rd & Castor Extension MD Culvert	74							
CUC005	Kerrs Ridge Rd & Castor Extension MD Culvert	71	1-5 years	Concrete Repairs (barrel)	\$ 10,000.00		\$ 10,000.00		
CUC006	Winchester Main St & Henderson Creek MD Culvert	59	1-5 years	Install code compliant Barriers and End Treatments (<1 year) , Concrete Repairs (Barrel)	\$ 75,500.00	\$ 35,000.00	\$ 110,500.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUC007	Guy Rd & East Justus MD Culvert	74	<1 year	Install code compliant approach Barrier	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUC008	Nation Valley Rd & Servage MD Culvert	43	1-5 years	Structure Replacement	\$ 210,000.00	\$ 85,000.00	\$ 295,000.00	Rehabilitation/ Replacement study	\$ 20,000.00
CUC009	Nation River Rd & Eager MD Culvert	74	6-10 years	Install code compliant Approach Barrier (<1 year), Concrete Repairs (barrel)	\$ 53,000.00		\$ 53,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUS001	Marionville Rd & Lough MD Culvert	75	<1 year	Install code compliant barrier on North side, End treatment on South barrier	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUS002	Carruthers Rd & Muffat Creek MD Culvert	67	<1 year	Install code compliant Barriers and End Treatments	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUS003	Allen Rd & Allen Creek MD Culvert	75	<1 year	Install code compliant approach Barrier	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUS004	Jennings Rd & Castor Extension MD Culvert	66	1-5 years	Structure Replacement	\$ 252,000.00	\$ 85,000.00	\$ 337,000.00	Rehabilitation/ Replacement study, Monitoring Deformation	\$ 22,500.00
CUS005	Kerrs Ridge Rd Allowance & Castor Extension MD Culvert	64	6-10 years	Structure Replacement	\$ 240,000.00	\$ 85,000.00	\$ 325,000.00	Rehabilitation/ Replacement study, Monitoring Deformation	\$ 22,500.00
CUS006	Spruit Rd & Castor Extension MD Culvert	59	1-5 years	Structure Replacement	\$ 206,000.00	\$ 85,000.00	\$ 291,000.00	Rehabilitation/ Replacement study	\$ 20,000.00
CUS007	(Could not locate structure)								
CUS008	Liscumb Rd & Tighe MD Culvert	70	<1 year	Install code compliant Barriers and End Treatments	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUS009	Boyne Rd & Kittle Creek MD Culvert	75	<1 year	Install code compliant Barriers and End Treatments	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUS010	Development Rd CPR Railway Culvert	41	<1 year	Structure Replacement	\$ 367,000.00	\$ 85,000.00	\$ 452,000.00	Rehabilitation/ Replacement study	\$ 20,000.00
CUS011	Kittle Rd & Kittle Creek MD Culvert	69	<1 year	Install code compliant Barriers and End Treatments	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUS012	Finch Winchester Boundary Rd & Stoney Creek MD Culvert	64	<1 year	Install code compliant Barriers and End Treatments	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUS013	Van Camp Rd & North Branch South Nation River MD Culvert	73	6-10 years	Concrete Repairs (barrel)	\$ 18,000.00		\$ 18,000.00	Monitoring Crack width	\$ 2,500.00
CUS014	River Rd & Kittle Creek MD Culvert	62	1-5 years	Structure Replacement	\$ 367,000.00	\$ 85,000.00	\$ 452,000.00	Rehabilitation/ Replacement study	\$ 20,000.00
CUS015	Guy Rd & Mullin MD Culvert	73	6-10 years	Structure Replacement	\$ 222,000.00	\$ 85,000.00	\$ 307,000.00	Rehabilitation/ Replacement study	\$ 20,000.00
CUS016	Pemberton & Mulin Rd MD Culvert	63	1-5 years	Structure Replacement	\$ 336,000.00	\$ 85,000.00	\$ 421,000.00	Rehabilitation/ Replacement study	\$ 20,000.00
CUS017	Nation Valley Rd & Dillabough Creek MD Culvert	75	<1 year	Install code compliant Barriers and End Treatments	\$ 48,000.00		\$ 48,000.00	Rehabilitation / Replacement study for barrier only	\$ 5,000.00
CUS018	Webb Rd & Whittaker MD Culvert	47	1-5 years	Structure Replacement	\$ 167,000.00	\$ 85,000.00	\$ 252,000.00	Rehabilitation/ Replacement study	\$ 20,000.00
CUS019	Hollister Rd & Moffat Creek MD Culvert	60	1-5 years	Structure Replacement	\$ 278,000.00	\$ 85,000.00	\$ 363,000.00	Rehabilitation/ Replacement study	\$ 20,000.00
CUS020	Hollister Rd Equalizer Culvert	60	1-5 years	Structure Replacement	\$ 297,000.00	\$ 85,000.00	\$ 382,000.00	Rehabilitation/ Replacement study	\$ 20,000.00
CUS021	Nesbitt Rd & Whittaker MD Culvert	75							
CUS022	Nesbitt Rd & Barkley Creek MD Culvert	65	1-5 years	Structure Replacement	\$ 462,000.00	\$ 85,000.00	\$ 547,000.00	Rehabilitation/ Replacement study, Monitoring crack width	\$ 22,500.00

APPENDIX C-1

BRIDGES
(18 STRUCTURES)

Appendix C-1: Summary of Maintenance Needs -Bridges

[illegible]

APPENDIX C-2

CULVERTS
(31 STRUCTURES)

Appendix C-2: Summary of Maintenance Needs - Culverts

[illegible]

APPENDIX D

BCI SUMMARY

Appendix D: BCI Summary							
Bridges				Culverts			
No #	BCI	No #	BCI	No #	BCI	No #	BCI
BRH001	70			CUC001	70		
BRH002	73			CUC002	74		
BRH003	73			CUC003	74		
BRH004				CUC004	74		
BRH005	65			CUC005	71		
BRH006	71			CUC006	59		
BRH007	73			CUC007	74		
BRH008	73			CUC008	43		
BRH009	58			CUC009	74		
BRH010	75			CUS001	75		
BRH011	73			CUS002	67		
BRH012	41			CUS003	75		
BRH013	72			CUS004	66		
BRH014	73			CUS005	64		
BRH015	71			CUS006	59		
BRH016	75			CUS007			
BRH017	74			CUS008	70		
BRT001	75			CUS009	75		
				CUS010	41		
				CUS011	69		
				CUS012	64		
				CUS013	73		
				CUS014	62		
				CUS015	73		
				CUS016	63		
				CUS017	75		
				CUS018	47		
				CUS019	60		
				CUS020	60		
				CUS021	75		
				CUS022	65		

APPENDIX E

10 YEAR ASSET MANAGEMENT PLAN

Appendix E- 10 Year Asset Management Plan

	Recommended Work					Further Investigations			
Year	Structure #	Structure Name	Type	Structure Description	Cost Estimate	Type	Structure #	Structure Name	Cost Estimate
2023	CUS010	Development Rd CPR Railway Culvert	Replacement	3-Cell CSP Round Culvert	\$ 452,000.00	Rehabilitation/ Replacement study	CUS004	Jennings Rd & Castor Extension MD Culvert	\$ 20,000.00
	CUS018	Webb Rd & Whittaker MD Culvert	Replacement	4-Cell CSP Round Culvert	\$ 252,000.00	Rehabilitation/ Replacement study	BRH012	Nation Valley Rd & Barkley Creek Bridge	\$ 20,000.00
	CUS004	Jennings Rd & Castor Extension MD Culvert	Design & Tender		\$ 40,000.00	Rehabilitation/ Replacement study	BRH006	Development Rd & North Branch of South Nation River MD Bridge	\$ 20,000.00
	BRH012	Nation Valley Rd & Barkley Creek Bridge	Design & Tender		\$ 50,000.00	Rehabilitation/ Replacement study	CUC008	Liscumb Rd & Tighe MD Culvert	\$ 20,000.00
	Total				\$ 794,000.00	Total \$ 80,000.00			
2024	CUS004	Jennings Rd & Castor Extension MD Culvert	Replacement	SPCSP Arch Culvert	\$ 337,000.00	Deck Condition Surveys	BRH013, BRH002, BRH003, BRH007, BRH014, BRH017, BRH016, BRH001, BRH008	Multiple Structures	\$ 90,000.00
	BRH012	Nation Valley Rd & Barkley Creek Bridge	Replacement	Concrete Rigid Frame CIP T-Beam	\$ 560,000.00		Rehabilitation/ Replacement study	BRH011	Nation Valley Rd & South Nation River Bridge
		Guiderail Contract	Design & Tender	CUC006, CUS012, CUS002, CUS011, CUS008, CUC003, CUC009, CUS009, CUS001, CUS003, CUS017	\$ 60,000.00				
		Misc. Bridge Repairs	Design & Tender	BRH006, BRH013, BRH011, BRH002, BRH003, BRH007, BRH014, BRH017	\$ 50,000.00				
	Total				\$ 1,007,000.00	Total \$ 110,000.00			
2025		Guiderail Contract	Design & Tender	CUC006, CUS012, CUS002, CUS011, CUS008, CUC003, CUC009, CUS009, CUS001, CUS003, CUS017	\$ 528,000.00	Rehabilitation/ Replacement study	CUS020	Hollister Rd Equalizer Culvert	\$ 20,000.00
		Misc. Bridge Repairs	Rehabilitation	BRH006, BRH013, BRH011, BRH002, BRH003, BRH007, BRH014, BRH017	\$ 729,500.00	Rehabilitation/ Replacement study	CUS019	Hollister Rd & Moffat Creek MD Culvert	\$ 20,000.00
	CUS020	Hollister Rd Equalizer Culvert	Design & Tender		\$ 40,000.00	Rehabilitation/ Replacement study	CUS005	Kerrs Ridge Rd Allowance & Castor Extension MD Culvert	\$ 20,000.00
	CUS019	Hollister Rd & Moffat Creek MD Culvert	Design & Tender		\$ 40,000.00				
	Total				\$ 1,337,500.00	Total \$ 60,000.00			
2026	CUS020	Hollister Rd Equalizer Culvert	Replacement	2-Cell CSP Round Culvert	\$ 382,000.00	Rehabilitation/ Replacement study	BRH009	Cameron Rd & Near Boundary Rd Bridge	\$ 20,000.00
	CUS019	Hollister Rd & Moffat Creek MD Culvert	Replacement	2-Cell CSP Culvert	\$ 363,000.00	Rehabilitation/ Replacement study	CUS006	Spruit Rd & Castor Extension MD Culvert	\$ 20,000.00
	BRH009	Cameron Rd & Near Boundary Rd Bridge	Design & Tender		\$ 40,000.00	Rehabilitation/ Replacement study	CUS022	Nesbitt Rd & Barkley Creek MD Culvert	\$ 20,000.00
	CUS006	Spruit Rd & Castor Extension MD Culvert	Design & Tender		\$ 40,000.00	Rehabilitation/ Replacement study	CUS014	River Rd & Kittle Creek MD Culvert	\$ 20,000.00
	Total				\$ 825,000.00	Total \$ 80,000.00			
2027	BRH009	Cameron Rd & Near Boundary Rd Bridge	Major Rehabilitation	Slab on Steel I-Girders	\$ 480,000.00	Rehabilitation/ Replacement study	CUS016	Guy Rd & Mullin MD Culvert	\$ 20,000.00
	CUS006	Spruit Rd & Castor Extension MD Culvert	Replacement	SPCSP Arch Culvert	\$ 291,000.00	Rehabilitation/ Replacement study	CUS004	Jennings Rd & Castor Extension MD Culvert	\$ 20,000.00
	CUS022	Nesbitt Rd & Barkley Creek MD Culvert	Design & Tender		\$ 40,000.00	Rehabilitation/ Replacement study	CUS015	Guy Rd & Mullin MD Culvert	\$ 20,000.00
	CUC008	Liscumb Rd & Tighe MD Culvert	Design & Tender		\$ 50,000.00				
	Total				\$ 861,000.00	Total \$ 60,000.00			
2028	CUS022	Nesbitt Rd & Barkley Creek MD Culvert	Replacement	SPCSP Arch Culvert	\$ 547,000.00				
	CUC008	Liscumb Rd & Tighe MD Culvert	Replacement	Concrete Rigid Frame (Open Footing)	\$ 295,000.00				
	CUS016	Guy Rd & Mullin MD Culvert	Design & Tender		\$ 40,000.00				
	BRH001	Belmeade Rd & South Castor Creek Bridge	Design & Tender		\$ 50,000.00				
	Total				\$ 932,000.00	Total \$ -			
2029	CUS016	Guy Rd & Mullin MD Culvert	Replacement	SPCSP Arch Culvert	\$ 421,000.00				
	BRH001	Belmeade Rd & South Castor Creek Bridge	Minor Rehabilitation	Slab on Concrete Box Girders	\$ 560,000.00				
	CUS005	Kerrs Ridge Rd Allowance & Castor Extension MD Culvert	Design & Tender		\$ 40,000.00				
	CUS014	River Rd & Kittle Creek MD Culvert	Design & Tender		\$ 40,000.00				
	Total				\$ 1,061,000.00	Total \$ -			
2030	CUS005	Kerrs Ridge Rd Allowance & Castor Extension MD Culvert	Replacement	SPCSP Arch Culvert	\$ 325,000.00				
	CUS014	River Rd & Kittle Creek MD Culvert	Replacement	CSP Horizontal Ellipse Culvert	\$ 452,000.00				
	CUS015	Guy Rd & Mullin MD Culvert	Design & Tender		\$ 40,000.00				
		Misc. Culvert Repairs	Design & Tender	CUC006, CUC005, CUS013	\$ 40,000.00				
	Total				\$ 857,000.00	Total \$ -			
2031	CUS015	Guy Rd & Mullin MD Culvert	Replacement	SPCSP Arch Culvert	\$ 307,000.00				
		Misc. Culvert Repairs	Rehabilitation	CUC006, CUC005, CUS013	\$ 138,500.00				
	BRH005	Liscumb Rd & Annable MD Bridge	Design & Tender		\$ 50,000.00				
	Total				\$ 495,500.00	Total \$ -			
2032	BRH005	Liscumb Rd & Annable MD Bridge	Minor Rehabilitation	Concrete Rigid Frame	\$ 237,000.00				
	Total				\$ 237,000.00	Total \$ -			

ATTACHMENT 1

OSIM INSPECTION REPORTS & BCI FORMS

BRIDGES

Inventory Data:

Structure Name	Belmade Rd & South Castor Creek Bridge									
Main Hwy/Road #	Belmade Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	5.0km West of County Rd 31									
Latitude	45.1253948			Longitude	-75.4990661					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
					Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>		
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>		
					Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>		
MTO District	42 - Ottawa			Posted Speed	80 km/h		No. of Lanes	2		
Old County	SDG			AADT	360		% Trucks	<input type="checkbox"/>		
Geographic Twp.	<input type="text"/>			Inspection Route Sequence	<input type="text"/>					
Structure Type	Slab on Concrete Box Girders			Interchange Number	<input type="text"/>					
Total Deck Length	12.2		m	Interchange Structure Number	<input type="text"/>					
Overall Str. Width	10.5		m	Min. Vertical Clearance	<input type="text"/> m					
Total Deck Area	128.1		sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>		
					School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>		
Roadway Width	7.0		m	Detour Length Around Bridge	<input type="text"/> km					
Skew Angle	20		Degrees	Direction of Structure	East/West					
No. of Spans	1			Fill on Structure	<input type="text"/> m					
Span Lengths	12.2		m							

Historical Data:

Year Built	1981	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	October 8, 2020	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.63		
OSIM		2022	70.00		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 8, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Avasar Pradaliya, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Partly Cloudy				
Temperature:	1 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:		X		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	X			
	Concrete Substructure Condition Survey:	X			
	Detailed Coating Condition Survey:	X			
	Detailed Timber Investigation:	X			
	Post-Tensioned Strand Investigation:	X			
Underwater Investigation:		X			
Fatigue Investigation:		X			
Seismic Investigation:		X			
Structure Evaluation:		X			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	X			
	Monitoring Crack Widths:	X			
Investigation Notes:	Deck Condition Survey Recommended Based on Age of Structure				

Overall Structure Notes:								
Recommended Work on	<input type="checkbox"/>	None	<input checked="" type="checkbox"/> X	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input type="checkbox"/>	Replace
Timing of Recommended Work:			<input checked="" type="checkbox"/> X	1 to 5 years		<input type="checkbox"/>	6 to 10 years	
Overall Comments:	Structure is in generally good to fair condition. Failure of east expansion joint was noted with damage to the surrounding concrete on the fascia. Impact damage at NE barrier, pothole in west approach, spalls noted in barrier posts, Scaling and spalls noted on curbs, map cracking on soffit.							
Date of Next Inspection:	2024							

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	NE: 73.7, SE: 36, SW: 70.4, NW: 36.2					
Element Name:	Barrier	Width:						
Location:	NE, SE, NW & SW of Structure	Height:						
Material:	Steel	Count (items):	4					
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	216.3 m					
Environment:	Severe	Limited Inspection						
Protection System:	None					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m		212.3		4			
Comments:	Generally in good condition. Delineators missing at all four corners. Impact damage noted at northeast							
Recommended Work:		Rehab		Replace	Maintenance Needs: 18 - (Other)			
		1-5 years		6-10 years	X	Urgent	1 year	2 years
					Install delineators at all corners			

Element Group:	Approaches	Length:	12.2					
Element Name:	Curb and Gutters	Width:						
Location:	NE, SE, NW & SW of Structure	Height:	0.3					
Material:	Cast-In-Place Concrete	Count (items):	4					
Element Type:	Concrete Curb & Gutters	Total Quantity:	48.0 m					
Environment:	Severe	Limited Inspection						
Protection System:	None					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m		48.8					
Comments:	Generally in good condition							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Approaches	Length:	6						
Element Name:	Wearing Surface	Width:	7						
Location:	East and West Side of Structure	Height:							
Material:	Asphalt	Count (items):	2						
Element Type:	Asphalt Surface Treatment	Total Quantity:	84.0 m ²						
Environment:	Severe	Limited Inspection							
Protection System:	None					Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		76.4	5.0	2.5				
Comments:	Evidence of localized settlement and edge alligator cracking was noted on both west and east asphalt surface treatments. Pothole noted on West approach								
Recommended Work:		Rehab		Replace	Maintenance Needs: 15				
		1-5 years		6-10 years		Urgent	1 year	X	2 years
					Repair asphalt surface treatment and patch pothole				

Element Group:	Joins	Length:	9.2				
Element Name:	Armouring/Retaining Devices	Width:					
Location:	East Side of Structure	Height:					
Material:	Other	Count (items):					
Element Type:	Expansion Joint Armouring	Total Quantity:	9.2	m			
Environment:	Severe	Limited Inspection	X				
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m				9.2		
Comments:	Structure lacks expansion joint on west deck end. East expansion joint has been partially paved over and inspection was restricted. Minor corrosion was noted on expansion joint armouring over safety curb. Severe disintegration was noted on fascia adjacent to the expansion joint which could be result of leakage from expansion joint. Leaking failure and deformation at northeast.						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Barriers	Length:	1.6				
Element Name:	Posts	Width:	0.4				
Location:	NE, NW, SE & SW of Structure	Height:	1				
Material:	Cast-In-Place Concrete	Count (items):	4				
Element Type:	Reinforced concrete End Posts	Total Quantity:	15.36	m ²			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		15.16	0.2			
Comments:	Generally in good condition with some light spalls at bases of west posts.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Barriers	Length:	23				
Element Name:	Railing System	Width:					
Location:	North and South Sides of Structure	Height:					
Material:	Steel	Count (items):	2				
Element Type:	3 Rail Metal Railing on Steel Posts	Total Quantity:	46	m			
Environment:	Severe	Limited Inspection					
Protection System:	Hot Dip Galvanizing					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		46				
Comments:	Generally in good condition						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Barriers	Length:						
Element Name:	Posts	Width:						
Location:	North and South Sides of Structure	Height:						
Material:	Steel	Count (items):	22					
Element Type:	Steel Posts	Total Quantity:	22 Each					
Environment:	Severe	Limited Inspection						
Protection System:	Hot Dip Galvanizing					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		21		1			
Comments:	Generally in good condition. Disconnected and damaged barrier post at northeast							
Recommended Work:		Rehab		Replace	Maintenance Needs: 18			
		1-5 years		6-10 years	X	Urgent	1 year	2 years
					Replace barrier post			

Element Group:	Sidewalk/Curbs	Length:	26.2					
Element Name:	Curbs	Width:	1.0					
Location:	North South Sides of Structure	Height:	0.25					
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Reinforced Concrete Curbs	Total Quantity:	65.5 m ²					
Environment:	Severe	Limited Inspection						
Protection System:	None					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		51.9	12.4	1.2			
Comments:	Minor abrasions and medium to wide cracks were noted. Scaling and spalling at southwest curb flare present. Narrow-medium cracks notes with possible alkali-aggregate reaction.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Decks	Length:	12.2					
Element Name:	Wearing Surface	Width:	7					
Location:	Top of Deck	Height:						
Material:	Asphalt	Count (items):						
Element Type:	Asphalt Surface Treatment	Total Quantity:	85.4 m ²					
Environment:	Severe	Limited Inspection						
Protection System:	None					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		81.8	2.4	1.2			
Comments:	Narrow to medium map cracking and edge cracking were noted. Bridge deck has been covered by asphalt surface treatment layer with no waterproofing layer which could have adverse impact on superstructure in long-term. Ponding was noted along all sides (Exposed deck with no drains)							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Decks	Length:	17.4				
Element Name:	Deck Top	Width:	10.5				
Location:	Top of Deck	Height:					
Material:	Cast-in-Place Concrete	Count (items):					
Element Type:	Deck Top	Total Quantity:	182.7	m ²			
Environment:	Moderate	Limited Inspection	X				
Protection System:	Asphalt Surface Treatment					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good 181.2	Fair 1.0	Poor* 0.5		
Comments:	Previous inspection notes localized spall on the exposed surface of deck - not observed at the time of inspection.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Decks	Length:	9.4				
Element Name:	Soffit - Thin Slab	Width:	1.55				
Location:	North and South Sides of Structure	Height:					
Material:	Precast Concrete	Count (items):	2				
Element Type:	Soffit - Exterior	Total Quantity:	29.14	m ²			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good 8.74	Fair 11.66	Poor* 8.74		
Comments:	Evidence of severe disintegration was noted on south fascia adjacent to expansion joint. Evidence of localized spalls was noted on soffit exterior. Wide map cracking along southwest half of soffit and most of north side.						
Recommended Work:	X	Rehab		Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	
Concrete repair to soffit exterior adjacent to expansion joint							

Element Group:	Decks	Length:	2.0				
Element Name:	Soffit - Thin Slab	Width:	9.6				
Location:	East Underside of Structure	Height:					
Material:	Precast Concrete	Count (items):	1				
Element Type:	Soffit - End	Total Quantity:	19.2	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good 17.4	Fair 1.2	Poor* 0.6		
Comments:	Wide cracks and efflorescence was noted on east bridge end adjacent to expansion joint						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Decks	Length:	9.4					
Element Name:	Soffit - Thin Slab	Width:	9.6					
Location:	Underside of Structure	Height:						
Material:	Precast Concrete	Count (items):						
Element Type:	Soffit - Interior	Total Quantity:	90.2	m ²				
Environment:	Benign	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		90.2					
Comments:	Generally in good condition							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Abutments	Length:						
Element Name:	Bearings	Width:						
Location:	East and West Abutment Walls	Height:						
Material:	Plastic	Count (items):	16					
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	16	Each				
Environment:	Benign	Limited Inspection			X			
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		16					
Comments:	Generally in good condition, limited access to bearing pads, condition is based on accessible bearing pads							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Abutments	Length:						
Element Name:	Ballast Walls	Width:	9.6					
Location:	East and West Abutment Walls	Height:	0.9					
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Reinforced Concrete Walls	Total Quantity:	17.3	m ²				
Environment:	Benign	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		17.3					
Comments:	Ballast walls were inaccessible for inspection due to box girders. Condition state is based on the visible sections of the ballast walls. Visible sections of the ballast walls were in good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Abutment	Length:							
Element Name:	Abutment Walls	Width:	9.6						
Location:	East and West Underside of Structure	Height:	3.2						
Material:	Cast-in-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	61.4 m ²						
Environment:	Benign	Limited Inspection	X						
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		49.40	10	2				
Comments:	Generally in good to fair condition with narrow AAR cracking throughout. Wide vertical crack at full height on east and west side.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Abutments	Length:	7.0						
Element Name:	Wingwalls	Width:							
Location:	NE, SE, NW & SW OF Structure	Height:	1.5						
Material:	Cast-in-place Concrete	Count (items):	4.0						
Element Type:	Reinforced Concrete Walls	Total Quantity:	42.0 m ²						
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		29.4	12.6					
Comments:	Generally in good to fair condition with medium map cracking throughout.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Abutment Walls and Wingwalls	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection		X					
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:								
Element Name:	Embankments	Width:								
Location:	NE, SE, NW & SW Side of Structure	Height:								
Material:	Native Material	Count (items):	4							
Element Type:	Embankment	Total Quantity:	Each							
Environment:	Moderate	Limited Inspection								
Protection System:	Vegetation						Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each		4.00							
Comments:	Embankments are moderately sloped and well vegetated.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams	Length:								
Element Name:	Streams and Waterways	Width:								
Location:	Below Structure	Height:								
Material:	Native	Count (items):	All							
Element Type:	Stream	Total Quantity:	All N/A							
Environment:	Benign	Limited Inspection								
Protection System:	None						Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Low volume and moderate flow with no obstructions noted.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Armouring Joint	Replace armouring joint and seal		X		\$ 60,000.00
Deck Soffit/Fascia	Localized Concrete Repair associated with Joint deficiency		X		\$ 10,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 75,000.00

Associated Work	Comments	Estimated Cost
Approaches		\$ -
Detours		\$ -
Traffic Control		\$ -
Utilities		\$ -
Right of Way		\$ -
Environmental Study		\$ -
Other		\$ -
Contingencies		\$ -
Total cost:		\$ -

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD. & SOUTH CASTOR
CREEK BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH001




Photo 1 Structure from east approach




Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD. & SOUTH CASTOR
CREEK BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH001



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD. & SOUTH CASTOR
CREEK BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH001



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

BELMADE RD. & SOUTH CASTOR
CREEK BRIDGE

SITE PHOTOGRAPHS

Site No.:BRH001



Photo 7 Alligator cracking in west approach wearing surface



Photo 8 Pothole in west approach

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD. & SOUTH CASTOR
CREEK BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH001



Photo 9 Spall on northeast barrier curb



Photo 10 Impact damage at northeast approach barrier

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD. & SOUTH CASTOR
CREEK BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH001



Photo 11 Spall at east joint and deck



Photo 12 Disconnected and damaged barrier post

MUNICIPAL STRUCTURE INSPECTION FORM

BELMADE RD. & SOUTH CASTOR
CREEK BRIDGE

SITE PHOTOGRAPHS

Site No.:BRH001



Photo 13 Spall and efflorescence at southeast joint and deck fascia



Photo 14 Wide vertical crack in east abutment wall with possible AAR

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD. & SOUTH CASTOR
CREEK BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH001



Photo 15 Evidence of joint failure at east abutment wall



Photo 16 Scaling on deck barrier curb

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD. & SOUTH CASTOR
CREEK BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH001



Photo 17 Scaling on curb and damage at northeast joint

Structure Condition Summary Form

Structure Name Belmade Rd & South Castor Creek Bridge
Structure Number BRH001
Date of Inspection December 8, 2022
Consultant HP Engineering Inc.
Contract Number 22087 (HP)

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in	Element	Element	Element	Total Replaceme	Current Element	Element	Performance	Maintenance
					excellent condition (1.00)	Quantity in Good Condition (0.75)	Quantity in Fair Condition (0.4)	Quantity in Poor Condition (0)					
Abutment	Abutment Walls	Sq.m	900.00	61.4		49.4	10	2	55260	36945	67	00	00
	Ballast Walls	Sq.m	350.00	17.3		17.3			6055	4541	75	00	00
	Bearings	Each	1000.00	16		16			16000	12000	75	00	00
	Wingwalls	Sq.m	350.00	42		29.4	12.6		14700	9482	65	00	00
Approaches	Curb and Gutters	m	25.00	48.8		48.8			1220	915	75	00	00
	Barrier	m	0.00	216.3		212.3		4	0	0		00	18
	Wearing Surface	Sq.m	6.00	83.9		76.4	5	2.5	503	356	71	00	15
Barriers	Posts (Concrete)	Sq.m	200.00	13.56		13.36	0.2		2712	2020	74	00	00
	Posts (Steel)	Each	200.00	22		21		1	4400	3150	72	00	00
	Railing Systems	m	200.00	46		46			9200	6900	75	00	00
Decks	Deck Top-Thin Slab	Sq.m	120.00	182.7		181.2	1	0.5	21924	16356	75	00	00
	Soffit- Thin Slab	Sq.m	120.00	138.54		116.34	12.86	9.34	16625	11088	67	00	00
	Wearing Surface	Sq.m	25.00	85.4		81.8	2.4	1.2	2135	1558	73	00	00
Embankments and	Embankments	Each	0.00	4		4			0	0		00	00
Joints	Armouring / Retaining Devices	m	1.00	9.2				9.2	9	0		00	00
Sidewalks/ Curbs	Curbs	Sq.m	40.00	65.5		51.9	12.4	1.2	2620	1755	67	00	00
									153363	107066			

Conditon Index 70

Inventory Data:

Structure Name	Belmade Rd & South Castor River Bridge									
Main Hwy/Road #	Belmade Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	2.1km West of County Rd 31									
Latitude	45.1366902			Longitude	-75.4657242					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
					Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>		
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>		
					Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>		
MTO District	42 - Ottawa			Posted Speed	80 km/h		No. of Lanes	2		
Old County	SDG			AADT	360		% Trucks	<input type="checkbox"/>		
Geographic Twp.	<input type="text"/>			Inspection Route Sequence	<input type="text"/>					
Structure Type	Slab on Concrete Box Girders			Interchange Number	<input type="text"/>					
Total Deck Length	17.4		m	Interchange Structure Number	<input type="text"/>					
Overall Str. Width	10.5		m	Min. Vertical Clearance	<input type="text"/> m					
Total Deck Area	182.7		sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>		
					School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>		
Roadway Width	7.3		m	Detour Length Around Bridge	<input type="text"/> km					
Skew Angle	0		Degrees	Direction of Structure	East/West					
No. of Spans	1			Fill on Structure	<input type="text"/> m					
Span Lengths	16.6		m							

Historical Data:

Year Built	1981	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	October 8, 2020	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	73.36		
OSIM		2022	73.00		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 8, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Avasar Pradaliya, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Partly Cloudy				
Temperature:	1 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:		x		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
Investigation Notes:	Deck Condition Survey Recommended Based on Age of Structure				

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years					
Overall Comments:	Structure is in generally good to fair condition. Failure of east expansion joint was noted with damage to the surrounding concrete on the fascia. Wide cracks on concrete barrier posts/walls. Cracks present at northwest wingwall. Aggradation and vegetation growth along sides of approach wearing surface.						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Accessories (Attachments and Signs)				Length:				
Element Name:	Signs				Width:				
Location:	NE and SW Side of structure				Height:				
Material:	Steel				Count (items):	2			
Element Type:	Hazard Markers				Total Quantity:	2.0 Each			
Environment:	Severe				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units		Exc.		Good	Fair		Poor*	
	Each							2	
Comments:	Approaches to the structure are missing hazard markers on northwest and southeast sides. Hazard markers on both sides (northeast & southwest) have been tilted and damaged.								
Recommended Work:			Rehab		Replace	Maintenance Needs: 18 - (Other)			
			1-5 years		6-10 years	X	Urgent	1 year	2 years
						Replace and install hazard markers at all four quadrants			

Element Group:	Approaches				Length:	NE: 74, SE: 35.4, SW: 74.7, NW: 36.3			
Element Name:	Barriers				Width:				
Location:	NE, SE, NW & SW of Structure				Height:				
Material:	Steel				Count (items):	4			
Element Type:	Steel Flex Beam on Steel Posts (SBGR)				Total Quantity:	220.4 m			
Environment:	Severe				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units		Exc.		Good	Fair		Poor*	
	m				220.4				
Comments:	Generally in good condition								
Recommended Work:			Rehab		Replace	Maintenance Needs:			
			1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Approaches				Length:	12			
Element Name:	Curb and Gutters				Width:				
Location:	NE, NW, SW & SE Side of Structure				Height:	0.3			
Material:	Cast-in-Place Concrete				Count (items):	4			
Element Type:	Concrete Curb & Gutters				Total Quantity:	48.0 m			
Environment:	Severe				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units		Exc.		Good	Fair		Poor*	
	m				48				
Comments:	Generally in good condition								
Recommended Work:			Rehab		Replace	Maintenance Needs:			
			1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Approaches	Length:	6.0					
Element Name:	Wearing Surface	Width:	7.3					
Location:	East and West Sides of Structure	Height:						
Material:	Asphalt	Count (items):	2					
Element Type:	Asphalt Surface Treatment	Total Quantity:	87.6	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		79.70	5	2.6			
Comments:	Evidence of localized settlement was noted on both west and east asphalt surface treatments. Longitudinal alligator cracking at sides and transverse alligator cracking at west joint.							
Recommended Work:		Rehab		Replace	Maintenance Needs: 12			
		1-5 years		6-10 years	Urgent	X	1 year	2 years
					Repair asphalt surface treatment on approaches. Route and seat cracks			

Element Group:	Joints	Length:	10.5					
Element Name:	Other	Width:						
Location:	East Side of Structure	Height:						
Material:	Other	Count (items):						
Element Type:	Expansion Joints	Total Quantity:	10.5	m ²				
Environment:	Severe	Limited Inspection	X					
Protection System:	Asphalt Wearing Surface						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²				10.5			
Comments:	Structure lacks expansion joint on west deck end. East expansion joint has been paved over and inspection was restricted. East expansion joint over safety curbs has been covered with steel plate. Severe disintegration was noted on fascia adjacent to the expansion joint which could be result of leakage from expansion joint.							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
	X	1-5 years		6-10 years	Urgent		1 year	2 years

Element Group:	Barriers	Length:	1.6					
Element Name:	Posts	Width:	0.4					
Location:	NE, NW, SW & SE Side of Structure	Height:	1.0					
Material:	Cast-in-place concrete	Count (items):	4					
Element Type:	Reinforced Concrete End Posts	Total Quantity:	15.36	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		13.1	7	3			
Comments:	Wide cracks, medium to severe delamination, and spall was noted. Possible AAR with efflorescence.							
Recommended Work:	X	Rehab		Replace	Maintenance Needs:			
	X	1-5 years		6-10 years	Urgent		1 year	2 years
Repair concrete end posts/walls								

Element Group:	Barriers	Length:						
Element Name:	Railing Systems	Width:						
Location:	North and South of Structure	Height:						
Material:	Steel	Count (items):	22					
Element Type:	Steel Posts	Total Quantity:	22 Each					
Environment:	Severe	Limited Inspection						
Protection System:	Hot Dip Galvanizing							Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies		
	Each		22					
Comments:	Generally in good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Sidewalk/Curbs	Length:	27.4					
Element Name:	Curbs	Width:	1.0					
Location:	North South Sides of Structure	Height:	0.25					
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Reinforced Concrete Curbs	Total Quantity:	68.5 m ²					
Environment:	Severe	Limited Inspection						
Protection System:	None							Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies		
	m ²		64.9	2.4	1.2			
Comments:	Minor scaling and abrasions due to snow plow machines noted. Localized spall and abrasion. Medium spall at northeast joint.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	X 2 years
					Concrete repairs			

Element Group:	Decks	Length:	17.4					
Element Name:	Wearing Surface	Width:	7.3					
Location:	Top of Deck	Height:						
Material:	Asphalt	Count (items):						
Element Type:	Asphalt Surface Treatment	Total Quantity:	127.0 m ²					
Environment:	Severe	Limited Inspection						
Protection System:	None							Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies		
	m ²		116.8	10.0	0.2			
Comments:	Generally in good condition. Surface treatment does not cover full width of deck and is not waterproofed which may have adverse impact on superstructure in long term.							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years
Waterproof and repave								

Element Group:	Decks	Length:	17.4				
Element Name:	Deck Top - Thin slab	Width:	10.5				
Location:	Top of Deck	Height:					
Material:	Cast-in-Place Concrete	Count (items):					
Element Type:	Deck Top	Total Quantity:	182.7	m ²			
Environment:	Severe	Limited Inspection	X				
Protection System:	Asphalt Surface Treatment					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		182.7	10.0	0.2		
Comments:	light Scaling, ponding, and light raveling noted in exposed portion of deck.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	14.6				
Element Name:	Soffit - Thin Slab	Width:	1.55				
Location:	North and South Sides of Structure	Height:					
Material:	Precast Concrete	Count (items):	2				
Element Type:	Soffit - Exterior	Total Quantity:	45.3	m ²			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		42.00	2.00	1.20		
Comments:	Severe disintegration was noted on south fascia adjacent to expansion joint. Localized spalls was noted on soffit exterior. AAR noted near concret barrier						
Recommended Work:	X	Rehab	Replace	Maintenance Needs:			
	X	1-5 years	6-10 years	Urgent	1 year	2 years	
Concrete repair to soffit exterior adjacent to expansion joint							

Element Group:	Decks	Length:	2.0				
Element Name:	Soffit - Thin Slab	Width:	9.6				
Location:	East Underside of Structure	Height:					
Material:	Precast Concrete	Count (items):	1				
Element Type:	Soffit - End	Total Quantity:	19.2	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		19.2	0.2	0.1		
Comments:	Generally in good condition (box girders) with small spalls on south fascia						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	14.6				
Element Name:	Soffit - Thin Slab	Width:	9.6				
Location:	Underside of Structure	Height:					
Material:	Precast Concrete	Count (items):					
Element Type:	Soffit - Interior	Total Quantity:	140.2	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		140.2	0	0		
Comments:	Generally in good condition (box girders) with small spall at center						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutments	Length:					
Element Name:	Bearings	Width:					
Location:	East and West Abutment Walls	Height:					
Material:	Plastic	Count (items):	16				
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	16	Each			
Environment:	Benign	Limited Inspection		X			
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		16				
Comments:	Generally in good condition, limited access to bearing pads, condition is based on accessible bearing pads						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutments	Length:					
Element Name:	Ballast Walls	Width:	9.6				
Location:	East and West Abutment Walls	Height:	0.9				
Material:	Cast-In-Place Concrete	Count (items):	2				
Element Type:	Reinforced Concrete Walls	Total Quantity:	17.3	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		17.3				
Comments:	Ballast walls were inaccessible for inspection due to box girders. Condition state is based on the visible sections of the ballast walls. Visible sections of the ballast walls were in good condition.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutment	Length:							
Element Name:	Abutment Walls	Width:	9.6						
Location:	East and West Underside of Structure	Height:	3.2						
Material:	Cast-in-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	61.4 m ²						
Environment:	Benign	Limited Inspection	X						
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		57.00	3	1				
Comments:	Generally in good to fair condition with narrow AAR crackig throughout. Wide vertical crack at full height on east and west side.								
Recommended Work:	X	Rehab		Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years
Concrete repairs on abutment walls									

Element Group:	Abutments	Length:	5.0						
Element Name:	Wingwalls	Width:							
Location:	NE, SE, NW & SW OF Structure	Height:	1.5						
Material:	Cast-in-place Concrete	Count (items):	4.0						
Element Type:	Reinforced Concrete Walls	Total Quantity:	30.0 m ²						
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		26.5	2.5	1				
Comments:	Evidence of wide map cracking was noted at northeast and northwest								
Recommended Work:	X	Rehab		Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years
Concrete repairs to wingwalls									

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Abutment Walls and Wingwalls	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams				Length:					
Element Name:	Embankments				Width:					
Location:	NE, SE, NW & SW Side of Structure				Height:					
Material:	Native Material				Count (items):	6				
Element Type:	Embankment				Total Quantity:	6 Each				
Environment:	Moderate				Limited Inspection					
Protection System:	Vegetation								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each		4.00							
Comments:	Embankments are moderately sloped and well vegetated.									
Recommended Work:			Rehab		Replace	Maintenance Needs:				
			1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams				Length:					
Element Name:	Streams and Waterways				Width:					
Location:	Below Structure				Height:					
Material:	Native				Count (items):	All				
Element Type:	Stream				Total Quantity:	All N/A				
Environment:	Benign				Limited Inspection					
Protection System:	None								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Low volume and low flow from south to north with no flow obstructions noted. Meander present downstream (north)									
Recommended Work:			Rehab		Replace	Maintenance Needs:				
			1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Armouring Joint	Replace armouring joint and seal		X		\$ 60,000.00
Deck Soffit/Fascia	Localized Concrete Repair associated with Joint deficiency		X		\$ 10,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 60,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD & SOUTH CASTOR
RIVER BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH002



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD & SOUTH CASTOR
RIVER BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH002



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD & SOUTH CASTOR
RIVER BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH002



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

BELMADE RD & SOUTH CASTOR
RIVER BRIDGE

SITE PHOTOGRAPHS

Site No.:BRH002



Photo 7 Pothole, patch, and crack at southwest approach wearing surface



Photo 8 Vegetation and aggradation at southwest approach (typical)

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD & SOUTH CASTOR
RIVER BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH002



Photo 9 Spall on northwest barrier curb at transition



Photo 10 Wide AAR cracking at northwest barrier end wall

MUNICIPAL STRUCTURE INSPECTION FORM

**BELMADE RD & SOUTH CASTOR
RIVER BRIDGE**

SITE PHOTOGRAPHS

Site No.:BRH002



Photo 11 Spall at northeast barrier curb near joint



Photo 12 Wide crack at northeast barrier end wall

MUNICIPAL STRUCTURE INSPECTION FORM

BELMADE RD & SOUTH CASTOR
RIVER BRIDGE

SITE PHOTOGRAPHS

Site No.:BRH002



Photo 13 Spall at southeast joint and deck fascia



Photo 14 Exposed concrete deck top beside surface treatment

MUNICIPAL STRUCTURE INSPECTION FORM

BELMADE RD & SOUTH CASTOR
RIVER BRIDGE

SITE PHOTOGRAPHS

Site No.:BRH002



Photo 15 Evidence of leaking and joint failure at east abutment wall



Photo 16 Small spall on south box girder side (named as soffit in report)

MUNICIPAL STRUCTURE INSPECTION FORM

BELMADE RD & SOUTH CASTOR
RIVER BRIDGE

SITE PHOTOGRAPHS

Site No.:BRH002



Photo 17 Cracks in northwest abutment wall



Photo 18 Crack in west abutment wall

Structure Condition Summary Form

Structure Name Belmade Rd & South Castor River Bridge
Structure Number BRH002
Date of Inspection December 8, 2022
Consultant HP Engineering Inc.
Contract Number 22087 (HP)

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in excellent condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Abutment	Abutment Walls	Sq.m	900.00	61		57	3	1	54900	39555	72	00	00
	Ballast Walls	Sq.m	350.00	17.3		17.3			6055	4541	75	00	00
	Bearings	Each	1000.00	16		16			16000	12000	75	00	00
	Wingwalls	Sq.m	350.00	30		26.5	2.5	1	10500	7306	70	00	00
Accessories	Signs	Each	0.00	2				2	0	0		00	18
Approaches	Curb and Gutters	m	25.00	48		48			1200	900	75	00	00
	Barrier	m	0.00	220.4		220.4			0	0		00	00
	Wearing Surface	Sq.m	6.00	87.3		79.7	5	2.6	524	371	71	00	12
Barriers	Posts (Concrete)	Each	200.00	15.36		13.1	7	3	3072	2525	82	00	00
	Posts (Steel)	Each	200.00	22		22			4400	3300	75	00	00
Decks	Deck Top-Thin Slab	Sq.m	120.00	192.9		182.7	10	0.2	23148	16923	73	00	00
	Soffit- Thin Slab	Sq.m	120.00	204.9		201.4	2.2	1.3	24588	18232	74	00	00
	Wearing Surface	Sq.m	25.00	127		116.8	10	0.2	3175	2290	72	00	00
Embankments and	Embankments	Each	0.00	4		4			0	0		00	00
Streams	Streams and Waterways	All	0.00	1		1			0	0		00	00
Foundations	Foundations (below ground level)	N/A	0.00	1		1			0	0		00	00
Joints	Armouring / Retaining Devices	m	1.00	10.5				10.5	11	0		00	00
Sidewalks/ Curbs	Curbs	Sq.m	40.00	68.5		64.9	2.4	1.2	2740	1985	72	00	08
									150312	109928			

Conditon Index 73

Inventory Data:

Structure Name	Ormond Bridge				
Main Hwy/Road #	Ormond Road	Services on structure:	Navig. Water	Non-Navig.	Ped.
	On Structure		Rail	Road	Other
	Under Structure			X	
		Services under structure:	Navig. Water	Non-Navig.	Ped.
			Rail	Road	Other
				X	
Structure Location	0.2km West of Bisson Road				
Latitude	45.1653584	Longitude	-75.3556303		
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid. Desig./not list	Cons/not App. Desig. & List	List/n.d.
			X		
MTO Region	40 - Eastern	Road Class:	Freeway	Arterial	
			Collector	Local	X
MTO District	42 - Ottawa	Posted Speed	80 km/h	No. of Lanes	2
Old County	SDG	AADT	40	% Trucks	
Geographic Twp.		Inspection Route Sequence			
Structure Type	Reinforced Concrete Sold Slab	Interchange Number			
Total Deck Length	32.3 m	Interchange Structure Number			
Overall Str. Width	9.1 m	Min. Vertical Clearance			
Total Deck Area	293.9 sq. m	Special Routes:	Transit	Truck	
			School	Bicycle	
Roadway Width	7.5 m	Detour Length Around Bridge			
Skew Angle	30 Degrees	Direction of Structure	East/West		
No. of Spans	3	Fill on Structure			
Span Lengths	9.4,12.7,9.4 m				

Historical Data:

Year Built	1979	Year of Last Major Rehab.	
Last OSIM Inspection	October 10, 2020	Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	72.99		
OSIM		2022	73		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	2° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:		<input checked="" type="checkbox"/> x		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input type="checkbox"/> x			
	Concrete Substructure Condition Survey:	<input type="checkbox"/> x			
	Detailed Coating Condition Survey:	<input type="checkbox"/> x			
	Detailed Timber Investigation:	<input type="checkbox"/> x			
	Post-Tensioned Strand Investigation:	<input type="checkbox"/> x			
Underwater Investigation:		<input type="checkbox"/> x			
Fatigue Investigation:		<input type="checkbox"/> x			
Seismic Investigation:		<input type="checkbox"/> x			
Structure Evaluation:		<input type="checkbox"/> x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	<input type="checkbox"/> x			
	Monitoring Crack Widths:	<input type="checkbox"/> x			
		Total Costs			\$ 15,000.00
Investigation Notes:	Deck Condition Survey Recommended Based on Age of Structure				

Overall Structure Notes:								
Recommended Work on	<input type="checkbox"/>	None	<input checked="" type="checkbox"/> X	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input type="checkbox"/>	Replace
Timing of Recommended Work:		<input checked="" type="checkbox"/> X	1 to 5 years		<input type="checkbox"/>	6 to 10 years		
Overall Comments:	New end treatments installed since previous inspection. Settlement of the approaches noted at both ends of structure with large potholes also noted. Collision damage noted on south deck barrier. Localised spall noted on both deck top and deck soffit. Medium vertical cracks on abutment walls.							
Date of Next Inspection:	December 2024							

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Sealing (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	NE: 20.9, SE: 17.1, SW: 17.1, NW: 20.9				
Element Name:	Barrier	Width:					
Location:	NE, SE, NW & SW of Structure	Height:					
Material:	Steel	Count (items):	4				
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	76.0 m				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		76				
Comments:	New end treatments installed since previous inspection. Approach barrier is generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Approaches	Length:	6				
Element Name:	Wearing Surface	Width:	7.5				
Location:	East and West Side of Structure	Height:					
Material:	Gravel	Count (items):	2				
Element Type:	Gravel Wearing Surface	Total Quantity:	90.0 m ²				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		75	10.0	5.0	9	
Comments:	Large potholes noted on approach wearing surface. Settlement noted at ends of approach at interface with deck.						
Recommended Work:		Rehab	Replace	Maintenance Needs: 12			
		1-5 years	6-10 years	Urgent	1 year	X 2 years	
	Patch potholes						

Element Group:	Joints	Length:	10.5				
Element Name:	Armouring/Retaining Devices	Width:					
Location:	East & West Side of Structure	Height:					
Material:	Steel	Count (items):	4				
Element Type:	Expansion Joint Armouring	Total Quantity:	42 m				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		41.3	0.7			
Comments:	Light to medium rust and some abrasions noted on joint armouring. Expansion joints were covered by debris.						
Recommended Work:		Rehab	Replace	Maintenance Needs: 2			
		1-5 years	6-10 years	Urgent	1 year	X 2 years	
	Clear debris						

Element Group:	Joins	Length:	10.5							
Element Name:	Concrete End Dams	Width:	0.35							
Location:	East & West Ends of Structure	Height:								
Material:	Cast-In-Place Concrete	Count (items):	2							
Element Type:	Concrete End Dams	Total Quantity:	7.35	m ²						
Environment:	Severe	Limited Inspection								
Protection System:	None								Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies				
	m ²		6.35	0.5	0.5					
Comments:	Light to medium scaling, some small spalls and some abrasions noted on the concrete end dams.									
Recommended Work:		Rehab		Replace	Maintenance Needs: 8					
		1-5 years		6-10 years		Urgent		1 year	X	2 years
					Concrete Repairs					

Element Group:	Joins	Length:	10.5							
Element Name:	Seals/Sealants	Width:								
Location:	East & West side of Structure	Height:								
Material:	Rubber	Count (items):	2							
Element Type:	Strip Seal	Total Quantity:	2	each						
Environment:	Severe	Limited Inspection	X							
Protection System:	None								Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies				
	each		2							
Comments:	Expansion joints appear to be in good condition. Seals are covered with debris.									
Recommended Work:		Rehab	X	Replace	Maintenance Needs: 2					
	X	1-5 years		6-10 years		Urgent		1 year	X	2 years
					Clear debris					

Element Group:	Barriers	Length:	0.9							
Element Name:	Barrier/Parapet Walls	Width:	0.3							
Location:	NE, NW, SE & SW of Structure	Height:	0.9							
Material:	Cast-In-Place Concrete	Count (items):	4							
Element Type:	Reinforced concrete End Posts	Total Quantity:	8.3	m ²						
Environment:	Severe	Limited Inspection								
Protection System:	None								Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies				
	m ²		8.3							
Comments:	Light scaling noted on concrete end post.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Barriers	Length:	38.4				
Element Name:	Railing System	Width:					
Location:	North and South Sides of Structure	Height:					
Material:	Steel	Count (items):	2				
Element Type:	Steel Flex Beam	Total Quantity:	76.8	m			
Environment:	Severe	Limited Inspection					
Protection System:	Hot Dip Galvanizing					Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	m		65.8	8	3		
Comments:	Light corrosion and abrasions noted on flex beam. Collision damage noted on south barrier.						
Recommended Work:		Rehab	Replace	Maintenance Needs: 3			
		1-5 years	6-10 years	Urgent	1 year	X 2 years	
				Replace damaged Sections			

Element Group:	Barriers	Length:					
Element Name:	Posts	Width:					
Location:	North and South Sides of Structure	Height:					
Material:	Cast-in-Place Concrete	Count (items):	20				
Element Type:	Reinforced Concrete Posts	Total Quantity:	20	Each			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	Each		20				
Comments:	Generally in good condition with some rotated spacers noted on posts.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Coating	Length:					
Element Name:	Railing Systems/Hand Railings	Width:					
Location:	On Bridge Railing	Height:					
Material:	Other	Count (items):					
Element Type:	Hot Dip Galvanizing	Total Quantity:	76.8	m			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	m		76.8				
Comments:	Coating is generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	32.3					
Element Name:	Deck Top (Exposed)	Width:	9.1					
Location:	Top of Deck	Height:						
Material:	Cast-in-Place Concrete	Count (items):						
Element Type:	Deck Top (Exposed)	Total Quantity:	293.93	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*			
			276.33	9.6	8.0			
Comments:	Light scaling, wide longitudinal and transverse cracks and localized spall noted on concrete deck top. Gravel and debris build up noted at edges of deck top.							
Recommended Work:		Rehab	Replace	Maintenance Needs: 2				
		1-5 years	6-10 years		Urgent	1 year	X	2 years
				Clean Debris				

Element Group:	Decks	Length:	2					
Element Name:	Soffit - Thin Slab (End)	Width:	11.5					
Location:	East & West Underside of Structure of Structure	Height:						
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Soffit - End	Total Quantity:	46.0	m ²				
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*			
			46.00					
Comments:	End portion of soffit appears to be in good condition.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year		2 years

Element Group:	Decks	Length:	28.3					
Element Name:	Soffit - Thin Slab (Exterior)	Width:	1.5					
Location:	North and South Side of Structure	Height:						
Material:	Precast Concrete	Count (items):	2					
Element Type:	Soffit - Exterior	Total Quantity:	84.9	m ²				
Environment:	Benign	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*			
			83.9	0.5	0.5			
Comments:	Small spall noted on north side of exterior soffit. Overall generally in good condition.							
Recommended Work:		Rehab	Replace	Maintenance Needs: 8				
		1-5 years	6-10 years		Urgent	1 year	X	2 years
				Concrete Repairs				

Element Group:	Decks	Length:	27.5				
Element Name:	Soffit - Thin Slab (Interior)	Width:	7.1				
Location:	Underside of Structure	Height:					
Material:	Precast Concrete	Count (items):					
Element Type:	Soffit - Interior	Total Quantity:	195.25	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		178.07	9.4	7.8		
Comments:	Wide map cracks noted throughout soffit, with localized spall noted on midspan of interior soffit. Barn swallow nests observed at time of inspection.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutments	Length:					
Element Name:	Bearings	Width:					
Location:	On East and West Abutment Walls	Height:					
Material:	Plastic	Count (items):	2				
Element Type:	Elastomeric Bearing Pads - Polystyrene	Total Quantity:	2	Each			
Environment:	Benign	Limited Inspection		X			
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		2				
Comments:	Bearings appear to be in good condition.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutments	Length:					
Element Name:	Ballast Walls	Width:	9.1				
Location:	East and West Underside of Structure	Height:	0.5				
Material:	Cast-In-Place Concrete	Count (items):	2				
Element Type:	Reinforced Concrete Walls	Total Quantity:	9.1	m ²			
Environment:	Benign	Limited Inspection	X				
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		9.1				
Comments:	Ballast walls were inaccessible for inspection due to end portion of deck. Condition state is based on the visible sections of the ballast walls. Visible sections of the ballast walls were in good condition.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutment	Length:								
Element Name:	Abutment Walls	Width:	9.1							
Location:	East and West Underside of Structure	Height:	2							
Material:	Cast-in-Place Concrete	Count (items):	2							
Element Type:	Reinforced Concrete Walls	Total Quantity:	36.4 m ²							
Environment:	Benign	Limited Inspection								
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		32.20	4.2						
Comments:	Generally in good condition with medium vertical cracks and narrow map cracks noted throughout. Graffiti noted on abutment wall surface.									
Recommended Work:		Rehab		Replace	Maintenance Needs: 2					
		1-5 years		6-10 years		Urgent		1 year	X	2 years
Clean graffiti										

Element Group:	Abutments	Length:	3.05							
Element Name:	Wingwalls	Width:								
Location:	NE, SE, NW & SW OF Structure	Height:	1.2							
Material:	Cast-in-place Concrete	Count (items):	4.0							
Element Type:	Reinforced Concrete Walls	Total Quantity:	14.6 m ²							
Environment:	Moderate	Limited Inspection								
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		14.6							
Comments:	Generally in good to fair condition with medium map cracking throughout.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Piers	Length:	0.50							
Element Name:	Shafts/Columns/Piles Bents	Width:	10.6							
Location:	Underside of Structure	Height:	4.8							
Material:	Cast-in-place Concrete	Count (items):	2.0							
Element Type:	Reinforced Concrete Walls	Total Quantity:	213.12 m ²							
Environment:	Benign	Limited Inspection								
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		209.52	2.4	1.2					
Comments:	Wide vertical crack noted on pier shaft. Graffiti also noted.									
Recommended Work:		Rehab		Replace	Maintenance Needs: 8 & 2					
		1-5 years		6-10 years		Urgent		1 year	X	2 years
Concrete Repairs, and clean graffiti										

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Abutment Walls and Wingwalls	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW Side of Structure	Height:							
Material:	Native Material	Count (items):	4						
Element Type:	Embankment	Total Quantity:	Each						
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Embankments are moderately sloped, well vegetated and appear to be stable. Evidence of a person living under the bridge.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Below Structure	Height:							
Material:	Native	Count (items):	All						
Element Type:	Stream	Total Quantity:	N/A						
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	High volume and low flow from south to north with no flow obstructions noted at time of inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Deck Top	Concrete Repairs		X		\$ 16,000.00
Deck Soffit	Concrete Repairs		X		\$ 19,500.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 35,500.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>



Photo 1 Structure from east approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

ORMOND BRIDGE

BRIDGE

SITE PHOTOGRAPHS

Site No.:BRH003



Photo 5 North elevation



Photo 6 South elevation



Photo 7 New end treatments at west end of structure



Photo 8 Large potholes and settlement noted on east approach



Photo 9 Abrasions noted on strip seal on east expansion joint



Photo 10 Collision damage on southwest corner of deck barrier



Photo 11 Abrasions and scaling on exposed concrete deck top.



Photo 12 Localized spalls on interior soffit



Photo 13 Typical view of south exterior soffit



Photo 14 Typical view of northeast wingwall



Photo 15 East underside of structure



Photo 16 Graffiti on west face of pier

Structure Condition Summary Form

Structure Name Ormond Bridge
Structure Number BRH003
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	76.00	0.00	76.00	0.00	0.00	0	0		00	00
	Wearing Surface	Sq.m	6.00	90.00	0.00	75.00	10.00	5.00	540	362	67	09	12
Barriers	Barrier/ Parapet Walls	Sq.m	100.00	8.30	0.00	8.30	0.00	0.00	830	623	75	00	00
	Railing Systems	m	200.00	76.80	0.00	65.80	8.00	3.00	15360	10510	68	00	03
	Posts (Steel/Concrete)	Each	200.00	20.00	0.00	20.00	0.00	0.00	4000	3000	75	00	00
	Armouring / Retaining Devices	m	1.00	42.00	0.00	41.30	0.70	0.00	42	31	74	00	00
Joints	Concrete End Dams	Sq.m	2100.00	7.35	0.00	6.35	0.50	0.50	15435	10421	68	00	08
	Seals/ Sealants	Each	0.00	2.00	0.00	2.00	0.00	0.00	0	0		00	00
Decks	Deck Top - Thin Slab	Sq.m	120.00	293.93	0.00	276.33	9.60	8.00	35272	25331	72	00	12
	Soffit - Thin Slab	Sq.m	120.00	326.15	0.00	307.95	9.90	8.30	39138	28191	72	00	00
Coatings	Railing Systems/ Hand Railing	Sq.m	125.00	76.80	0.00	76.80	0.00	0.00	9600	7200	75	00	00
	Wingwalls - Gabion Baskets	Each	300.00	14.60	0.00	14.60	0.00	0.00	4380	3285	75	00	00
Abutment	Ballast Walls	Sq.m	350.00	9.10	0.00	9.10	0.00	0.00	3185	2389	75	00	00
	Bearings	Each	1000.00	2.00	0.00	2.00	0.00	0.00	2000	1500	75	00	00
	Abutment Walls	Sq.m	900.00	36.40	0.00	32.20	4.20	0.00	32760	23247	71	01	08
Piers	Shafts/ Columns/ Pier Bents	Sq.m	900.00	213.12	0.00	209.52	2.40	1.20	191808	142290	74	00	08 &02
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00

354350258378

Bridge Condition Index (BCI)

73

Inventory Data:

Structure Name		Liscumb Rd & Annable MD Bridge								
Main Hwy/Road #	Main Hwy/Road #	Liscumb Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>
	On Structure	<input checked="" type="checkbox"/>	Rail		<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>
		<input type="checkbox"/>			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>
Structure Location		0.35km West of County Rd 3								
Latitude	45.10424		Longitude	-75.3622						
Owner(s)	Township of North Dundas		Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	List/n.d.	<input type="checkbox"/>			
				Design./not list <input type="checkbox"/>	Desig. & List <input type="checkbox"/>					
MTO Region	40 - Eastern		Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>					
				Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>					
MTO District	42 - Ottawa		Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG		AADT	438		% Trucks	<input type="checkbox"/>			
Geographic Twp.			Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	Concrete Rigid Frame		Interchange Number	<input type="checkbox"/>						
Total Deck Length	5.3 m		Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	6.4 m		Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	33.9 sq. m		Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>					
				School <input type="checkbox"/>	Bicycle <input type="checkbox"/>					
Roadway Width	4.6 m		Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	30 Degrees		Direction of Structure	East/West						
No. of Spans	1.0		Fill on Structure	<input type="checkbox"/> m						
Culvert Length	<input type="checkbox"/> m									
Span Lengths	5.3 m									

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	68.57		
OSIM		2022	65.46		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	5 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study	<input checked="" type="checkbox"/>			
Material Condition Survey				
Detailed Deck Condition Survey:	<input checked="" type="checkbox"/>			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>			
Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Timber Investigation:	<input checked="" type="checkbox"/>			
Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/>			
Underwater Investigation:	<input checked="" type="checkbox"/>			
Fatigue Investigation:	<input checked="" type="checkbox"/>			
Seismic Investigation:	<input checked="" type="checkbox"/>			
Structure Evaluation:	<input checked="" type="checkbox"/>			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/>			
Monitoring Crack Widths:	<input checked="" type="checkbox"/>			
Investigation Notes:				

Overall Structure Notes:				
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years		
Overall Comments:	Structure is in generally good to fair condition. Guide rail appears to have been replaced since last inspection. Repave asphalt wearing surface in 1-5 years - potholes, patches, rutting, ponding, and wide cracks noted. Repairs required at concrete soffit. Light abrasions on structure guide rail. Scaling present on exterior soffit. Spall, scaling, ECR, and damp stains noted on interior soffit. Light scaling and scour noted on abutment walls			
Date of Next Inspection:	2024			

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Accessories (attachments and signs)	Length:							
Element Name:	Signs	Width:							
Location:	NE, NW, SE, SW Side of structure	Height:							
Material:	Steel	Count (items):	4						
Element Type:	Hazard Markers	Total Quantity:	4.0 Each						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Generally in good condition								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches	Length:	NW & SW: 15.3m, SE:16.5, NE: 15.9						
Element Name:	Barriers	Width:							
Location:	NE, NW, SE, SW Sides of structure	Height:							
Material:	Steel	Count (items):	4						
Element Type:	Steel Flex Beam on Steel Posts	Total Quantity:	63.00 m						
Environment:	Severe	Limited Inspection							
Protection System:	Hot dip galvanizing								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		63.00						
Comments:	Appears to have been replaced since last inspection								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches	Length:	6						
Element Name:	Wearing Surface	Width:	4.6						
Location:	East and West Side of Structure	Height:							
Material:	Asphalt	Count (items):	2						
Element Type:	Asphalt wearing surface	Total Quantity:	55.20 m2						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m2		29.20	13.00	13.00				
Comments:	Wide transverse cracks, rutting, ponding, potholes, and previous patches noted								
Recommended Work:		Rehab	x	Replace	Maintenance Needs:				
	x	1-5 years		6-10 years		Urgent		1 year	2 years
Repave approach wearing surface									

Element Group:	Barriers	Length:	10.7
Element Name:	Railing Systems	Width:	
Location:	North and South Side of Structure	Height:	
Material:	Steel	Count (items):	2
Element Type:	Steel Flex Beam	Total Quantity:	21.4 m
Environment:	Severe	Limited Inspection	
Protection System:	Hot dip galvanizing		
Condition Data:	Units	Exc.	Good
	m		18.40
			3.00
Comments:	Generally in good condition with light abrasions noted.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Barriers	Length:	
Element Name:	Posts	Width:	
Location:	North and South Sides of Structure	Height:	
Material:	Steel	Count (items):	10
Element Type:	Steel Posts	Total Quantity:	10.00 Eah
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	Each		9.00
			1.0
Comments:	Generally in good condition with collision damage noted		
Recommended Work:	Rehab	Replace	Maintenance Needs: 18
	1-5 years	6-10 years	Urgent
			X
			1 year
			2 years
			Repair bridge post

Element Group:	Coating	Length:	
Element Name:	Railing Systems/ Hand railings	Width:	
Location:	On bridge railing	Height:	
Material:	Other	Count (items):	
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	21.40 m
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m		21.40
Comments:	Generally in good condition.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Decks	Length:	5.3				
Element Name:	Wearing Surface	Width:	4.6				
Location:	Top of deck	Height:					
Material:	Asphalt	Count (items):					
Element Type:	Asphalt Wearing Surface	Total Quantity:	24.38	m2			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		9.75	9.75	4.88		
Comments:	Wide transverse cracks, rutting, ponding, potholes, and previous patches noted						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	
Repave asphalt wearing surface							

Element Group:	Decks	Length:	5.3				
Element Name:	Deck Top - Thick Slab	Width:	6.4				
Location:	Below Roadway	Height:					
Material:	Cast-in-place concrete	Count (items):					
Element Type:	Reinforced concrete deck top	Total Quantity:	33.92	m2			
Environment:	Moderate	Limited Inspection		X			
Protection System:	Asphalt wearing surface					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		29.92	4.00			
Comments:	Condition of the deck is assumed based on the condition of asphalt wearing surface and soffit.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Decks	Length:	5.3				
Element Name:	Soffit - Thick Slab	Width:	1.6				
Location:	North and South Side of Structure	Height:					
Material:	Cast-in-place concrete	Count (items):	2				
Element Type:	Soffit - Exterior	Total Quantity:	16.96	m2			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		8.48	8.48			
Comments:	Moderate to severe scaling present throughout the exterior soffit.						
Recommended Work:		Rehab		Replace	Maintenance Needs: 8		
		1-5 years		6-10 years	Urgent	x 1 year 2 years	
Concrete repairs							

Element Group:	Decks	Length:	5.3				
Element Name:	Soffit - Thick Slab	Width:	4.4				
Location:	Underside of structure	Height:					
Material:	Cast-in-place concrete	Count (items):					
Element Type:	Soffit - Interior	Total Quantity:	23.32	m2			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		16.32	3.50	3.50		
Comments:	Small spall with ECR noted. Light to moderate scaling and wet stains present near exterior soffit.						
Recommended Work:		Rehab		Replace	Maintenance Needs: 8		
		1-5 years		6-10 years	Urgent	X 1 year 2 years	
				Concrete repairs			

Element Group:	Abutments	Length:					
Element Name:	Abutment walls	Width:	6.4				
Location:	East and West Underside of Structure	Height:	1.5				
Material:	Cast-in-place concrete	Count (items):	2				
Element Type:	Reinforced concrete walls	Total Quantity:	19.2	m2			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		14.20	4.00	1		
Comments:	Wet stains, moderate scour at waterline, and light scaling present throughout.						
Recommended Work:		Rehab		Replace	Maintenance Needs: 8		
		1-5 years		6-10 years	Urgent	x 1 year 2 years	
				Concrete repairs			

Element Group:	Abutments	Length:	2.7				
Element Name:	Wingwalls	Width:					
Location:	NE, NW, SE & SW of Structure	Height:	1.5				
Material:	Cast-in-place concrete	Count (items):	4				
Element Type:	Reinforced concrete walls	Total Quantity:	16.2	m2			
Environment:	moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		16.2	2			
Comments:	Generally in good condition with light scaling						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below abutment walls and wingwalls	Height:							
Material:	Unknown	Count (items):	All						
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection		X				N/A	
Protection System:	Unknown							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, NW, SE & SW Sides of structure	Height:							
Material:	Rip-Rap	Count (items):	4						
Element Type:	Embankment	Total Quantity:	4						
Environment:	Moderate	Limited Inspection							Each
Protection System:	Vegetation							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		3	1					
Comments:	Embankments are moderately sloped, well vegetated, and stable, with some loss of fill at the southeast								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and streams	Length:							
Element Name:	Slope Protection	Width:							
Location:	NE, NW, SE & SW Sides of structure	Height:							
Material:	Vegetation	Count (items):	4						
Element Type:	Slope Protection	Total Quantity:	4						
Environment:	Moderate	Limited Inspection							Each
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		3	1					
Comments:	Generally in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and streams			Length:			
Element Name:	Streams and waterways			Width:			
Location:	Below Structure			Height:			
Material:	Native			Count (items):	All		
Element Type:	Streams and waterways			Total Quantity:	All		
Environment:	Benign			Limited Inspection			N/A
Protection System:	None						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	N/A		All				
Comments:	Low volume and low flow from north to south with no visible obstructions noted.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Wearing Surfaces	Repave asphalt		X		\$ 50,000.00
Soffit	Concrete Repairs		X		\$ 10,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 60,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 35,000.00

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Annable MD Bridge

SITE PHOTOGRAPHS

Site No.:BRH005



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Annable MD Bridge

SITE PHOTOGRAPHS

Site No.:BRH005



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Annable MD Bridge

SITE PHOTOGRAPHS

Site No.:BRH005



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Annable MD Bridge

SITE PHOTOGRAPHS

Site No.:BRH005



Photo 7 **Structure and approach barrier and end treatment (typical)**



Photo 8 **Transverse cracks, patched potholes, and raveling on wearing surface**

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Annable MD Bridge

SITE PHOTOGRAPHS

Site No.:BRH005



Photo 9 Potholes, ponding, and cracks in asphalt wearing surface



Photo 10 Light abrasions on guide rail posts

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Annable MD Bridge

SITE PHOTOGRAPHS

Site No.:BRH005



Photo 11 Disconnected/rotated barrier post and loss of fill at the southeast



Photo 12 Scaling on deck soffit exterior/fascia (typ.)



Photo 13 Small spall with ECR on the deck soffit



Photo 14 Scaling and wet stains on deck soffit



Photo 15 Scaling, wet stains, and light scour on abutment walls



Photo 16 Scaling and wet stains on deck soffit

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Annable MD Bridge

SITE PHOTOGRAPHS

Site No.:BRH005



Photo 17 Scaling on wingwalls

Structure Condition Summary Form

Structure Name Nation Valley Rd & Barkley Creek Bridge
Structure Number BRH005
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	63.00		63.00			0	0		00	00
	Wearing Surface	Sq.m	6.00	55.20		29.20	13.00	13.00	331	163	49	00	00
Accessories	Signs	Each	0.00	4.00		4.00			0	0		00	00
Barriers	Railing Systems	m	200.00	21.40		18.40	3.00		4280	3000	70	00	00
	Posts (Steel/Concrete)	Each	200.00	10.00		9.00		1.00	2000	1350	68	00	18
	Wearing Surface	Sq.m	25.00	24.38		9.75	9.75	4.88	610	280	46	00	00
Decks	Deck Top - Thick Slab	Sq.m	350.00	33.92		29.92	4.00		11872	8414	71	00	00
	Soffit - Thick Slab	Sq.m	350.00	40.28		24.80	11.98	3.50	14098	8187	58	00	08
Coatings	Railing Systems/ Hand Railing	Sq.m	125.00	21.40		21.40			2675	2006	75	00	00
Abutment	Wingwalls	Sq.m	350.00	18.20		16.20	2.00		6370	4533	71	00	00
	Abutment Walls	Sq.m	900.00	19.20		14.20	4.00	1.00	17280	11025	64	00	08
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		3.00	1.00		0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		3.00	1.00		0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Inventory Data:

Structure Name	Development Rd & North Branch of South Nation River MD Bridge									
Main Hwy/Road #	Development Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	X		Rail	<input type="checkbox"/>	Road	X	Other	<input type="checkbox"/>	
	Under Structure									
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	X	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	1.2km North of Van Camp Road									
Latitude	45.044685			Longitude	-75.449811					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid:	X	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
					Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>		
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>		
					Collector	<input type="checkbox"/>	Local	X		
MTO District	42 - Ottawa			Posted Speed	80 km/h		No. of Lanes	2		
Old County	SDG			AADT	399		% Trucks	<input type="checkbox"/>		
Geographic Twp.				Inspection Route Sequence	<input type="checkbox"/>					
Structure Type	Slab on Steel I Girders			Interchange Number	<input type="checkbox"/>					
Total Deck Length	25.9		m	Interchange Structure Number	<input type="checkbox"/>					
Overall Str. Width	9.6		m	Min. Vertical Clearance	<input type="checkbox"/> m					
Total Deck Area	248.6		sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>		
					School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>		
Roadway Width	8.0		m	Detour Length Around Bridge	<input type="checkbox"/> km					
Skew Angle	57.2		Degrees	Direction of Structure	North/South					
No. of Spans	1			Fill on Structure	<input type="checkbox"/> m					
			23.9							
Span Lengths	12.2		m							

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	October 8, 2020	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	71.53		
OSIM		2022	71.00		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy				
Temperature:	1° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			<input checked="" type="checkbox"/>		\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:		<input checked="" type="checkbox"/>		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>			
	Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>			
	Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>			
	Detailed Timber Investigation:	<input checked="" type="checkbox"/>			
	Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/>			
Underwater Investigation:		<input checked="" type="checkbox"/>			
Fatigue Investigation:		<input checked="" type="checkbox"/>			
Seismic Investigation:		<input checked="" type="checkbox"/>			
Structure Evaluation:		<input checked="" type="checkbox"/>			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/>			
	Monitoring Crack Widths:	<input checked="" type="checkbox"/>			
		Total Costs			\$ 35,000.00
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input checked="" type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years	<input checked="" type="checkbox"/> 6 to 10 years					
Overall Comments:	Structure is in generally good to localized fair/poor condition. Jammed joint seals observed on both sides of deck. Wide pattern cracks, potholes and settlement noted on both approaches. Existing deck barrier does not confirm to current standards and should be replaced. Spall with exposed corroded reinforcement on south abutment wall below bearing pad.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	

Maintenance Needs

01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	NE: 92.3, SE: 27.5, SW: 18.0, NW: 67.5							
Element Name:	Development Rd & North Branch of South Nation F	Width:								
Location:	NE, SE, NW & SW of Structure		Height:							
Material:	Steel	Count (items):	4							
Element Type:	Steel Flex Beam on Steel Posts (SBGR)		Total Quantity:	205.3					m	
Environment:	Severe		Limited Inspection							
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m		198.3	5	2					
Comments:	New approach barrier installed since previous inspection. Collision damage noted on northeast barrier. Moderate to severe rot noted on existing timber posts.									
Recommended Work:		Rehab		Replace	Maintenance Needs:				3	
		1-5 years		6-10 years		Urgent	1 year	X	2 years	
					Repair damage section					

Element Group:	Approaches	Length:	6							
Element Name:	Wearing Surface	Width:	8							
Location:	North & South of Structure		Height:							
Material:	Asphalt	Count (items):	2							
Element Type:	Asphalt Surface Treatment		Total Quantity:	96.0					m ²	
Environment:	Severe		Limited Inspection							
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²				96.0	9				
Comments:	Wide map cracking, wide transverse cracks, large potholes and some settlement of approaches noted on both approaches. Some previous patches also observed.									
Recommended Work:		Rehab	X	Replace	Maintenance Needs:					
	X	1-5 years		6-10 years		Urgent	1 year		2 years	

Element Group:	Joints	Length:	14.6							
Element Name:	Concrete End Dams	Width:	0.25							
Location:	North & South Ends of Structure		Height:							
Material:	Cast-In-Place Concrete	Count (items):	2							
Element Type:	Concrete End Dams		Total Quantity:	7.3					m	
Environment:	Severe		Limited Inspection							
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m			4.1	3.2					
Comments:	Medium to severe abrasions and scaling noted on concrete end dams.									
Recommended Work:		Rehab	X	Replace	Maintenance Needs:					
	X	1-5 years		6-10 years		Urgent	1 year		2 years	
					Install supports.					

Element Group:	Seals/Sealants	Length:	14.6				
Element Name:	Seals/Sealants	Width:					
Location:	North & South Sides of Structure	Height:					
Material:	Plastic	Count (items):	2				
Element Type:	Strip Seal	Total Quantity:	29.2 m				
Environment:	Severe	Limited Inspection	X				
Protection System:	None					Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	m				29.2	7	
Comments:	There is a missing portion of seal at the south side of structure. Expansion joint seals are jammed. Debris buildup noted along seals.						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	
					Install supports.		

Element Group:	Barriers	Length:	2.25				
Element Name:	Posts	Width:	0.35				
Location:	NE, NW, SE & SW of Structure	Height:	1.1				
Material:	Cast-In-Place Concrete	Count (items):	4				
Element Type:	Reinforced concrete End Posts	Total Quantity:	22.95 m ²				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	m ²		22.49	0.5		8	
Comments:	Light to medium scaling noted on concrete end walls. Existing barrier is not code compliant and should be replaced with code compliant barrier.						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Barriers	Length:	35.1				
Element Name:	Railing System	Width:					
Location:	East & West Sides of Structure	Height:					
Material:	Steel	Count (items):	2				
Element Type:	Steel Post and Panel Railing	Total Quantity:	70.2 m				
Environment:	Severe	Limited Inspection					
Protection System:	Hot Dip Galvanizing					Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	m		69.5	0.7		8	
Comments:	Light to medium rust noted throughout. Existing barrier is not code compliant and should be replaced with a code compliant barrier.						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Sidewalk/Curbs	Length:	39.6					
Element Name:	Curbs	Width:	0.85					
Location:	East & West Sides of Structure	Height:	0.3					
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Reinforced Concrete Curbs	Total Quantity:	91.08	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		85.62	5.5				
Comments:	Light to medium scaling and abrasions due to snow plow machines noted.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:						
Element Name:	Drainage System	Width:						
Location:	East & West Side of Structure	Height:						
Material:	Steel	Count (items):	8					
Element Type:	Steel Drain Pipes	Total Quantity:	8.0	each				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	each		8					
Comments:	Some light corrosion noted on drain pipes. Deck drains have been partially blocked by debris.							
Recommended Work:		Rehab		Replace	Maintenance Needs: 2			
		1-5 years		6-10 years	Urgent	1 year	X 2 years	

Element Group:	Decks	Length:	26.9					
Element Name:	Deck Top (Exposed)	Width:	9.6					
Location:	Top of Deck	Height:						
Material:	Cast-in-Place Concrete	Count (items):						
Element Type:	Deck Top	Total Quantity:	248.6	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		243.7	5.0				
Comments:	Light to medium scaling and abrasions due to snow plow equipment noted. Spall noted at northeast corner of deck top. Debris build-up observed along edges.							
Recommended Work:		Rehab		Replace	Maintenance Needs: 2			
		1-5 years		6-10 years	Urgent	1 year	X 2 years	

Element Group:	Decks	Length:	2.0
Element Name:	Soffit - Thin Slab (End)	Width:	8.4
Location:	East Underside of Structure	Height:	
Material:	Precast Concrete	Count (items):	2
Element Type:	Soffit - End	Total Quantity:	33.6 m ²
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		33.6
Comments:	End portion of soffit appears to be in good condition.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Decks	Length:	21.9
Element Name:	Soffit - Thin Slab (Exterior)	Width:	1.05
Location:	East Underside of Structure	Height:	
Material:	Precast Concrete	Count (items):	2
Element Type:	Soffit - Exterior	Total Quantity:	46 m ²
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		46.0
Comments:	Exterior soffit appears to be in generally good condition.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Decks	Length:	21.9
Element Name:	Soffit - Thin Slab	Width:	7
Location:	Underside of Structure	Height:	
Material:	Precast Concrete	Count (items):	1
Element Type:	Soffit - Interior	Total Quantity:	153.3 m ²
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		153.3
Comments:	Generally in good condition with some coating failure noted.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Beams/Main Longitudinal Elements (MLE's)			Length:	4			
Element Name:	Girders - End			Width:	0.4			
Location:	North & South Underside of Structure			Height:	1.1			
Material:	Steel			Count (items):	5			
Element Type:	Steel I Girders			Total Quantity:	68.3 m ²			
Environment:	Benign			Limited Inspection				
Protection System:	Coating						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		67	1.3				
Comments:	Some peeling coating and light rust noted on end girders.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Beams/Main Longitudinal Elements (MLE's)			Length:	21.9			
Element Name:	Girders - Intermediate			Width:	0.4			
Location:	Underside of Deck			Height:	1.1			
Material:	Steel			Count (items):	5			
Element Type:	Steel I Girders			Total Quantity:	373.94 m ²			
Environment:	Benign			Limited Inspection				
Protection System:	Coating						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		369.46	4.5				
Comments:	Some peeling coating and light rust noted on girders.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Beams/Main Longitudinal Elements (MLE's)			Length:				
Element Name:	Diaphragms - End			Width:				
Location:	North & South Underside of Structure			Height:				
Material:	Steel			Count (items):	8			
Element Type:	Steel I Diaphragms			Total Quantity:	8 each			
Environment:	Benign			Limited Inspection				
Protection System:	Coating						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	each		8					
Comments:	End diaphragms are generally in good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Beams/Main Longitudinal Elements (MLE's)	Length:							
Element Name:	Diaphragms - Intermediate	Width:							
Location:	Underside of Deck	Height:							
Material:	Steel	Count (items):	8						
Element Type:	Rectangular Diaphragms	Total Quantity:	8 Each						
Environment:	Benign	Limited Inspection							
Protection System:	Coating								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		8						
Comments:	Some coating failure and light corrosion noted on interior diaphragms.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Abutments	Length:							
Element Name:	Bearings	Width:							
Location:	North & South Abutment Walls	Height:							
Material:	Plastic	Count (items):	10						
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	10 Each						
Environment:	Benign	Limited Inspection			X				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		9	1					
Comments:	Damaged bearing pad noted on south wall. Likely from spall below bearing pad on concrete bearing seat.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Abutments	Length:							
Element Name:	Ballast Walls	Width:	10.3						
Location:	East and West Underside of Structure	Height:	1						
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	20.6 m ²						
Environment:	Benign	Limited Inspection	X						
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		20.6						
Comments:	Limited inspection due to end diaphragms. Visible portions of ballast wall were in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Abutment	Length:				
Element Name:	Abutment Walls	Width:	10.3			
Location:	East and West Underside of Structure	Height:	4.4			
Material:	Cast-in-Place Concrete	Count (items):	2			
Element Type:	Reinforced Concrete Walls	Total Quantity:	89.6 m ²			
Environment:	Benign	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m ²		77.40	7.7	4.5	
Comments:	Wide vertical cracks noted on south abutment wall below girders. Medium vertical cracks noted on north wall. Spall with exposed corroded reinforcement below girder end on south wall.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Abutments	Length:	6.9			
Element Name:	Wingwalls	Width:				
Location:	NE, SE, NW & SW OF Structure	Height:	4.5			
Material:	Cast-in-place Concrete	Count (items):	5.0			
Element Type:	Reinforced Concrete Walls	Total Quantity:	123.8 m ²			
Environment:	Moderate	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m ²		120.8	3.0		
Comments:	Map cracking and medium transverse cracks with some efflorescence staining noted on wingwalls.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Foundations	Length:				
Element Name:	Foundation (Below Ground Level)	Width:				
Location:	Below Abutment Walls and Wingwalls	Height:				
Material:	Unknown	Count (items):				
Element Type:	Unknown	Total Quantity:	All			
Environment:	Benign	Limited Inspection		X		
Protection System:	Unknown					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	N/A		All			0
Comments:	No visible evidence of foundation instability was noted during the inspection.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW Side of Structure	Height:							
Material:	Native Material	Count (items):	4						
Element Type:	Embankment	Total Quantity:	Each						
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Embankments are steeply sloped, well vegetated and appear to be stable.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Below Structure	Height:							
Material:	Native	Count (items):	All						
Element Type:	Stream	Total Quantity:	N/A						
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	moderate volume and moderate flow from west to east with no obstructions noted at time of inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Approaches	Repave Asphalt Wearing Surface	X			\$ 14,500.00
Seals/Sealants	Replace Joint Seals	X			\$ 73,000.00
Barriers	Replace Barrier	X			\$ 174,500.00
Abutment Wall	Concrete Repairs	X			\$ 11,500.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 273,500.00

Associated Work	Comments	Estimated Cost
Approaches		\$ -
Detours		\$ 35,000.00
Traffic Control		\$ -
Utilities		\$ -
Right of Way		\$ -
Environmental Study		\$ -
Other		\$ -
Contingencies		\$ -
Total cost:		\$ 35,000.00

Justification
<div></div>



Photo 1 Structure from north approach



Photo 2 Structure from south approach



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure



Photo 5 East elevation



Photo 6 West elevation



Photo 7 Wide pattern cracks, potholes and asphalt patches on north approach



Photo 8 Collision damage on southwest guiderail



Photo 9 Missing portion of seal on north expansion joint



Photo 10 Scaling on top of west concrete curb



Photo 11 Elevation view of west deck barrier



Photo 12 Abrasions and small spall on exposed deck surface



Photo 13 Typical view of east exterior soffit



Photo 14 Typical view of interior soffit



Photo 15 Corrosion and coating failure on north end of interior girder



Photo 16 Light corrosion and coating failure on east exterior girder



Photo 17 Crack on northwest wingwall



Photo 18 Medium cracks with efflorescence on southeast wingwall



Photo 19 Delamination on south abutment wall below girder



Photo 20 North Underside of Structure



Photo 21 Spall below girder end on north abutment wall



Photo 22 Wide vertical crack on south abutment wall

Structure Condition Summary Form

Structure Name Development Rd North Branch of South Nation River MD Bridge
Structure Number BRH006
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	205.30	0.00	198.30	5.00	5.00	0	0		00	00
	Wearing Surface	Sq.m	6.00	96.00	0.00	0.00	0.00	96.00	576	0		09	00
Barriers	Railing Systems	m	200.00	70.20	0.00	69.50	0.70	0.00	14040	10481	75	08	00
	Posts (Steel/Concrete)	Each	200.00	22.95	0.00	22.49	0.50	0.00	4590	3414	74	08	00
Joints	Concrete End Dams	Sq.m	2100.00	7.30	0.00	0.00	4.10	3.20	15330	3444	22	00	00
	Seals/ Sealants	Each	0.00	29.20	0.00	0.00	0.00	29.20	0	0		07	00
Sidewalks/ Curbs	Curbs	Sq.m	40.00	91.08	0.00	85.62	5.50	0.00	3643	2657	73	00	00
	Drainage System	Each	0.00	8.00	0.00	8.00	0.00	0.00	0	0		00	02
Decks	Deck Top - Thin Slab	Sq.m	120.00	248.60	0.00	243.70	5.00	0.00	29832	22173	74	00	02
	Soffit - Thin Slab	Sq.m	120.00	232.90	0.00	232.90	0.00	0.00	27948	20961	75	00	00
Beams/ Main Longitudinal Elements	Girders -Steel	Sq.m	420.00	442.24	0.00	436.46	5.80	0.00	185741	138459	75	00	00
	Diaphragms - Steel, wood etc.	Each	0.00	16.00	0.00	16.00	0.00	0.00	0	0		00	00
Abutment	Wingwalls	Sq.m	350.00	123.80	0.00	120.80	3.00	0.00	43330	32130	74	00	00
	Ballast Walls	Sq.m	350.00	20.60	0.00	20.60	0.00	0.00	7210	5408	75	00	00
	Bearings	Each	1000.00	10.00	0.00	10.00	0.00	0.00	10000	7500	75	00	00
	Abutment Walls	Sq.m	900.00	89.60	0.00	77.40	7.70	4.50	80640	55017	68	00	00
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00

422880301643

Bridge Condition Index (BCI)

71

Inventory Data:

Structure Name	Levere Rd & North Branch South Nation River Bridge									
Main Hwy/Road #	Levere Road		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.4 km East of Development Road									
Latitude	45.0456626			Longitude	-75.4447956					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
					Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>		
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>		
					Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>		
MTO District	42 - Ottawa			Posted Speed	60 km/h		No. of Lanes	2		
Old County	SDG			AADT	72		% Trucks	<input type="checkbox"/>		
Geographic Twp.	<input type="text"/>			Inspection Route Sequence	<input type="text"/>					
Structure Type	Slab on Concrete Box Girders			Interchange Number	<input type="text"/>					
Total Deck Length	14.7		m	Interchange Structure Number	<input type="text"/>					
Overall Str. Width	8.5		m	Min. Vertical Clearance	<input type="text"/> m					
Total Deck Area	125.0		sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>		
					School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>		
Roadway Width	7.0		m	Detour Length Around Bridge	5.1		km			
Skew Angle	<input type="text"/>		Degrees	Direction of Structure	East/West					
No. of Spans	1			Fill on Structure	<input type="text"/> m					
Span Lengths	13.7		m							

Historical Data:

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	October 8, 2020	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	73.14		
OSIM		2022	73		

Appraisal Indices:	Comments:
Fatigue:	
Seismic:	
Scour:	
Flood:	
Geometrics:	
Barrier:	
Curb:	
Load Capacity:	
Key Aspects:	

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	2° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:		X		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	X			
	Concrete Substructure Condition Survey:	X			
	Detailed Coating Condition Survey:	X			
	Detailed Timber Investigation:	X			
	Post-Tensioned Strand Investigation:	X			
Underwater Investigation:		X			
Fatigue Investigation:		X			
Seismic Investigation:		X			
Structure Evaluation:		X			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	X			
	Monitoring Crack Widths:	X			
					Total Costs \$ 15,000.00
Investigation Notes: Deck condition survey recommended due to age of structure.					

Overall Structure Notes:							
Work on Structure:	<input type="checkbox"/> None	<input checked="" type="checkbox"/> X	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input type="checkbox"/>	Replace
Timing of Recommended Work:	<input type="checkbox"/>	<input checked="" type="checkbox"/> X	1 to 5 years	<input type="checkbox"/>	<input type="checkbox"/>	6 to 10 years	
Overall Comments:	Structure is in generally in good condition. Wearing surface has been repaved, and new approach barrier installed, since previous inspection. Evidence of leakage between centre box girders below centreline of deck at location of cold joint.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	NE: 15.24, SE: 7.62, SW: 15.24, NW: 7.62						
Element Name:	Barrier	Width:							
Location:	NE, SE, NW & SW of Structure	Height:							
Material:	Steel	Count (items):	4						
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	76.2 m						
Environment:	Severe	Limited Inspection							
Protection System:	None								
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies			
	m		76.2						
Comments:	Generally in good condition. New end treatments installed since previous inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches	Length:	6						
Element Name:	Wearing Surface	Width:	7						
Location:	East and West Side of Structure	Height:							
Material:	Asphalt	Count (items):	2						
Element Type:	Asphalt Surface Treatment	Total Quantity:	84.0 m ²						
Environment:	Severe	Limited Inspection							
Protection System:	None								
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies			
	m ²		84						
Comments:	Repaved since previous inspection. Wearing surface is generally in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Joints	Length:	8.5						
Element Name:	Concrete End Dam	Width:	0.3						
Location:	East & West Ends of Structure	Height:							
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	Concrete End Dam	Total Quantity:	5.1 m ²						
Environment:	Severe	Limited Inspection	X						
Protection System:	None								
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies			
	m ²		4.6	0.3	0.2				
Comments:	Medium abrasions and scaling due to snow removal equipment noted on concrete end dams								
Recommended Work:		Rehab		Replace	Maintenance Needs: 8				
		1-5 years		6-10 years		Urgent	X	1 year	2 years
					Concrete Repairs				

Element Group:	Seals/Sealants	Length:	8.5						
Element Name:	Seals/Sealants	Width:							
Location:	East & West Ends of Structure	Height:							
Material:	Plastic	Count (items):	2						
Element Type:	Strip Seal	Total Quantity:	17 m						
Environment:	Severe	Limited Inspection	X						
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		17						
Comments:	Seals appear to be in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Barriers	Length:	14.7						
Element Name:	Railing System	Width:							
Location:	North and South Sides of Structure	Height:							
Material:	Steel	Count (items):	2						
Element Type:	Steel Flex Beam	Total Quantity:	29.4 m						
Environment:	Severe	Limited Inspection							
Protection System:	Hot Dip Galvanizing							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		29.4						
Comments:	Generally in good condition, with some light corrosion and minor abrasions noted on flex beam. New approach barrier installed since previous inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Barriers	Length:							
Element Name:	Posts	Width:							
Location:	North and South Sides of Structure	Height:							
Material:	Steel	Count (items):	26						
Element Type:	Steel HSS Posts	Total Quantity:	26 Each						
Environment:	Severe	Limited Inspection							
Protection System:	Hot Dip Galvanizing							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		26						
Comments:	Generally in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Decks	Length:	14.7
Element Name:	Wearing Surface	Width:	7
Location:	Top of Deck	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Surface Treatment	Total Quantity:	102.9 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		102.9
Comments:	Deck has been paved since previous inspection. Deck wearing surface appears to be in good condition.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Decks	Length:	14.7
Element Name:	Deck Top (Covered)	Width:	8.5
Location:	Top of Deck	Height:	
Material:	Cast-in-Place Concrete	Count (items):	
Element Type:	Deck Top	Total Quantity:	125 m ²
Environment:	Moderate	Limited Inspection	X
Protection System:	Asphalt Surface Treatment		
Condition Data:	Units	Exc.	Good
	m ²		102.50
Comments:	Deck has been paved since previous inspection. Previous inspection noted cold joint, and delamination on exposed concrete deck surface, not seen in this inspection. Condition rating is based on previous condition rating. Evidence of leakage noted between centre box girders.		
Recommended Work:	X	Rehab	Replace
	X	1-5 years	6-10 years
			Urgent
			1 year
			2 years

Element Group:	Decks	Length:	2
Element Name:	Soffit - Thin Slab (End)	Width:	9.4
Location:	North and South Sides of Structure	Height:	
Material:	Precast Concrete	Count (items):	2
Element Type:	Soffit - End	Total Quantity:	37.4 m ²
Environment:	Moderate	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		31.79
Comments:	Evidence of leakage, efflorescence, and delaminations with corroded reinforcement present between box girders, reflecting leakage between joint in concrete deck.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			X
			1 year
			2 years
			Concrete Repairs

Element Group:	Decks	Length:	9.7						
Element Name:	Soffit - Thin Slab (Exterior)	Width:	1.5						
Location:	East Underside of Structure	Height:							
Material:	Precast Concrete	Count (items):	2						
Element Type:	Soffit - Exterior	Total Quantity:	28.13	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	m ²		28.1						
Comments:	Exterior soffit appears to be in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent	1 year	2 years		

Element Group:	Decks	Length:	9.7						
Element Name:	Soffit - Thin Slab (Interior)	Width:	7.4						
Location:	Underside of Structure	Height:							
Material:	Precast Concrete	Count (items):							
Element Type:	Soffit - Interior	Total Quantity:	71.8	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	m ²		65.32	4.31	2.15				
Comments:	Evidence of leakage, efflorescence, and delaminations with corroded reinforcement present between box girders, reflecting leakage between joint in concrete deck.								
Recommended Work:	X	Rehab	Replace	Maintenance Needs:					
	X	1-5 years	6-10 years		Urgent	1 year	2 years		

Element Group:	Abutments	Length:							
Element Name:	Bearings	Width:							
Location:	East and West Abutment Walls	Height:							
Material:	Plastic	Count (items):	14						
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	14	Each					
Environment:	Benign	Limited Inspection		X					
Protection System:	None								Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	Each		14						
Comments:	Generally in good condition, limited access to bearing pads, condition is based on accessible bearing pads								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent	1 year	2 years		

Element Group:	Abutments	Length:							
Element Name:	Ballast Walls	Width:	8.2						
Location:	East and West Abutment Walls	Height:	0.9						
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	14.8 m ²						
Environment:	Benign	Limited Inspection	X						
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		14.8						
Comments:	Ballast walls were inaccessible for inspection due to box girders. Condition state is based on the visible sections of the ballast walls. Visible sections of the ballast walls were in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Abutment	Length:							
Element Name:	Abutment Walls	Width:	8.2						
Location:	East and West Underside of Structure	Height:	3.6						
Material:	Cast-in-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	59 m ²						
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		59.00						
Comments:	Generally in good condition with some salt staining at the top of the walls. Scaling on the west wall around drain outlets.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Abutments	Length:	4.8						
Element Name:	Wingwalls	Width:							
Location:	NE, SE, NW & SW OF Structure	Height:	1.5						
Material:	Cast-in-place Concrete	Count (items):	4.0						
Element Type:	Reinforced Concrete Walls	Total Quantity:	28.8 m ²						
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		28.8						
Comments:	Generally in good condition with some narrow cracks noted on wingwalls.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Abutment Walls and Wingwalls	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW Side of Structure	Height:							
Material:	Native Material	Count (items):	4						
Element Type:	Embankment	Total Quantity:	Each						
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Embankments are steeply sloped, well vegetated and appear stable.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Below Structure	Height:							
Material:	Native	Count (items):	All						
Element Type:	Stream	Total Quantity:	N/A						
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Moderate volume and moderate flow from north to south with no obstructions noted at time of inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Deck Top	Concrete Repairs		X		\$ 15,000.00
Deck Soffit	Concrete Repairs		X		\$ 6,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 21,000.00

Associated Work	Comments	Estimated Cost
Approaches		\$ -
Detours		\$ -
Traffic Control		\$ -
Utilities		\$ -
Right of Way		\$ -
Environmental Study		\$ -
Other		\$ -
Contingencies		\$ -
Total cost:		\$ -

Justification

LEVERE Rd & NORTH BRANCH SOUTH NATION RIVER BRIDGE

BRIDGE

SITE PHOTOGRAPHS

Site No.:BRH007



Photo 1 Structure from east approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure



Photo 5 North elevation



Photo 6 South elevation



Photo 7 East approach wearing surface



Photo 8 Seal at east end of structure



Photo 9 Abrasions on north deck barrier



Photo 10 New asphalt at west end of deck wearing surface



Photo 11 Efflorescence and evidence of leakage between box girders



Photo 12 View of north exterior girder



Photo 13 East underside of structure



Photo 14 Typical view of northwest wingwall



Photo 15 Scaling on north abutment wall



Photo 16 Staining at top of west abutment wall

Structure Condition Summary Form

Structure Name

Structure Number

Date of Inspection

Project No.

Consultant

Levere Rd & North Branch South Nation River Bridge

BRH007

December 1, 2022

22087

HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	76.20	0.00	76.20	0.00	0.00	0	0		00	00
	Wearing Surface	Sq.m	6.00	84.00	0.00	84.00	0.00	0.00	504	378	75	00	
Barriers	Railing Systems	m	200.00	29.40	0.00	29.40	0.00	0.00	5880	4410	75	00	00
	Posts (Steel/Concrete)	Each	200.00	26.00	0.00	26.00	0.00	0.00	5200	3900	75	00	00
Joints	Concrete End Dams	Sq.m	2100.00	5.10	0.00	4.60	0.30	0.20	10710	7497	70	00	08
	Seals/ Sealants	Each	0.00	2.00	0.00	2.00	0.00	0.00	0	0		00	00
Decks	Wearing Surface	Sq.m	25.00	102.90	0.00	102.90	0.00	0.00	2573	1929	75	00	00
	Deck Top - Thin Slab	Sq.m	120.00	124.95	0.00	102.50	15.00	7.50	14994	9945	66	00	00
	Soffit - Thin Slab	Sq.m	120.00	137.33	0.00	125.21	8.02	4.02	16480	11654	71	00	00
	Wingwalls	Sq.m	350.00	28.80	0.00	28.80	0.00	0.00	10080	7560	75	00	00
Abutment	Ballast Walls	Sq.m	350.00	14.80	0.00	14.80	0.00	0.00	5180	3885	75	00	00
	Bearings	Each	1000.00	14.00	0.00	14.00	0.00	0.00	14000	10500	75	00	00
	Abutment Walls	Sq.m	900.00	59.00	0.00	59.00	0.00	0.00	53100	39825	75	01	08
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									138700	101483			
Bridge Condition Index (BCI)	73												

Inventory Data:

Structure Name	Van Camp Road & North Branch South Nation River Bridge									
Main Hwy/Road #	Belmade Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.5km east of Development Road									
Latitude	45.03686		Longitude	-75.4361						
Owner(s)	Township of North Dundas		Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
				Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern		Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
				Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa		Posted Speed	80 km/h		No. of Lanes	2			
Old County	SDG		AADT	250		% Trucks	<input type="checkbox"/>			
Geographic Twp.	<input type="text"/>		Inspection Route Sequence	<input type="text"/>						
Structure Type	Slab on Concrete Box Girders		Interchange Number	<input type="text"/>						
Total Deck Length	<input type="text"/> 14.7 m		Interchange Structure Number	<input type="text"/>						
Overall Str. Width	<input type="text"/> 9.0 m		Min. Vertical Clearance	<input type="text"/> m						
Total Deck Area	<input type="text"/> 132.3 sq. m		Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
				School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	<input type="text"/> 6.0 m		Detour Length Around Bridge	<input type="text"/> km						
Skew Angle	<input type="text"/> 10 Degrees		Direction of Structure	East/West						
No. of Spans	<input type="text"/> 1		Fill on Structure	<input type="text"/> m						
Span Lengths	<input type="text"/> 13.7 m									

Historical Data:

Year Built	<input type="text"/> 1979	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text"/> October 9, 2020	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.63		
OSIM		2022	73		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	0°C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:		x		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
		Total Costs			\$ 15,000.00
Investigation Notes: Detailed Condition Survey is recommended due to age of structure					

Overall Structure Notes:							
Recommended Work on	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:		<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years				
Overall Comments:	Structure is in generally good condition. Wide cracks noted in west approach wearing surface at deck interface. New approach barrier end treatments installed since previous inspection. Collision damage noted on existing approach barrier. Spall with exposed corroded reinforcement on southeast corner.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	NE: 30.5, SE: 24.8, SW: 28.6, NW: 24.8				
Element Name:	Barrier	Width:					
Location:	NE, SE, NW & SW of Structure	Height:					
Material:	Steel	Count (items):	4				
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	108.7 m				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m	Exc.	Good 90	Fair 11.5	Poor* 7.2		
Comments:	New end treatments installed since previous inspection. Collision damage noted on existing guiderail.						
Recommended Work:		Rehab	Replace	Maintenance Needs: 3			
		1-5 years	6-10 years	Urgent	X	1 year	2 years
				Replace damaged barrier sections			

Element Group:	Approaches	Length:	6				
Element Name:	Wearing Surface	Width:	6				
Location:	East and West Side of Structure	Height:					
Material:	Asphalt	Count (items):	2				
Element Type:	Asphalt Surface Treatment	Total Quantity:	72.0 m ²				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good 71.5	Fair 0.5	Poor*		
Comments:	Cracks and potholes forming at west approach at interface with deck. Minor settlement noted at both ends of deck. Previous patch repairs noted.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent		1 year	2 years
				Repair asphalt surface treatment and patch pothole			

Element Group:	Joints	Length:	9.2				
Element Name:	Other	Width:					
Location:	East & West Side of Structure	Height:					
Material:	Other	Count (items):					
Element Type:	Expansion Joint	Total Quantity:	9.2 m				
Environment:	Severe	Limited Inspection	X				
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m	Exc.	Good 9.2	Fair	Poor*		
Comments:	StrExpansion joint have been paved over. Light corroion noted at visible portions of joints.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent		1 year	2 years
				Install supports.			

Element Group:	Barriers	Length:	24.7					
Element Name:	Railing System	Width:						
Location:	North and South Sides of Structure	Height:						
Material:	Steel	Count (items):	2					
Element Type:	Steel Flex Beam	Total Quantity:	49.4	m				
Environment:	Severe	Limited Inspection						
Protection System:	Hot Dip Galvanizing						Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies		
	m		45.4	3.0	1.0			
Comments:	Collision damage noted on north railing. Corrosion noted on posts and dents noted throughout.							
Recommended Work:		Rehab	Replace	Maintenance Needs:			3	
		1-5 years	6-10 years	Urgent	1 year	X	2 years	
				Repair damaged portions				

Element Group:	Barriers	Length:					
Element Name:	Posts	Width:					
Location:	North and South Sides of Structure	Height:					
Material:	Steel	Count (items):	12				
Element Type:	Steel Posts	Total Quantity:	12	Each			
Environment:	Severe	Limited Inspection					
Protection System:	Hot Dip Galvanizing						Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	Each		12				
Comments:	Light corrosion noted on the base plates of barrier posts.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year		2 years

Element Group:	Decks	Length:	14.7				
Element Name:	Wearing Surface	Width:	6				
Location:	Top of Deck	Height:					
Material:	Asphalt	Count (items):					
Element Type:	Asphalt Surface Treatment	Total Quantity:	88.2	m ²			
Environment:	Severe	Limited Inspection					
Protection System:	None						Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	m ²		88.2				
Comments:	Light ravelling and light tire rutting noted throughout. Previous comments noted that no waterproofing has been placed below wearing surface.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year		2 years

Element Group:	Decks	Length:	14.7						
Element Name:	Deck Top	Width:	9						
Location:	Top of Deck	Height:							
Material:	Cast-in-Place Concrete	Count (items):							
Element Type:	Deck Top	Total Quantity:	132.3	m ²					
Environment:	Moderate	Limited Inspection	X						
Protection System:	Asphalt Surface Treatment							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		131.9	0.3	0.1				
Comments:	Deck top is partially covered by asphalt wearing surface. Wide cracks at south end of deck where deck top is exposed.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 12					
		1-5 years	6-10 years		Urgent		1 year	X	2 years

Element Group:	Decks	Length:	2						
Element Name:	Soffit - Thin Slab (End)	Width:	10.4						
Location:	North and South Sides of Structure	Height:							
Material:	Precast Concrete	Count (items):	2						
Element Type:	Soffit - End	Total Quantity:	41.6	m ²					
Environment:	Moderate	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		41.60						
Comments:	End soffit appears to be in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Decks	Length:	10.7						
Element Name:	Soffit - Thin Slab (Exterior)	Width:	0.7						
Location:	East Underside of Structure	Height:							
Material:	Precast Concrete	Count (items):	2						
Element Type:	Soffit - Exterior	Total Quantity:	14.98	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		14.38	0.35	0.25				
Comments:	Cracks on north side of soffit. Severe spall with exposed corroded reinforcement and west stain noted on southeast corner. Spall at southwest corner and centre of exterior soffit.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 8					
		1-5 years	6-10 years		Urgent		1 year	X	2 years
				Concrete Repairs					

Element Group:	Decks	Length:	10.7						
Element Name:	Soffit - Thin Slab (Interior)	Width:	9						
Location:	Underside of Structure	Height:							
Material:	Precast Concrete	Count (items):	1						
Element Type:	Soffit - Interior	Total Quantity:	96.3	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		96.3						
Comments:	Generally in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Abutments	Length:							
Element Name:	Bearings	Width:							
Location:	East and West Abutment Walls	Height:							
Material:	Plastic	Count (items):	14						
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	14	Each					
Environment:	Benign	Limited Inspection			X				
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		14						
Comments:	Generally in good condition, limited access to bearing pads, condition is based on accessible bearing pads								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Abutments	Length:							
Element Name:	Ballast Walls	Width:	8.8						
Location:	East and West Underside of Structure	Height:	0.7						
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	12.3	m ²					
Environment:	Benign	Limited Inspection	X						
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		12.3						
Comments:	Ballast walls were inaccessible for inspection due to box girders. Condition state is based on the visible sections of the ballast walls. Visible sections of the ballast walls were in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Abutment	Length:							
Element Name:	Abutment Walls	Width:	8.8						
Location:	East and West Underside of Structure	Height:	2.8						
Material:	Cast-in-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	49.3 m ²						
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		45.70	2.4	1.2				
Comments:	Generally in good condition with a wide vertical crack noted on abutment walls. Graffiti noted throughout.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 08, 02					
		1-5 years	6-10 years		Urgent		1 year	X	2 years
Concrete repairs, and clean structure									

Element Group:	Abutments	Length:	5.0						
Element Name:	Wingwalls	Width:							
Location:	NE, SE, NW & SW OF Structure	Height:	1.5						
Material:	Cast-in-place Concrete	Count (items):	4.0						
Element Type:	Reinforced Concrete Walls	Total Quantity:	30.0 m ²						
Environment:	Moderate	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		30.0						
Comments:	Generally in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Abutment Walls and Wingwalls	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams			Length:						
Element Name:	Embankments			Width:						
Location:	NE, SE, NW & SW Side of Structure			Height:						
Material:	Native Material			Count (items):	4					
Element Type:	Embankment			Total Quantity:	4 Each					
Environment:	Moderate			Limited Inspection						
Protection System:	Vegetation							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each			4						
Comments:	Embankments are moderately sloped, well vegetated with moderate erosion noted at all corners.									
Recommended Work:		Rehab	Replace	Maintenance Needs:						
		1-5 years	6-10 years		Urgent		1 year	2 years		

Element Group:	Embankments and Streams			Length:						
Element Name:	Streams and Waterways			Width:						
Location:	Below Structure			Height:						
Material:	Native			Count (items):	All					
Element Type:	Stream			Total Quantity:	All N/A					
Environment:	Benign			Limited Inspection						
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Moderate volume and moderate flow from south to north with no obstructions noted at time of inspection.									
Recommended Work:		Rehab	Replace	Maintenance Needs:						
		1-5 years	6-10 years		Urgent		1 year	2 years		

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ -

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification



Photo 1 Structure from east approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure



Photo 5 North elevation



Photo 6 South elevation



Photo 7 Collision damage on existing approach barrier at northeast corner of structure



Photo 8 Severe rot on timber posts at southeast approach barrier



Photo 9 Small potholes at south edge of east approach wearing surface



Photo 10 Light corrosion noted on visible portions of expansion joint



Photo 11 Elevation view of north barrier



Photo 12 Wide crack and small potholes at west end of deck, at joint location



Photo 13 Spall with exposed corroded reinforcement at southeast corner



Photo 14 Staining at edges of underside of structure



Photo 15 Typical view of west end of soffit



Photo 16 East Underside of Structure



Photo 17 Elevation view of northwest wingwall



Photo 18 Graffiti on east abutment wall



Photo 19 Moderate erosion at southeast embankment

Structure Condition Summary Form

Structure Name Van Camp Road North Branch South Nation River Bridge
Structure Number BRH008
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	108.70	0.00	90.00	11.50	7.20	0	0		00	03
	Wearing Surface	Sq.m	6.00	72.00	0.00	71.50	0.50	0.00	432	323	75	00	15
Barriers	Railing Systems	m	200.00	49.40	0.00	45.40	3.00	1.00	9880	7050	71	00	03
	Posts (Steel/Concrete)	Each	200.00	12.00	0.00	12.00	0.00	0.00	2400	1800	75	00	00
Joins	Armouring / Retaining Devices	m	1.00	9.20	0.00	9.20	0.00	0.00	9	7	75	00	00
Decks	Wearing Surface	Sq.m	25.00	88.20	0.00	88.20	0.00	0.00	2205	1654	75	00	00
	Deck Top - Thin Slab	Sq.m	120.00	132.30	0.00	131.90	0.30	0.10	15876	11885	75	00	12
	Soffit - Thin Slab	Sq.m	120.00	152.88	0.00	152.28	0.35	0.25	18346	13722	75	00	08
	Wingwalls	Sq.m	350.00	30.00	0.00	30.00	0.00	0.00	10500	7875	75	08	08
Abutment	Ballast Walls	Sq.m	350.00	12.30	0.00	12.30	0.00	0.00	4305	3229	75	00	00
	Bearings	Each	1000.00	14.00	0.00	14.00	0.00	0.00	14000	10500	75	00	00
	Abutment Walls	Sq.m	900.00	49.30	0.00	45.70	2.40	1.20	44370	31712	71	00	08
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	0.00	4.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00

122323

89756

Bridge Condition Index (BCI)

73

Inventory Data:

Structure Name	Cameron Rd & Near Boundary Rd Bridge									
Main Hwy/Road #	Cameron Road		Services on Structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services Under Structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	50m East of Boundary Rd									
Latitude	44.995		Longitude	-75.51611						
Owner(s)	City of Brockville		Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
				Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern		Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
				Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa		Posted Speed	60km/h		No. of Lanes	2			
Old County	SDG		AADT	205		% Trucks	<input type="checkbox"/>			
Geographic Twp.	<input type="text"/>		Inspection Route Sequence	<input type="text"/>						
Structure Type	Slab on Steel I Girders		Interchange Number	<input type="text"/>						
Total Deck Length	<input type="text"/> 11.5 m		Interchange Structure Number	<input type="text"/>						
Overall Str. Width	<input type="text"/> 6.0 m		Min. Vertical Clearance	<input type="text"/> m						
Total Deck Area	<input type="text"/> 69.0 sq. m		Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
				School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	<input type="text"/> 10.4 m		Detour Length Around Bridge	<input type="text"/> km						
Skew Angle	<input type="text"/> 20 Degrees		Direction of Structure	East/West						
No. of Spans	<input type="text"/> 1		Fill on Structure	<input type="text"/> m						
Span Lengths	<input type="text"/> 10.70 m									

Historical Data:

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text"/>	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	61.23		
OSIM		2022	58		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Sarah Vandergeest P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy				
Temperature:	-2 °C				

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study:		x		\$ 20,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
	Total Cost			\$ 20,000.00
Investigation Notes:				

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input checked="" type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years					
Overall Comments:	Approach barrier has been replaced since previous inspection. Spalls with exposed corroded reinforcement and localized severe scaling noted throughout concrete elements. Rust, flaking, and minor sag noted at interior girders. Severe corrosion and section loss noted on steel diaphragms. Wide vertical cracks on abutments below girders and extend onto soffit.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies		
01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	NE & SE: 30.48m , NW & SW: 13.3m			
Element Name:	Barrier	Width:				
Location:	NE, SE, NW & SW of Structure		Height:			
Material:	Steel	Count (items):	4			
Element Type:	Steel Flex Beam on Steel Posts		Total Quantity:	87.6 m		
Environment:	Severe	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units m	Exc.	Good 87.6	Fair	Poor*	
Comments:	Barrier has been replaced since previous inspection. Generally in good condition.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Approaches	Length:	6.0			
Element Name:	Wearing Surface	Width:	6.0			
Location:	East and West of Surface		Height:			
Material:	Asphalt	Count (items):	2			
Element Type:	Asphalt Wearing Surface		Total Quantity:	36.6 m ²		
Environment:	Severe	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units m ²	Exc.	Good 36.6	Fair	Poor*	
Comments:	Light to medium ravelling and light tire rutting noted on wearing surface. Vegetation growth noted at edges.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Accessories	Length:				
Element Name:	Signs	Width:				
Location:	NE, NW, SE & SW of Structure		Height:			
Material:	Steel	Count (items):	4			
Element Type:	Steel Hazard Signs		Total Quantity:	4.0 Each		
Environment:	Severe	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units Each	Exc.	Good	Fair 1	Poor*	
Comments:	Hazard signs are generally in good condition.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years
					Install supports.	

Element Group:	Barrier	Length:	18.3
Element Name:	Railing System	Width:	
Location:	North and South Sides of Structure	Height:	
Material:	Steel	Count (items):	2
Element Type:	Steel Flex Beam on Steel Posts	Total Quantity:	36.6 m
Environment:	Severe	Limited Inspection	
Protection System:	Hot Dip Galvanizing		
Condition Data:	Units	Exc.	Good
	m		36.6
Comments:	Barrier is generally in good condition.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Barrier	Length:	
Element Name:	Posts	Width:	
Location:	North and South Sides of Structure	Height:	
Material:	Steel	Count (items):	20
Element Type:	Steel I Posts	Total Quantity:	20 Each
Environment:	Severe	Limited Inspection	
Protection System:	Hot Dip Galvanizing		
Condition Data:	Units	Exc.	Good
	Each		20
Comments:	Posts are generally in good condition. Missing blot noted on north barrier post.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Decks	Length:	11.5
Element Name:	Wearing Surface	Width:	6.0
Location:	Top of Deck	Height:	
Material:	Asphalt	Count (items):	1
Element Type:	Asphalt Wearing Surface	Total Quantity:	69 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		67.6
Comments:	Light to medium ravelling noted on wearing surface.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Decks	Length:	11.5
Element Name:	Deck Top	Width:	6.00
Location:	Top of Deck	Height:	
Material:	Cast-In-Place Concrete	Count (items):	1
Element Type:	Thin Slab	Total Quantity:	69.0 m ²
Environment:	Moderate	Limited Inspection	X
Protection System:	Asphalt Wearing Surface		
Condition Data:	Units	Exc.	Good
	m ²		38
		Fair	20.7
		Poor*	10.4
Comments:	Limited inspection since being covered by asphalt. Rating is based on the condition of the wearing surface and soffit.		
Recommended Work:	X	Rehab	Replace
	X	1-5 years	6-10 years
Maintenance Needs:		Urgent	1 year
			2 years

Element Group:	Decks	Length:	11.5
Element Name:	Soffit- Thick Slab (Exterior)	Width:	0.40
Location:	North & South Edges of Structure	Height:	
Material:	Cast-In-Place Concrete	Count (items):	2
Element Type:	Thin Slab	Total Quantity:	9.2 m ²
Environment:	Moderate	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		2.30
		Fair	4.60
		Poor*	2.30
Comments:	Local spall noted on north exterior soffit. Localized moderate scaling noted throughout exterior soffit.		
Recommended Work:	X	Rehab	Replace
	X	1-5 years	6-10 years
Maintenance Needs:		Urgent	1 year
			2 years

Element Group:	Decks	Length:	11.5
Element Name:	Soffit- Thick Slab (Interior)	Width:	5.00
Location:	Underside of Structure	Height:	
Material:	Cast-In-Place Concrete	Count (items):	1
Element Type:	Thick Slap	Total Quantity:	57.5 m ²
Environment:	Moderate	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		19.60
		Fair	20.70
		Poor*	17.30
Comments:	Localized spall with exposed corroded reinforcement noted on interior portion of soffit. Large spall with exposed corroded reinforcement noted at soffit ends adjacent to ballast wall on west side of structure. Evidence of water leakage eg. Wet areas, efflorescence, rust stains and delaminations noted on interior soffit. Wide longitudinal cracks also noted.		
Recommended Work:	X	Rehab	Replace
	X	1-5 years	6-10 years
Maintenance Needs:		Urgent	1 year
			2 years

Element Group:	Beams/Main Longitudinal Elements	Length:	11.5					
Element Name:	Girders	Width:	0.2					
Location:	Underside of Structure	Height:	0.46					
Material:	Cast-In-Place Concrete	Count (items):	5					
Element Type:	Steel I Girders	Total Quantity:	87.40	m ²				
Environment:	Benign	Limited Inspection						
Protection System:	Patina							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		56.9	18.0	12.5			
Comments:	Medium to severe flaking noted on interior girders. Medium rust and slight sag noted							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Beams/Main Longitudinal Elements	Length:						
Element Name:	Diaphragms	Width:						
Location:	North & South Underside of Structure	Height:						
Material:	Steel	Count (items):	12					
Element Type:	Tir Rod Diaphragms	Total Quantity:	12	each				
Environment:	Benign	Limited Inspection	X	Due to st				
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	each		5.0	3.0	4.0			
Comments:	Severe corrosion and section loss noted throughout diaphragms.							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Abutments	Length:						
Element Name:	Ballast Walls	Width:	6.0					
Location:	East & West Underside of Structure	Height:	0.48					
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Reinforced Concrete Wall	Total Quantity:	5.76	m ²				
Environment:	Benign	Limited Inspection	X	Due to structure height and diaphragms				
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		2.76	1.50	1.50			
Comments:	Condition rating based on visible portions of ballast walls. Wide vertical cracks extending from abutments and soffit ends noted.							
Recommended Work:	X	Rehab		Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Abutments	Length:	3.4					
Element Name:	Wingwalls	Width:						
Location:	NE, SE, NW & SW of Structure	Height:	1.5					
Material:	Cast-In-Place Concrete	Count (items):	4					
Element Type:	Wingwalls	Total Quantity:	20.4	m ²				
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		14.10	4.00	2.30			
Comments:	Spall with exposed corroded reinforcement noted on walls. Spall at southeast corner at abutment interface. Localized severe honeycombing noted throughout. Stained medium pattern cracks.							
Recommended Work:	X	Rehab		Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Abutments	Length:						
Element Name:	Abutments walls	Width:	6.0					
Location:	East and West Underside of Structure	Height:	2.8					
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Concrete Abutment walls	Total Quantity:	33.6	m ²				
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		23.6	6.0	4.0			
Comments:	Wide vertical crack noted on abutments below girders. Spall at top of southeast corner of abutments. Moderate to localized severe honeycombing noted on walls and severe scaling observed around drains.							
Recommended Work:	X	Rehab		Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Foundation	Length:						
Element Name:	Foundation (below ground level)	Width:						
Location:	Below Grade	Height:						
Material:	Unknown	Count (items):						
Element Type:	Unknown	Total Quantity:	All					
Environment:	Benign	Limited Inspection	X					
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	All		100%					
Comments:	No evidence of foundation instability at time of inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Embankments & Streams	Length:			
Element Name:	Embankments	Width:			
Location:	NE, SE, NW & SW OF Structure	Height:			
Material:	Native Soil	Count (items):			
Element Type:	Embankment	Total Quantity:		4	
Environment:	Moderate	Limited Inspection			
Protection System:	None				
Condition Data:	Units	Exc.	Good	Fair	Poor*
	Each		2	2	
Comments:	Moderately sloped, well vegetated and stable embankments. Evidence of medium erosion on northeast and northwest embankment.				
Recommended Work:		Rehab	Replace	Maintenance Needs: 13	
		1-5 years	6-10 years	Urgent	X 1 year 2 years

Element Group:	Embankments & Streams	Length:			
Element Name:	Streams & Waterways	Width:			
Location:	Under Structure	Height:			
Material:	Native	Count (items):			
Element Type:	Stream	Total Quantity:		All	
Environment:	Moderate	Limited Inspection			
Protection System:	None				
Condition Data:	Units	Exc.	Good	Fair	Poor*
	All		100%		0
Comments:	Low volume and flow from south to north, with no flow obstructions noted at time of inspection.				
Recommended Work:		Rehab	Replace	Maintenance Needs:	
		1-5 years	6-10 years	Urgent	1 year 2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
	Major Rehabilitation		X		\$ 393,600.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 393,600.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification
<div></div>



Photo 1 Structure from east approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure



Photo 5 North elevation



Photo 6 South elevation



Photo 7 Typical view of approach barrier end treatment, northwest corner shown



Photo 8 Vegetation growth at edges of roadway



Photo 9 Typical barrier elevation



Photo 10 Moderate ravelling on deck wearing surface



Photo 11 Large spall with ECR at west end of soffit



Photo 12 Moderate scaling on south exterior soffit



Photo 13 Rust stains efflorescence on interior soffit



Photo 14 Flaking on bottom flange of exterior girder



Photo 15 Corrosion on steel tie diaphragm



Photo 16 Spall and wide vertical crack below girder on west abutment wall



Photo 17 Severe honeycombing on northwest wingwall



Photo 18 East underside of structure

Structure Condition Summary Form

Structure Name Cameron Rd Near Boundary Rd Bridge
Structure Number BRH009
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	87.60	0.00	87.60	0.00	0.00	0	0		00	00
	Wearing Surface	Sq.m	6.00	36.60	0.00	36.60	0.00	0.00	220	165	75	00	15
Barriers	Railing Systems	m	200.00	36.60	0.00	36.60	0.00	0.00	7320	5490	75	00	00
	Posts (Steel/Concrete)	Each	200.00	20.00	0.00	20.00	0.00	0.00	4000	3000	75	00	00
Decks	Wearing Surface	Sq.m	25.00	69.00	0.00	67.60	1.40	0.00	1725	1282	74	00	00
	Deck Top - Thin Slab	Sq.m	120.00	69.00	0.00	38.00	20.70	10.40	8280	4414	53	00	12
	Soffit - Thin Slab	Sq.m	120.00	66.70	0.00	21.90	25.30	19.60	8004	3185	40	00	00
Beams/ Main Longitudinal Elements	Girders -Steel	Sq.m	420.00	87.40	0.00	56.90	18.00	12.50	36708	20948	57	00	00
	Diaphragms - Steel, wood etc.	Each	0.00	12.00	0.00	5.00	3.00	4.00	0	0		00	00
Abutment	Wingwalls	Sq.m	350.00	20.40	0.00	14.10	4.00	2.30	7140	4261	60	08	08
	Ballast Walls	Sq.m	350.00	5.76	0.00	2.76	1.50	1.50	2016	935	46	00	00
	Abutment Walls	Sq.m	900.00	33.60	0.00	23.60	6.00	4.00	30240	18090	60	01	08
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	2.00	2.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									105653	61768			
Bridge Condition Index (BCI)	58												

Inventory Data:

Structure Name	Cameron Rd & North Branch of South Nation River MD Bridge									
Main Hwy/Road #	Cameron Road		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	1.5km West of County Road 3									
Latitude	4503032		Longitude	-75.41273						
Owner(s)	Township of North Dundas		Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
				Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern		Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
				Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa		Posted Speed	80 km/h		No. of Lanes	2			
Old County	SDG		AADT	205		% Trucks	<input type="checkbox"/>			
Geographic Twp.	<input type="text"/>		Inspection Route Sequence	<input type="text"/>						
Structure Type	Slab on CPCI Girders		Interchange Number	<input type="text"/>						
Total Deck Length	<input type="text"/> 18.3 m		Interchange Structure Number	<input type="text"/>						
Overall Str. Width	<input type="text"/> 9 m		Min. Vertical Clearance	<input type="text"/> m						
Total Deck Area	<input type="text"/> 164.7 sq. m		Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
				School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	<input type="text"/> 7.3 m		Detour Length Around Bridge	<input type="text"/> km						
Skew Angle	<input type="text"/> Degrees		Direction of Structure	East/West						
No. of Spans	<input type="text"/> 1		Fill on Structure	<input type="text"/> m						
Span Lengths	<input type="text"/> 17 m									

Historical Data:

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text"/> October 9, 2020	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.95		
OSIM		2022	75		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu,				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy				
Temperature:	0° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
		Total Costs \$ -			
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:		<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years				
Overall Comments:	Structure is in generally good condition. New approach barrier was installed since previous inspection. Spalls on exterior faces of barrier wall where the new approach barrier anchors were installed. Deck barrier arrangement is not code compliant and should be updated in the next rehabilitaiton.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	NE:32.4 , SE:167.6 , SW: 35.14, NW: 31.3						
Element Name:	Barrier	Width:							
Location:	NE, SE, NW & SW of Structure	Height:							
Material:	Steel	Count (items):	4						
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	265.4 m						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		265.4						
Comments:	New end treatments and approach barrier installed since previous inspection. New barrier appears to be in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches	Length:	6						
Element Name:	Wearing Surface	Width:	7.3						
Location:	East and West Side of Structure	Height:							
Material:	Asphalt	Count (items):	2						
Element Type:	Asphalt Surface Treatment	Total Quantity:	87.6 m ²						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		78.6	5.0	4.0				
Comments:	Wide transverse cracks noted adjacent to ends of deck. Medium pattern cracks noted on east and west approach.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 12				
		1-5 years		6-10 years		Urgent		1 year	X 2 years
	Repair asphalt surface treatment and patch pothole								

Element Group:	Approaches	Length:	6						
Element Name:	Approach Slab	Width:	7.3						
Location:	East & West of Structure	Height:							
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	Concrete Approach Slab	Total Quantity:	87.6 m						
Environment:	Moderate	Limited Inspection	X						
Protection System:	Approach Wearing Surface								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		87.6						
Comments:	Approach slabs are assumed to be generally in good condition								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Accessories	Length:							
Element Name:	Utilities	Width:							
Location:	South side of Structure	Height:							
Material:	Steel	Count (items):	1						
Element Type:	Mounted Utility Pipe	Total Quantity:	1.0 each						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units each	Exc.	Good 1.0	Fair	Poor*				
Comments:	Generally in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Barriers	Length:	30						
Element Name:	Barrier/Parapet Walls	Width:	0.25						
Location:	North & South Sides of Structure	Height:	0.6						
Material:	Cast-in-Place Concrete	Count (items):	2						
Element Type:	Parapet Wall - Interior Face	Total Quantity:	51.00 m ²						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m ²	Exc.	Good 49.5	Fair 1.0	Poor*	0.5			
Comments:	Spalls, light to medium abrasions and light to moderate scaling noted on interior face. Small spalls with exposed corroded reinforcement due to low cover observed. Barrier arrangement is not code compliant and should be updated during next rehabilitation.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 8				
		1-5 years		6-10 years		Urgent		1 year	X 2 years

Element Group:	Barriers	Length:	30						
Element Name:	Barrier/Parapet Walls	Width:							
Location:	North & South Sides of Structure	Height:	0.6						
Material:	Cast-in-Place Concrete	Count (items):	2						
Element Type:	Parapet Wall - Exterior Face	Total Quantity:	36 m ²						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m ²	Exc.	Good 29	Fair 5.0	Poor*	2.0			
Comments:	Spalls on exterior face of walls where the approach barrier anchors have been installed. Barrier arrangement is not code compliant and should be updated during next rehabilitation.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 8				
		1-5 years		6-10 years		Urgent		1 year	X 2 years
					Concrete Repairs				

Element Group:	Barriers	Length:	28.6				
Element Name:	Hand Railings	Width:					
Location:	North and South Sides of Structure	Height:					
Material:	Steel	Count (items):	2				
Element Type:	Double Pipe hand Railings	Total Quantity:	57.2	m			
Environment:	Severe	Limited Inspection					
Protection System:	Hot Dip Galvanizing					Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	m		57	0.2			
Comments:	Generally in good condition with a localized dent and some minor rust noted.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Coating	Length:					
Element Name:	Railing System / Hand Railings	Width:					
Location:	On Hand Railings	Height:					
Material:	Other	Count (items):					
Element Type:	Hot Dip Galvanizing	Total Quantity:	81.7	Each			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	Each		81.7				
Comments:	Generally in good condition with some light rust noted.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Sidewalk/Curbs	Length:	30				
Element Name:	Curbs	Width:	0.15				
Location:	North South Sides of Structure	Height:	0.6				
Material:	Cast-In-Place Concrete	Count (items):	2				
Element Type:	Reinforced Concrete Curbs	Total Quantity:	45	m ²			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	m ²		40.0	5.0			
Comments:	Light to moderate scaling, abrasions and some narrow to medium transverse cracks noted on curbs.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:						
Element Name:	Drainage System	Width:						
Location:	North & South Side of Structure	Height:						
Material:	Steel	Count (items):	4					
Element Type:	Steel drain Pipes	Total Quantity:	4.0 each					
Environment:	Severe	Limited Inspection						
Protection System:	Hot Dip Galvanizing						Perform. Deficiencies	
Condition Data:	Units each	Exc.	Good 4	Fair	Poor*			
Comments:	Medium rust and some patina noted on downspouts of drain pipes. Deck drains were partially blocked by debris.							
Recommended Work:		Rehab		Replace	Maintenance Needs: 2			
		1-5 years		6-10 years	Urgent	X	1 year	2 years
					Clean debris			

Element Group:	Decks	Length:	18.3					
Element Name:	Wearing Surface	Width:	7.3					
Location:	Top of Deck	Height:						
Material:	Asphalt	Count (items):						
Element Type:	Asphalt Surface Treatment	Total Quantity:	133.59 m ²					
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good 131.59	Fair 2.0	Poor*			
Comments:	Light ravelling and pattern cracks forming on deck wearing surface.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent		1 year	2 years

Element Group:	Decks	Length:	19.3					
Element Name:	Deck Top	Width:	9					
Location:	Top of Deck	Height:						
Material:	Cast-in-Place Concrete	Count (items):						
Element Type:	Deck Top	Total Quantity:	164.7 m ²					
Environment:	Moderate	Limited Inspection	X					
Protection System:	Asphalt Surface Treatment						Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good 164.7	Fair	Poor*			
Comments:	Deck top is assumed to be in good condition due to condition of wearing surface and deck soffit.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent		1 year	2 years

Element Group:	Decks	Length:	18.3
Element Name:	Soffit - Thin Slab (Exterior)	Width:	1.15
Location:	North and South Sides of Structure	Height:	
Material:	Precast Concrete	Count (items):	2
Element Type:	Soffit - Exterior	Total Quantity:	42.09 m ²
Environment:	Moderate	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		42.09
Comments:	Some staining noted on exterior soffit. Generally in good condition.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Decks	Length:	18.3
Element Name:	Soffit - Thin Slab	Width:	5.5
Location:	Underside of Structure	Height:	
Material:	Precast Concrete	Count (items):	1
Element Type:	Soffit - Interior	Total Quantity:	99.74 m ²
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		98.7
Comments:	Generally in good condition with some moderate honeycombing noted on interior soffit.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Beams/Main Longitudinal Elements (MLE's)	Length:	18.3
Element Name:	Girders	Width:	0.46
Location:	Underside of Structure	Height:	0.9
Material:	Precast Concrete	Count (items):	5
Element Type:	CPCI Girders	Total Quantity:	290.97 m ²
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		290.97
Comments:	Generally in good condition		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Beams/Main Longitudinal Elements (MLE's)	Length:	1.4				
Element Name:	Diaphragms	Width:	0.3				
Location:	East & West End of Structure	Height:	0.9				
Material:	Cast-In-Place Concrete	Count (items):	5				
Element Type:	Rectangular Diaphragm	Total Quantity:	14.7 m ²				
Environment:	Benign	Limited Inspection					
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	
	m ²		14.7				
Comments:	Generally in good condition						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year	2 years

Element Group:	Abutments	Length:					
Element Name:	Bearings	Width:					
Location:	East and West Abutment Walls	Height:					
Material:	Neoprene	Count (items):	10				
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	10 Each				
Environment:	Benign	Limited Inspection	X				
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	
	Each		10				
Comments:	Generally in good condition, limited access to bearing pads, condition is based on accessible bearing pads						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year	2 years

Element Group:	Abutments	Length:					
Element Name:	Ballast Walls	Width:	8.2				
Location:	East and West Underside of Structure	Height:	0.6				
Material:	Cast-In-Place Concrete	Count (items):	2				
Element Type:	Reinforced Concrete Walls	Total Quantity:	9.84 m ²				
Environment:	Benign	Limited Inspection	X				
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	
	m ²		9.84				
Comments:	Ballast walls were inaccessible for inspection due to end diaphragms. Condition state is based on the visible sections of the ballast walls. Visible sections of the ballast walls were in good condition.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year	2 years

Element Group:	Abutment	Length:								
Element Name:	Abutment Walls	Width:	8.2							
Location:	East and West Underside of Structure	Height:	3							
Material:	Cast-in-Place Concrete	Count (items):	2							
Element Type:	Reinforced Concrete Walls	Total Quantity:	49.2 m ²							
Environment:	Benign	Limited Inspection								
Protection System:	None								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		47.70	1	0.5					
Comments:	Spall and delamination noted at north end of west wall.									
Recommended Work:		Rehab		Replace	Maintenance Needs: 8					
		1-5 years		6-10 years		Urgent		1 year	X	2 years
Concrete Repairs										

Element Group:	Abutments	Length:	5.85							
Element Name:	Wingwalls	Width:								
Location:	NE, SE, NW & SW OF Structure	Height:	2.1							
Material:	Cast-in-place Concrete	Count (items):	4.0							
Element Type:	Reinforced Concrete Walls	Total Quantity:	49.14 m ²							
Environment:	Moderate	Limited Inspection								
Protection System:	None								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		48.94	0.1	0.1					
Comments:	Generally in good condition with small localized spalls and some staining on wingwalls.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Foundations	Length:								
Element Name:	Foundation (Below Ground Level)	Width:								
Location:	Below Abutment Walls and Wingwalls	Height:								
Material:	Unknown	Count (items):								
Element Type:	Unknown	Total Quantity:	All							
Environment:	Benign	Limited Inspection			X					
Protection System:	Unknown								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	No visible evidence of foundation instability was noted during the inspection.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams				Length:				
Element Name:	Embankments				Width:				
Location:	NE, SE, NW & SW Side of Structure				Height:				
Material:	Native Material				Count (items):	4			
Element Type:	Embankment				Total Quantity:	4 Each			
Environment:	Moderate				Limited Inspection				
Protection System:	Rip-Rap								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each			4					
Comments:	Embankments are Steeply sloped, well vegetated with medium erosion noted at all corners of structure								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments and Streams				Length:				
Element Name:	Slope Protection				Width:				
Location:	NE, SE, NW & SW Side of Structure				Height:				
Material:	Rip-Rap				Count (items):	4			
Element Type:	Stone Slope Protection				Total Quantity:	4 Each			
Environment:	Moderate				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each			4					
Comments:	Generally in good condition								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments and Streams				Length:				
Element Name:	Streams and Waterways				Width:				
Location:	Below Structure				Height:				
Material:	Native				Count (items):	All			
Element Type:	Stream				Total Quantity:	All N/A			
Environment:	Benign				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Low volume and moderate flow from north to south with no obstructions noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent	1 year	2 years	

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ -

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>



Photo 1 Structure from east approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure



Photo 5 North elevation



Photo 6 South elevation



Photo 7 New end treatment at southeast corner



Photo 8 Medium pattern cracks on east approach wearing surface



Photo 9 Abrasions on south curb



Photo 10 Spall on south barrier wall



Photo 11 Spall on exterior of southwest end of barrier wall



Photo 12 Wide crack at west end of deck



Photo 13 Debris blocking deck drain



Photo 14 Typical view of south exterior soffit



Photo 15 Typical view of interior soffit



Photo 16 View of interior girder



Photo 17 West underside of structure



Photo 18 Elevation view of southeast wingwall



Photo 19 Staining and delamination on north end of east abutment wall

Structure Condition Summary Form

Structure Name Cameron Rd North Branch of South nation River MD Bridge
Structure Number BRH010
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	212.30	0.00	212.30	0.00	0.00	0	0		00	00
	Wearing Surface	Sq.m	6.00	87.60	0.00	78.60	5.00	4.00	526	366	70	00	12
Accessories	Approach Slabs	Sq.m	140.00	87.60	0.00	87.60	0.00	0.00	12264	9198	75	00	00
	Utilities	Each	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
Barriers	Barrier/ Parapet Walls (interior)	Sq.m	100.00	51.00	0.00	49.50	1.00	0.50	5100	3753	74	00	08
	Barrier/ Parapet Walls (exterior)	Sq.m	100.00	36.00	0.00	29.00	5.00	2.00	3600	2375	66	00	08
Sidewalks/ Curbs	Hand Railings	m	100.00	57.20	0.00	57.00	0.20	0.00	5720	4283	75	00	00
	Curbs	Sq.m	40.00	45.00	0.00	40.00	5.00	0.00	1800	1280	71	00	08
Decks	Drainage System	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Wearing Surface	Sq.m	25.00	133.59	0.00	131.59	2.00	0.00	3340	2487	74	00	00
Beams/ Main Longitudinal Elements	Deck Top - Thin Slab	Sq.m	120.00	164.70	0.00	164.70	0.00	0.00	19764	14823	75	00	12
	Soffit - Thin Slab	Sq.m	120.00	141.83	0.00	140.83	1.00	0.00	17020	12723	75	00	00
Coatings	Girders	Sq.m	200.00	290.97	0.00	290.97	0.00	0.00	58194	43646	75	01	00
	Diaphragms - Concrete	Each	0.00	14.70	0.00	14.70	0.00	0.00	0	0		00	00
Abutment	Railing Systems/ Hand Railing	Sq.m	125.00	81.70	0.00	81.70	0.00	0.00	10213	7659	75	00	00
	Wingwalls	Sq.m	350.00	49.14	0.00	48.14	0.10	0.10	17199	12651	74	08	08
Embankments and Streams	Ballast Walls	Sq.m	350.00	9.84	0.00	9.84	0.00	0.00	3444	2583	75	00	00
	Bearings	Each	1000.00	10.00	0.00	10.00	0.00	0.00	10000	7500	75	00	00
	Abutment Walls	Sq.m	900.00	49.20	0.00	49.20	0.00	0.00	44280	33210	75	01	08
	Embankments	Each	0.00	4.00	0.00	0.00	4.00	0.00	0	0		00	00
	Slope Protection	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									212462	158536			

Bridge Condition Index (BCI) 75

Inventory Data:

Structure Name		Nation Valley Rd and South Nation Bridge							
Main Hwy/Road #	Nation Valley Rd	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		70m South of River Rd							
Latitude	45.0681762	Longitude	-75.2806069						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	Design./not list <input type="checkbox"/>	Cons/not App. <input type="checkbox"/>	Design. & List <input type="checkbox"/>	List/n.d. <input type="checkbox"/>	
MTO Region	40 - Eastern	Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>	Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>			
MTO District	42 - Ottawa	Posted Speed	50 km/h		No. of Lanes	2			
Old County	SDG	AADT	117		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	Slab on CPCI Girders	Interchange Number	<input type="checkbox"/>						
Total Deck Length	69.1 m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	9.2 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	635.7 sq. m	Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>	School <input type="checkbox"/>	Bicycle <input type="checkbox"/>			
Roadway Width	7.3 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	<input type="checkbox"/> Degrees	Direction of Structure	North/South						
No. of Spans	3	Fill on Structure	<input type="checkbox"/> m						
Culvert Length	<input type="checkbox"/> m								
Span Lengths	21.3, 26.5, 21.3 m								

Historical Data:

Year Built	1980	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.44		
OSIM		2022	72.58		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	5 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 20,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:				
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years		
Overall Comments:	Structure is in generally good to localized fair/poor condition - abrasions and deformations noted on guide rail throughout. Small spalls and cracks on concrete barrier posts noted. Approach barrier has been recently replaced. Asphalt surface treatment partially covers both expansion joints, with debris noted in joint seals. abrasions and rust on joint armouring. pothole noted on north approach. Spalls, ECR, and wet stains noted along exterior soffit. Delamination noted on end diaphragms. Cracks, efflorescence, AAR, and spalls noted on abutment walls and wingwalls			
Date of Next Inspection:	2024			

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Accessories (Attachments and Signs)	Length:							
Element Name:	Utilities	Width:							
Location:	NE, NW, SW & SE Side of Structure	Height:							
Material:	Steel	Count (items):	3						
Element Type:	Hazard Markers	Total Quantity:	3 Each						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		3.00						
Comments:	Generally in good condition								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches	Length:	NE: 21, NW: 25, SE: 54, SW: 29.3						
Element Name:	Barriers	Width:							
Location:	NE, NW, SW & SE Side of Structure	Height:							
Material:	Steel/Wood	Count (items):	4						
Element Type:	Steel Flex Beam on Wood Posts	Total Quantity:	129.60 m						
Environment:	Severe	Limited Inspection							
Protection System:	Hot dip galvanizing								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		129.60						
Comments:	Approach barriers have been replaced since last inspection - all in generally good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches	Length:							
Element Name:	Barrier Posts - Timber	Width:							
Location:	NE, NW, SW & SE Side of Structure	Height:							
Material:	Wood	Count (items):	14						
Element Type:	Timber Barrier posts	Total Quantity:	14.00 Each						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		2.00	12.00					
Comments:	Timber approach barrier posts are in generally fair condition, with rot, weathing, checks and splits throughout								
Recommended Work:		Rehab	x	Replace	Maintenance Needs:				
	x	1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches	Length:	6
Element Name:	Wearing Surface	Width:	7.3
Location:	North and South approaches to structure	Height:	
Material:	Asphalt	Count (items):	2
Element Type:	Asphalt surface treatment	Total Quantity:	87.6 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		79.72
			5.26
			2.63
Comments:	Medium settlement and pothole noted at the north approach		
Recommended Work:	Rehab	Replace	Maintenance Needs: 12
	1-5 years	6-10 years	Urgent X 1 year 2 years
	Patch pothole		

Element Group:	Joints	Length:	9.2
Element Name:	Armouring/retaining Devices	Width:	
Location:	North and south of structure	Height:	
Material:	Steel	Count (items):	4
Element Type:	Armouring/retaining Devices	Total Quantity:	36.80 m
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m		18.40
			18.40
Comments:	Light rust with abrasions and scores noted. North expansion joint is partially covered by asphalt, with signs of leaking and steel flaking. South expansion joint covered with asphalt.		
Recommended Work:	Rehab	Replace	Maintenance Needs: 2
	1-5 years	6-10 years	Urgent 1 year X 2 years
	Remove debris		

Element Group:	Joints	Length:	9.2
Element Name:	Concrete End Dams	Width:	0.35
Location:	North and South of structure	Height:	
Material:	Cast-in-place concrete	Count (items):	1
Element Type:	Concrete End Dams	Total Quantity:	12.88 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		6.88
			6.00
Comments:	Moderate abrasion and scaling noted, with some spalls. Both expansion joints are partially covered with asphalt.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Joints	Length:	9.2
Element Name:	Seals/Sealants	Width:	
Location:	North Side of Structure	Height:	
Material:	Plastic	Count (items):	
Element Type:	Strip Seal	Total Quantity:	2 Each
Environment:		Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	Each		Fair
			Poor*
			2.0
Comments:	Both seals are filled with debris and are failing		
Recommended Work:		Rehab	X
	X	1-5 years	6-10 years
Replace expansion joints			
Maintenance Needs:	2		
	Urgent	X	1 year
			2 years
Remove debris from expansion joints			

Element Group:	Barriers	Length:	43.2
Element Name:	Railing Systems	Width:	
Location:	East and West Sides of structure	Height:	
Material:	Steel	Count (items):	2
Element Type:	Steel flex beam on concrete posts	Total Quantity:	86.4 m
Environment:	Severe	Limited Inspection	
Protection System:	Hot dip galvanizing		
Condition Data:	Units	Exc.	Good
	m		66.4
			20.0
Comments:	Generally in good condition with light abrasion and deformation throughout		
Recommended Work:		Rehab	
		1-5 years	6-10 years
Maintenance Needs:			
	Urgent		1 year
			2 years

Element Group:	Barriers	Length:	
Element Name:	Posts	Width:	
Location:	East and West sides of structure	Height:	
Material:	Cast-in-place concrete	Count (items):	66
Element Type:	Reinforced concrete posts	Total Quantity:	66 Each
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	Each		55.5
			10
			0.5
Comments:	Narrow cracks at railing with small spalls throughout. 3 medium spaklls @ railing connection at east barrier.		
Recommended Work:		Rehab	
		1-5 years	6-10 years
Maintenance Needs:	8		
	Urgent	X	1 year
			2 years
Repair concrete			

Element Group:	Barriers	Length:	0.5					
Element Name:	Posts	Width:	0.3					
Location:	East and West sides of structure	Height:	1.2					
Material:	Cast-in-place concrete	Count (items):	4					
Element Type:	Reinforced concrete end posts	Total Quantity:	6	m2				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m2		5	1				
Comments:	Generally in good condition with light map cracking and small spall at northeast							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	69.1					
Element Name:	Wearing surface	Width:	7.3					
Location:	Top of deck	Height:						
Material:	Asphalt	Count (items):						
Element Type:	Asphalt surface treatments	Total Quantity:	504.43	m2				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m2		503.43	1.00				
Comments:	Loss of asphalt at south of deck							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	69.1					
Element Name:	Deck top	Width:	9.2					
Location:	Top of deck	Height:						
Material:	cast-in-place concrete	Count (items):						
Element Type:	Deck top	Total Quantity:	635.7	m2				
Environment:	severe	Limited Inspection	X					
Protection System:	Asphalt surface treatment						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m2		635.7					
Comments:	Deck top is in generally good condition and partially covered with asphalt surface treatment							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Decks				Length:	2				
Element Name:	Soffit - Thin slab				Width:	6.2				
Location:	North and south underside of structure				Height:					
Material:	Steel				Count (items):	2				
Element Type:	Soffit-End				Total Quantity:	24.6 m2				
Environment:	Benign		Limited Inspection							
Protection System:	None						Perform. Deficiencies			
Condition Data:	Units		Exc.		Good	Fair		Poor*		
	m2				24.6					
Comments:	Generally in good condition									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Decks				Length:	69.1					
Element Name:	Soffit - Thin slab				Width:	0.9					
Location:	East and West underside of structure				Height:						
Material:	Cast-in-place concrete				Count (items):	2					
Element Type:	Soffit- Exterior				Total Quantity:	124.38 m2					
Environment:	Moderate		Limited Inspection								
Protection System:	None							Perform. Deficiencies			
Condition Data:	Units		Exc.	Good	Fair		Poor*				
	m2			96	19		9				
Comments:	Evidence of localized spalls and wet stains noted. Spall with exposed ECR noted, and severe spall and rust stain noted on fascia adjacent to expansion joint.										
Recommended Work:		X	Rehab		Replace	Maintenance Needs:					
		X	1-5 years		6-10 years		Urgent		1 year		2 years
Repair concrete											

Element Group:	Decks				Length:	64.1						
Element Name:	Soffit - Thin slab				Width:	6.2						
Location:	Underside of structure				Height:							
Material:	Steel				Count (items):							
Element Type:	Soffit - Interior				Total Quantity:	397.4 m2						
Environment:	Benign				Limited Inspection							
Protection System:	None							Perform. Deficiencies				
Condition Data:	Units		Exc.		Good	Fair					Poor*	
	m2				397.4							
Comments:	Generally in good condition. Bird nest was noted at the time of inspection											
Recommended Work:		Rehab		Replace	Maintenance Needs:							
		1-5 years		6-10 years		Urgent		1 year		2 years		

Element Group:	Beams/Main Longitudinal Elements (MLE's)			Length:	4		
Element Name:	Girders			Width:	0.56		
Location:	North and South Underside of Structure			Height:	1.2		
Material:	Precast Concrete			Count (items):	4		
Element Type:	CPCA Girders (1200) - End			Total Quantity:	65.28		
Environment:	Benign			Limited Inspection			
Protection System:	None						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		61.68	2.40	1.20		
Comments:	Delaminations noted.						
Recommended Work:		Rehab		Replace	Maintenance Needs: 8		
		1-5 years		6-10 years	Urgent	1 year	2 years
	Concrete repairs to girders						

Element Group:	Beams/Main Longitudinal Elements (MLE's)			Length:	64.1		
Element Name:	Girders			Width:	0.56		
Location:	Underside of structure			Height:	1.2		
Material:	Precast concrete			Count (items):	4		
Element Type:	CPCI Girders (1200) - Middle			Total Quantity:	1046.11		
Environment:	Benign			Limited Inspection			
Protection System:	None						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		1046.1				
Comments:	Generally in good condition						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year	2 years

Element Group:	Beams/Main Longitudinal Elements (MLE's)			Length:	3		
Element Name:	Diaphragms			Width:	0.3		
Location:	North and South Underside of Structure			Height:	0.5		
Material:	Cast-in-place Concrete			Count (items):	6		
Element Type:	RC Rectangular Solid Diaphragms - End			Total Quantity:	23.4		
Environment:	Benign			Limited Inspection			
Protection System:	None						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		20.34	2.04	1.02		
Comments:	Spall and delamination noted.						
Recommended Work:		Rehab		Replace	Maintenance Needs: 8		
		1-5 years		6-10 years	Urgent	1 year	2 years

Element Group:	Beams/Main Longitudinal Elements (MLE's)	Length:	3
Element Name:	Diaphragms	Width:	0.3
Location:	On Pier Caps	Height:	0.5
Material:	Cast-in-place Concrete	Count (items):	6
Element Type:	RC Rectangular Solid Diaphragms - - Intermediate	Total Quantity:	23.4 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units m2	Exc.	Good 23.40
		Fair	Poor*
Comments:	Generally in good condition.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Abutments	Length:	
Element Name:	Bearings	Width:	
Location:	On North and South Abutment Walls	Height:	
Material:	Plastic	Count (items):	8
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	8 Each
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units Each	Exc.	Good 7
		Fair 1	Poor*
Comments:	Generally in good condition with crack in NE Bearing.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Abutments	Length:	
Element Name:	Ballast Walls	Width:	8.8
Location:	On North and South Abutment Walls	Height:	1.2
Material:	Cast-in-place Concrete	Count (items):	2
Element Type:	Reinforced concrete walls	Total Quantity:	21.12 m2
Environment:	Benign	Limited Inspection	X
Protection System:	None		
Condition Data:	Units m2	Exc.	Good 21.12
		Fair	Poor*
Comments:	Access to ballast walls was limited due to end diaphragms. Condition state is based on the visible sections of the ballast walls - Generally in good condition		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Abutments	Length:					
Element Name:	Abutment Walls	Width:	8.8				
Location:	North and South underside of structure	Height:	1				
Material:	Cast-in-place concrete	Count (items):	2				
Element Type:	Reinforced concrete walls	Total Quantity:	17.6 N/A				
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	N/A		14.00	2.40	1.20		
Comments:	Wide vertical crack noted, and wide map cracking and AAR noted throughout.						
Recommended Work:	X	Rehab		Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutments	Length:	4.8				
Element Name:	Wingwalls	Width:					
Location:	NE, NW, SW, & SE Side of Structure	Height:	2				
Material:	Cast-in-place Concrete	Count (items):	4				
Element Type:	Reinforced concrete walls	Total Quantity:	38.4 m2				
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		26.40	6.00	6.00		
Comments:	Generally in good condition with efflorescence, medium transverse cracks, spall, and narrow-medium cracks.						
Recommended Work:	X	Rehab		Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Piers	Length:					
Element Name:	Bearings	Width:					
Location:	On pier caps	Height:					
Material:	Plastic	Count (items):	8				
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	8 Each				
Environment:	Benign	Limited Inspection	X				
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		8				
Comments:	Access to pier bearings is limited.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Piers	Length:	8.8				
Element Name:	Caps	Width:	0.5				
Location:	Over Pier Shafts	Height:	0.7				
Material:	Cast-in-place Concrete	Count (items):	2				
Element Type:	Reinforced Concrete Pier Caps	Total Quantity:	43.64	m2			
Environment:	Benign	Limited Inspection	X				
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m2	Exc.	Good 43.64	Fair	Poor*		
Comments:	Generally in good condition						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Piers	Length:	0.9				
Element Name:	Shafts/Columns/ Pile Bents	Width:	0.9				
Location:	Below Pier caps	Height:	4.5				
Material:	Steel	Count (items):	2				
Element Type:	Steel Fram Shafts	Total Quantity:	25.43	m2			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m2	Exc.	Good 25.43	Fair	Poor*		
Comments:	Generally in good condition						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Foundations	Length:					
Element Name:	Foundation (Below Ground Level)	Width:					
Location:	Below Abutment walls, wingwalls, and piers	Height:					
Material:	Unknown	Count (items):	All				
Element Type:	Unknown	Total Quantity:	All	N/A			
Environment:	Benign	Limited Inspection	X				
Protection System:	Unknown					Perform. Deficiencies	
Condition Data:	Units N/A	Exc.	Good All	Fair	Poor*		
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SE, SW of structure, and below abutmen		Height:					
Material:	Vegetation		Count (items):	6				
Element Type:	Embankment		Total Quantity:	6				
Environment:	Moderate		Limited Inspection				Each	
Protection System:	Rip-Rap						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		6.00					
Comments:	Embankments are moderately sloped, well vegetated, and stable							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope Protection	Width:						
Location:	NE, NW, SE, SW of structure, and below abutmen		Height:					
Material:	Rip-Rap		Count (items):	4				
Element Type:	Slope Protection		Total Quantity:	4				
Environment:	Moderate		Limited Inspection				Each	
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4.00					
Comments:	Generally in good condition							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and streams	Length:						
Element Name:	Streams and waterways	Width:						
Location:	Below Structure		Height:					
Material:	Native		Count (items):	All				
Element Type:	Streams and waterways		Total Quantity:	All				
Environment:	Benign		Limited Inspection				N/A	
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Medioium volume and low flow from west to east with no flow obstructions noted.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Coating	Length:					
Element Name:	Railing Systems / Hand Railings	Width:					
Location:	On Bridge Railing	Height:					
Material:	Other	Count (items):					
Element Type:	Coating - Hot dip galvanizing	Total Quantity:		86.4	m		
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	N/A		86.40				
Comments:	Generally in good condition						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Joints Seals	Replacement		X		\$ 41,000.00
Overhangs	Concrete Repairs		X		\$ 22,500.00
Girders	Concrete Repairs		X		\$ 15,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 78,500.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 35,000.00

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and South Nation River Bridge

SITE PHOTOGRAPHS

Site No.:BRH011



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and South Nation River Bridge

SITE PHOTOGRAPHS

Site No.:BRH011



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and South Nation River Bridge

SITE PHOTOGRAPHS

Site No.:BRH011



Photo 5 East elevation



Photo 6 West elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and South Nation River Bridge

SITE PHOTOGRAPHS

Site No.:BRH011



Photo 7 Abrasion and deformation on southeast approach barrier (typ.)



Photo 8 Spall on Northeast concrete end-post

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and South Nation River Bridge

SITE PHOTOGRAPHS

Site No.:BRH011



Photo 9 Spall on concrete deck post (typ.)



Photo 10 Partially covered expansion joint at north (typ.)

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and South Nation River Bridge

SITE PHOTOGRAPHS

Site No.:BRH011



Photo 11 Rust, abrasion on armouring (typ.). Debris and failing deck seal at North



Photo 12 Spalls on deck fascia/soffit at north expansion joint, with squished seal



Photo 13 Rot, checks and splits at southwest approach barrier post (typ.)



Photo 14 Delamination along west soffit overhang (typ.)

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and South Nation River Bridge

SITE PHOTOGRAPHS

Site No.:BRH011



Photo 15 South pier cap, bridge soffit, and girders



Photo 16 Steel frame pier shaft at South end of bridge



Photo 17 Evidence of failure at the south expansion joint with spalls and stains



Photo 18 Cracks and delamination in south concrete girders and diaphragms



Photo 19 ECR and spalls at south girder ends and diaphragms



Photo 20 Spalls and ECR at northeast overhang (typ.)

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and South Nation River Bridge

SITE PHOTOGRAPHS

Site No.:BRH011



Photo 21 Crack and Spall at northwest wingwall



Photo 22 Cracks on South abutment wall.

Structure Condition Summary Form

Structure Name Nation Valley Rd & South Nation River Bridge
Structure Number BRH011
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	129.60		129.60			0	0		00	00
	Wearing Surface	Sq.m	6.00	87.68		79.79	5.26	2.63	526	372	71	00	12
Accessories	Signs	Each	0.00	3.00		3.00			0	0		00	00
	Barrier/ Parapet Walls	Sq.m	100.00	6.00		5.00	1.00		600	415	69	00	00
Barriers	Railing Systems	m	200.00	86.40		66.40	20.00		17280	11560	67	00	00
	Railing Systems - Timber	m	100.00	14.00		2.00	12.00		1400	630	45	00	00
	Posts (Steel/Concrete)	Each	200.00	66.00		55.50	10.00	0.50	13200	9125	69	00	00
	Armouring / Retaining Devices	m	1.00	36.90		18.40	18.50		37	21	57	00	00
Joints	Concrete End Dams	Sq.m	2100.00	12.88		6.88	6.00		27048	15876	59	00	00
	Seals/ Sealants	Each	0.00	2.00				2.00	0	0		00	02
	Wearing Surface	Sq.m	25.00	504.43		503.43	1.00		12611	9449	75	00	00
Decks	Deck Top - Thin Slab	Sq.m	120.00	635.70		635.70			76284	57213	75	00	00
	Soffit - Thin Slab	Sq.m	120.00	546.00		518.00	19.00	9.00	65520	47532	73	00	00
Beams/ Main Longitudinal	Girders	Sq.m	200.00	1,111.38		1,107.78	2.40	1.20	222276	166359	75	00	08
Elements	Diaphragms - Concrete	Each	0.00	46.80		43.74	2.04	1.02	0	0		00	08
Coatings	Railing Systems/ Hand Railing	Sq.m	125.00	17.60		14.00	2.40	1.20	2200	1433	65	00	00
	Wingwalls	Sq.m	350.00	38.40		26.40	6.00	6.00	13440	7770	58	00	00
Abutment	Ballast Walls	Sq.m	350.00	21.12		21.12			7392	5544	75	00	00
	Bearings	Each	1000.00	8.00		7.00	1.00		8000	5650	71	00	00
	Abutment Walls	Sq.m	900.00	17.60		14.00	2.40	1.20	15840	10314	65	00	00
	Bearings	Each	1000.00	8.00		8.00			8000	6000	75	00	00
Piers	Caps	Sq.m	900.00	43.64		43.64			39276	29457	75	00	00
	Shafts/ Columns/ Pier Bents	Sq.m	900.00	25.43		25.43			22887	17165	75	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	6.00		6.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

553817401885

Bridge Condition Index (BCI)

72.57

Inventory Data:

Structure Name		Nation Valley Rd and Barkley Creek Bridge							
Main Hwy/Road #	Nation Valley Rd	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		5.0 km West of County Rd 43							
Latitude	45.0666325	Longitude	-75.2830706						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
			Design./not list	<input type="checkbox"/>	Design. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern	Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
			Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa	Posted Speed	50 km/h		No. of Lanes	2			
Old County	SDG	AADT	49		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	Concrete Rigid Frame CIP - T-beam	Interchange Number	<input type="checkbox"/>						
Total Deck Length	7 m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	6 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	42.0 sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
			School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	4.8 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	<input type="checkbox"/> Degrees	Direction of Structure	East/West						
No. of Spans	1.0	Fill on Structure	<input type="checkbox"/> m						
Culvert Length	<input type="checkbox"/> m								
Span Lengths	7.0 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	44.32		
OSIM		2022	41.43		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	5 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 20,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:				
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input checked="" type="checkbox"/> Replace
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years		
Overall Comments:	Replace structure in 1-5 years - Structure is in overall poor condition with cracks, efflorescence, spalls, and ECR on all concrete components. Rotation of abutment walls noted. Concrete barriers are detached and leaning outward.			
Date of Next Inspection:	2024			

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	6
Element Name:	Wearing Surface	Width:	4.8
Location:	East and West approaches to structure	Height:	
Material:	Gravel	Count (items):	2
Element Type:	Gravel Wearing Surface	Total Quantity:	57.6 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		57.60
Comments:	Generally in good condition		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Barriers	Length:	1
Element Name:	Railing Systems	Width:	0.3
Location:	North and South Sides of Structure	Height:	0.4
Material:	cast-in-place concrete	Count (items):	10
Element Type:	Concrete Railing & posts	Total Quantity:	7.00 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		7.00
Comments:	Severe Spall, disintegration, ECR, and section loss was noted.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	X 1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Barriers	Length:	0.3
Element Name:	Posts	Width:	0.4
Location:	North & South Side of Structure	Height:	1
Material:	Cast-in-place Concrete	Count (items):	12
Element Type:	Reinforced concrete Posts	Total Quantity:	12.00 Each
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	Each		12.00
Comments:	Severe Spall, disintegration, ECR, and section loss was noted.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	x 1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Sidewalks/Curbs	Length:	11						
Element Name:	Curbs	Width:	0.5						
Location:	North and South Side of Structure	Height:	0.2						
Material:	Cast-in-place concrete	Count (items):	2						
Element Type:	Reinforced concrete Safety Curb	Total Quantity:	15.4 m2						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m2	Exc.	Good	Fair	Poor*				
Comments:	Generally in poor condition with severe disintegration noted throughout.								
Recommended Work:		Rehab	x	Replace	Maintenance Needs:				
	x	1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Decks	Length:	7						
Element Name:	Wearing Surface	Width:	4.8						
Location:	Top of Deck	Height:							
Material:	Gravel	Count (items):							
Element Type:	Gravel Wearing Surface	Total Quantity:	33.60 m2						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m2	Exc.	Good	Fair	Poor*				
Comments:	Generally in good condition with loss of gravel at southwest and potholes forming.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Decks	Length:	7						
Element Name:	Deck Top - Thick Slab	Width:	6						
Location:	Top of Deck	Height:							
Material:	Cast-in-place Concrete	Count (items):							
Element Type:	Deck Top	Total Quantity:	42.00 m2						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m2	Exc.	Good	Fair	Poor*				
Comments:	Condition of the deck top is based on the condition of the soffit.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Decks	Length:	7.0				
Element Name:	Soffit - Thick Slab	Width:	1.6				
Location:	North and South Side of structure	Height:					
Material:	Cast-in-place concrete	Count (items):	2				
Element Type:	Soffit - Exterior	Total Quantity:	22.4	m2			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		2.24	13.44	6.72		
Comments:	Delamination and wide cracks with efflorescence noted						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Decks	Length:	7				
Element Name:	Soffit - Thick Slab	Width:	4				
Location:	Underside of structure	Height:					
Material:	Cast-in-place concrete	Count (items):					
Element Type:	Soffit-Interior	Total Quantity:	28	m2			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		13.0	10.0	5.0		
Comments:	Delaminations, ECR, Efflorescence, active wet stains, and hairline cracks noted throughout.						
Recommended Work:		Rehab	x	Replace	Maintenance Needs:		
	x	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutments	Length:					
Element Name:	Abutment Walls	Width:	6.0				
Location:	East and West Underside of Structure	Height:	4.0				
Material:	Cast-in-place concrete	Count (items):	2				
Element Type:	Reinforced concrete walls	Total Quantity:	48	m2			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		7.40	30.00	10.60		
Comments:	Severe delamination and wide cracks with efflorescence noted.						
Recommended Work:		Rehab	x	Replace	Maintenance Needs:		
	x	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutments	Length:	2.0							
Element Name:	Wingwalls	Width:								
Location:	NE, NW, SE, & SW Side of structure		Height:	1.3						
Material:	Cast-in-place concrete		Count (items):	4						
Element Type:	Reinforced concrete walls		Total Quantity:	10.4				m2		
Environment:	Moderate		Limited Inspection							
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m2			7.80	2.60					
Comments:	Outward rotation noted in walls, with severe delamination, disintegration, wide cracks, and efflorescence stains noted.									
Recommended Work:		Rehab	x	Replace	Maintenance Needs:					
	x	1-5 years		6-10 years		Urgent		1 year	2 years	

Element Group:	Foundations	Length:								
Element Name:	Foundation (Below Ground)	Width:								
Location:	Below abutment walls, wingwalls		Height:							
Material:	Unknown		Count (items):	All						
Element Type:	Unknown		Total Quantity:	All N/A						
Environment:	Benign		Limited Inspection			x				
Protection System:	Unknown							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year	2 years	

Element Group:	Embankments and Streams	Length:								
Element Name:	Embankments	Width:								
Location:	NE, NW, SE & SW of Structure		Height:							
Material:	Rockfill		Count (items):	4						
Element Type:	Embankments		Total Quantity:	4 Each						
Environment:	Moderate		Limited Inspection							
Protection System:	Vegetation							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each		3	1						
Comments:	Embankments are moderately sloped, well vegetated, and stable. Minor erosion present at the southwest.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year	2 years	

Element Group:	Embankments and Streams	Length:					
Element Name:	Slope Protection	Width:					
Location:	NE, NW, SE, SW of structure, and below abutmen		Height:				
Material:	Vegetation		Count (items):	4			
Element Type:	Slope Protection		Total Quantity:	4			
Environment:	Moderate		Limited Inspection			Each	
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		3.00	1.00			
Comments:	Generally in good condition.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Embankments and streams	Length:					
Element Name:	Streams and waterways	Width:					
Location:	Below Structure		Height:				
Material:	Native		Count (items):	All			
Element Type:	Streams and waterways		Total Quantity:	All N/A			
Environment:	Benign		Limited Inspection				
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	N/A		All				
Comments:	Low volume and medium flow from south to north with with some non-obstructive debris below bridge						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Structure	Replacement		X		\$ 420,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 420,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			
Traffic Control			\$ 60,000.00
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 110,000.00

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley and Barkley Creek Bridge

SITE PHOTOGRAPHS

Site No.:BRH012



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley and Barkley Creek Bridge

SITE PHOTOGRAPHS

Site No.:BRH012



Photo3 Eastapproach from centre of structure



Photo4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley and Barkley Creek Bridge

SITE PHOTOGRAPHS

Site No.:BRH012



Photo5 Northelevation



Photo6 Southelevation

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley and Barkley Creek Bridge

SITE PHOTOGRAPHS

Site No.:BRH012



Photo 7 Deflection, section loss, spalls, ECR, and disintegration on north barrier (typ.)



Photo 8 Deformed hazard sign at southeast

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley and Barkley Creek Bridge

SITE PHOTOGRAPHS

Site No.:BRH012



Photo9 Rotated and spalled concrete retaining walls at the northeast (typ.)



Photo 10 Spalls and efflorescence at northeast deck fascia/wingwall

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley and Barkley Creek Bridge

SITE PHOTOGRAPHS

Site No.:BRH012




Photo 11 Spall at base of northwest wing wall



Photo 12 Efflorescence, damp stains, CR, cracks, and scaling on girders and abutment

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley and Barkley Creek Bridge

SITE PHOTOGRAPHS

Site No.:BRH012



Photo 13 ECR, spalls, efflorescence and cracks on soffit (typ.)



Photo 14 Cracks, scaling, spalls, and ECR on South fascia (typ.)

Structure Condition Summary Form

Structure Name Nation Valley Rd & Barkley Creek Bridge
Structure Number BRH012
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Approach Slabs	Sq.m	140.00	57.60		57.60			8064	6048	75	00	00
Barriers	Railing Systems	m	200.00	7.00				7.00	1400	0		00	00
	Posts (Steel/Concrete)	Each	200.00	12.00				12.00	2400	0		00	00
Sidewalks/ Curbs	Curbs	Sq.m	40.00	15.40			9.24	6.16	616	148	24	00	00
	Wearing Surface	Sq.m	25.00	33.60		29.60	4.00		840	595	71	00	00
Decks	Deck Top - Thick Slab	Sq.m	350.00	42.00		21.25	12.77	7.98	14700	7366	50	00	00
	Soffit - Thick Slab	Sq.m	350.00	50.40		15.24	23.44	11.72	17640	7282	41	00	00
Abutment	Wingwalls	Sq.m	350.00	10.40			7.80	2.60	3640	1092	30	00	00
	Abutment Walls	Sq.m	900.00	48.00		7.40	30.00	10.60	43200	15795	37	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		3.00	1.00		0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		3.00	1.00		0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

									92500	38326
Bridge Condition Index (BCI)	41.43									

Inventory Data:

Structure Name	Timmins Rd & North Branch South Nation River Bridge									
Main Hwy/Road #	Timmins Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.8km South of County Rd 3									
Latitude	45.02092		Longitude	-75.38608						
Owner(s)	Township of North Dundas		Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
				Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern		Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
				Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa		Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG		AADT	75		% Trucks	<input type="checkbox"/>			
Geographic Twp.	<input type="text"/>		Inspection Route Sequence	<input type="text"/>						
Structure Type	Slab on Concrete Box Girders		Interchange Number	<input type="text"/>						
Total Deck Length	<input type="text"/> 20.8 m		Interchange Structure Number	<input type="text"/>						
Overall Str. Width	<input type="text"/> 10.1 m		Min. Vertical Clearance	<input type="text"/> m						
Total Deck Area	<input type="text"/> 210.08 sq. m		Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
				School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	<input type="text"/> 9.0 m		Detour Length Around Bridge	<input type="text"/> km						
Skew Angle	<input type="text"/> 19.3 Degrees		Direction of Structure	North/South						
No. of Spans	<input type="text"/> 1		Fill on Structure	<input type="text"/> m						
Span Lengths	<input type="text"/> 19.4 m									

Historical Data:

Year Built	<input type="text"/> 1987	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text"/> October 9, 2020	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	72.44		
OSIM		2022	72		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashligh, chest waders, and other equipment as required.				
Weather:	Cloudy				
Temperature:	0° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:		<input checked="" type="checkbox"/>		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>			
	Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>			
	Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>			
	Detailed Timber Investigation:	<input checked="" type="checkbox"/>			
	Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/>			
Underwater Investigation:		<input checked="" type="checkbox"/>			
Fatigue Investigation:		<input checked="" type="checkbox"/>			
Seismic Investigation:		<input checked="" type="checkbox"/>			
Structure Evaluation:		<input checked="" type="checkbox"/>			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/>			
	Monitoring Crack Widths:	<input checked="" type="checkbox"/>			
		Total Costs			\$ 15,000.00
Investigation Notes:	Deck Condition Survey Recommended Based on Age of Structure				

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years	<input checked="" type="checkbox"/> 6 to 10 years					
Overall Comments:	Puncture noted in seal, and evidence of leakage noted on substructure. Seals are damaged and should be replaced. Collision damage at southeast of barrier. Wide cracks noted on deck top. Severe spalls with exposed corroded reinforcement and disintegration on exterior soffit.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length: NE: 22.86, SE: 19.05, SW: 22.86, NW: 19.05							
Element Name:	Barrier	Width:							
Location:	NE, SE, NW & SW of Structure	Height:							
Material:	Steel	Count (items): 4							
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity: 83.82 m							
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		76.81	5	2				
Comments:	New end treatments installed since previous inspection. Collision damage noted on steel flex beam throughout. Rotated spacers throughout.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 3					
		1-5 years	6-10 years		Urgent	X	1 year		2 years
				Repair damaged sections					

Element Group:	Approaches	Length: 6.0							
Element Name:	Wearing Surface	Width: 9.0							
Location:	North & South of Structure	Height:							
Material:	Asphalt	Count (items): 2							
Element Type:	Asphalt Surface Treatment	Total Quantity: 108.0 m ²							
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		72.0	24.0	12.0				
Comments:	Large potholes on both approaches.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 12					
		1-5 years	6-10 years		Urgent		1 year	X	2 years
				Repair asphalt surface treatment and patch pothole					

Element Group:	Joints	Length: 10.7							
Element Name:	Armouring/Retaining Devices	Width:							
Location:	North & South Ends of Structre	Height:							
Material:	Steel	Count (items): 6							
Element Type:	Armouring/Retaining Devices	Total Quantity: 64.2 m							
Environment:	Severe	Limited Inspection		X	Due to Debris				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		59.9	4.3					
Comments:	Limited inspection due to debris. Light to medium corrosion noted on visible potions.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 2					
		1-5 years	6-10 years		Urgent	x	1 year		2 years

Element Group:	Joins	Length:	10.7				
Element Name:	Concrete End Dams	Width:	0.4				
Location:	North & South Side of Structure	Height:					
Material:	Cast-in-Place Concrete	Count (items):	2				
Element Type:	Reinforced Concrete End Dams	Total Quantity:	8.56	m ²			
Environment:	Severe	Limited Inspection	X	Due to Debris			
Protection System:	None				Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		7.06	1.5			
Comments:	Limited inspection due to debris. Medium scaling and abrasions noted on visible portions.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Joins	Length:					
Element Name:	Seals/Sealants	Width:					
Location:	North & South Ends of Structure	Height:					
Material:	Rubber	Count (items):	2				
Element Type:	Strip Seal	Total Quantity:	2	each			
Environment:	Severe	Limited Inspection					
Protection System:	None				Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	each				2.0		
Comments:	Seal puncture noted on seal. Active leakage noted on soffit ends and abutments. Seals should be replaced.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Barriers	Length:	28.7				
Element Name:	Railing System	Width:					
Location:	East & West Sides of Structure	Height:					
Material:	Steel	Count (items):	2				
Element Type:	Steel Flex Beam Railing	Total Quantity:	57.4	m			
Environment:	Severe	Limited Inspection					
Protection System:	Hot Dip Galvanizing				Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		53.4	2	2		
Comments:	Generally in good condition with some collision damage noted at southeast corner.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	X	1 year	
						2 years	
				Replace damaged sections			

Element Group:	Barriers	Length:					
Element Name:	Posts	Width:					
Location:	East & South Sides of Structure	Height:					
Material:	Timber	Count (items):	29				
Element Type:	Timber Posts	Total Quantity:	29 Each				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		24	5			
Comments:	Moderate splits and rot noted throughout posts. Missing spacer noted at southwest corner.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	20.8			
Element Name:	Deck Top - Exposed	Width:	10.1			
Location:	Top of Deck	Height:				
Material:	Cast-in-Place Concrete	Count (items):				
Element Type:	Deck Top	Total Quantity:	210.08 m ²			
Environment:	Severe	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m ²		197.48	8.4	4.2	
Comments:	Wide cracks, abrasions and light to moderate scaling noted on top of exposed deck top.					
Recommended Work:	X	Rehab	Replace	Maintenance Needs:		
	X	1-5 years	6-10 years	Urgent	1 year	2 years

Element Group:	Decks	Length:	2			
Element Name:	Soffit - Thin Slab (End)	Width:	11.7			
Location:	North and South Sides of Structure	Height:				
Material:	Precast Concrete	Count (items):	2			
Element Type:	Soffit - End	Total Quantity:	23.4 m ²			
Environment:	Moderate	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m ²		23.40			
Comments:	Light map cracks and efflorescence noted on end soffit.					
Recommended Work:		Rehab	Replace	Maintenance Needs:		
		1-5 years	6-10 years	Urgent	1 year	2 years

Element Group:	Decks	Length:	16.8				
Element Name:	Soffit - Thin Slab (Exterior)	Width:	2.1				
Location:	East Underside of Structure	Height:					
Material:	Precast Concrete	Count (items):	2				
Element Type:	Soffit - Exterior	Total Quantity:	70.56	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		59.5	7.4	3.7		
Comments:	Wide cracks, delaminations, severe spall and efflorescence staining noted on west fascia. Severe spall and disintegration with exposed corroded reinforcement noted on east fascia.						
Recommended Work:	X	Rehab	Replace	Maintenance Needs:			
	X	1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	16.8				
Element Name:	Soffit - Thin Slab (Interior)	Width:	9.6				
Location:	Underside of Structure	Height:					
Material:	Precast Concrete	Count (items):					
Element Type:	Soffit - Interior	Total Quantity:	161.28	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		161.28				
Comments:	Generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Abutments	Length:					
Element Name:	Bearings	Width:					
Location:	North & South Abutment Walls	Height:					
Material:	Plastic	Count (items):	16				
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	16	Each			
Environment:	Benign	Limited Inspection	X				
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		16				
Comments:	Limited inspection of bearings. Condition rating based on condition of accesible bearing pads.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Abutments	Length:							
Element Name:	Ballast Walls	Width:	9.6						
Location:	On Abutment Walls	Height:	0.7						
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	13.44 m ²						
Environment:	Benign	Limited Inspection	X						
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		13.44						
Comments:	Ballast walls were inaccessible for inspection due to box girders. Condition state is based on the visible sections of the ballast walls. Visible sections of the ballast walls were in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Abutment	Length:							
Element Name:	Abutment Walls	Width:	9.6						
Location:	North & South Underside of Strucutre	Height:	1.52						
Material:	Cast-in-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	29.18 m ²						
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		29.18						
Comments:	Damp stains on top of abutment wall, evidence of leakage. Overall in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Abutments	Length:	4.0						
Element Name:	Wingwalls	Width:							
Location:	NE, SE, NW & SW OF Structure	Height:	1.5						
Material:	Cast-in-place Concrete	Count (items):	4.0						
Element Type:	Reinforced Concrete Walls	Total Quantity:	23.7 m ²						
Environment:	Moderate	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		15.2	5.69	2.84				
Comments:	Wide cracks and efflorescence noted throughout wingwalls.								
Recommended Work:	X	Rehab	Replace	Maintenance Needs:					
	X	1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Foundations	Length:				
Element Name:	Foundation (Below Ground Level)	Width:				
Location:	Below Abutment Walls and Wingwalls	Height:				
Material:	Unknown	Count (items):				
Element Type:	Unknown	Total Quantity:		All		
Environment:	Benign	Limited Inspection		X		
Protection System:	Unknown					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	N/A		All			0
Comments:	No visible evidence of foundation instability was noted during the inspection.					
Recommended Work:		Rehab	Replace	Maintenance Needs:		
		1-5 years	6-10 years	Urgent	1 year	2 years

Element Group:	Embankments and Streams	Length:				
Element Name:	Embankments	Width:				
Location:	NE, SE, NW & SW of Structure	Height:				
Material:	Native Material	Count (items):		4		
Element Type:	Embankment	Total Quantity:		Each		
Environment:	Moderate	Limited Inspection				
Protection System:	Vegetation					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	Each		4.00			
Comments:	Embankments are moderately sloped, well vegetated and appear to be stable.					
Recommended Work:		Rehab	Replace	Maintenance Needs:		
		1-5 years	6-10 years	Urgent	1 year	2 years

Element Group:	Embankments and Streams	Length:				
Element Name:	Streams and Waterways	Width:				
Location:	Below Structure	Height:				
Material:	Native	Count (items):		All		
Element Type:	Stream	Total Quantity:		All N/A		
Environment:	Benign	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	N/A		All			
Comments:	Medium volume and low flow from west to east with no flow obstructions noted at time of inspection. Severe meander noted both upstream and downstream of structure.					
Recommended Work:		Rehab	Replace	Maintenance Needs:		
		1-5 years	6-10 years	Urgent	1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Seals	Replace Joint Seals		X		\$ 25,500.00
Soffit - Exterior	Concrete Repairs		X		\$ 9,500.00
Wingwalls	Concrete Repairs		X		\$ 7,500.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 42,500.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>



Photo 1 Structure from north approach



Photo 2 Structure from south approach



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure



Photo 5 East elevation



Photo 6 West elevation



Photo 7 New end treatments installed on north approach



Photo 8 Collision damage at southwest end treatment



Photo 9 Large potholes on north approach



Photo 10 Damaged seal at north expansion joint



Photo 11 Typical elevation view of east deck barrier



Photo 12 Wide cracks and abrasions on deck top



Photo 13 Crack at southwest corner of exterior soffit



Photo 14 Spall with exposed corroded reinforcement on east fascia




Photo 15 Typical view of abutment bearings



Photo 16 Elevation view of northeast wingwall



Photo 17 Damp staining and evidence of leakage on south abutment wall



Photo 18 South Abutment Wall

Structure Condition Summary Form

Structure Name Timmins Rd & North Branch South Nation River Bridge
Structure Number BRH013
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	83.82	0.00	76.81	5.00	2.00	0	0		00	03
	Wearing Surface	Sq.m	6.00	108.00	0.00	72.00	24.00	12.00	648	382	59	00	12
Barriers	Railing Systems	m	200.00	57.40	0.00	53.40	2.00	2.00	11480	8170	71	00	03
	Posts - Timber	Each	50.00	29.00	0.00	24.00	5.00	0.00	1450	1000	69	00	00
Joints	Armouring / Retaining Devices	m	1.00	64.20	0.00	59.90	4.30	0.00	64	47	73	00	00
	Concrete End Dams	Sq.m	2100.00	8.56	0.00	7.06	1.50	0.00	17976	12380	69	00	00
	Seals/ Sealants	Each	0.00	2.00	0.00	0.00	0.00	2.00	0	0		00	00
Decks	Deck Top - Thin Slab	Sq.m	120.00	210.08	0.00	197.48	8.40	4.20	25210	18176	72	00	12
	Soffit - Thick Slab	Sq.m	350.00	255.24	0.00	244.18	7.40	3.70	89334	65133	73	00	00
Abutment	Wingwalls	Sq.m	350.00	23.70	0.00	15.20	5.69	2.84	8295	4787	58	00	00
	Ballast Walls	Sq.m	350.00	13.44	0.00	13.44	0.00	0.00	4704	3528	75	00	00
	Bearings	Each	1000.00	16.00	0.00	16.00	0.00	0.00	16000	12000	75	00	00
	Abutment Walls	Sq.m	900.00	29.18	0.00	29.18	0.00	0.00	26262	19697	75	00	00
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									201423	145298			
Bridge Condition Index (BCI)	72												

Inventory Data:

Structure Name	Bridge St & South Nation River Bridge									
Main Hwy/Road #	Bridge Street		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.3km North of Sandt Road Road									
Latitude	44.98924			Longitude	-75.45054					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
					Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>		
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>		
					Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>		
MTO District	42 - Ottawa			Posted Speed	80 km/h		No. of Lanes	2		
Old County	SDG			AADT	350		% Trucks	<input type="checkbox"/>		
Geographic Twp.	<input type="text"/>			Inspection Route Sequence	<input type="text"/>					
Structure Type	Slab on Concrete Box Girders			Interchange Number	<input type="text"/>					
Total Deck Length	30.2		m	Interchange Structure Number	<input type="text"/>					
Overall Str. Width	7		m	Min. Vertical Clearance	<input type="text"/> m					
Total Deck Area	211.4		sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>		
					School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>		
Roadway Width	4.9		m	Detour Length Around Bridge	<input type="text"/> km					
Skew Angle	<input type="text"/>		Degrees	Direction of Structure	North/South					
No. of Spans	1			Fill on Structure	<input type="text"/> m					
Span Lengths	30.2		m							

Historical Data:

Year Built	1977	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	October 9, 2020	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	72.75		
OSIM		2022	73		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Partly Cloudy				
Temperature:	0°C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:		<input checked="" type="checkbox"/>		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>			
	Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>			
	Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>			
	Detailed Timber Investigation:	<input checked="" type="checkbox"/>			
	Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/>			
Underwater Investigation:		<input checked="" type="checkbox"/>			
Fatigue Investigation:		<input checked="" type="checkbox"/>			
Seismic Investigation:		<input checked="" type="checkbox"/>			
Structure Evaluation:		<input checked="" type="checkbox"/>			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/>			
	Monitoring Crack Widths:	<input checked="" type="checkbox"/>			
		Total Costs			\$ 15,000.00
Investigation Notes:	Deck Condition Survey Recommended Based on Age of Structure				

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years					
Overall Comments:	Structure is in generally good condition. Evidence of leaking at northeast corner of joint seal. Some damage noted on south seal. Spalls, delaminations, and abrasions throughout barrier walls. Underside of structure is generally in good condition. Some scaling noted around abutment wall drains.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	NE: 18.3, SE:15.3 , SW: 29.9, NW: 9.7					
Element Name:	Barrier	Width:						
Location:	NE, SE, NW & SW of Structure	Height:						
Material:	Steel	Count (items):	4					
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	73.2 m					
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m		73.2					
Comments:	Generally in good condition with some rust noted on steel flex beam.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Approaches	Length:	6.0					
Element Name:	Wearing Surface	Width:	4.9					
Location:	North & South of Structure	Height:						
Material:	Asphalt	Count (items):	2					
Element Type:	Asphalt Wearing Surface	Total Quantity:	58.8 m ²					
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		55.8	3.0				
Comments:	Wearing surface is generally in good condition with some light ravelling noted throughout and medium cracks at interface with deck.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Approaches	Length:	6					
Element Name:	Approach Slab	Width:	4.9					
Location:	North & South of Structure	Height:						
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Approach Slabs	Total Quantity:	58.8 m					
Environment:	Moderate	Limited Inspection	X					
Protection System:	Approach Wearing Surface						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m		58.8					
Comments:	Condition rating based on condition of wearing surface. Assumed to be in good condition.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Joints	Length:	4.9					
Element Name:	Armouring/Retaining Devices	Width:						
Location:	North & South Side of Structure	Height:						
Material:	Steel	Count (items):	4					
Element Type:	Expansion Joint Armouring	Total Quantity:	19.6	m				
Environment:	Severe	Limited Inspection						
Protection System:	None							Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies		
	m		17.6	2				
Comments:	Light rust and abrasions noted on joint armouring.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Joints	Length:	4.9					
Element Name:	Concrete End Dams	Width:	0.25					
Location:	North & South Side of Structure	Height:						
Material:	Cast-in-Place Concrete	Count (items):	4					
Element Type:	Concrete End Dams	Total Quantity:	4.9	m				
Environment:	Severe	Limited Inspection						
Protection System:	None							Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies		
	m		4.72	0.12	0.06			
Comments:	Light abrasions, popouts and light scaling noted on concrete end dams.							
Recommended Work:		Rehab	Replace	Maintenance Needs: 08				
		1-5 years	6-10 years		Urgent	1 year	X	2 years

Element Group:	Joints	Length:	4.9						
Element Name:	Seals/Sealants	Width:							
Location:	North & South Side of Structure	Height:							
Material:	Neoprene	Count (items):	2						
Element Type:	Expansion Joint Seal	Total Quantity:	2	Each					
Environment:	Severe	Limited Inspection	X	Due to Snow					
Protection System:	None							Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	Each			1	1.0				
Comments:	Damage noted on south joint seal. Evidence of leakage noted at northeast corner. Seals also appear to be compressed.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs:				
	X	1-5 years	6-10 years		Urgent	1 year	2 years		

Element Group:	Barriers	Length:	42.4					
Element Name:	Barrier/Parapet Walls (Interior)	Width:	0.2					
Location:	East & West Side of Deck	Height:	0.9					
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Reinforced Concrete Barrier Walls - Interior Fa	Total Quantity:	93.28	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		48.51	29.85	14.92			
Comments:	Medium to severe abrasions, light to severe scaling, spalls with exposed corroded reinforcement and delaminations noted on interior face of parapet wall.							
Recommended Work:	X	Rehab	Replace	Maintenance Needs:				
	X	1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Barriers	Length:	42.4					
Element Name:	Barrier/Parapet Walls (Exterior)	Width:						
Location:	East & West Side of Deck	Height:	0.9					
Material:	Cast-In-Place Concrete	Count (items):	2					
Element Type:	Reinforced Concrete Barrier Walls - Exterior Fa	Total Quantity:	76.32	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	Hot Dip Galvanizing						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		56.86	12.97	6.49			
Comments:	Delaminations and spalls with expsoed corroded reinforcement noted on exterior of east barrier wall.							
Recommended Work:	X	Rehab	Replace	Maintenance Needs:				
	X	1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Barriers	Length:	40.9					
Element Name:	Hand Railings	Width:						
Location:	East & West Side of Deck	Height:	0.9					
Material:	Steel	Count (items):	2					
Element Type:	Steel Single Pipe Railing	Total Quantity:	81.8	m				
Environment:	Severe	Limited Inspection						
Protection System:	Hot Dip Galvanizing						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m		81.8					
Comments:	Generally in good condition with a missing end cap noted at southeast end of railing.							
Recommended Work:		Rehab	Replace	Maintenance Needs: 3				
		1-5 years	6-10 years		Urgent	1 year	X 2 years	
				Replace missing end cap				

Element Group:	Sidewalk/Curbs	Length:	42.4					
Element Name:	Curbs	Width:	1.2					
Location:	East & West sides of Structure	Height:	0.2					
Material:	Cast-In-Place Concrete	Count (items):	1					
Element Type:	Reinforced Concrete Curbs	Total Quantity:	59.4	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*			
			44.22	10.09	5.05			
Comments:	Medium to severe abrasions noted on vertical face of sidewalks due to snow plow equipment. Delaminations, spalls and asphalt patch noted on curb.							
Recommended Work:	X	Rehab	Replace	Maintenance Needs:				
	X	1-5 years	6-10 years		Urgent		1 year	2 years

Element Group:	Decks	Length:						
Element Name:	Drainage System	Width:						
Location:	East & West Sides of Deck	Height:						
Material:	Steel	Count (items):	6					
Element Type:	Steel Drain Pipes	Total Quantity:	6.0	each				
Environment:	Severe	Limited Inspection						
Protection System:	Hot Dip Galvanizing						Perform. Deficiencies	
Condition Data:	Units each	Exc.	Good	Fair	Poor*			
			6					
Comments:	Generally in good condition.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent		1 year	2 years

Element Group:	Decks	Length:	30.2					
Element Name:	Wearing Surface	Width:	4.9					
Location:	Top of Deck	Height:						
Material:	Asphalt	Count (items):						
Element Type:	Asphalt Surface Treatment	Total Quantity:	148.0	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*			
			137.77	5.77	4.44			
Comments:	Wide map cracks, and wide longitudinal and transverse cracks noted on surface.							
Recommended Work:		Rehab	Replace	Maintenance Needs: 12				
		1-5 years	6-10 years		Urgent	X	1 year	2 years

Element Group:	Decks	Length:	30.2				
Element Name:	Deck Top	Width:	7				
Location:	Top of Deck	Height:					
Material:	Cast-in-Place Concrete	Count (items):					
Element Type:	Deck Top	Total Quantity:	211.4	m ²			
Environment:	Moderate	Limited Inspection	X				
Protection System:	Asphalt Surface Treatment					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*		
			211.4				
Comments:	Condition rating based on condition of deck wearing surface and deck soffit. Assumed to be in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	2				
Element Name:	Soffit - Thin Slab (End)	Width:	5.92				
Location:	North and South underside of structure	Height:					
Material:	Precast Concrete	Count (items):	2				
Element Type:	Soffit - End	Total Quantity:	23.7	m ²			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*		
			23.70				
Comments:	End portion of soffit appear to be in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	26.2				
Element Name:	Soffit - Thin Slab (Exterior)	Width:	0.8				
Location:	East & West Sides of Strucutre	Height:					
Material:	Precast Concrete	Count (items):	2				
Element Type:	Soffit - Exterior	Total Quantity:	41.92	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*		
			41.9				
Comments:	Exterior soffit appears to be in good condition with some staining noted.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	26.2						
Element Name:	Soffit - Thin Slab (Interior)	Width:	4.32						
Location:	Underside of Structure	Height:							
Material:	Precast Concrete	Count (items):	1						
Element Type:	Soffit - Interior	Total Quantity:	113.18	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		113.18						
Comments:	Interior soffit generally appears to be in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Beams/Main Longitudinal Elements MLE's	Length:	4						
Element Name:	Girders - (End)	Width:	0.58						
Location:	North & South Underside of Structure	Height:	1.4						
Material:	Precast Concrete	Count (items):	3						
Element Type:	CPCI Girders - End	Total Quantity:	54.48	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		54.48						
Comments:	End portions of girders appear to be in good condition. Two barn swallow nests noted.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Beams/Main Longitudinal Elements MLE's	Length:	26.2						
Element Name:	Girders - (Intermediate)	Width:	0.58						
Location:	Underside of Structure	Height:	1.4						
Material:	Precast Concrete	Count (items):	3						
Element Type:	CPCI Girders - Middle	Total Quantity:	356.84	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		356.84						
Comments:	Girders appear to be in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Beams/Main Longitudinal Elements MLE's	Length:	2.16				
Element Name:	Diaphragms - (End)	Width:	0.3				
Location:	North & South Underside of Strucutre	Height:	1.4				
Material:	Precast Concrete	Count (items):	4				
Element Type:	Rectangular Diaphragms	Total Quantity:	26.8 m ²				
Environment:	Benign	Limited Inspection					
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	
	m ²		26.8				
Comments:	Diaphragms appear to be in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years		Urgent	1 year	2 years

Element Group:	Beams/Main Longitudinal Elements MLE's	Length:	2.16				
Element Name:	Diaphragms - (Intermediate)	Width:	0.26				
Location:	Underside of Deck	Height:	1.4				
Material:	Precast Concrete	Count (items):	3				
Element Type:	Rectangular Diaphragms - Intermediate	Total Quantity:	26.8 m ²				
Environment:	Benign	Limited Inspection					
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	
	m ²		26.8				
Comments:	Diaphragms appear to be in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years		Urgent	1 year	2 years

Element Group:	Abutments	Length:					
Element Name:	Bearings	Width:					
Location:	On North & South Abutment Walls	Height:					
Material:	Neoprene	Count (items):	6				
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	6 Each				
Environment:	Benign	Limited Inspection					
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	
	Each		6				
Comments:	Bearings appear to be in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years		Urgent	1 year	2 years

Element Group:	Abutments	Length:								
Element Name:	Ballast Walls	Width:	7							
Location:	East and West underside of Structure	Height:	1							
Material:	Cast-In-Place Concrete	Count (items):	3							
Element Type:	Reinforced Concrete Walls	Total Quantity:	14					m ²		
Environment:	Benign	Limited Inspection	X	Due to er						
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		14							
Comments:	Ballast walls were inaccessible for inspection due to end diaphragms. Evidence of leaking seals noted at northeast corner of walls.									
Recommended Work:		Rehab	Replace	Maintenance Needs:						
		1-5 years	6-10 years		Urgent		1 year		2 years	

Element Group:	Abutment	Length:								
Element Name:	Abutment Walls	Width:	7							
Location:	North & South Underside of Structure	Height:	2.4							
Material:	Cast-in-Place Concrete	Count (items):	2							
Element Type:	Reinforced Concrete Walls	Total Quantity:	33.6					m ²		
Environment:	Benign	Limited Inspection								
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		29.60	2.0	2.0					
Comments:	Generally in good condition with some scaling noted around drain.									
Recommended Work:	x	Rehab	Replace	Maintenance Needs:						
	x	1-5 years	6-10 years		Urgent		1 year		2 years	

Element Group:	Abutments	Length:	6.1							
Element Name:	Wingwalls	Width:								
Location:	NE, SE, NW & SW OF Structure	Height:	1.6							
Material:	Cast-in-place Concrete	Count (items):	4.0							
Element Type:	Reinforced Concrete Walls	Total Quantity:	39.0					m ²		
Environment:	Moderate	Limited Inspection								
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		39.0							
Comments:	Generally in good condition.									
Recommended Work:		Rehab	Replace	Maintenance Needs:						
		1-5 years	6-10 years		Urgent		1 year		2 years	

Element Group:	Foundations	Length:						
Element Name:	Foundation (Below Ground Level)	Width:						
Location:	Below Abutment Walls and Wingwalls	Height:						
Material:	Unknown	Count (items):						
Element Type:	Unknown	Total Quantity:	All					
Environment:	Benign	Limited Inspection			X			
Protection System:	Unknown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All			0		
Comments:	No visible evidence of foundation instability was noted during the inspection.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, SE, NW & SW Side of Structure	Height:						
Material:	Native Material	Count (items):	4					
Element Type:	Embankment	Total Quantity:	Each					
Environment:	Moderate	Limited Inspection						
Protection System:	Vegetation						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		3.00	1				
Comments:	Embankments are moderately sloped and well vegetated. Moderate erosion noted at northeast embankment.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Streams and Waterways	Width:						
Location:	Below Structure	Height:						
Material:	Native	Count (items):	All					
Element Type:	Stream	Total Quantity:	N/A					
Environment:	Benign	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	High volume and low flow from south to north with no flow obstructions noted. Evidence of medium to severe erosion noted along southeast portion of stream.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Joint Seals	Replace Joint Seals		X		\$ 25,000.00
Barrier Walls	Concrete Repairs		X		\$ 43,000.00
Concrete Curbs	Concrete Repairs		X		\$ 10,500.00
Abutment Wall	Concrete Repairs		X		\$ 5,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 83,500.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification



Photo 1 Structure from north approach



Photo 2 Structure from south approach



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure



Photo 5 East elevation



Photo 6 West elevation



Photo 7 Light rust on southwest guiderail transition



Photo 8 Wide crack on south approach wearing surface



Photo 9 Damage on south joint seal



Photo 10 Spall on top face of concrete sidewalk



Photo 11 Spalls and disintegration noted on south end of east barrier wall



Photo 12 Wide longitudinal and transverse cracks on deck wearing surface



Photo 13 Typical view of west exterior soffit



Photo 14 Typical view of interior soffit



Photo 15 View of north end of interior girder



Photo 16 Typical view of end diaphragm



Photo 17 North Underside of Structure



Photo 18 Elevation view of northwest wingwall



Photo 19 Scaling and graffiti around drains on abutment wall



Photo 20 Typical view of north abutment wall



Photo 21 Damp stains and evidence of leaking seal on northeast corner of ballast wall

Structure Condition Summary Form

Structure Name Bridge St & South Nation River Bridge
Structure Number BRH014
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	73.20	0.00	73.20	0.00	0.00	0	0		00	00
	Wearing Surface	Sq.m	6.00	55.80	0.00	55.80	3.00	0.00	335	258	77	00	00
	Approach Slabs	Sq.m	140.00	55.80	0.00	55.80	0.00	0.00	7812	5859	75	00	00
Barriers	Barrier/ Parapet Walls (interior)	Sq.m	100.00	93.28	0.00	48.51	29.85	14.92	9328	4832	52	00	00
	Barrier/ Parapet Walls (exterior)	Sq.m	100.00	76.32	0.00	56.86	12.97	6.49	7632	4783	63	00	00
	Hand Railings	m	100.00	81.80	0.00	81.80	0.00	0.00	8180	6135	75	00	03
Joints	Armouring / Retaining Devices	m	1.00	19.60	0.00	17.60	2.00	0.00	20	14	71	00	00
	Concrete End Dams	Sq.m	2100.00	4.90	0.00	4.72	0.12	0.06	10290	7535	73	00	08
	Seals/ Sealants	Each	0.00	2.00	0.00	0.00	1.00	1.00	0	0		00	00
Sidewalks/ Curbs	Curbs	Sq.m	40.00	59.40	0.00	44.22	10.09	5.05	2376	1488	63	00	00
	Drainage System	Each	0.00	6.00	0.00	6.00	0.00	0.00	0	0		00	00
	Wearing Surface	Sq.m	25.00	148.00	0.00	137.77	5.77	4.44	3700	2641	71	00	12
Decks	Deck Top - Thin Slab	Sq.m	120.00	211.40	0.00	211.40	0.00	0.00	25368	19026	75	00	00
	Soffit - Thin Slab	Sq.m	120.00	178.80	0.00	178.80	0.00	0.00	21456	16092	75	00	00
	Girders	Sq.m	200.00	411.32	0.00	411.32	0.00	0.00	82264	61698	75	00	00
Beams/ Main Longitudinal Elements	Diaphragms - Concrete	Each	0.00	53.60	0.00	53.60	0.00	0.00	0	0		00	00
	Wingwalls	Sq.m	350.00	39.00	0.00	39.00	0.00	0.00	13650	10238	75	00	00
	Ballast Walls	Sq.m	350.00	14.00	0.00	14.00	0.00	0.00	4900	3675	75	00	00
Abutment	Bearings	Each	1000.00	6.00	0.00	6.00	0.00	0.00	6000	4500	75	00	00
	Abutment Walls	Sq.m	900.00	33.60	0.00	29.60	2.00	2.00	30240	20700	68	00	00
	Embankments	Each	0.00	4.00	0.00	3.00	1.00	0.00	0	0		00	00
Embankments and Streams	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00

233550169474

Bridge Condition Index (BCI)

73

Inventory Data:

Structure Name	Limerick Rd and McMillan Rd Bridge									
Main Hwy/Road #	Limerick Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.8km East of County Rd 8									
Latitude	45.0798707			Longitude	-75.2027987					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
					Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>		
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>		
					Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>		
MTO District	42 - Ottawa			Posted Speed	60 km/h		No. of Lanes	2		
Old County	SDG			AADT	76		% Trucks	<input type="checkbox"/>		
Geographic Twp.	<input type="checkbox"/>			Inspection Route Sequence	<input type="checkbox"/>					
Structure Type	Concrete Rigid Frame - Arch			Interchange Number	<input type="checkbox"/>					
Total Deck Length	14		m	Interchange Structure Number	<input type="checkbox"/>					
Overall Str. Width	8.5		m	Min. Vertical Clearance	<input type="checkbox"/> m					
Total Deck Area	119.0		sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>		
					School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>		
Roadway Width	7.0		m	Detour Length Around Bridge	<input type="checkbox"/> km					
Skew Angle	20		Degrees	Direction of Structure	East/West					
No. of Spans	1			Fill on Structure	<input type="checkbox"/> m					
Span Lengths	12.8		m							

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.63		
OSIM		2022	71.00		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	11/25/2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Avasar Pradaliya, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Partly Cloudy / Rainy				
Temperature:	4° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			x		\$ 5,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years					
Overall Comments:	Structure is in generally good condition. Spalls and scaling noted on abutment walls, coating failure on structure barrier, honeycombing on abutment walls, light scaling throughout concrete components, damp stains noted at soffit adjacent to drains. No approach barriers present - A code compliant barrier and end-treatments should be installed at the approaches.						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	6
Element Name:	Wearing Surface	Width:	7
Location:	East and West Side of Structure	Height:	
Material:	Asphalt	Count (items):	2
Element Type:	Asphalt Surface Treatment	Total Quantity:	84.0 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units m ²	Exc.	Good 83.1
			Fair 0.9
			Poor*
			Perform. Deficiencies
Comments:	Generally in good condition. Light raveling was noted with a large pothole and washout at the southeast approach. No approach barrier - A code compliant barrier and end-treatments should be installed at the approaches		
Recommended Work:		Rehab	Replace
		1-5 years	6-10 years
			Urgent
			1 year
			X
			2 years
			Repair asphalt surface treatment and patch pothole

Element Group:	Barriers	Length:	12.8
Element Name:	Railing System	Width:	
Location:	North and South Sides of Structure	Height:	
Material:	Steel	Count (items):	2
Element Type:	Steel post and panel railing	Total Quantity:	25.6 m
Environment:	Severe	Limited Inspection	
Protection System:	Coating		
Condition Data:	Units m	Exc.	Good 20.6
			Fair 5
			Poor*
			Perform. Deficiencies
Comments:	Light to medium corrosion was noted on the barrier railings, with some coating failure noted.		
Recommended Work:		Rehab	Replace
		1-5 years	6-10 years
			Urgent
			1 year
			2 years

Element Group:	Barriers	Length:	0.6
Element Name:	Barrier/Parapet Walls	Width:	0.3
Location:	NE, NW, SW, & SE sides of structure	Height:	1
Material:	Cast-in-place concrete	Count (items):	4
Element Type:	Reinforced concrete end posts	Total Quantity:	6.24 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units m ²	Exc.	Good 5.34
			Fair 0.6
			Poor* 0.3
			Perform. Deficiencies
Comments:	Localized spall with ECR was noted at the NW		
Recommended Work:		Rehab	Replace
		1-5 years	6-10 years
			Urgent
			X
			1 year
			2 years
			Concrete repairs to end posts

Element Group:	Coating	Length:					
Element Name:	Railing systems / Hand railings	Width:					
Location:	On bridge railing	Height:					
Material:	Other	Count (items):					
Element Type:	Coating	Total Quantity:	25.6				m
Environment:	Severe	Limited Inspection					
Protection System:	None						Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	m		14.90	7.1	3.6		
Comments:	Evidence of coating failure such as flaking and peeling was noted.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	x	1 year	2 years
				Repair to bridge railing coating			

Element Group:	Sidewalks/Curbs	Length:	14
Element Name:	Curbs	Width:	0.75
Location:	North and South side of structure	Height:	0.3
Material:	Cast-In-Place Concrete	Count (items):	2
Element Type:	Reinforced concrete safety curb	Total Quantity:	29.4 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		28.2
Comments:	Evidence of light to medium scaling was noted with spall at northeast.		
Recommended Work:		Rehab	Replace
		1-5 years	6-10 years
		Urgent	1 year
			2 years

Element Group:	Decks	Length:					
Element Name:	Drainage System	Width:					
Location:	North and South Sides of Structure	Height:					
Material:	Other	Count (items):	2				
Element Type:	Steel Drain Pipes	Total Quantity:	2	Each			
Environment:	Severe	Limited Inspection					
Protection System:	Hot Dip Galvanizing						
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform.	
	Each		2			Deficiencies	
Comments:	Deck drain downspouts lack extension beyond soffit.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	14				
Element Name:	Wearing surface	Width:	7				
Location:	Top of Deck	Height:	#REF!				
Material:	Asphalt	Count (items):					
Element Type:	Asphalt wearing surface	Total Quantity:	98	m2			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m2		98		1		
Comments:	Generally in good condition with vegetation growth noted adjacent to bridge barriers.						
Recommended Work:		Rehab	Replace	Maintenance Needs: 18			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	14				
Element Name:	Deck Top - Thick Slab	Width:	8.5				
Location:	Below Roadway	Height:					
Material:	Cast-in-place concrete	Count (items):					
Element Type:	Deck top	Total Quantity:	119	m ²			
Environment:	Moderate	Limited Inspection		x			
Protection System:	Asphalt Wearing Surface					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		119.0				
Comments:	Limited inspection - The condition of the deck is estimated based on the soffit and asphalt wearing surface overall condition - Generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	14				
Element Name:	Soffit - Thick Slab	Width:	1.7				
Location:	North and south side of structure	Height:					
Material:	Cast-in-place concrete	Count (items):	2				
Element Type:	Soffit - Exterior	Total Quantity:	47.6	m ²			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		47.6				
Comments:	Generally in good condition						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	14						
Element Name:	Soffit - Thick Slab	Width:	6.5						
Location:	Underside of Structure	Height:							
Material:	Cast-in-place concrete	Count (items):							
Element Type:	Soffit - Interior	Total Quantity:	91	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*				
			88.60	1.9	0.50				
Comments:	Moderate scaling and runoff infiltration noted adjacent to deck drain downspouts. Small spall with ECR noted at the west.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 8					
		1-5 years	6-10 years		Urgent	1 year	X	2 years	
				Concrete Repairs					

Element Group:	Abutments	Length:							
Element Name:	Abutment wall	Width:	9						
Location:	East and West underside of structure	Height:	3.2						
Material:	Cast-in-place concrete	Count (items):	2						
Element Type:	Reinforced concrete walls	Total Quantity:	57.6	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*				
			47.23	6.91	3.46				
Comments:	Localized spall, ECR, efflorescence, and wide cracks noted on east abutment walls. Moderate to severe honeycombing noted at west. Wide map cracking and severe erosion along springline noted.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 8					
		1-5 years	6-10 years		Urgent	1 year	X	2 years	
				Concrete Repairs					

Element Group:	Retaining Walls	Length:	5.0						
Element Name:	Walls	Width:							
Location:	NE, NW, SE, SW side of structure	Height:	2.75						
Material:	Cast-in-place concrete	Count (items):	4						
Element Type:	Reinforced concrete retaining walls	Total Quantity:	55	m ²					
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*				
			45.1	6.6	3.3				
Comments:	Wide map cracking noted along springline.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 8					
		1-5 years	6-10 years		Urgent	1 year	X	2 years	
				Concrete Repairs					

Element Group:	Foundations	Length:				
Element Name:	Foundation (Below Ground Level)	Width:				
Location:	Below abutment walls, wingwalls	Height:				
Material:	Unknown	Count (items):	All			
Element Type:	Unknown	Total Quantity:	All	m ²		
Environment:	Benign	Limited Inspection		X		
Protection System:	Unknown				Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m ²		All			
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted at the time of inspection					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Embankments and Streams	Length:				
Element Name:	Embankments	Width:				
Location:	NE, NW, SE, SW of structure	Height:				
Material:	Rip-Rap	Count (items):	4			
Element Type:	Embankment	Total Quantity:	4	Each		
Environment:	Moderate	Limited Inspection				
Protection System:	Vegetation				Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	Each		3	1		
Comments:	Embankments are moderately sloped, well vegetated, and stable. Steep embankment with moderate erosion at southwest.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Embankments and Streams	Length:				
Element Name:	Slope Protection	Width:				
Location:	NE, NW, SE and SW side of structure	Height:				
Material:	Vegetation	Count (items):	4			
Element Type:	Slope Protection	Total Quantity:	4	Each		
Environment:	Moderate	Limited Inspection				
Protection System:	None				Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	Each		3	1		
Comments:	Generally in good condition with some erosion at the southwest embankment					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Embankments and Streams			Length:				
Element Name:	Streams and Waterways			Width:				
Location:	Below Structure			Height:				
Material:	Native			Count (items):	All			
Element Type:	Stream			Total Quantity:	All			N/A
Environment:	Benign			Limited Inspection	X			
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Medium volume and low flow from south to north with no visible flow obstructions noted.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Approach Barrier	Install code-compliant approach barrier and end-treatment			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 48,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>

MUNICIPAL STRUCTURE INSPECTION FORM

Limerick Rd McMillan Bridge

SITE PHOTOGRAPHS

Site No.:BRH015



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Limerick Rd McMillan Bridge

SITE PHOTOGRAPHS

Site No.:BRH015



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Limerick Rd McMillan Bridge

SITE PHOTOGRAPHS

Site No.:BRH015



Photo 5 North elevation



Photo 6 South elevation



Photo 7 Spall at Northwest barrier end wall with ECR



Photo 8 Corrosion and coating failure at north barrier railing (typical)



Photo 9 Vegetation along north edge of asphalt over deck (typical)



Photo 10 Wet areas around drain downspouts on soffit



Photo 11 Spalls and honeycombing at springline along east abutment wall (typical)



Photo 12 Spalling on east curb

Structure Condition Summary Form

Structure Name Limerick Rd and McMillan Rd Bridge
Structure Number BRH015
Date of Inspection November 25, 2022
Consultant HP Engineering Inc.
Contract Number 22087 (HP)

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in excellent condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Abutment	Abutment Walls	Sq.m	900.00	57.6		47.23	6.91	3.46	51840	34368	66	00	00
Approaches	Wearing Surface	Sq.m	6.00	84		83.1	0.9		504	376	75	00	00
Barriers	Barrier/ Parapet Walls	Sq.m	100.00	6.24		5.34	0.6	0.3	624	425	68	00	00
	Railing Systems	m	200.00	25.6		20.6	5		5120	3490	68	00	00
Coatings	Railing Systems/ Hand Railing	Sq.m	125.00	25.6		14.9	7.1	3.6	3200	1752	55	00	00
Decks	Deck Top-Thick Slab	Sq.m	350.00	119		119			41650	31238	75	00	00
	Drainage System	Each	0.00	2		2			0	0		00	00
	Soffit- Thick Slab	Sq.m	350.00	138.6		136.2	1.9	0.5	48510	36019	74	00	00
	Wearing Surface	Sq.m	25.00	99		98		1	2475	1838	74	00	00
Embankments and Streams	Embankments	Each	0.00	4		3	1		0	0		00	00
	Slope Protection	Each	0.00	4		3	1		0	0		00	00
	Streams and Waterways	All	0.00	1		1			0	0		00	00
Foundations	Foundations (below ground level)	N/A	0.00	1		1			0	0		00	00
Retaining Walls	Walls	Sq.m	350.00	55		45.1	6.6	3.3	19250	12763	66	00	00
Sidewalks/ Curbs	Curbs	Sq.m	40.00	29.4		28.2	1.2		1176	865	74	00	00
									174349	123132			
Conditon Index	71												

Inventory Data:

Structure Name	West Bridge				
Main Hwy/Road #	Wallace Road	Services on structure:	<i>Navig. Water</i> <input type="checkbox"/> <i>Rail</i> <input type="checkbox"/>	<i>Non-Navig. Road</i> <input checked="" type="checkbox"/> <i>Ped. Other</i> <input type="checkbox"/>	
	On Structure <input checked="" type="checkbox"/>				
	Under Structure <input type="checkbox"/>	Services under structure:	<i>Navig. Water</i> <input type="checkbox"/> <i>Rail</i> <input type="checkbox"/>	<i>Non-Navig. Road</i> <input checked="" type="checkbox"/> <i>Ped. Other</i> <input type="checkbox"/>	
Structure Location	0.1km South of Nation River Road				
Latitude	44.95978	Longitude	-75.47725		
Owner(s)	Township of North Dundas	Heritage Designation	<i>Not Consid. Desig./not list</i> <input checked="" type="checkbox"/> <i>Cons/not App. Desig. & List</i> <input type="checkbox"/>	<i>List/n.d.</i> <input type="checkbox"/>	
MTO Region	40 - Eastern	Road Class:	<i>Freeway</i> <input type="checkbox"/> <i>Collector</i> <input type="checkbox"/>	<i>Arterial Local</i> <input checked="" type="checkbox"/>	
MTO District	42 - Ottawa	Posted Speed	80 km/h	No. of Lanes	2
Old County	SDG	AADT	100	% Trucks	
Geographic Twp.		Inspection Route Sequence			
Structure Type	Slab on CPCl Girders	Interchange Number			
Total Deck Length	32.2 m	Interchange Structure Number			
Overall Str. Width	9.7 m	Min. Vertical Clearance			
Total Deck Area	312.3 sq. m	Special Routes:	<i>Transit</i> <input type="checkbox"/> <i>School</i> <input type="checkbox"/>	<i>Truck Bicycle</i> <input type="checkbox"/>	
Roadway Width	8.5 m	Detour Length Around Bridge			
Skew Angle	10 Degrees	Direction of Structure	East/West		
No. of Spans	1	Fill on Structure			
Span Lengths	31.2 m				

Historical Data:

Year Built	1981	Year of Last Major Rehab.	
Last OSIM Inspection	October 9, 2020	Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.9		
OSIM		2022	75		

Appraisal Indices:	Comments:
Fatigue:	
Seismic:	
Scour:	
Flood:	
Geometrics:	
Barrier:	
Curb:	
Load Capacity:	
Key Aspects:	

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy				
Temperature:	-2 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:		X		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
					Total Costs \$ 15,000.00
Investigation Notes: Condition Survey recommended due to age of structure					

Overall Structure Notes:					
Work on Structure:	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace	
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years			
Overall Comments:	Structure is generally in good condition. New end treatments have been installed since previous inspection. Small spalls and narrow cracks noted on ends of girders. Wide longitudinal crack observed at centreline of wearing surface.				
Date of Next Inspection:	december 2024				

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	

Maintenance Needs

01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	NE: 31.7, SE: 22.8, SW: 22.8, NW: 26.2						
Element Name:	Barrier	Width:							
Location:	NE, SE, NW & SW of Structure	Height:							
Material:	Steel	Count (items):	4						
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	103.5 m						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		99.4	4.1					
Comments:	New end treatments have been installed since previous inspection. New portions of guiderail are generally in good condition. Rust noted on steel flex beam. Light to medium rot noted on timber posts.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Approaches	Length:	6.00						
Element Name:	Wearing Surface	Width:	8.6						
Location:	East and West Side of Structure	Height:							
Material:	Asphalt	Count (items):	2						
Element Type:	Wearing Surface	Total Quantity:	103.2 m ²						
Environment:	Severe	Limited Inspection	X						
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		103.2	0.0	0.0				
Comments:	Wide transverse cracks at the end of approach slabs. Potholes and wide cracks noted on wearing surface.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 12					
		1-5 years	6-10 years		Urgent		1 year	X	2 years
				Repair asphalt surface treatment and patch pothole					

Element Group:	Approaches	Length:	6.00						
Element Name:	Approach Slab	Width:	8.6						
Location:	East and West Side of Structure	Height:							
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	Concrete approach slab	Total Quantity:	103.2 m ²						
Environment:	moderate	Limited Inspection	X						
Protection System:	Wearing Surface								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		103.2						
Comments:									
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Joints	Length:	10
Element Name:	Armouring/Retaining Devices	Width:	
Location:	East & West Side of Structure	Height:	
Material:	Steel	Count (items):	4
Element Type:	Armouring/Retaining Devices	Total Quantity:	40 m
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m		40
Comments:	Light rust and abrasions noted on armouring.		

Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Joints	Length:	10
Element Name:	Concrete End Dams	Width:	0.3
Location:	East & West Side of Structure	Height:	
Material:	Cast-In-Place Concrete	Count (items):	4
Element Type:	Concrete End Dams	Total Quantity:	12 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		12.0
Comments:	Light abrasions and light scaling noted on end dams.		

Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Joints	Length:	10
Element Name:	Seals/Sealants	Width:	
Location:	East & West Side of Structure	Height:	
Material:	Plastic	Count (items):	2
Element Type:	Strip Seal	Total Quantity:	2 each
Environment:	Severe	Limited Inspection	x Due to si
Protection System:	None		
Condition Data:	Units	Exc.	Good
	each		2
Comments:	Light rust and abrasions noted on armouring.		

Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Barriers	Length:	43.2								
Element Name:	Railing System	Width:									
Location:	North and South Sides of Structure		Height:								
Material:	Steel/Wood		Count (items):	2							
Element Type:	Steel Flex Beam on Wood Posts		Total Quantity:	86.4					m		
Environment:	Severe		Limited Inspection								
Protection System:	Hot Dip Galvanizing							Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*						
	m		84.4	2.0							
Comments:	Light corrosion noted on channel portion of railing. Localized dents also noted on flex beam.										
Recommended Work:		Rehab	Replace	Maintenance Needs:							
		1-5 years	6-10 years		Urgent		1 year		2 years		

Element Group:	Barriers	Length:									
Element Name:	Posts	Width:									
Location:	North and South Sides of Structure		Height:								
Material:	Wood		Count (items):	46							
Element Type:	Wood Posts		Total Quantity:	46					Each		
Environment:	Severe		Limited Inspection								
Protection System:	None							Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*						
	Each		40.0	6.0							
Comments:	Generally in good condition with some light to medium splits in posts and rotated spacers noted. Localized light corrosion on post base plates noted.										
Recommended Work:		Rehab	Replace	Maintenance Needs:							
		1-5 years	6-10 years		Urgent		1 year		2 years		

Element Group:	Decks	Length:	32.3								
Element Name:	Wearing Surface	Width:	8.5								
Location:	Top of Deck		Height:								
Material:	Asphalt		Count (items):								
Element Type:	Asphalt Wearing Surface		Total Quantity:	274.6					m ²		
Environment:	Severe		Limited Inspection		X	Due to snow					
Protection System:	None							Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*						
	m ²		261.7	8.6	4.3						
Comments:	Potholes forming along centreline. Wide longitudinal crack noted at centreline.										
Recommended Work:		Rehab	Replace	Maintenance Needs: 12							
		1-5 years	6-10 years		Urgent	X	1 year		2 years		

Element Group:	Decks	Length:	32.3				
Element Name:	Deck Top	Width:	9.7				
Location:	Top of Deck	Height:					
Material:	Cast-in-Place Concrete	Count (items):					
Element Type:	Deck Top	Total Quantity:	313.3	m ²			
Environment:	Moderate	Limited Inspection	X				
Protection System:	Asphalt Wearing Surface					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good 313.3	Fair	Poor*		
Comments:	Condition rating based on condition of wearing surface and soffit.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years		Urgent	1 year 2 years	

Element Group:	Decks	Length:	2.0				
Element Name:	Soffit - Thin Slab (End)	Width:	8.2				
Location:	East & West Ends of Structure	Height:					
Material:	Precast Concrete	Count (items):	2				
Element Type:	Soffit - Ends	Total Quantity:	32.8	m ²			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good 32.80	Fair	Poor*		
Comments:	End portion of soffit appears to be generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years		Urgent	1 year 2 years	

Element Group:	Decks	Length:	28.2				
Element Name:	Soffit - Thin Slab (Exterior)	Width:	0.65				
Location:	North & South Sides of Structure	Height:					
Material:	Cast-in-Place Concrete	Count (items):	2				
Element Type:	Soffit - Thin Slab (Exterior)	Total Quantity:	36.7	m ²			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good 36.5	Fair 0.1	Poor* 0.1		
Comments:	Small spall at southeast end of exterior soffit.						
Recommended Work:		Rehab	Replace	Maintenance Needs: 08			
		1-5 years	6-10 years		Urgent	1 year X 2 years	

Element Group:	Decks	Length:	28.2						
Element Name:	Soffit - Thin Slab	Width:	6.3						
Location:	Underside of Structure	Height:							
Material:	Cast-in-Place Concrete	Count (items):							
Element Type:	Soffit - Interior	Total Quantity:	177.7	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		177.7						
Comments:	Generally in good condition								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Beams/Main Longitudinal Element (MLE's)	Length:	4.0						
Element Name:	Girders	Width:	0.6						
Location:	East & West Underside of Structure	Height:	1.4						
Material:	Precast Concrete	Count (items):	5						
Element Type:	CPCI Girders (1400) - End	Total Quantity:	90.8	m ²					
Environment:	Benign	Limited Inspection			X				
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		90.6	0	0				
Comments:	Small spall noted on exterior of northeast girder. Spall with exposed corroded reinforcement on southwest exterior girder. Narrow map crack on exterior girder flange of southeast girder.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 08					
		1-5 years	6-10 years		Urgent		1 year	X	2 years

Element Group:	Beams/Main Longitudinal Element (MLE's)	Length:	28.3						
Element Name:	Girders	Width:	0.6						
Location:	Underside of Structure	Height:	1.4						
Material:	Precast Concrete	Count (items):	5						
Element Type:	CPCI Girders (1400) - End	Total Quantity:	642.4	m ²					
Environment:	Benign	Limited Inspection			X				
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		642.4						
Comments:	Generally in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Beams/Main Longitudinal Element (MLE's)	Length:	1.5				
Element Name:	Diaphragms (End)	Width:	0.3				
Location:	East & West Underside of Structure	Height:	1.4				
Material:	Precast Concrete	Count (items):	8				
Element Type:	RC Rectangular Diaphragms	Total Quantity:	37.2	m ²			
Environment:	Benign	Limited Inspection		X			
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		37.2				
Comments:	Generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Beams/Main Longitudinal Element (MLE's)	Length:	1.5				
Element Name:	Diaphragms (Middle)	Width:	0.3				
Location:	Underside of Structure	Height:	1.4				
Material:	Precast Concrete	Count (items):	8				
Element Type:	RC Rectangular Diaphragms - Intermediate	Total Quantity:	37.2	m ²			
Environment:	Benign	Limited Inspection		X			
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		37.2				
Comments:	Generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Abutments	Length:					
Element Name:	Bearings	Width:					
Location:	East and West Underside of Structure	Height:					
Material:	Plastic	Count (items):	10				
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	10	Each			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		10				
Comments:	Bearings appear to be generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Abutments	Length:							
Element Name:	Ballast Walls	Width:	9.7						
Location:	East and West Underside of Structure	Height:	1.0						
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	19.4 m ²						
Environment:	Benign	Limited Inspection	X						
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*				
			19.2	0.1	0.1				
Comments:	Limited inspection due to end diaphragms. Spall noted on west ballast wall at end of girder. Visible portions of ballast wall were generally in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 8					
		1-5 years	6-10 years		Urgent		1 year	X	2 years

Element Group:	Abutment	Length:							
Element Name:	Abutment Walls	Width:	9.7						
Location:	East and West Underside of Structure	Height:	2.1						
Material:	Cast-in-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	40.7 m ²						
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*				
			40.6	0.1					
Comments:	Graffiti on east wall. Localized moderate honeycombing noted on north corner of east wall.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Abutments	Length:	5.5						
Element Name:	Wingwalls	Width:							
Location:	NE, SE, NW & SW OF Structure	Height:	1.5						
Material:	Cast-in-place Concrete	Count (items):	4.0						
Element Type:	Reinforced Concrete Walls	Total Quantity:	33.0 m ²						
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*				
			33.0	0.0					
Comments:	Generally in good condition with vegetation growing on northeast wall.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Abutment Walls and Wingwalls	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection		X					
Protection System:	Unknown							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams			Length:					
Element Name:	Embankments			Width:					
Location:	NE, SE, NW & SW Side of Structure			Height:					
Material:	Native Material			Count (items):		4			
Element Type:	Embankment			Total Quantity:		Each			
Environment:	Moderate			Limited Inspection					
Protection System:	Vegetation							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Embankments are moderately sloped and well vegetated.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams			Length:					
Element Name:	Streams and Waterways			Width:					
Location:	Below Structure			Height:					
Material:	Native			Count (items):		All			
Element Type:	Stream			Total Quantity:		All N/A			
Environment:	Benign			Limited Inspection					
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Low volume and moderate flow from south to north with no obstructions noted.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Justification



Photo 1 Structure from east approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure



Photo 5 North elevation



Photo 6 South elevation



Photo 7 New end treatment at southeast corner



Photo 8 Wide crack at end of approach slab on east wearing surface



Photo 9 Abrasions on east joint armouring and scaling on concrete end dams



Photo 10 Typical elevation of deck barrier, north barrier shown



Photo 11 Wide longitudinal crack at centreline of deck wearing surface



Photo 12 Typical view of north exterior soffit



Photo 13 Typical view of interior soffit



Photo 14 Small spall at west end of south girder



Photo 15 Spall at east end of interior girder



Photo 16 Graffiti on east end diaphragm



Photo 17 Bearing at northwest corner of structure



Photo 18 Narrow cracks on northwest wingwall



Photo 19 Localized moderate honeycombing on east abutment wall

Structure Condition Summary Form

Structure Name West Bridge
Structure Number BRH016
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	103.50	0.00	99.40	4.10	0.00	0	0		00	00
	Wearing Surface	Sq.m	6.00	103.20	0.00	103.20	0.00	0.00	619	464	75	00	12
	Approach Slabs	Sq.m	140.00	103.20	0.00	103.20	0.00	0.00	14448	10836	75	00	00
Barriers	Railing Systems	m	200.00	86.40	0.00	84.40	2.00	0.00	17280	12820	74	00	00
	Posts - Timber	Each	50.00	46.00	0.00	40.00	6.00	0.00	2300	1620	70	00	00
	Armouring / Retaining Devices	m	1.00	40.00	0.00	40.00	0.00	0.00	40	30	75	00	00
Joints	Concrete End Dams	Sq.m	2100.00	12.00	0.00	12.00	0.00	0.00	25200	18900	75	00	00
	Seals/ Sealants	Each	0.00	2.00	0.00	2.00	0.00	0.00	0	0		00	00
	Wearing Surface	Sq.m	25.00	274.60	0.00	261.70	8.60	4.30	6865	4993	73	00	12
Decks	Deck Top - Thin Slab	Sq.m	120.00	313.30	0.00	313.30	0.00	0.00	37596	28197	75	00	00
	Soffit - Thin Slab	Sq.m	120.00	247.20	0.00	247.00	0.10	0.10	29664	22235	75	00	08
Beams/ Main Longitudinal Elements	Girders	Sq.m	200.00	733.20	0.00	733.00	0.10	0.10	146640	109958	75	00	08
	Diaphragms - Concrete	Each	0.00	74.40	0.00	74.40	0.00	0.00	0	0		00	00
	Wingwalls	Sq.m	350.00	33.00	0.00	33.00	0.00	0.00	11550	8663	75	00	00
Abutment	Ballast Walls	Sq.m	350.00	19.40	0.00	19.20	0.10	0.10	6790	5054	74	00	08
	Bearings	Each	1000.00	10.00	0.00	10.00	0.00	0.00	10000	7500	75	00	00
	Abutment Walls	Sq.m	900.00	40.70	0.00	40.60	0.10	0.00	36630	27441	75	00	00
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									345622	258711			

Bridge Condition Index (BCI)

75

Inventory Data:

Structure Name	Bigford Bridge				
Main Hwy/Road #	Kirkwood Rd	Services on structure:	<i>Navig. Water</i> <input type="checkbox"/> <i>Rail</i> <input type="checkbox"/>	<i>Non-Navig. Road</i> <input checked="" type="checkbox"/> <i>Ped. Other</i> <input type="checkbox"/>	
	On Structure <input checked="" type="checkbox"/>				
	Under Structure <input type="checkbox"/>	Services under structure:	<i>Navig. Water</i> <input checked="" type="checkbox"/> <i>Rail</i> <input type="checkbox"/>	<i>Non-Navig. Road</i> <input type="checkbox"/> <i>Ped. Other</i> <input type="checkbox"/>	
Structure Location	0.2km North of County Road 5				
Latitude	45.00415	Longitude	-75.36276		
Owner(s)	Township of North Dundas	Heritage Designation	<i>Not Consid. Desig./not list</i> <input checked="" type="checkbox"/> <i>Cons/not App. Desig. & List</i> <input type="checkbox"/>	<i>List/n.d.</i> <input type="checkbox"/>	
MTO Region	40 - Eastern	Road Class:	<i>Freeway</i> <input type="checkbox"/> <i>Collector</i> <input type="checkbox"/>	<i>Arterial Local</i> <input checked="" type="checkbox"/>	
MTO District	42 - Ottawa	Posted Speed	80 km/h	No. of Lanes	2
Old County	SDG	AADT	50	% Trucks	
Geographic Twp.		Inspection Route Sequence			
Structure Type	Solid Slab	Interchange Number			
Total Deck Length	12.2 m	Interchange Structure Number			
Overall Str. Width	10.5 m	Min. Vertical Clearance			
Total Deck Area	128.1 sq. m	Special Routes:	<i>Transit School</i> <input type="checkbox"/> <i>Truck Bicycle</i> <input type="checkbox"/>		
Roadway Width	7.0 m	Detour Length Around Bridge			
Skew Angle	20 Degrees	Direction of Structure	North/South		
No. of Spans	1	Fill on Structure			
Span Lengths	12.2 m				

Historical Data:

Year Built	1983	Year of Last Major Rehab.	
Last OSIM Inspection	October 9, 2020	Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	73.23		
OSIM		2022	74		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	-1 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:		x		\$ 15,000.00
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
		Total Costs			\$ 15,000.00

Investigation Notes:

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years					
Overall Comments:	Structure is in generally good to condition. Wide transverse cracks noted on concrete deck top. With some small spalls noted on concrete posts. Graffiti noted on north underside of structure. Settlement of roadway noted on both approaches.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Sealing (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	NE: 22.86, SE: 22.86, SW: 45.7, NW: 45.7				
Element Name:	Barrier	Width:					
Location:	NE, SE, NW & SW of Structure	Height:					
Material:	Steel	Count (items):	4				
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	137.1 m				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		133.12	3	1		
Comments:	Generally in good condition. New end treatments installed since previous inspection. Minor to severe rot noted on existing timber posts. Collision damage noted on steel flex beam.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			18 - (Other)
		1-5 years	6-10 years	X	Urgent	1 year	2 years
				Repair section with collision damage			

Element Group:	Approaches	Length:	6				
Element Name:	Wearing Surface	Width:	7.5				
Location:	North & South of Structure	Height:					
Material:	Asphalt	Count (items):	2				
Element Type:	Asphalt Surface Treatment	Total Quantity:	90.0 m ²				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		80.1	5.4	4.5	9	
Comments:	Settlement noted on both approaches . Some washout noted at edges of approaches.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			12
		1-5 years	6-10 years		Urgent	1 year	X 2 years
				Repair asphalt surface treatment and patch pothole			

Element Group:	Accessories	Length:					
Element Name:	Signs	Width:					
Location:	NE, SE, NW & SW of Structure	Height:					
Material:	Steel	Count (items):	4				
Element Type:	Steel hazard Signs	Total Quantity:	4.0 each				
Environment:	Severe	Limited Inspection					
Protection System:	Hot Dip Galvanized					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	each		4.0				
Comments:	Generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years		Urgent	1 year	2 years

Element Group:	Joins	Length:	9.8				
Element Name:	Armouring/Retaining Devices	Width:					
Location:	North & South Ends of Structure	Height:					
Material:	Steel	Count (items):	2				
Element Type:	Armouring/Retaining Devices	Total Quantity:	19.6	m			
Environment:	Severe	Limited Inspection	X	Due to Debris			
Protection System:	None				Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		19.4	0.2			
Comments:	Limited inspection due to debris. Some light to localized medium rust noted on visible portions of armouring.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	
				Install supports.			

Element Group:	Joins	Length:	9.8				
Element Name:	Concrete End Dams	Width:	0.35				
Location:	North & South Ends of Structure	Height:					
Material:	Cast-in-Place Concrete	Count (items):	2				
Element Type:	Concrete End Dams	Total Quantity:	6.86	m ²			
Environment:	Severe	Limited Inspection	X	Due to Debris			
Protection System:	None				Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		6.72	0.14			
Comments:	Limited inspection due to debris. Light to medium abrasions and scaling noted on visible portions.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	
				Install supports.			

Element Group:	Joins	Length:					
Element Name:	Seals/Sealants	Width:					
Location:	North & South Ends of Structure	Height:					
Material:	Neoprene	Count (items):	2				
Element Type:	Strip Seal	Total Quantity:	2	each			
Environment:	Severe	Limited Inspection	X				
Protection System:	None				Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		2				
Comments:	Limited inspection due to debris. No evidence of leakage noted at time of inspection.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	
				Install supports.			

Element Group:	Barriers	Length:	0.4					
Element Name:	Barrier/Parapet Walls	Width:	0.4					
Location:	NE, NW, SE & SW of Structure	Height:	1.6					
Material:	Cast-In-Place Concrete	Count (items):	4					
Element Type:	Reinforced concrete End Posts	Total Quantity:	3.2	m ²				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		3.20					
Comments:	Generally in good condition with some pattern cracking noted.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Barriers	Length:	50					
Element Name:	Railing System	Width:						
Location:	East & West Sides of Structure	Height:						
Material:	Steel	Count (items):	2					
Element Type:	Steel Flex Beam	Total Quantity:	100	m				
Environment:	Severe	Limited Inspection						
Protection System:	Hot Dip Galvanizing						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m		100					
Comments:	Generally in good condition with some rotated spacers noted.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Barriers	Length:	0.3					
Element Name:	Posts	Width:	0.3					
Location:	East & West sides of Structure	Height:	1.03					
Material:	Cast-in-Place Concrete	Count (items):	52					
Element Type:	Concrete Barrier posts	Total Quantity:	52	Each				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		48	3	1			
Comments:	Small spalls, and pattern map cracks noted on concrete barrier posts.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	X 2 years	

Element Group:	Coating	Length:					
Element Name:	Railing System/Hand Railings	Width:					
Location:	On Bridge Railing	Height:					
Material:	Other	Count (items):					
Element Type:	Hot Dip Galvanizing	Total Quantity:	100.0	m			
Environment:	Severe	Limited Inspection					
Protection System:	None						
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies	
	m		100				
Comments:	Coating is generally in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	43			
Element Name:	Deck Top (Exposed)	Width:	9.8			
Location:	Top of Deck	Height:				
Material:	Cast-in-Place Concrete	Count (items):				
Element Type:	Deck Top	Total Quantity:	421.4 m ²			
Environment:	Severe	Limited Inspection	X			
Protection System:	None					
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies
	m ²		408.76	8.43	4.21	
Comments:	Wide transverse cracks noted on deck surface. Debris accumulation throughout edges of deck.					
Recommended Work:	X	Rehab	Replace	Maintenance Needs:		
	X	1-5 years	6-10 years	Urgent	1 year	2 years

Element Group:	Decks	Length:	2			
Element Name:	Soffit - Thin Slab (End)	Width:	11			
Location:	North and South Sides of Structure	Height:				
Material:	Cast-in-Place Concrete	Count (items):	2			
Element Type:	Soffit - End	Total Quantity:	44 m ²			
Environment:	Benign	Limited Inspection				
Protection System:	None					
Condition Data:	Units	Exc.	Good	Fair	Poor*	Perform. Deficiencies
	m ²		44.00			
Comments:	Graffiti noted on north end of soffit. End of soffit appears to be in good condition.					
Recommended Work:		Rehab	Replace	Maintenance Needs: 2		
		1-5 years	6-10 years	Urgent	1 year	X 2 years

Element Group:	Decks	Length:	39.0				
Element Name:	Soffit - Thin Slab (Exterior)	Width:	1.6				
Location:	East Underside of Structure	Height:					
Material:	Precast Concrete	Count (items):	2				
Element Type:	Soffit - Exterior	Total Quantity:	124.8	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		124.8				
Comments:	Exterior soffit generally appears to be in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Decks	Length:	39				
Element Name:	Soffit - Thin Slab (Interior)	Width:	7.8				
Location:	Underside of Structure	Height:					
Material:	Precast Concrete	Count (items):					
Element Type:	Soffit - Interior	Total Quantity:	304.2	m ²			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		304.2				
Comments:	Interior soffit appears to be in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Abutments	Length:					
Element Name:	Bearings	Width:					
Location:	On North & South Abutment Wall	Height:					
Material:	Neoprene	Count (items):	10				
Element Type:	Elastomeric Bearing Pads - Neoprene	Total Quantity:	10	Each			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		10				
Comments:	Bearing pads appear to be in good condition.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Element Group:	Abutments	Length:							
Element Name:	Ballast Walls	Width:	9.8						
Location:	North & South Underside of Structure	Height:	0.6						
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	11.76 m ²						
Environment:	Benign	Limited Inspection	X						
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		11.76						
Comments:	Ballast walls were inaccessible for inspection due to concrete deck. Visible sections appear to be in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Abutment	Length:							
Element Name:	Abutment Walls	Width:	9.8						
Location:	North & South Underside of Structure	Height:	0.9						
Material:	Cast-in-Place Concrete	Count (items):	2						
Element Type:	Reinforced Concrete Walls	Total Quantity:	17.6 m ²						
Environment:	Benign	Limited Inspection	X						
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		17.60						
Comments:	Graffiti on north abutment wall. Abutment walls appear to be in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 2					
		1-5 years	6-10 years		Urgent		1 year	X	2 years

Element Group:	Abutments	Length:	3.5						
Element Name:	Wingwalls	Width:							
Location:	NE, SE, NW & SW OF Structure	Height:	1.6						
Material:	Cast-in-place Concrete	Count (items):	4.0						
Element Type:	Reinforced Concrete Walls	Total Quantity:	22.4 m ²						
Environment:	Moderate	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		22.4						
Comments:	Wingwalls are generally in good condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Piers	Length:						
Element Name:	Shafts/Columns/ Pile Bents	Width:	0.5					
Location:	Underside of Structure	Height:	4.2					
Material:	Steel	Count (items):	12.0					
Element Type:	Steel Circular Shafts	Total Quantity:	79.1 m ²					
Environment:	Benign	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		79.1					
Comments:	Pier shafts appear to be in good condition with some light staining noted on top of shafts.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Foundations	Length:						
Element Name:	Foundation (Below Ground Level)	Width:						
Location:	Below Abutment Walls and Pier Shafts	Height:						
Material:	Unknown	Count (items):						
Element Type:	Unknown	Total Quantity:	All					
Environment:	Benign	Limited Inspection					X	
Protection System:	Unknown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All			0		
Comments:	No visible evidence of foundation instability was noted during the inspection.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, SE, NW, SW, S & N Side of Structure	Height:						
Material:	Native Material	Count (items):	6					
Element Type:	Embankment	Total Quantity:	6 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	Rip-Rap Slope Protection						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		6.00					
Comments:	Embankments are moderately sloped, well vegetated and appear to be stable.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:							
Element Name:	Slope Protection	Width:							
Location:	N, NE, SE, S, NW & SW Side of Structure	Height:							
Material:	Rip-Rap	Count (items):	5						
Element Type:	Stone Slope Protection	Total Quantity:	5	Each					
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		5.00	1					
Comments:	Some loss of rip-rap material on north embankment.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Below Structure	Height:							
Material:	Native	Count (items):	All						
Element Type:	Stream	Total Quantity:	All	N/A					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	High volume and low flow from west to east with no obstructions noted at time of inspection.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Deck Top (Exposed)	Concrete Repairs		X		\$ 8,500.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 8,500.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification



Photo 1 Structure from north approach



Photo 2 Structure from south approach



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure



Photo 5 East elevation



Photo 6 West elevation



Photo 7 Settlement and large potholes on north wearing surface



Photo 8 New end treatment at southwest corner



Photo 9 North expansion joint covered by debris



Photo 10 Typical elevation view of east barrier



Photo 11 Small spall on concrete barrier post



Photo 12 Wide transverse cracks and abrasions on deck top



Photo 13 Typical view of west exterior soffit



Photo 14 Typical view of east exterior soffit



Photo 15 View of interior soffit



Photo 16 Small spall on south side of interior soffit




Photo 17 Typical view of south bearing



Photo 18 South abutment wall



Photo 19 Graffiti on north underside of structure



Photo 20 Typical view of south pier shafts



Photo 21 Staining on top of pier shafts

Structure Condition Summary Form

Structure Name Bigford Bridge
Structure Number BRH017
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	137.10	0.00	133.12	3.00	1.00	0	0		00	18
	Wearing Surface	Sq.m	6.00	90.00	0.00	80.10	5.40	4.50	540	373	69	00	12
Barriers	Barrier/ Parapet Walls	Sq.m	100.00	3.20	0.00	3.20	0.00	0.00	320	240	75	00	00
	Railing Systems	m	200.00	100.00	0.00	100.00	0.00	0.00	20000	15000	75	00	00
	Posts (Steel/Concrete)	Each	200.00	52.00	0.00	48.00	3.00	1.00	10400	7440	72	00	08
	Armouring / Retaining Devices	m	1.00	19.60	0.00	19.40	0.20	0.00	20	15	75	00	00
Joints	Concrete End Dams	Sq.m	2100.00	6.86	0.00	6.72	0.14	0.00	14406	10702	74	00	00
	Seals/ Sealants	Each	0.00	2.00	0.00	2.00	0.00	0.00	0	0		00	00
Decks	Deck Top - Thick Slab	Sq.m	350.00	421.40	0.00	408.76	8.43	4.21	147490	108480	74	00	00
	Soffit - Thick Slab	Sq.m	350.00	473.00	0.00	473.00	0.00	0.00	165550	124163	75	00	00
Coatings	Railing Systems/ Hand Railing	Sq.m	125.00	100.00	0.00	100.00	0.00	0.00	12500	9375	75	00	00
	Wingwalls	Sq.m	350.00	17.60	0.00	17.60	0.00	0.00	6160	4620	75	08	08
Abutment	Ballast Walls	Sq.m	350.00	11.76	0.00	11.76	0.00	0.00	4116	3087	75	00	00
	Bearings	Each	1000.00	10.00	0.00	10.00	0.00	0.00	10000	7500	75	00	00
	Abutment Walls	Sq.m	900.00	17.60	0.00	17.60	0.00	0.00	15840	11880	75	01	08
Piers	Shafts/ Columns/ Pier Bents	Sq.m	900.00	79.10	0.00	79.10	0.00	0.00	71190	53393	75	00	00
Embankments and Streams	Embankments	Each	0.00	6.00	0.00	6.00	0.00	0.00	0	0		00	00
	Slope Protection	Each	0.00	6.00	0.00	5.00	1.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									478532	356266			

Bridge Condition Index (BCI)

74

Inventory Data:

Structure Name	Chesterville Dam Structure Pedestrian Bridge									
Main Hwy/Road #			Services on structure:	Navig. Water		Non-Navig.		Ped.	X	
	On Structure	X		Rail		Road		Other		
	Under Structure			Services under structure:		Navig. Water		Non-Navig.	X	Ped.
				Rail		Road		Other		
Structure Location	30m South of Water St.									
Latitude	45.1012649			Longitude	-75.2259991					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid. Desig./not list	X	Cons/not App. Desig. & List		List/n.d.	
MTO Region	40 - Eastern			Road Class:	Freeway		Arterial		Local	X
					Collector					
MTO District	42 - Ottawa			Posted Speed			No. of Lanes	2		
Old County	SDG			AADT	N/A		% Trucks			
Geographic Twp.				Inspection Route Sequence						
Structure Type	Pedestrian Bridge (Solid Slab)			Interchange Number						
Total Deck Length	42		m	Interchange Structure Number						
Overall Str. Width	4		m	Min. Vertical Clearance						
Total Deck Area	168.0		sq. m	Special Routes:	Transit		Truck		Bicycle	
					School					
Roadway Width	4.0		m	Detour Length Around Bridge						
Skew Angle			Degrees	Direction of Structure	North/South					
No. of Spans	6			Fill on Structure						
Span Lengths	7.0		m							

Historical Data:

Year Built		Year of Last Major Rehab.	
Last OSIM Inspection		Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.81		
OSIM		2022	74.79		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection: Chesterville	11/25/2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Partly Cloudy / Rainy				
Temperature:	4° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study					
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation: Pedestrian Bridge (Solid Slab)		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input checked="" type="checkbox"/> X	None	<input type="checkbox"/>	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:				1 to 5 years		6 to 10 years	
Overall Comments:	Structure is generally in good condition - Limited access to soffit and abutment walls, visible portions are in generally good condition with some map cracking and scaling on the east edge of top of deck. Approaches should be regraded. Corrosion noted on bollard base plates with missing bolts						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Accessories (Attachments and Signs)				Length:				
Element Name:	Other				Width:				
Location:	North and South side of Structure				Height:				
Material:	Steel				Count (items):	2			
Element Type:	Bollard				Total Quantity:	2.0 Each			
Environment:	Severe				Limited Inspection				
Protection System:	Coating				Perform. Deficiencies				
Condition Data:	Units	Exc.	Good	Fair					Poor*
	Each			2.0					
Comments:	Corrosion at baseplates with paint failure and missing bolts noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 18				
		1-5 years		6-10 years		Urgent	X	1 year	2 years
					Replace missing bolts				

Element Group:	Approaches				Length:	20			
Element Name:	Barriers				Width:				
Location:	NE & SE sides of structure				Height:				
Material:	Steel				Count (items):	2			
Element Type:	Steel post and panel railing				Total Quantity:	40 m			
Environment:	Severe				Limited Inspection				
Protection System:	Hot dip Galvanizing				Perform. Deficiencies				
Condition Data:	Units	Exc.	Good	Fair					Poor*
	m		40						
Comments:	Generally in good condition with light abrasion								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches				Length:	6			
Element Name:	Wearing Surface				Width:	4			
Location:	North and South structure approaches				Height:				
Material:	Gravel				Count (items):	2			
Element Type:	Gravel wearing surface				Total Quantity:	48.00 m ²			
Environment:	Severe				Limited Inspection				
Protection System:	None				Perform. Deficiencies				
Condition Data:	Units	Exc.	Good	Fair					Poor*
	m ²		48						
Comments:	Settlement of gravel +/- 25mm below edge dams at deck ends								
Recommended Work:		Rehab		Replace	Maintenance Needs: 18				
		1-5 years		6-10 years		Urgent		1 year	X 2 years
					Regrade				

Element Group:	Joints	Length:	10				
Element Name:	Armouring/Retaining Devices	Width:					
Location:	North and South Side of Structure	Height:					
Material:	Steel	Count (items):	4				
Element Type:	Armouring/Retaining Devices	Total Quantity:	40	m			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		38.00	2.0			
Comments:	Generally in good condition with light to medium corrosion noted.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Joints	Length:	10				
Element Name:	Concrete End Dams	Width:	0.35				
Location:	North and South sides of Structure	Height:					
Material:	Cast-In-Place Concrete	Count (items):	2				
Element Type:	Concrete End Dams	Total Quantity:	7	m ²			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		6.8	0.2			
Comments:	Generally in good condition with some light spalling at approach end dams noted.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Joints	Length:	10				
Element Name:	Seals/Sealants	Width:					
Location:	North and South Side of Structure	Height:					
Material:	Plastic	Count (items):	2				
Element Type:	Strip Seal	Total Quantity:	2	Each			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		2				
Comments:	Generally in good condition with some minor debris build up.						
Recommended Work:		Rehab		Replace	Maintenance Needs: 02		
		1-5 years		6-10 years	Urgent	1 year X 2 years	
					Clean joint seal		

Element Group:	Barriers	Length:	42				
Element Name:	Railing Systems	Width:					
Location:	East and West sides of Structure	Height:					
Material:	Steel	Count (items):	2				
Element Type:	Steel post and panel railing	Total Quantity:	84	m			
Environment:	Severe	Limited Inspection					
Protection System:	Hot dip galvanizing					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		83.6	0.2			
Comments:	Generally in good condition. Localized deformation on pickets (x2) and localized light corrosion on anchor bolts						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Coating	Length:					
Element Name:	Railing Systems	Width:					
Location:	Over bridge railings	Height:					
Material:	Other	Count (items):					
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	124	m			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		124.0				
Comments:	Generally in good condition						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Decks	Length:	42				
Element Name:	Deck Top - Thick Slab	Width:	10				
Location:	Top of Deck	Height:					
Material:	Cast-in-place concrete	Count (items):					
Element Type:	Reinforced concrete deck top - exposed	Total Quantity:	420.0	m ²			
Environment:	Severe	Limited Inspection		X			
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		420				
Comments:	Access to the west side of the bridge was limited due to dam structure. Limited inspection due to snow. Light scaling noted at chamfer on east edge of deck, with light map cracking present.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Decks	Length:	2				
Element Name:	Soffit - Thick Slab	Width:	11				
Location:	Norht and South underside of structure	Height:					
Material:	Cast-in-place concrete	Count (items):	2				
Element Type:	Soffit-end	Total Quantity:	44	m ²			
Environment:	Benign	Limited Inspection		X			
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*		
			44.00				
Comments:	Limited inspection - No access. Condition of soffit is based on condition of top of deck - No visible defects noted.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Decks	Length:	38				
Element Name:	Soffit - Thick Slab	Width:	1.5				
Location:	East and West side of structure	Height:					
Material:	Cast-in-place concrete	Count (items):	2				
Element Type:	Soffit - Exterior	Total Quantity:	114	m ²			
Environment:	Moderate	Limited Inspection		X			
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*		
			114.00				
Comments:	Limited inspection - No access. Condition of soffit is based on condition of top of deck - No visible defects noted.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Decks	Length:	38				
Element Name:	Soffit - Thick Slab	Width:	8				
Location:	Underside of structure	Height:					
Material:	Cast-in-place concrete	Count (items):	2				
Element Type:	Soffit - Interior	Total Quantity:	304	m ²			
Environment:	Benign	Limited Inspection		X			
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*		
			304.0				
Comments:	Limited inspection - No access. Condition of soffit is based on condition of top of deck - No visible defects noted.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Abutments	Length:						
Element Name:	Abutment walls	Width:	10					
Location:	North and South Underside of structure	Height:	3.5					
Material:	Cast-in-place concrete	Count (items):	2					
Element Type:	Reinforced concrete walls	Total Quantity:	70 m ²					
Environment:	Benign	Limited Inspection		X				
Protection System:	None					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		70					
Comments:	No access - Visible portions are in generally good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Abutments	Length:	10					
Element Name:	Wingwalls	Width:						
Location:	NE, NW, SE, SW of structure	Height:	3					
Material:	Cast-in-place concrete	Count (items):	4					
Element Type:	Reinforced concrete walls	Total Quantity:	120 m ²					
Environment:	Moderate	Limited Inspection						
Protection System:	None					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		108	12				
Comments:	Medium to light map cracking noted with efflorescence and graffiti noted.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Piers	Length:	0.6					
Element Name:	Shafts/columns/Pile bent	Width:	10					
Location:	Below abutment walls and wingwalls	Height:	3.5					
Material:	Unknown	Count (items):	5					
Element Type:	Unknown	Total Quantity:	371 m ²					
Environment:	Benign	Limited Inspection		X				
Protection System:	Unknown					Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		371					
Comments:	No access - Visible portions are in generally good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Foundations	Length:						
Element Name:	Foundation (Below ground)	Width:						
Location:	Below abutment walls and wingwalls	Height:						
Material:	Unknown	Count (items):	All					
Element Type:	Unknown	Total Quantity:	All N/A					
Environment:	Benign	Limited Inspection	X					
Protection System:	Unknown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted at the time of inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, SE, NW, & SW of Structure	Height:						
Material:	Rip-Rap	Count (items):	4					
Element Type:	Embankment	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	Vegetation						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4.00					
Comments:	Embankments are moderately sloped, well vegetated and stable.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Embankments and streams	Length:						
Element Name:	Slope Protection	Width:						
Location:	NE, SE, NW, & SW of Structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Slope Protection	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4.00					
Comments:	Generally in good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Embankments and Streams	Length:						
Element Name:	Streams and waterways	Width:						
Location:	Below Structure	Height:						
Material:	Native	Count (items):	All					
Element Type:	Stream	Total Quantity:	All			N/A		
Environment:	Benign	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	High volume and high flow from west to east, with no flow obstructions noted.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ -

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>

MUNICIPAL STRUCTURE INSPECTION FORM

Chesterville Dam Structure Pedestrian Bridge SITE PHOTOGRAPHS

Site No.:BRT001



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

Chesterville Dam Structure Pedestrian Bridge SITE PHOTOGRAPHS

Site No.:BRT001



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Chesterville Dam Structure Pedestrian Bridge SITE PHOTOGRAPHS

Site No.:BRT001



Photo 5 East elevation



Photo 6 Channel and structure underside view from the Northeast



Photo 7 Corrosion and missing bolts at south bollard base (typical)



Photo 8 Barrier along east edge of deck



Photo 9 Perforation in deck barrier picket



Photo 10 Corrosion and debris at South deck joint (typical)

MUNICIPAL STRUCTURE INSPECTION FORM

Chesterville Dam Structure Pedestrian Bridge SITE PHOTOGRAPHS

Site No.:BRT001



Photo 11 Abrasion at North end dam (Typical)



Photo 12 Map cracking on wingwalls (typical)

Structure Condition Summary Form

Structure Name	Chesterville Dam Structure Pedestrian Bridge
Structure Number	BRT001
Date of Inspection	November 25, 2022
Consultant	HP Engineering Inc.
Contract Number	22087 (HP)

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in excellent condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Abutment	Abutment Walls	Sq.m	900.00	70		70			63000	47250	75	00	00
	Wingwalls	Sq.m	350.00	120		108	12		42000	30030	72	00	00
Accessories	Signs	Each	0.00	2			2		0	0		00	18
Approaches	Barrier	m	0.00	40		40			0	0		00	00
	Wearing Surface	Sq.m	6.00	48		48			288	216	75	00	18
Barriers	Railing Systems	m	200.00	83.8		83.6	0.2		16760	12556	75	00	00
Coatings	Railing Systems/ Hand Railing	Sq.m	125.00	124		124			15500	11625	75	00	00
Decks	Deck Top-Thick Slab	Sq.m	350.00	420		420			147000	110250	75	00	00
	Soffit- Thick Slab	Sq.m	350.00	462		462			161700	121275	75	00	00
Embankments and Streams	Embankments	Each	0.00	4		4			0	0		00	00
	Slope Protection	Each	0.00	4		4			0	0		00	00
	Streams and Waterways	All	0.00	1		1			0	0		00	00
Foundations	Foundations (below ground level)	N/A	0.00	1		1			0	0		00	00
Joints	Armouring / Retaining Devices	m	1.00	40		38	2		40	29	73	00	00
	Concrete End Dams	Sq.m	2100.00	7		6.8	0.2		14700	10878	74	00	00
	Seals/ Sealants	Each	0.00	2		2			0	0		00	02
Piers	Shafts/ Columns/ Pier Bents	Sq.m	900.00	371		371			333900	250425	75	00	00

794888	594534
--------	--------

Conditon Index	74.79
----------------	-------

ATTACHMENT 2

OSIM INSPECTION REPORTS & BCI FORMS

CULVERTS

Inventory Data:

Structure Name		Cayer Rd & McLean MD Culvert							
Main Hwy/Road #	Cayer Rd	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		0.5km South of County Rd 13							
Latitude	45.137014	Longitude	-75.378067						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
			Design./not list	<input type="checkbox"/>	Design. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern	Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
			Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa	Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG	AADT	668		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	Precast Concrete Box Culvert	Interchange Number	<input type="checkbox"/>						
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	3.0 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	<input type="checkbox"/> sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
			School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	6.4 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	<input type="checkbox"/> Degrees	Direction of Structure	North/South						
No. of Spans	1	Fill on Structure	0.4 m						
Culvert Length	11.7 m								
Span Lengths	3.0 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	73.65		
OSIM		2022	70.45		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study	<input checked="" type="checkbox"/>			
Material Condition Survey				
Detailed Deck Condition Survey:	<input checked="" type="checkbox"/>			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>			
Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Timber Investigation:	<input checked="" type="checkbox"/>			
Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/>			
Underwater Investigation:	<input checked="" type="checkbox"/>			
Fatigue Investigation:	<input checked="" type="checkbox"/>			
Seismic Investigation:	<input checked="" type="checkbox"/>			
Structure Evaluation:	<input checked="" type="checkbox"/>			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/>			
Monitoring Crack Widths:	<input checked="" type="checkbox"/>			
Investigation Notes:				

Overall Structure Notes:				
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years		
Overall Comments:	Structure is in generally good condition. Structure Barrier and End-treatments have been recently replaced. Cracks, potholes, and patches noted in asphalt wearing surface. Scaling and disintegration of the concrete block retaining walls noted. Leaking noted at joints in concrete culvert - deck should be waterproofed. Washout present at southeast and northeast embankments.			
Date of Next Inspection:	2024			

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	

Maintenance Needs

01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	34.15
Element Name:	Barriers	Width:	
Location:	East and West Side of Structure	Height:	
Material:	Steel	Count (items):	2
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	68.3 m
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m		68.30
Comments:	Guide rail and end treatments have been recently replaced and are in generally good condition.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	6.4
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	384.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		378.24
Comments:	Sealed, wide transverse cracks noted. Longitudinal alligator cracking and some raveling present.		
Recommended Work:	x Rehab	Replace	Maintenance Needs:
	x 1-5 years	6-10 years	Urgent 1 year 2 years
Repave and waterproof deck			

Element Group:	Culverts	Length:	1.4
Element Name:	Inlet Components	Width:	0.6
Location:	West Side of Structure	Height:	2.4
Material:	Precast Concrete	Count (items):	2
Element Type:	Stacked Concrete block retaining walls	Total Quantity:	8.4 m2
Environment:	Moderate	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		3.40
Comments:	Severe disintegration noted.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Culverts	Length:	11.7			
Element Name:	Barrels	Width:	3			
Location:	Below Roadway	Height:	2.5			
Material:	Cast-in-place concrete	Count (items):	1			
Element Type:	RC Rigid Frame Barrel (Open footing)	Total Quantity:	128.7	m2		
Environment:	Benign	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m2		124.84	2.57	1.29	
Comments:	Evidence of active leaking was noted at first joint from west.					
Recommended Work:	X	Rehab		Replace	Maintenance Needs:	
	X	1-5 years		6-10 years	Urgent	1 year 2 years
Waterproof deck along with repave						

Element Group:	Culverts	Length:	1.4			
Element Name:	Outlet Components	Width:	0.6			
Location:	East Side of Structure	Height:	2.4			
Material:	Precast Concrete	Count (items):	2			
Element Type:	Stacked Concrete block retaining walls	Total Quantity:	8.4	m2		
Environment:	Moderate	Limited Inspection				
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m2		8.40	3.00	1.00	
Comments:	Evidence of active leaking was noted at first joint from west.					
Recommended Work:		Rehab		Replace	Maintenance Needs: 8	
		1-5 years		6-10 years	Urgent X	1 year 2 years
Concrete repairs						

Element Group:	Foundations	Length:				
Element Name:	Foundation (Below Ground Level)	Width:				
Location:	Below Barrel	Height:				
Material:	Unknown	Count (items):				
Element Type:	Unknown	Total Quantity:	All	N/A		
Environment:	Benign	Limited Inspection	X			
Protection System:	Unknown					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	N/A		All			
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, NW, SW & SE Side of Structure		Height:						
Material:	Rip-Rap		Count (items):	4					
Element Type:	Embankment		Total Quantity:	4					
Environment:	Moderate		Limited Inspection						
Protection System:	Vegetation							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		2	2					
Comments:	Embankments are moderately sloped, well vegetated, and stable. Washouts present at northeast and southeast.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Slope Protection	Width:							
Location:	NE, NW, SW & SE Side of Structure		Height:						
Material:	Vegetation		Count (items):	4					
Element Type:	Slope Protection		Total Quantity:	4					
Environment:	Moderate		Limited Inspection						
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each				4				
Comments:	Generally in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Under structure		Height:						
Material:	Native		Count (items):	All					
Element Type:	Streams		Total Quantity:	All					
Environment:	Benign		Limited Inspection						N/A
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Low volume and low flow from west to east with no visible obstruction noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Wearing Surface	Repave and waterproof deck		X		\$ 40,000.00
Inlet Component	Concrete Repairs		x		\$ 10,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 50,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 35,000.00

Justification
<div></div>

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd McLean MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC001



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd McLean MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC001



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd McLean MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC001



Photo 5 East elevation



Photo 6 West elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd McLean MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC001



Photo 7 Longitudinal alligator cracks, with patches and raveling on wearing surface



Photo 8 Severe disintegration at southwest retaining wall



Photo 9 View through barrel and leaking at segment joints



Photo 10 Scaling/disintegration on northeast retaining wall

Structure Condition Summary Form

Structure Name Cayer Rd & McLean MD Culvert
Structure Number CUC001
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	68.30		68.30			0	0		00	00
	Wearing Surface	Sq.m	6.00	393.24		378.24	15.00		2359	1738	74	00	00
Culvert	Inlet Components	Sq.m	350.00	8.40		3.40	1.00	4.00	2940	1033	35	00	00
	Outlet Components	Sq.m	350.00	12.40		8.40	3.00	1.00	4340	2625	60	00	00
	Barrel	Sq.m	350.00	128.70		124.84	2.57	1.29	45045	33130	74	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
Embankments and Streams	Embankments	Each	0.00	4.00		4.00			0	0		00	00
	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00
									54684	38526			
Bridge Condition Index (BCI)	70.45												

Inventory Data:

Structure Name				Cayer Rd & Cinnamon MD Culvert			
Main Hwy/Road #	Cayer Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>
	Under Structure	<input type="checkbox"/>					
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>
Structure Location				1.3km South of County Rd 13			
Latitude		45.12935		Longitude		-75.37231	
Owner(s)	Township of North Dundas		Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>
				Design./not list	<input type="checkbox"/>	Design. & List	<input type="checkbox"/>
MTO Region	40 - Eastern		Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>
				Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>
MTO District	42 - Ottawa		Posted Speed	60 km/h		No. of Lanes	2
Old County	SDG		AADT	668		% Trucks	<input type="checkbox"/>
Geographic Twp.			Inspection Route Sequence	<input type="checkbox"/>			
Structure Type	Concrete Rigid frame		Interchange Number	<input type="checkbox"/>			
Total Deck Length	<input type="checkbox"/> m		Interchange Structure Number	<input type="checkbox"/>			
Overall Str. Width	6.1 m		Min. Vertical Clearance	<input type="checkbox"/> m			
Total Deck Area	<input type="checkbox"/> sq. m		Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>
				School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>
Roadway Width	19.5 m		Detour Length Around Bridge	<input type="checkbox"/> km			
Skew Angle	<input type="checkbox"/> Degrees		Direction of Structure	North/South			
No. of Spans	1		Fill on Structure	1.2 m			
Culvert Length	19.5 m						
Span Lengths	6.1 m						

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.85		
OSIM		2022	74.21		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study	<input checked="" type="checkbox"/>			
Material Condition Survey				
Detailed Deck Condition Survey:	<input checked="" type="checkbox"/>			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>			
Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Timber Investigation:	<input checked="" type="checkbox"/>			
Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/>			
Underwater Investigation:	<input checked="" type="checkbox"/>			
Fatigue Investigation:	<input checked="" type="checkbox"/>			
Seismic Investigation:	<input checked="" type="checkbox"/>			
Structure Evaluation:	<input checked="" type="checkbox"/>			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/>			
Monitoring Crack Widths:	<input checked="" type="checkbox"/>			
Investigation Notes:				

Overall Structure Notes:				
Recommended Work on	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:		<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years	
Overall Comments:	Structure is in generally good condition. Barriers and end-treatments have been recently replaced and are in generally good condition. Wide cracks and patches noted on asphalt wearing surface above structure. Some ponding present above the structure and around barrier posts. Light scaling throughout the barrel, with honeycombing and localized spalls at both ends of barrel.			
Date of Next Inspection:	2024			

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	

Maintenance Needs

01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Barriers	Length:	8.3
Element Name:	Railing Systems	Width:	
Location:	East and West Side of Structure	Height:	
Material:	Steel	Count (items):	2
Element Type:	Steel Flex Beam on Steel Posts	Total Quantity:	16.6 m
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units m	Exc.	Good 15.60
			Fair 1.00
			Poor*
Comments:	Guide rail and end treatments have been recently replaced and are in generally good condition. Some ponding is present around posts above structure.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	6
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	360.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units m2	Exc.	Good 352.00
			Fair 4.00
			Poor* 4.00
Comments:	Wide transverse cracks, alligator cracks, and sealed cracks/patches noted on asphalt wearing surface, with some small-medium sized potholes.		
Recommended Work:	Rehab	Replace	Maintenance Needs: 15
	1-5 years	6-10 years	Urgent X 1 year 2 years
	Rout and seal asphalt wearing surface		

Element Group:	Culverts	Length:	19.5
Element Name:	Barrels	Width:	6.1
Location:	Below Roadway	Height:	2.8
Material:	Cast-in-place concrete	Count (items):	1
Element Type:	RC Rigid Frame Barrel (Open footing)	Total Quantity:	228.15 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units m2	Exc.	Good 225.15
			Fair 1.50
			Poor* 1.50
Comments:	Honeycombing and localized spall present on both ends of barrel with light scaling throughout.		
Recommended Work:	Rehab	Replace	Maintenance Needs: 8
	1-5 years	6-10 years	Urgent x 1 year 2 years
Concrete repairs	Concrete repairs to barrel		

Element Group:	Foundations	Length:						
Element Name:	Foundation (Below Ground Level)	Width:						
Location:	Below Barrel	Height:						
Material:	Unknown	Count (items):						
Element Type:	Unknown	Total Quantity:	All	N/A				
Environment:	Benign	Limited Inspection	X					
Protection System:	Unknown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Gravel	Count (items):	4					
Element Type:	Embankment	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	Vegetation / Gabion baskets						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4					
Comments:	Embankments are moderately sloped, well vegetated, and stable							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope Protection	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Vegetation / Gabion baskets	Count (items):	4					
Element Type:	Slope Protection	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each				4			
Comments:	Generally in good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Under structure	Height:							
Material:	Native	Count (items):	All						
Element Type:	Streams	Total Quantity:	All N/A						
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	No flow noted in barrel at the time of the inspection. Sediment accumulation noted within barrel.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ -

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Cinnamon MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC002



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Cinnamon MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC002



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Cinnamon MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC002



Photo 5 East elevation



Photo 6 West elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Cinnamon MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC002



Photo 7 Replaced barrier and end-treatment (typical)



Photo 8 Ponding at barrier posts above structure

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Cinnamon MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC002



Photo 9 Wide transverse crack in wearing surface above structure with scaling and patches



Photo 10 Spall/honeycombing at southeast of barrel



Photo 11 View through barrel from the East



Photo 12 Spalls and honeycombing at the northwest of barrel.

Structure Condition Summary Form

Structure Name Cayer Rd & Cinnamon MD Culvert
Structure Number CUC002
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	360.00		352.00	4.00	4.00	2160	1594	74	00	15
Barriers	Railing Systems	m	200.00	16.60		15.60	1.00		3320	2420	73	00	00
Culvert	Barrel	Sq.m	350.00	228.15		225.15	1.50	1.50	79853	59312	74	00	08
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

										85333	63325			
Bridge Condition Index (BCI)	74.21													

Structure Name	Thompson Rd & Black Creek MD Culvert									
Main Hwy/Road #	Thompson Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	Intersection of Thompson Rd and Steen Rd									
Latitude	45.15021			Longitude	-75.31702					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid.	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
					Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>		
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>		
					Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>		
MTO District	42 - Ottawa			Posted Speed	60 km/h		No. of Lanes	2		
Old County	SDG			AADT	232		% Trucks	<input type="checkbox"/>		
Geographic Twp.	<input type="text"/>			Inspection Route Sequence	<input type="text"/>					
Structure Type	Precast concrete Box culvert			Interchange Number	<input type="text"/>					
Total Deck Length	<input type="text"/> m			Interchange Structure Number	<input type="text"/>					
Overall Str. Width	3.6m <input type="text"/> m			Min. Vertical Clearance	<input type="text"/> m					
Total Deck Area	<input type="text"/> sq. m			Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>		
					School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>		
Roadway Width	6.0 <input type="text"/> m			Detour Length Around Bridge	<input type="text"/> km					
Skew Angle	<input type="text"/> Degrees			Direction of Structure	East/West <input type="text"/>					
No. of Spans	1 <input type="text"/>			Fill on Structure	0.5m <input type="text"/> m					
Culvert Length	15.9 <input type="text"/> m									
Span Lengths	3.6 <input type="text"/> m									

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text"/>	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	75.00		
OSIM		2022	73.66		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 5,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:						
Recommended Work on	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace		
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years		<input type="checkbox"/> 6 to 10 years			
Overall Comments:	Structure is in generally good condition. Light scaling along the bottom haunches of the box culvert, along both sides. Small spalls noted at inlet and outlet and a few on the barrel side walls. Evidence of leaking joint at second joint from the south. Gabion basket is leaning towards stream at the southwest. No guide rail present above the structure - A code compliant barrier and end-treatments should be installed above the structure. Rehabilitation study recommended for guide rail only.					
Date of Next Inspection:	2024					

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approach	Length:	60
Element Name:	Wearing surface	Width:	6
Location:	Over culvert	Height:	
Material:	Gravel	Count (items):	
Element Type:	Gravel Wearing Surface	Total Quantity:	360 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		360.00
Comments:	Generally in good condition with no significant defects.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Culverts	Length:	15.9
Element Name:	Barrels	Width:	3.6
Location:	Below roadway	Height:	2.8
Material:	Precast Concrete	Count (items):	1
Element Type:	Precast Concrete Box Culvert	Total Quantity:	203.52 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		195.52
Comments:	Generally in good condition. Small spalls noted at inlet, outlet and culvert side walls. Evidence of leaking seen at second joint from the south. Light scaling along bottom haunches on both sides of culvert.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Foundations	Length:	
Element Name:	Foundation (Below Ground Level)	Width:	
Location:	Below Barrel	Height:	
Material:	Unknown	Count (items):	
Element Type:	Unknown	Total Quantity:	All N/A
Environment:	Benign	Limited Inspection	X
Protection System:	Unknown		
Condition Data:	Units	Exc.	Good
	N/A		All
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Embankments and Streams	Length:								
Element Name:	Embankments	Width:								
Location:	NE, NW, SW & SE Side of Structure		Height:							
Material:	Vegetation		Count (items):	4						
Element Type:	Embankment		Total Quantity:	4		Each				
Environment:	Moderate		Limited Inspection							
Protection System:	Gabion Baskets						Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each		4							
Comments:	Embankments are moderately sloped, well vegetated, and stable									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams	Length:								
Element Name:	Slope Protection	Width:								
Location:	NE, NW, SW & SE Side of Structure		Height:							
Material:	Gabion Baskets		Count (items):	4						
Element Type:	Slope Protection		Total Quantity:	4		Each				
Environment:	Moderate		Limited Inspection							
Protection System:	None						Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each		4	1						
Comments:	Generally in good condition - Baskets at the southwest are leaning towards channel.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams	Length:								
Element Name:	Streams and Waterways	Width:								
Location:	Under structure		Height:							
Material:	Native		Count (items):	All						
Element Type:	Streams		Total Quantity:	All		N/A				
Environment:	Benign		Limited Inspection							
Protection System:	None						Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Low volume and low flow from south to north with no visible obstructions noted. Light debris present at north channel									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Barriers	Install barriers and end-treatments			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 48,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Thompson Rd & Black Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC003



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Thompson Rd & Black Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC003



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Thompson Rd & Black Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC003



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Thompson Rd & Black Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC003



Photo 7 Light scaling along bottom haunches of culvert (typical)



Photo 8 Leaking at second joint from the south

MUNICIPAL STRUCTURE INSPECTION FORM

Thompson Rd & Black Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC003



Photo 9 Light spalls on North end of culvert (typical throughout)



Photo 10 Southwest gabion wall leaning towards channel

Structure Condition Summary Form

Structure Name

Thompson Rd & Black Creek MD Culvert

Structure Number

CUC003

Date of Inspection

2022/11/25

Project No.

22087

Consultant

HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Approach Slabs	Sq.m	140.00	0.00					0	0		00	00
Culvert	Barrel	Sq.m	350.00	203.52		195.52	8.00		71232	52444	74	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00
									73392	54064			
Bridge Condition Index (BCI)	73.66												

Inventory Data:

Structure Name		Cayer Rd & Castor Creek Extension MD Culvert							
Main Hwy/Road #	Cayer Rd	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		2.4km South of County Rd 13							
Latitude	45.1211	Longitude	-75.36599						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	List/n.d. <input type="checkbox"/>				
			Design./not list <input type="checkbox"/>	Design. & List <input type="checkbox"/>					
MTO Region	40 - Eastern	Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>					
			Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>					
MTO District	42 - Ottawa	Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG	AADT	668		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	2-Cell Precast Concrete Box Culvert	Interchange Number	<input type="checkbox"/>						
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	8.5 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	<input type="checkbox"/> sq. m	Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>					
			School <input type="checkbox"/>	Bicycle <input type="checkbox"/>					
Roadway Width	6.0 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	30 Degrees	Direction of Structure	North/South						
No. of Spans	2	Fill on Structure	0.3 m						
Culvert Length	18 m								
Span Lengths	4.0, 4.0 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	73.99		
OSIM		2022	73.64		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study	<input checked="" type="checkbox"/>			
Material Condition Survey				
Detailed Deck Condition Survey:	<input checked="" type="checkbox"/>			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>			
Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Timber Investigation:	<input checked="" type="checkbox"/>			
Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/>			
Underwater Investigation:	<input checked="" type="checkbox"/>			
Fatigue Investigation:	<input checked="" type="checkbox"/>			
Seismic Investigation:	<input checked="" type="checkbox"/>			
Structure Evaluation:	<input checked="" type="checkbox"/>			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/>			
Monitoring Crack Widths:	<input checked="" type="checkbox"/>			
Investigation Notes:				

Overall Structure Notes:						
Recommended Work on	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace		
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years		<input type="checkbox"/> 6 to 10 years			
Overall Comments:	Structure is in generally good condition. Edge and transverse alligator cracks, along with potholes noted in asphalt wearing surface. Barrier and end-treatments have been recently replaced. Scaling, spalls, ecr, and cracks noted on concrete barrels. Large obstructions at inlet of both barrels should be removed.					
Date of Next Inspection:	2024					

Suspected Performance Deficiencies

- | | | |
|---|--|--|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |
| Maintenance Needs | | |
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	42.7
Element Name:	Barriers	Width:	
Location:	East & West Side of Structure	Height:	
Material:	Steel / Wood	Count (items):	2
Element Type:	Steel Flex Beam on Wood Posts	Total Quantity:	85.4 m
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m		85.40
Comments:	Guide rail and end treatments have been recently replaced.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	6
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	360.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		353.40
Comments:	Edge cracking, medium potholes, and transverse alligator cracks present throughout.		
Recommended Work:	Rehab	Replace	Maintenance Needs: 15
	1-5 years	6-10 years	Urgent X 1 year 2 years
	Rout and seal asphalt wearing surface		

Element Group:	Culverts	Length:	18.0
Element Name:	Barrels	Width:	4
Location:	Below Roadway	Height:	3.2
Material:	Precast Concrete	Count (items):	2
Element Type:	Precast Concrete Box culverts	Total Quantity:	374.4 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		364.40
Comments:	Narrow to medium cracks noted on barrier walls. Spalls with ECR noted on top of deck ends at inlet and outlet. Light scaling present on vertical faces of barrel ends. Map cracking (AAR) noted on barrel walls. Second joint from the East is leaking.		
Recommended Work:	Rehab	Replace	Maintenance Needs: 8
	1-5 years	6-10 years	Urgent x 1 year 2 years
Concrete repairs	Concrete repairs to barrel		

Element Group:	Foundations		Length:				
Element Name:	Foundation (Below Ground Level)		Width:				
Location:	Below Barrel		Height:				
Material:	Unknown		Count (items):				
Element Type:	Unknown		Total Quantity:	All		N/A	
Environment:	Benign		Limited Inspection	X			
Protection System:	Unknown					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	N/A		All				
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year	2 years

Element Group:	Embankments and Streams		Length:				
Element Name:	Embankments		Width:				
Location:	NE, NW, SW & SE Side of Structure		Height:				
Material:	Gravel		Count (items):	4			
Element Type:	Embankment		Total Quantity:	4		Each	
Environment:	Moderate		Limited Inspection				
Protection System:	Vegetation / Gabion baskets					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		4				
Comments:	Embankments are moderately sloped, well vegetated, and stable						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year	2 years

Element Group:	Embankments and Streams		Length:				
Element Name:	Slope Protection		Width:				
Location:	NE, NW, SW & SE Side of Structure		Height:				
Material:	Vegetation / Gabion baskets		Count (items):	4			
Element Type:	Slope Protection		Total Quantity:	4		Each	
Environment:	Moderate		Limited Inspection				
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	Each		4				
Comments:	Generally in good condition.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year	2 years

Element Group:	Embankments and Streams			Length:					
Element Name:	Streams and Waterways			Width:					
Location:	Under structure			Height:					
Material:	Native			Count (items):	All				
Element Type:	Streams			Total Quantity:	All				
Environment:	Benign			Limited Inspection				N/A	
Protection System:	None						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Shallow, low volume and low flow from west to east with large channel obstructions at inlet.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 18				
		1-5 years		6-10 years		Urgent	x	1 year	2 years
					Remove obstruction				

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Castor Extension MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC004



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Castor Extension MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC004



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Castor Extension MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC004



Photo 5 East elevation



Photo 6 West elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Castor Extension MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC004



Photo 7 Recently installed guide rail and end-treatments



Photo 8 Medium pothole and transverse alligator cracks in approach wearing surface

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Castor Extension MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC004




Photo 9 Light spall on south wall of south barrel (typical)



Photo 10 Spall with damp stain on north barrel soffit (typical)



Photo 11 Spall with ECR at northeast barrel end



Photo 12 Scaling and cracks at west barrel ends (typical)

MUNICIPAL STRUCTURE INSPECTION FORM

Cayer Rd & Castor Extension MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC004



Photo 13 Leaking at second joint from East



Photo 14 Heavy/Large obstructions at culvert inlet

Structure Condition Summary Form

Structure Name Cayer Rd & Castor Extension MD Culvert
Structure Number CUC004
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	85.40		85.40			0	0		00	00
	Wearing Surface	Sq.m	6.00	360.00		353.40	3.60	3.00	2160	1599	74	00	15
Culvert	Barrel	Sq.m	350.00	374.40		364.40	6.00	4.00	131040	96495	74	00	08
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	18

										133200	98094
Bridge Condition Index (BCI)	73.64										

Inventory Data:

Structure Name	Kerrs Ridge Rd Allowance & Castor Extension MD Culvert									
Main Hwy/Road #	Kerrs Road		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.6km Wset of Jennings Road									
Latitude	45.09437		Longitude	-75.42706						
Owner(s)	Township of North Dundas		Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	Design./not list <input type="checkbox"/>	Cons/not App. <input type="checkbox"/>	Design. & List <input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
MTO Region	40 - Eastern		Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>	Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>			
MTO District	42 - Ottawa		Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG		AADT	49		% Trucks	<input type="checkbox"/>			
Geographic Twp.	<input type="text"/>		Inspection Route Sequence	<input type="text"/>						
Structure Type	Structural Plate Corrugated Steel Pipe Arch Culvert		Interchange Number	<input type="text"/>						
Total Deck Length	<input type="text"/> m		Interchange Structure Number	<input type="text"/>						
Overall Str. Width	4 m		Min. Vertical Clearance	<input type="text"/> m						
Total Deck Area	<input type="text"/> sq. m		Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>	School <input type="checkbox"/>	Bicycle <input type="checkbox"/>			
Culvert Length	15.0 m									
Roadway Width	5.0 m		Detour Length Around Bridge	<input type="text"/> km						
Skew Angle	<input type="text"/> Degrees		Direction of Structure	East						
No. of Spans	1		Fill on Structure	0.8 m						
Span Lengths	4 m									

Historical Data:

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	November 2, 2020	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	63.5		
OSIM		2022	63.50		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 8, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Avasar Pradaliya, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	3 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			X		\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	X			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/>	None	<input type="checkbox"/>	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input checked="" type="checkbox"/> X Replace
Timing of Recommended Work:				1 to 5 years	X	6 to 10 years	
Overall Comments:	Structure is generally in good to fair condition with minor to moderate sag noted in middle of barrel and cracks noted at several bolted connections. Evidence of leakage and efflorescence noted at waterline of west barrel wall. Severe settlement noted on approach wearing surface and no approach barrier observed.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:					
Element Name:	Barrier	Width:					
Location:	NE, SE, NW & SW of Structure	Height:					
Material:	Steel	Count (items):					
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	m				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m						
Comments:	No approach barrier observed at time of inspection. A code compliant approach barrier should be installed when structure is replaced.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Approaches	Length:	60				
Element Name:	Wearing Surface	Width:	5				
Location:	East & West of Structure	Height:					
Material:	Gravel	Count (items):					
Element Type:	Gravel Wearing Surface	Total Quantity:	300.0 m ²				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		80.0	120.0	100.0	9 & 10	
Comments:	Generally approach wearing surface is in fair to poor condition. Severe settlement noted on wearing surface with moderate to severe tire rutting and potholes also noted on wearing surface.						
Recommended Work:		Rehab		Replace	Maintenance Needs: 18		
		1-5 years		6-10 years	Urgent	X 1 year 2 years	
					Regrade gravel wearing surface		

Element Group:	Culverts	Length:	13.7				
Element Name:	Barrels	Width:	4.6				
Location:	Below Roadway	Height:	2.7				
Material:	Corrugated Steel	Count (items):	1				
Element Type:	SPCSP Arch Culvert	Total Quantity:	292.80 m				
Environment:	Benign	Limited Inspection					
Protection System:	Hot Dip Galvanizing					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		213.74	49.78	29.28		
Comments:	Mild to medium sag noted at the middle of the barrel. Light corrosion noted along springline with some cracks noted at bolted connections. Evidence of leakage and efflorescence noted at waterline on west wall. Missing bolts observed throughout barrel.						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
		1-5 years	X	6-10 years	Urgent	1 year 2 years	

Element Group:	Coatings	Length:							
Element Name:	Structural Steel	Width:							
Location:	On Culvert Barrel	Height:							
Material:	Coating	Count (items):							
Element Type:	Coating - Hot Dip Galvanized	Total Quantity:	292.8	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		287.88	2.87	2.05				
Comments:	Minor coating loss noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Barrel	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW Side of Structure	Height:							
Material:	Native Material	Count (items):	4						
Element Type:	Embankment	Total Quantity:	Each						
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Embankments are moderately sloped, well vegetated and appear stable.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams				Length:				
Element Name:	Streams and Waterways				Width:				
Location:	Below Structure				Height:				
Material:	Native				Count (items):	All			
Element Type:	Stream				Total Quantity:	All N/A			
Environment:	Benign				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Moderate volume and flow from north to south with obstructions noted at the south side of structure.								
Recommended Work:		Rehab		Replace	Maintenance Needs:	18			
		1-5 years		6-10 years		Urgent	X	1 year	2 years
Clear obstruction									

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Culverts	Replace Structure	X			\$ 240,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 240,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification
<div></div>



Photo 1 Structure from East approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure



Photo 5 North elevation



Photo 6 South elevation



Photo 7 Severe settlement on east approach wearing surface



Photo 8 Interior of barrel from north side of structure



Photo 9 Light corrosion and missing bolt on east barrel wall



Photo 10 Cracks at bolt line at barrel wall



Photo 11 Evidence of leakage and efflorescence at bolt line on west barrel wall



Photo 12 Debris blocking south side of barrel

Structure Condition Summary Form

Structure Name Kerrs Ridge Rd Allowance & Castor Extension MD Culvert
Structure Number CUS005
Date of Inspection December 8, 2022
Consultant HP Engineering Inc.
Contract Number 22087 (HP)

					Element Qty. in excellent condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity									
Approaches	Wearing Surface	Sq.m	6.00	300.00	0.00	80.00	120.00	100.00	1800	648	36	9 & 10	18
Coatings	Structural steel	Sq.m	80.00	292.8	0	287.88	2.87	2.05	23424	17365	74	00	00
Culvert	Barrel	Sq.m	350.00	292.8	0	213.74	49.78	29.28	102480	63076	62	00	00
Embankments and Streams	Embankments	Each	0.00	4	0	4	0	0	0	0		00	00
	Streams and Waterways	All	0.00	1	0	1	0	0	0	0		00	18
									127704	81089			

Conditon Index 63.5

Inventory Data:

Structure Name	Winchester Main St & henderson Creek MD Culvert							
Main Hwy/Road #	Main St. East	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>
	On Structure <input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure	Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>
Structure Location	0.3km East of Ottawa St.							
Latitude	45.0953686	Longitude	-75.3471575					
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	List/n.d.	<input type="checkbox"/>		
			Desig./not list <input type="checkbox"/>	Desig. & List <input type="checkbox"/>				
MTO Region	40 - Eastern	Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>				
			Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>				
MTO District	42 - Ottawa	Posted Speed	50 km/h	No. of Lanes	2			
Old County	SDG	AADT	1810	% Trucks				
Geographic Twp.		Inspection Route Sequence						
Structure Type	Concrete Rigid Frame (Open Footing)	Interchange Number						
Total Deck Length		Interchange Structure Number						
Overall Str. Width	3.1	Min. Vertical Clearance						
Total Deck Area		Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>				
			School <input type="checkbox"/>	Bicycle <input type="checkbox"/>				
Roadway Width	9.8	Detour Length Around Bridge						
Skew Angle		Direction of Structure	East/West					
No. of Spans	1	Fill on Structure						
Culvert Length	15.3							
Span Lengths	3.1							

Historical Data:

Year Built		Year of Last Major Rehab.	
Last OSIM Inspection		Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	63.17		
OSIM		2022	58.96		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy, Light rain				
Temperature:	4 °C				

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 5,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years					
Overall Comments:	Minor rehabilitation in 1-5 years. Structure is in generally fair condition. Cracks noted in asphalt wearing surface. Barrier over structure is leaning outwards. Spalls, cracks, scour, and scaling noted throughout concrete culvert barrel and inlet components. A code-compliant barrier and end-treatments should be installed above the structure.						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	

Maintenance Needs

01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Barriers	Length:	5
Element Name:	Railing Systems	Width:	
Location:	North & South side of structure	Height:	
Material:	Steel	Count (items):	2
Element Type:	Steel railing	Total Quantity:	10 m
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units m	Exc.	Good 5.00
			Fair 5.00
			Poor*
Comments:	Generally in good to fair condition - North barrier is leaning outwards. No approach barriers present - A code compliant barrier and end-treatments should be installed above structure.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Approached	Length:	12
Element Name:	Curb and Gutters	Width:	
Location:	North and South sides of structure	Height:	
Material:	Cast-in-place concrete	Count (items):	2
Element Type:	Curb and Gutters	Total Quantity:	24 m
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units m	Exc.	Good 21.00
			Fair 2.00
			Poor* 1.00
Comments:	Medium scaling and wide cracks noted throughout.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	9.8
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	588.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units m2	Exc.	Good 579.18
			Fair 5.88
			Poor* 2.95
Comments:	Wide map cracking was noted above the structure, with ponding observed at the north above the structure		
Recommended Work:	Rehab	Replace	Maintenance Needs: 15
	1-5 years	6-10 years	Urgent X 1 year 2 years
	Rout and seal asphalt wearing surface		

Element Group:	Culverts	Length:							
Element Name:	Inlet Components	Width:							
Location:	Southeast Side of Structure	Height:							
Material:	Precast Concrete	Count (items):							
Element Type:	Stacked Concrete Block Retaining Wall	Total Quantity:	20.00	m2					
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m2	Exc.	Good 2.40	Fair 1.40	Poor*	0.2			
Comments:	Light to medium erosion/degradation and moderate scaling noted								
Recommended Work:	X	Rehab		Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years
Concrete repairs									

Element Group:	Culvert	Length:							
Element Name:	Inlet Components	Width:							
Location:	Southwest side of structure	Height:							
Material:	Cast-in-place Concrete	Count (items):							
Element Type:	Reinforced concrete wingwalls	Total Quantity:	4.80	m2					
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m2	Exc.	Good 3.20	Fair 1.20	Poor*	0.40			
Comments:	Medium erosion/degradation and spalls noted throughout.								
Recommended Work:	X	Rehab		Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years
Concrete repairs									

Element Group:	Culverts	Length:	15.3						
Element Name:	Barrels	Width:	3.1						
Location:	Below Roadway	Height:	1.5						
Material:	Cast-in-place concrete	Count (items):	1						
Element Type:	Concrete Rigid Frame (Open footing)	Total Quantity:	93.33	m2					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m2	Exc.	Good 58.33	Fair 24.00	Poor*	11.00			
Comments:	Severe scaling, spalling, and scour noted throughout the culvert barrel. Severe localized scour noted at the southwest barrel wall near inlet retaining wall. Rust and corrosion stains noted at and around steel in barrel soffit.								
Recommended Work:	X	Rehab		Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years
Concrete repairs									

Element Group:	Foundations	Length:						
Element Name:	Foundation (Below Ground Level)	Width:						
Location:	Below Barrel	Height:						
Material:	Unknown	Count (items):						
Element Type:	Unknown	Total Quantity:	All	N/A				
Environment:	Benign	Limited Inspection	X					
Protection System:	Unknown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Embankment	Total Quantity:	4	Each				
Environment:	Moderate	Limited Inspection						
Protection System:	Rip-Rap						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4					
Comments:	Embankments are moderately sloped, well vegetated, and stable							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope Protection	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Rip-Rap	Count (items):	4					
Element Type:	Slope Protection	Total Quantity:	4	Each				
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each				4			
Comments:	Rip-Rap material was not observed at the time of inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams			Length:					
Element Name:	Streams and Waterways			Width:					
Location:	Under structure			Height:					
Material:	Native			Count (items):	All				
Element Type:	Streams			Total Quantity:	All				
Environment:	Benign			Limited Inspection			N/A		
Protection System:	None						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Low volume and low flow from south to north with no visible obstructions noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent			
						1 year	2 years		

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Barrel	Concrete Repairs		X		\$ 27,500.00
Barriers	Install barriers and end-treatments			x	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 75,500.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ 35,000.00
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 35,000.00

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Winchester Main St. & Henderson Creek MD Culvert SITE PHOTOGRAPHS

Site No.:CUC006



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Winchester Main St. & Henderson Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC006



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Winchester Main St. & Henderson Creek MD Culvert SITE PHOTOGRAPHS

Site No.:CUC006



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Winchester Main St. & Henderson Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC006



Photo 7 North barrier railing leaning outwards



Photo 8 Scaling and cracks on southwest approach curb and gutter (typical)

MUNICIPAL STRUCTURE INSPECTION FORM

Winchester Main St. & Henderson Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC006



Photo 9 Map cracking on west approach wearing surface



Photo 10 Scaling, degradation, and spalls on SW concrete retaining wall

MUNICIPAL STRUCTURE INSPECTION FORM

Winchester Main St. & Henderson Creek MD Culvert SITE PHOTOGRAPHS

Site No.:CUC006



Photo 11 Scaling on SE concrete block retaining wall



Photo 12 View through culvert barrel from the north side



Photo 13 Cracks, scaling, spalls, staining, and scour throughout culvert (typ.)



Photo 14 Rust and corrosion stains on soffit at section joints

MUNICIPAL STRUCTURE INSPECTION FORM

Winchester Main St. & Henderson Creek MD Culvert SITE PHOTOGRAPHS

Site No.:CUC006



Photo 15 Pipe outlet in East culvert side wall



Photo 16 CSP culvert in West culvert side wall

Structure Condition Summary Form

Structure Name Winchester Main St & Henderson Creek MD Culvert
Structure Number CUC006
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Curb and Gutters	m	25.00	24.00		21.00	2.00	1.00	600	414	69	00	00
	Wearing Surface	Sq.m	6.00	588.00		579.18	5.88	2.94	3528	2620	74	00	15
Barriers	Railing Systems	m	200.00	10.00		5.00	5.00		2000	1150	58	00	00
Culvert	Inlet Components	Sq.m	350.00	8.80		5.60	2.60	0.60	3080	1834	60	00	00
	Barrel	Sq.m	350.00	93.33		58.33	24.00	11.00	32666	18672	57	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
Embankments and Streams	Embankments	Each	0.00	4.00		4.00			0	0		00	00
	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00
									41874	24690			
Bridge Condition Index (BCI)	58.96												

Inventory Data:

Structure Name		Guy Rd & East Justus MD Culvert							
Main Hwy/Road #	Guy Road	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		X	Rail	<input type="checkbox"/>	Road	X	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	X	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		2.5km West of County Rd 31							
Latitude	45.0502886	Longitude	-75.35644						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	Design./not list <input type="checkbox"/>	Design. & List <input type="checkbox"/>	List/n.d. <input type="checkbox"/>		
MTO Region	40 - Eastern	Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>	Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>			
MTO District	42 - Ottawa	Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG	AADT	152		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	Cast-in-Place Concrete Box Culvert	Interchange Number	<input type="checkbox"/>						
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	4.2 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	<input type="checkbox"/> sq. m	Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>	School <input type="checkbox"/>	Bicycle <input type="checkbox"/>			
Culvert Length	12.8 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Roadway Width	6.0 m	Direction of Structure	East/West						
Skew Angle	<input type="checkbox"/> Degrees	Fill on Structure	0.6 m						
No. of Spans	1								
Span Lengths	4.2 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	November 4, 2020	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	75		
OSIM		2022	74		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 8, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	2° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			x		
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
		Total Costs			\$ -
Investigation Notes: Rehabilitation Study for Guiderail Only					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years	<input checked="" type="checkbox"/> 6 to 10 years					
Overall Comments:	Structure is overall in good condition. Wide crack on barrel wall near waterline, and some localized honeycombing also observed. No approach barrier observed at time of inspection. A code compliant barrier should be replaced.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	

Maintenance Needs

01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:							
Element Name:	Barrier	Width:							
Location:	NE, SE, NW & SW of Structure	Height:							
Material:	Steel	Count (items):							
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	m						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	m					8			
Comments:	No approach barrier noted at time of inspection. A code compliant approach barrier should be installed.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent	1 year		2 years

Element Group:	Approaches	Length:	60						
Element Name:	Wearing Surface	Width:	6						
Location:	East and West Side of Structure	Height:							
Material:	Asphalt	Count (items):							
Element Type:	Asphalt Surface Treatment	Total Quantity:	360.0 m ²						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	m ²		358.5	1.0	0.5				
Comments:	Light ravelling along wearing surface observed. Alligator cracks observed along both edges, and potholes noted on south edge of wearing surface.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 12				
		1-5 years		6-10 years		Urgent	1 year	X	2 years
					Repair asphalt surface treatment and patch pothole				

Element Group:	Culverts	Length:	12.8						
Element Name:	Barrels	Width:	4.2						
Location:	East Side of Structure	Height:	2.5						
Material:	Other	Count (items):							
Element Type:	Expansion Joint Armouring	Total Quantity:	171.52 m						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	m		169.02	2.0	0.5				
Comments:	Wide cracks noted near waterline on barrel wall. Localized honeycombing also noted on walls.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs: 8				
	X	1-5 years		6-10 years		Urgent	1 year	X	2 years
					Concrete repairs				

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Abutment Walls and Wingwalls	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW Side of Structure	Height:							
Material:	Native Material	Count (items):	4						
Element Type:	Embankment	Total Quantity:	4 Each						
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		3.00	1					
Comments:	Embankments are moderately sloped, well vegetated with some moderate erosion noted on northwest corner.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Below Structure	Height:							
Material:	Native	Count (items):	All						
Element Type:	Stream	Total Quantity:	All N/A						
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A			All					
Comments:	Low volume and low flow from north to south with debris blocking outlet of barrel.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 18				
		1-5 years		6-10 years		Urgent	X	1 year	2 years
Remove debris									

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Approaches	Install Code Compliant Barrier			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 48,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>



Photo 1 Structure from east approach



Photo 2 East approach from centre of structure



Photo 3 West approach from centre of structure



Photo 4 North elevation



Photo 5 South elevation



Photo 6 Potholes and alligator cracks on south edge of wearing surface



Photo 7 Typical view of east barrel wall



Photo 8 Honeycombing on east wall



Photo 9 Debris blocking outlet of structure

Structure Condition Summary Form

Structure Name Guy Rd & East Justus MD Culvert
Structure Number CUC007
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	360.00	0.00	358.50	1.00	0.50	2160	1616	75	00	12
Culvert	Barrel	Sq.m	350.00	171.52	0.00	169.02	2.00	0.50	60032	44648	74	00	08
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	3.00	1.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	0.00	1.00	0.00	0	0		00	00
									62192	46263			
Bridge Condition Index (BCI)	74												

Inventory Data:

Structure Name		Nation Valley Rd and Servage MD Culvert							
Main Hwy/Road #	Nation Valley Rd	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		60m West of Forward Rd							
Latitude	45.07586	Longitude	-75.26137						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
			Design./not list	<input type="checkbox"/>	Design. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern	Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
			Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa	Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG	AADT	117		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	Concrete Rigid Frame (Open Footing)	Interchange Number	<input type="checkbox"/>						
Total Deck Length	7.5 m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	3.5 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	26.3 sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
			School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	4.6 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	<input type="checkbox"/> Degrees	Direction of Structure	East/West						
No. of Spans	1	Fill on Structure	0.6 m						
Culvert Length	7.5 m								
Span Lengths	3.5 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	43.50		
OSIM		2022	42.65		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 20,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:				
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input checked="" type="checkbox"/> Replace
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years		
Overall Comments:	Structure is in generally fair to poor condition. Transverse and longitudinal cracks noted on the asphalt wearing surface above the structure. Cracks, spalls, delamination, ECR and efflorescence noted throughout the concrete culvert barrel. Erosion noted at all corners. No barrier present - A code compliant barrier and end treatments should be installed above the structure.			
Date of Next Inspection:	2024			

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Accessories (Attachments and Signs)	Length:							
Element Name:	Utilities	Width:							
Location:	North Side of Structure	Height:							
Material:	Steel	Count (items):	1						
Element Type:	Utility Pipe	Total Quantity:	1 Each						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		1.00						
Comments:	General in good condition								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Accessories (Attachments and Signs)	Length:							
Element Name:	Utilities	Width:							
Location:	NE, NW, SW & SE Side of Structure	Height:							
Material:	Steel	Count (items):	4						
Element Type:	Hazard Markers	Total Quantity:	4 Each						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		2.00	2.00					
Comments:	Outward rotation of hazard markers noted on the south side								
Recommended Work:		Rehab		Replace	Maintenance Needs:				18
		1-5 years		6-10 years		Urgent	x	1 year	2 years
					Reinstall hazard markers				

Element Group:	Approaches	Length:	60						
Element Name:	Wearing Surface	Width:	4.6						
Location:	Over Culvert	Height:							
Material:	Asphalt	Count (items):							
Element Type:	Asphalt Wearing Surface	Total Quantity:	276.0 m2						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m2		271.00	5.00					
Comments:	Generally in good condition with medium longitudinal and transverse cracks. No barrier present - A code compliant barrier and end treatments should be installed above the structure.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Culverts	Length:							
Element Name:	Inlet Components	Width:							
Location:	South Side of Structure	Height:							
Material:	Cast-in-place concrete	Count (items):							
Element Type:	Reinforced concrete headwall and retaining walls	Total Quantity:	20.00	m2					
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m2	Exc.	Good 4.80	Fair 9.80	Poor* 5.4				
Comments:	Severe delamination and wide cracks noted with scaling and spalls throughout.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Culvert	Length:	7.5						
Element Name:	Barrels	Width:	3.5						
Location:	Below Roadway	Height:	2.4						
Material:	Cast-in-place concrete	Count (items):	1						
Element Type:	Concrete rigid frame (Open footing)	Total Quantity:	88.50 m2						
Environment:	Benign	Limited Inspection							
Protection System:	None		Perform. Deficiencies						
Condition Data:	Units m2	Exc. 35.40		Fair 26.55	Poor* 26.55				
Comments:	Wide cracks, spalls, disintegration, and ECR noted at barrel ends. Severe degradation, wide cracks, and efflorescence noted on barrel walls, along with wide map cracking and honeycombing.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Culverts	Length:							
Element Name:	Outlet Components	Width:							
Location:	North Side of Structure	Height:							
Material:	Cast-in-place concrete	Count (items):							
Element Type:	Reinforced concrete headwall and retaining walls	Total Quantity:	20	m2					
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units m2	Exc.	Good 6.8	Fair 8.8	Poor* 4.4				
Comments:	Severe delamination and wide cracks noted throughout.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Foundations	Length:								
Element Name:	Foundation (Below Ground Level)	Width:								
Location:	Below Barrel	Height:								
Material:	Unknown	Count (items):								
Element Type:	Unknown	Total Quantity:	All	N/A						
Environment:	Benign	Limited Inspection								
Protection System:	Unknown						Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted during the inspection.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams	Length:								
Element Name:	Embankments	Width:								
Location:	NE, NW, SW & SE Side of Structure	Height:								
Material:	Gravel	Count (items):	4							
Element Type:	Embankment	Total Quantity:	4							
Environment:	Moderate	Limited Inspection								
Protection System:	Rip-Rap						Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each		3		1					
Comments:	Minor washout at all four corners with severe washout at the northwest. Moderate vegetation present at all four embankments									
Recommended Work:		Rehab		Replace	Maintenance Needs: 13					
		1-5 years		6-10 years		Urgent	X	1 year		2 years
					Erosion control					

Element Group:	Embankments and Streams	Length:								
Element Name:	Slope Protection	Width:								
Location:	NE, NW, SW & SE Side of Structure	Height:								
Material:	Rip-Rap	Count (items):	4							
Element Type:	Slope Protection	Total Quantity:	4							
Environment:	Moderate	Limited Inspection								
Protection System:	None						Perform. Deficiencies			
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each				4					
Comments:	Rip-Rap material was not observed at the time of inspection.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Under structure	Height:							
Material:	Native	Count (items):	All						
Element Type:	Stream	Total Quantity:	All						
Environment:	Benign	Limited Inspection						N/A	
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Low volume and low flow from south to north with no visible obstructions noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Structure	Replacement		X		\$ 210,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 210,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification
<div></div>

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and Servage MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC008



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and Servage MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC008



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and Servage MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC008



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and Servage MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC008



Photo 7 Transverse crack in asphalt approach wearing surface above structure



Photo 8 Spalling, honeycombing, and efflorescence at north end of barrel (Typ.)

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd and Servage MD Culvert

SITE PHOTOGRAPHS

Site No.:CUC008



Photo 9 Cracks and efflorescence at north barrel, with spalls along deck



Photo 10 Scour/ severe scaling along concrete barrel walls (typ.)



Photo 11 Efflorescence and scaling on barrel soffit (typ.)



Photo 12 Severe scour/deterioration along barrel walls (typical)

Structure Condition Summary Form

Structure Name Nation Valley Rd & Servage MD Culvert
Structure Number CUC008
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	276.00		271.00	5.00		1656	1232	74	00	00
Accessories	Signs	Each	0.00	5.00		3.00	2.00		0	0		00	00
Culvert	Inlet Components	Sq.m	350.00	20.00		4.80	9.80	5.40	7000	2632	38	00	00
	Outlet Components	Sq.m	350.00	20.00		6.80	8.80	4.40	7000	3017	43	00	00
	Barrel	Sq.m	350.00	88.50		35.40	26.55	26.55	30975	13010	42	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
Embankments and Streams	Embankments	Each	0.00	4.00		3.00		1.00	0	0		00	13
	Slope Protection	Each	0.00	4.00		3.00		1.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00
									46631	19890			
Bridge Condition Index (BCI)	42.65												

Inventory Data:

Structure Name	Nation River Rd & Eager MD Culvert																	
Main Hwy/Road #	<table border="1"> <tr> <td>Nation River Road</td> <td></td> </tr> <tr> <td>On Structure</td> <td>X</td> </tr> <tr> <td>Under Structure</td> <td></td> </tr> </table>	Nation River Road		On Structure	X	Under Structure		Services on structure:	<table border="1"> <tr> <td>Navig. Water</td> <td></td> </tr> <tr> <td>Rail</td> <td></td> </tr> </table>	Navig. Water		Rail		<table border="1"> <tr> <td>Non-Navig. Road</td> <td>X</td> </tr> <tr> <td>Ped. Other</td> <td></td> </tr> </table>	Non-Navig. Road	X	Ped. Other	
Nation River Road																		
On Structure	X																	
Under Structure																		
Navig. Water																		
Rail																		
Non-Navig. Road	X																	
Ped. Other																		
		Services under structure:	<table border="1"> <tr> <td>Navig. Water</td> <td></td> </tr> <tr> <td>Rail</td> <td></td> </tr> </table>	Navig. Water		Rail		<table border="1"> <tr> <td>Non-Navig. Road</td> <td>X</td> </tr> <tr> <td>Ped. Other</td> <td></td> </tr> </table>	Non-Navig. Road	X	Ped. Other							
Navig. Water																		
Rail																		
Non-Navig. Road	X																	
Ped. Other																		
Structure Location	1.0 km East of Wallace Road																	
Latitude	44.96921	Longitude	-75.47351															
Owner(s)	Township of North Dundas	Heritage Designation	<table border="1"> <tr> <td>Not Consid: Desig./not list</td> <td>X</td> </tr> <tr> <td>Cons/not App. Desig. & List</td> <td></td> </tr> </table>	Not Consid: Desig./not list	X	Cons/not App. Desig. & List		List/n.d.										
Not Consid: Desig./not list	X																	
Cons/not App. Desig. & List																		
MTO Region	40 - Eastern	Road Class:	<table border="1"> <tr> <td>Freeway</td> <td></td> </tr> <tr> <td>Collector</td> <td></td> </tr> </table>	Freeway		Collector		<table border="1"> <tr> <td>Arterial Local</td> <td>X</td> </tr> </table>	Arterial Local	X								
Freeway																		
Collector																		
Arterial Local	X																	
MTO District	42 - Ottawa	Posted Speed	60 km/h	No. of Lanes	2													
Old County	SDG	AADT	316	% Trucks														
Geographic Twp.		Inspection Route Sequence																
Structure Type	PrecastConcrete Box Culvert	Interchange Number																
Total Deck Length		Interchange Structure Number																
Overall Str. Width	3	Min. Vertical Clearance																
Total Deck Area	17.4	Special Routes:	<table border="1"> <tr> <td>Transit School</td> <td></td> </tr> <tr> <td>Truck Bicycle</td> <td></td> </tr> </table>	Transit School		Truck Bicycle												
Transit School																		
Truck Bicycle																		
Roadway Width	5.8	Detour Length Around Bridge																
Skew Angle		Direction of Structure	North/South															
No. of Spans	1	Fill on Structure	1.5															
Span Lengths	3																	

Historical Data:

Year Built		Year of Last Major Rehab.	
Last OSIM Inspection	October 9, 2020	Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.63		
OSIM		2022	74		

Appraisal Indices:	Comments:
Fatigue:	
Seismic:	
Scour:	
Flood:	
Geometrics:	
Barrier:	
Curb:	
Load Capacity:	
Key Aspects:	

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy				
Temperature:	-1 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			X		\$ 5,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:				\$ -
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
					Total Costs \$ 5,000.00
Investigation Notes: Rehabilitation/Replacement Study is for barrier only.					

Overall Structure Notes:							
Work on Structure:	<input type="checkbox"/>	None	<input checked="" type="checkbox"/> X	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:	<input type="checkbox"/>	X	1 to 5 years	<input type="checkbox"/>	6 to 10 years		
Overall Comments:	Structure is in generally good condition. No approach barrier observed at time of inspection. A code compliant barrier should be installed. Honeycombing and disintegration noted on inlet and outlet components. Active leaking noted at joints in precast barrel segments.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:						
Element Name:	Barrier	Width:						
Location:	NE, SE, NW & SW of Structure	Height:						
Material:	Steel	Count (items):						
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	m					
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m					08		
Comments:	No approach barrier installed at time of inspection. A code compliant barrier should be installed.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Approaches	Length:	60					
Element Name:	Wearing Surface	Width:	5.8					
Location:	North & South of Structure	Height:						
Material:	Asphalt	Count (items):						
Element Type:	Asphalt Surface Treatment	Total Quantity:	348.0 m ²					
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		316	22.0	10.0			
Comments:	North approach is generally in good condition. Moderate ravelling, potholes and patched potholes observed on south wearing surface.							
Recommended Work:		Rehab	Replace	Maintenance Needs: 12				
		1-5 years	6-10 years		Urgent	1 year	X	2 years
				Repair asphalt surface treatment and patch pothole				

Element Group:	Accessories	Length:						
Element Name:	Signs	Width:						
Location:	NE, NW, SE & SW of Strucutre	Height:						
Material:	Steel	Count (items):	4					
Element Type:	Steel Hazard Signs	Total Quantity:	4 each					
Environment:	Severe	Limited Inspection	X					
Protection System:	Hot Dip Galvanizing						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	each		3	1				
Comments:	Hazard signs are generally in good condition. Dents noted in northeast hazard sign.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Culverts	Length:	1.4						
Element Name:	Inlet Components	Width:	0.9						
Location:	West side of Structure	Height:	2.4						
Material:	Precast Concrete	Count (items):	2						
Element Type:	Stacked Concrete Block Retaining Walls	Total Quantity:	9.24	m ²					
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		7.64	0.8	0.8				
Comments:	Disintegration noted at northwest corner of wall. Some disintegration also noted on the back of wall.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 08					
		1-5 years	6-10 years		Urgent		1 year	X	2 years

Element Group:	Culverts	Length:	1.4						
Element Name:	Outlet Components	Width:	0.9						
Location:	East Side of Structure	Height:	2.4						
Material:	Precast Concrete	Count (items):	2						
Element Type:	Stacked Concrete Block Retaining Walls	Total Quantity:	9.24	m ²					
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		7.24	2	2				
Comments:	Moderate to severe honeycombing noted on blocks. Disintegration noted throughout.								
Recommended Work:	X	Rehab	Replace	Maintenance Needs:					
		1-5 years	X	6-10 years		Urgent		1 year	2 years

Element Group:	Culverts	Length:	17.4						
Element Name:	Barrels	Width:	3						
Location:	Below Roadway	Height:	2.1						
Material:	Precast Concrete	Count (items):	1						
Element Type:	Precast Concrete box culvert	Total Quantity:	177.48	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		177.48						
Comments:	Generally in good condition with active leaking noted at all joints between precast segments.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Foundations	Length:						
Element Name:	Foundation (Below Ground Level)	Width:						
Location:	Below Barrel	Height:						
Material:	Unknown	Count (items):						
Element Type:	Unknown	Total Quantity:	All					
Environment:	Benign	Limited Inspection			X			
Protection System:	Unknown							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All			0		
Comments:	No visible evidence of foundation instability was noted during the inspection.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, SE, NW & SW Side of Structure	Height:						
Material:	Native Material	Count (items):	4					
Element Type:	Embankment	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	Vegetation							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4.00					
Comments:	Embankments are moderately sloped, well vegetated and appear to be stable.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:						
Element Name:	Streams and Waterways	Width:						
Location:	Below Structure	Height:						
Material:	Native	Count (items):	All					
Element Type:	Stream	Total Quantity:	All N/A					
Environment:	Benign	Limited Inspection						
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Moderate volume and high flow from west to east with no obstructions noted at time of inspection. Some minor erosion noted at outlet (east side) of barrel.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent		1 year	2 years

Justification



Photo 1 Structure from north approach



Photo 2 Structure from south approach



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure



Photo 5 East elevation



Photo 6 West elevation



Photo 7 Potholes and patched potholes noted on south wearing surface



Photo 8 Disintegration on southeast block wall



Photo 9 Honeycombing at northwest block wall



Photo 10 Interior view of barrel from east end



Photo 11 Active leaking at precast barrel joints

Structure Condition Summary Form

Structure Name Nation River Rd & Eager MD Culvert
Structure Number CUC009
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	348.00	0.00	316.00	22.00	10.00	2088	1475	71	00	12
	Inlet Components	Sq.m	350.00	9.24	0.00	7.64	0.80	0.80	3234	2118	65	00	08
Culvert	Outlet Components	Sq.m	350.00	9.24	0.00	7.24	2.00	2.00	3234	2181	67	00	00
	Barrel	Sq.m	350.00	177.48	0.00	177.48	0.00	0.00	62118	46589	75	00	00
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									70674	52361			

Bridge Condition Index (BCI)

74

Inventory Data:

Structure Name	Marionville Rd & Lough MD Culvert																	
Main Hwy/Road #	<table border="1"> <tr> <td>Marionville Road</td> <td></td> </tr> <tr> <td>On Structure</td> <td>X</td> </tr> <tr> <td>Under Structure</td> <td></td> </tr> </table>	Marionville Road		On Structure	X	Under Structure		Services on structure:	<table border="1"> <tr> <td>Navig. Water</td> <td></td> </tr> <tr> <td>Rail</td> <td></td> </tr> </table>	Navig. Water		Rail		<table border="1"> <tr> <td>Non-Navig. Road</td> <td>X</td> </tr> <tr> <td>Ped. Other</td> <td></td> </tr> </table>	Non-Navig. Road	X	Ped. Other	
Marionville Road																		
On Structure	X																	
Under Structure																		
Navig. Water																		
Rail																		
Non-Navig. Road	X																	
Ped. Other																		
		Services under structure:	<table border="1"> <tr> <td>Navig. Water</td> <td></td> </tr> <tr> <td>Rail</td> <td></td> </tr> </table>	Navig. Water		Rail		<table border="1"> <tr> <td>Non-Navig. Road</td> <td>X</td> </tr> <tr> <td>Ped. Other</td> <td></td> </tr> </table>	Non-Navig. Road	X	Ped. Other							
Navig. Water																		
Rail																		
Non-Navig. Road	X																	
Ped. Other																		
Structure Location	0.4km East of Rodney Ln																	
Latitude	45.1638561	Longitude	-75.396942															
Owner(s)	Township of North Dundas	Heritage Designation	<table border="1"> <tr> <td>Not Consid. Desig./not list</td> <td>X</td> </tr> <tr> <td>Cons/not App. Desig. & List</td> <td></td> </tr> </table>	Not Consid. Desig./not list	X	Cons/not App. Desig. & List		List/n.d.										
Not Consid. Desig./not list	X																	
Cons/not App. Desig. & List																		
MTO Region	40 - Eastern	Road Class:	<table border="1"> <tr> <td>Freeway</td> <td></td> </tr> <tr> <td>Collector</td> <td></td> </tr> </table>	Freeway		Collector		<table border="1"> <tr> <td>Arterial Local</td> <td>X</td> </tr> </table>	Arterial Local	X								
Freeway																		
Collector																		
Arterial Local	X																	
MTO District	42 - Ottawa	Posted Speed	60 km/h	No. of Lanes	2													
Old County	SDG	AADT	200	% Trucks														
Geographic Twp.		Inspection Route Sequence																
Structure Type	CSP Arch Culvert	Interchange Number																
Total Deck Length		Interchange Structure Number																
Overall Str. Width	3.2	Min. Vertical Clearance																
Total Deck Area		Special Routes:	<table border="1"> <tr> <td>Transit School</td> <td></td> </tr> <tr> <td>Truck Bicycle</td> <td></td> </tr> </table>	Transit School		Truck Bicycle												
Transit School																		
Truck Bicycle																		
Culvert Length	28.7	Detour Length Around Bridge																
Roadway Width	6.0	Direction of Structure	East/West															
Skew Angle	45	Fill on Structure	1.5															
No. of Spans	1																	
Span Lengths	3.2																	

Historical Data:

Year Built		Year of Last Major Rehab.	
Last OSIM Inspection	October 8, 2020	Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.67		
OSIM		2022	74.80		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 8, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Avasar Pradaliya, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	1 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			X		\$ 5,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	X			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
Investigation Notes: Rehabilitation/replacement study is for barrier only					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/>	None	<input checked="" type="checkbox"/> X	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:		<input checked="" type="checkbox"/> X	1 to 5 years		<input type="checkbox"/>	6 to 10 years	
Overall Comments:	Structure is in generally good condition. Existing end treatments are not code compliant and should be repalced. A code compliant barrier should be installed on north edge of roadway. Minor separation between plates at crown and south end of barrel noted. Alligator cracks and medium ravelling noted on wearing surface.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	93.3				
Element Name:	Barrier	Width:					
Location:	SE & SW of Structure	Height:					
Material:	Steel	Count (items):	1				
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	93.3	m			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		89.3	2	2	8	
Comments:	No approach barrier observed on the north side of roadway at time of inspection. Eccentric loader end treatments are not code compliant. A code compliant approach barrier on the north side of the roadway, and end treatments on existing barrier, should be installed. Collision damage noted on barrier.						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
	X	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Approaches	Length:	60				
Element Name:	Wearing Surface	Width:	6				
Location:	East & West of Structure	Height:					
Material:	Asphalt	Count (items):					
Element Type:	Asphalt Wearing Surface	Total Quantity:	360.0	m ²			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		342	12.0	6.0	0	
Comments:	Longitudinal alligator cracks, medium ravelling and cracking at edges noted throughout wearing surface. Patched potholes also observed.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year X 2 years	
					Wearing Surface Repairs		

Element Group:	Accessories	Length:					
Element Name:	Signs	Width:					
Location:	SE & SW of Structure	Height:					
Material:	Steel	Count (items):	2				
Element Type:	Hazard Markers	Total Quantity:	2.0	each			
Environment:	Severe	Limited Inspection					
Protection System:	Hot Dip Galvanizing					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	each		1	1.0			
Comments:	Hazard signs are generally in good condition, with some deflection noted on the southwest sign. Hazard signs should be installed on the north side of roadway.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent X	1 year 2 years	
					Install hazard signs		

Element Group:	Culverts	Length:	28.7							
Element Name:	Barrels	Width:	3.2							
Location:	Below Roadway	Height:	2							
Material:	Corrugated Steel	Count (items):	1							
Element Type:	CSP Arch Culvert	Total Quantity:	380.40 m							
Environment:	Benign	Limited Inspection								
Protection System:	Hot Dip Galvanizing								Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies				
	m		379.30	0.80	0.40					
Comments:	Minor separation noted between steel plates at crown of south end of barrel. Minor rust noted on exposed surface of barrel.									
Recommended Work:		Rehab	X	Replace	Maintenance Needs:					7
	X	1-5 years		6-10 years		Urgent		1 year	X	2 years

Element Group:	Foundations	Length:								
Element Name:	Foundation (Below Ground Level)	Width:								
Location:	Below Barrel	Height:								
Material:	Unknown	Count (items):								
Element Type:	Unknown	Total Quantity:	All							
Environment:	Benign	Limited Inspection			X					
Protection System:	Unknown								Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies				
	N/A		All			0				
Comments:	No visible evidence of foundation instability was noted during the inspection.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams	Length:								
Element Name:	Embankments	Width:								
Location:	NE, SE, NW & SW Side of Structure	Height:								
Material:	Native Material	Count (items):	4							
Element Type:	Embankment	Total Quantity:	Each							
Environment:	Moderate	Limited Inspection								
Protection System:	Slope Proteciton								Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies				
	Each		4.00							
Comments:	Embankments are moderately sloped, well vegetated and appear stable.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Embankments and Streams				Length:				
Element Name:	Slope Protection				Width:				
Location:	NE, SE, NW & SW Side of Structure				Height:				
Material:	Rip-Rap				Count (items):	4			
Element Type:	Stone Slope Protection				Total Quantity:	Each			
Environment:	Moderate				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Rip Rap is present on embankments.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams				Length:				
Element Name:	Streams and Waterways				Width:				
Location:	Below Structure				Height:				
Material:	Native				Count (items):	All			
Element Type:	Stream				Total Quantity:	N/A			
Environment:	Benign				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Low volume and low flow from south to north with no evidence of obstructions noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Barriers	Install Code Compliant Barrier on North Side of Roadway			X	\$ 36,000.00
	Install Code Compliant End Treatments on South Barrier			X	\$ 12,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 48,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>

MARIONVILLE Rd LOUGH MD CULVERT

CULVERT

SITE PHOTOGRAPHS

Site No.:CUS001



Photo 1 Structure from east approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure



Photo 5 North elevation



Photo 6 South elevation



Photo 7 Eccentric end loader at southwest corner of approach



Photo 8 Edge cracking on northwest edge of approach



Photo 9 Localized rust spots on exterior of barrel at south end



Photo 10 Interior of barrel from south end of barrel



Photo 11 Minor separation at plate connection at south end of barrel



Photo 12 Rip rap slope protection at southwest embankment

Structure Condition Summary Form

Structure Name Marionville Rd Lough MD Culvert
Structure Number CUS001
Date of Inspection December 8, 2022
Consultant HP Engineering Inc.
Contract Number 22087 (HP)

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in	Element Quantity in	Element Quantity in	Element Quantity in	Total Replaceme nt Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
					excellent condition (1.00)	Good Condition (0.75)	Fair Condition (0.4)	Poor Condition (0)					
Accessories	Signs	Each	0.00	2	0	1	2	0	0	0			0000
Approaches	Barrier	m	0.00	93.3	0	89.3	2	2	0	0			0800
	Wearing Surface	Sq.m	6.00	360.00	0.00	342.00	12.00	6.00	2160	1568	73		0012
Culvert	Barrel	Sq.m	350.00	380.4	0	379.3	0.8	0.4	133140	99678	75		0007
Embankments and	Embankments	Each	0.00	4	0	4	0	0	0	0			0000
Streams	Slope Protection	Each	0.00	4	0	4	0	0	0	0			0000
	Streams and Waterways	All	0.00	1	0	1	0	0	0	0			0000
									135300	101246			

Conditon Index 74.8

Inventory Data:

Structure Name		Carruthers Rd & Muffat Creek MD Culvert							
Main Hwy/Road #	Belmade Rd	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		0.85km East of County Rd 7							
Latitude	45.1917335	Longitude	-75.2836435						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
			Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern	Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
			Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa	Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG	AADT	100		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	SPCSP Arch Culvert	Interchange Number	<input type="checkbox"/>						
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	3.7 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	<input type="checkbox"/> sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
			School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	15.3 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	5.8 Degrees	Direction of Structure	East/West						
No. of Spans	1	Fill on Structure	0.5 m						
Span Lengths	3.7 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.57		
OSIM		2022	67.02		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy, Light rain				
Temperature:	3 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			X		\$ 5,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	X			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	X			
	Concrete Substructure Condition Survey:	X			
	Detailed Coating Condition Survey:	X			
	Detailed Timber Investigation:	X			
	Post-Tensioned Strand Investigation:	X			
Underwater Investigation:		X			
Fatigue Investigation:		X			
Seismic Investigation:		X			
Structure Evaluation:		X			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	X			
	Monitoring Crack Widths:	X			
Investigation Notes:					

Overall Structure Notes:								
Recommended Work on	<input type="checkbox"/>	None	<input checked="" type="checkbox"/> X	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input type="checkbox"/>	Replace
Timing of Recommended Work:		<input checked="" type="checkbox"/> X	1 to 5 years		<input type="checkbox"/>	6 to 10 years		
Overall Comments:	Structure is in generally good condition. No barrier present - A code compliant barrier and end-treatments should be installed above the structure. Cracks present in asphalt. Corrosion and galvanization failure below waterline. Minor erosion at embankments. Rout and seal cracks, replace missing nuts in barrel.							
Date of Next Inspection:	2024							

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	5.8
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	348.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		341.04
Comments:	No guide rail present above structure - A code compliant barrier and end treatments should be installed above the structure. Wide and medium transverse cracks noted above structure. Light longitudinal cracks and light raveling noted.		
Recommended Work:	Rehab	Replace	Maintenance Needs: 15
	1-5 years	6-10 years	Urgent x 1 year 2 years
Rout and seal asphalt wearing surface			

Element Group:	Culverts	Length:	16.8
Element Name:	Barrels	Width:	3.7
Location:	Below Roadway	Height:	2.6
Material:	Corrugated Steel	Count (items):	1
Element Type:	SPCSP Arch Culvert	Total Quantity:	185.5 m2
Environment:	Benign	Limited Inspection	
Protection System:	Hot Dip Galvanized		
Condition Data:	Units	Exc.	Good
	m2		154.5
Comments:	Evidence of localized dent was noted. Moderate corrosion at and below waterline. 4x missing nuts in the pipe arch walls. Minor sagging under roadway and minor deformation at south end.		
Recommended Work:	Rehab	Replace	Maintenance Needs: 18
	1-5 years	6-10 years	Urgent x 1 year 2 years
Replace missing nuts in barrel			

Element Group:	Coating	Length:	
Element Name:	Structural Steel	Width:	
Location:	On culvert barrel	Height:	
Material:	Other	Count (items):	
Element Type:	Structural steel coating	Total Quantity:	185.5 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		123.6
Comments:	Generally in good condition. Galvanizing failure at bottom 1/3 of pipe.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Foundations	Length:						
Element Name:	Foundation (below ground level)	Width:						
Location:	Below barrel	Height:						
Material:	unknown	Count (items):						
Element Type:	unknown	Total Quantity:	All	N/A				
Environment:	Benign	Limited Inspection		x				
Protection System:	Unkown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SW & SE sides of structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Embankments	Total Quantity:	4	Each				
Environment:	Moderate	Limited Inspection	X					
Protection System:	Rip-Rap						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		2	2.0				
Comments:	Embankments are moderately sloped with minor erosion at NW and NE corners							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	
				Erosion control				

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope protection	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Rip-Rap	Count (items):	4					
Element Type:	Embankment	Total Quantity:		Each				
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4	2				
Comments:	Generally in good condition. (Well vegetated) - rip-rap stone was missing at NW and NE corners							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:					
Element Name:	Streams and Waterways	Width:					
Location:	Under structure	Height:					
Material:	Native	Count (items):		All			
Element Type:	Stream	Total Quantity:		All N/A			
Environment:	Benign	Limited Inspection					
Protection System:	None						Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	N/A		All				
Comments:	Medium volume and no flow with no visible flow obstruction noted						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years		Urgent	1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Barriers	Install code compliant approach barrier and end-treatments			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ -

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Carruthers Rd & Muffat MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS002



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Carruthers Rd & Muffat MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS002



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Carruthers Rd & Muffat MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS002



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Carruthers Rd & Muffat MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS002



Photo 7 Transverse Crack in Approach Wearing Surface



Photo 8 Sagging in pipe arch below roadway



Photo 9 Loss of Rip-Rap at embankments (Typical)




Photo 10 Missing nut in barrel (Typical)

Structure Condition Summary Form

Structure Name

Carruthers Rd & Muffat Creek MD Culvert

Structure Number

CUS002

Date of Inspection

2022/11/25

Project No.

22087

Consultant

HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	348.00		341.04	3.48	3.48	2088	1543	74	00	15
Culvert	Barrel	Sq.m	350.00	185.40		154.50	30.90		64890	44882	69	00	00
Coatings	Structural steel	Sq.m	80.00	185.40		123.60	30.90	30.90	14832	8405	57	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		2.00	2.00		0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		2.00	2.00		0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

81810

54830

Bridge Condition Index (BCI)

67.02

Inventory Data:

Structure Name	Allen Road & Allen Creek MD Culvert									
Main Hwy/Road #	Allen Road	Services on Structure:	Navig. Water	<input type="checkbox"/>	Non-Navig. Water	<input type="checkbox"/>	Ped.	<input type="checkbox"/>		
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure		<input type="checkbox"/>							
		Services under Structure:	Navig. Water	<input type="checkbox"/>	Non-Navig. Water	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>		
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>		
Structure Location	0.5km South of French Settlement Road									
Latitude	45.08615		Longitude	-75.55013						
Owner/Custodian	Township of North Dundas	Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>		
			Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>				
MTO Region	40 - Eastern	Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>				
			Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>				
MTO District	42 - Ottawa	Posted Speed	60 km/h		No. of Lanes	2				
Old County	SDG	AADT	88		% Trucks	<input type="checkbox"/>				
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>							
Structure Type	Corrugated Steel Pipe Arch Culvert	Interchange Number	<input type="checkbox"/>							
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>							
Overall Str. Width	<input type="checkbox"/> 3.10 m	Min. Vertical Clearance	<input type="checkbox"/> m							
Total Deck Area	<input type="checkbox"/> 18.3 sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>				
			School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>				
Roadway Width	<input type="checkbox"/> 5.5 m	Detour Length Around Bridge	<input type="checkbox"/> km							
Skew Angle	<input type="checkbox"/> 5 Degrees	Direction of Structure	North/South							
No. of Spans	<input type="checkbox"/> 1	Fill on Structure	<input type="checkbox"/> 1.6 m							
Span Lengths	<input type="checkbox"/> 3.1 m									

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.75		
OSIM		2022	75		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Sarah Vandergeest P.Eng.		
Others in Party:	Adrian Hu		
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy		
Temperature:	-2 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study:		X		\$ 5,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	X			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
			Total Cost	\$ 5,000.00
Investigation Notes: Rehabilitation/Replacement Study is for approach barrier only				

Overall Structure Notes:				
Recommended Work on Structure:	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:	<input type="checkbox"/> None	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years	
Overall Comments:	Overall barrel is in good to fair condition with some light corrosion noted at waterline and salt stains observed at bolt line udner roadway. Slight sag noted under roadway. No approach barrier observed at time of inspection. A code compliant barrier should be installed.			
Date of Next Inspection:	December 2024			

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	-						
Element Name:	Barrier	Width:							
Location:	NE, SE, NW & SW of Structure		Height:						
Material:	Steel		Count (items):						
Element Type:	Steel Flex Beam on Steel Posts		Total Quantity:	m					
Environment:	Severe		Limited Inspection						
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m					8			
Comments:	No approach barrier observed at time of inspection. A code compliant barrier should be installed.								
Recommended Work:	X	Rehab	Replace	Maintenance Needs:					
	X	1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Approaches	Length:	60						
Element Name:	Wearing Surface	Width:	5.5						
Location:	North & South of Structure		Height:						
Material:	Asphalt		Count (items):	1					
Element Type:	Asphalt Wearing Surface		Total Quantity:	330.0 m ²					
Environment:	Severe		Limited Inspection						
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		320	7	3				
Comments:	Light to medium ravelling and medium to severe section loss noted at edges of wearing surface.								
Recommended Work:		Rehab	Replace	Maintenance Needs: 12					
		1-5 years	6-10 years		Urgent		1 year	X	2 years

Element Group:	Culverts	Length:	18.3						
Element Name:	Barrels	Width:	3.1						
Location:	Below Roadway		Height:	1.2					
Material:	Steel		Count (items):	1					
Element Type:	Corrugated Steel Arch Culvert		Total Quantity:	58.00 m ²					
Environment:	Benign		Limited Inspection	X	Due to w				
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		58.00						
Comments:	Limited inspection due to water level. Light corrosion noted at waterline and salt stains noted at bolt line under the road. Slight sag noted at middle of barrel. Missing bolt noted at west end of barrel.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent		1 year		2 years

Element Group:	Coating	Length:						
Element Name:	Structural Steel	Width:						
Location:	On Culvert Barrel	Height:						
Material:	Coating	Count (items):						
Element Type:	Coating - Hot Dip Galvanizing	Total Quantity:	58.00				m ²	
Environment:	Benign	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units m ²	Exc.	Good	Fair	Poor*			
			56.61	0.93	0.5			
Comments:	Generally in good condition with localized areas of coating failure noted.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Foundation	Length:						
Element Name:	Foundation (below ground level)	Width:						
Location:	Blow Grade	Height:						
Material:	Unknown	Count (items):						
Element Type:	Unknown	Total Quantity:	All					
Environment:	Benign	Limited Inspection	X					
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units All	Exc.	Good	Fair	Poor*			
			100%					
Comments:	No evidence of foundation instability at time of inspection.							
Recommended Work:		Rehab	Replace	Maintenance Nee				0
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments & Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, SE, NW & SW OF Structure	Height:						
Material:	Native Soil	Count (items):						
Element Type:	Embankment	Total Quantity:	4					
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units Each	Exc.	Good	Fair	Poor*			
			4.0					
Comments:	Embankments are moderately sloped well vegetated and appear to be stable.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments & Streams	Length:					
Element Name:	Streams & Waterways	Width:					
Location:	Under Structure	Height:					
Material:	Native	Count (items):					
Element Type:	Stream	Total Quantity:		All			
Environment:	Moderate	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	All		100%			0	
Comments:	Medium volume and low flow from west to east with no flow obstructions noted at time of inspection.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent	1 year	2 years	

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Approach Barrier	Install Code Compliant Approach Barrier			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 48,000.00

Associated Work	Comments	Estimated Cost
Approaches		\$ -
Detours		\$ -
Traffic Control		\$ -
Utilities		\$ -
Right of Way		\$ -
Environmental Study		\$ -
Other		\$ -
Contingencies		\$ -
Total cost:		\$ -

Justification



Photo 1 Structure from north approach



Photo 2 Structure from south approach



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure



Photo 5 East elevation



Photo 6 West elevation



Photo 7 Section loss at east edge of north wearing surface



Photo 8 Light corrosion at waterline at east end of barrel



Photo 9 Slight sag in barrel under road



Photo 10 Missing bolt at west end of barrel

Structure Condition Summary Form

Structure Name Allen RD & Allen Creek MD Culvert
Structure Number CUS003
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	330.00	0.00	320.00	7.00	3.00	1980	1457	74	00	12
Culvert	Barrel	Sq.m	350.00	58.00	0.00	58.00	0.00	0.00	20300	15225	75	00	00
Coatings	Structural steel	Sq.m	80.00	58.00	0.00	58.00	0.00	0.00	4640	3480	75	00	00
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									26920	20162			

Bridge Condition Index (BCI)

75

Structure Name		Jennings Rd & Castor Extension MD Culvert									
Main Hwy/Road #	Jennings Rd		Services on structure:	Navig. Water	<input type="text"/>	Non-Navig.	<input type="text"/>	Ped.	<input type="text"/>		
	On Structure	X		Rail	<input type="text"/>	Road	X	Other	<input type="text"/>		
	Under Structure	<input type="text"/>	Services under structure:	Navig. Water	<input type="text"/>	Non-Navig.	X	Ped.	<input type="text"/>		
				Rail	<input type="text"/>	Road	<input type="text"/>	Other	<input type="text"/>		
Structure Location		2.2km North of Spruit Rd									
Latitude	45.1004		Longitude	-75.42241							
Owner(s)	Township of North Dundas		Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	List/n.d. <input type="checkbox"/>					
				Desig./not list <input type="checkbox"/>	Desig. & List <input type="checkbox"/>						
MTO Region	40 - Eastern		Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>						
				Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>						
MTO District	42 - Ottawa		Posted Speed	50 km/h		No. of Lanes	2				
Old County	SDG		AADT	49		% Trucks	<input type="text"/>				
Geographic Twp.	<input type="text"/>		Inspection Route Sequence		<input type="text"/>						
Structure Type	Structural Plate Corrugated Steel Pipe Arch Culvert		Interchange Number		<input type="text"/>						
Total Deck Length	<input type="text"/>	m	Interchange Structure Number		<input type="text"/>						
Overall Str. Width	<input type="text"/>	m	Min. Vertical Clearance		<input type="text"/> m						
Total Deck Area	<input type="text"/>	sq. m	Special Routes:	Transit <input type="text"/>	Truck <input type="text"/>						
				School <input type="text"/>	Bicycle <input type="text"/>						
Culvert Length	<input type="text"/>	m									
Roadway Width	<input type="text"/>	m	Detour Length Around Bridge		<input type="text"/> km						
Skew Angle	<input type="text"/>	Degrees	Direction of Structure		North/South						
No. of Spans	<input type="text"/>		Fill on Structure		<input type="text"/> m						
Span Lengths	<input type="text"/>	m									

Year Built		Year of Last Major Rehab.	
Last OSIM Inspection	October 8, 2020	Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	66.1		
OSIM		2022	66.00		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 8, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Avasar Pradaliya, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	1 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			x		\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:		x		\$ 2,500.00
	Monitoring Crack Widths:	x			
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/>	None	<input type="checkbox"/>	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input checked="" type="checkbox"/> X Replace
Timing of Recommended Work:		<input checked="" type="checkbox"/> X	1 to 5 years			6 to 10 years	
Overall Comments:	Structure is in generally fair to poor condition. No approach barrier observed at time of inspection. Severe sag noted below roadway, with deformation noted at northwest corner. Wide horizontal cracks at boltline at northeast corner of structure.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:						
Element Name:	Barrier	Width:						
Location:	NE, SE, NW & SW of Structure	Height:						
Material:	Steel	Count (items):						
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	m					
Environment:	Severe	Limited Inspection						
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m							
Comments:	No approach barrier observed at time of inspection. A code compliant approach barrier should be installed when structure is replaced.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Approaches	Length:	60					
Element Name:	Wearing Surface	Width:	5.7					
Location:	North & South of Structure	Height:						
Material:	Gravel	Count (items):						
Element Type:	Gravel Wearing Surface	Total Quantity:	342.0 m ²					
Environment:	Severe	Limited Inspection						
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		300	42.0		9		
Comments:	Moderate to severe tire rutting and potholes noted on wearing surface.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Culverts	Length:	13.7					
Element Name:	Barrels	Width:	4.6					
Location:	Below Roadway	Height:	2.7					
Material:	Corrugated Steel	Count (items):	1					
Element Type:	SPCSP Arch Culvert	Total Quantity:	340.30 m					
Environment:	Benign	Limited Inspection						
Protection System:	Hot Dip Galvanizing							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m		272.24	34.03	34.03	1		
Comments:	Light corrosion noted along springline of barrel. Severe sag noted below roadway with large deformation at northwest corner. Wide horizontal crack at bolt lines at northeast near waterline. .							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Coatings	Length:							
Element Name:	Structural Steel	Width:							
Location:	On Culvert Barrel	Height:							
Material:	Coating	Count (items):							
Element Type:	Coating - Hot Dip Galvanized	Total Quantity:	340.3	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		337.85	1.43	1.02				
Comments:	Minor coating loss noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Barrel	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW Side of Structure	Height:							
Material:	Native Material	Count (items):	4						
Element Type:	Embankment	Total Quantity:	Each						
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Embankments are moderately sloped, well vegetated and appear stable.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams			Length:					
Element Name:	Streams and Waterways			Width:					
Location:	Below Structure			Height:					
Material:	Native			Count (items):	All				
Element Type:	Stream			Total Quantity:	All			N/A	
Environment:	Benign			Limited Inspection					
Protection System:	None						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Low volume and no flow with no obstructions noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Justification



Photo 1 Structure from north approach



Photo 2 Structure from south approach



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure



Photo 5 East elevation



Photo 6 West elevation



Photo 7 Tire rutting and potholes on south approach wearing surface



Photo 8 Deformation at northwest corner of structure



Photo 9 Interior of barrel from east end of structure



Photo 10 Severe sag in middle of barrel



Photo 11 Wide horizontal cracks at bolt line at northeast corner of barrel

Structure Condition Summary Form

Structure Name Jennings Rd & Castor Extension MD Culvert
Structure Number CUS004
Date of Inspection December 8, 2022
Consultant HP Engineering Inc.
Contract Number 22087 (HP)

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in excellent condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	342.00	0.00	300.00	42.00	0.00	2052	1451	71	00	00
Coatings	Structural steel	Sq.m	80.00	340.3	0	337.85	1.43	1.02	27224	20317	75	00	00
Culvert	Barrel	Sq.m	350.00	340.3	0	272.24	34.03	34.03	119105	76227	64	01	00
Embankments and Streams	Embankments	Each	0.00	4	0	4	0	0	0	0		00	00
	Streams and Waterways	All	0.00	1	0	1	0	0	0	0		00	00
									148381	97995			
Conditon Index	66.0												

Inventory Data:

Structure Name	Kerrs Ridge Rd Allowance & Castor Extension MD Culvert									
Main Hwy/Road #	Kerrs Road		Services on structure:	Navig. Water	<input type="text"/>	Non-Navig.	<input type="text"/>	Ped.	<input type="text"/>	
	On Structure	X		Rail	<input type="text"/>	Road	X	Other	<input type="text"/>	
	Under Structure	<input type="text"/>	Services under structure:	Navig. Water	<input type="text"/>	Non-Navig.	X	Ped.	<input type="text"/>	
				Rail	<input type="text"/>	Road	<input type="text"/>	Other	<input type="text"/>	
Structure Location	0.6km Wset of Jennings Road									
Latitude	45.09437			Longitude	-75.42706					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid. Desig./not list	<input checked="" type="checkbox"/>	Cons/not App. Desig. & List	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="text"/>	Arterial	<input type="text"/>	Local	X
				Collector	<input type="text"/>					
MTO District	42 - Ottawa			Posted Speed	60 km/h		No. of Lanes	2		
Old County	SDG			AADT	49		% Trucks	<input type="text"/>		
Geographic Twp.	<input type="text"/>			Inspection Route Sequence	<input type="text"/>					
Structure Type	Structural Plate Corrugated Steel Pipe Arch Culvert			Interchange Number	<input type="text"/>					
Total Deck Length	<input type="text"/> m		Interchange Structure Number	<input type="text"/>						
Overall Str. Width	4 m		Min. Vertical Clearance	<input type="text"/> m						
Total Deck Area	<input type="text"/> sq. m		Special Routes:	Transit	<input type="text"/>	Truck	<input type="text"/>			
				School	<input type="text"/>	Bicycle	<input type="text"/>			
Culvert Length	15.0 m									
Roadway Width	5.0 m		Detour Length Around Bridge	<input type="text"/> km						
Skew Angle	<input type="text"/> Degrees		Direction of Structure	East						
No. of Spans	1		Fill on Structure	0.8 m						
Span Lengths	4 m									

Historical Data:

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text" value="November 2, 2020"/>	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		
Rehab History: (Date / Description):			
<div></div>			

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	63.5		
OSIM		2022	63.50		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 8, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Avasar Pradaliya, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	3 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			x		\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:		x		\$ 2,500.00
	Monitoring Crack Widths:	x			
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/>	None	<input type="checkbox"/>	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input checked="" type="checkbox"/> X Replace
Timing of Recommended Work:	<input type="checkbox"/>		<input type="checkbox"/>	1 to 5 years	<input checked="" type="checkbox"/> X	<input type="checkbox"/>	6 to 10 years
Overall Comments:	Structure is generally in fair to poor condition with minor to moderate sag noted in middle of barrel and cracks noted at several bolted connections. Evidence of leakage and efflorescence noted at waterline of west barrel wall. Severe settlement noted on approach wearing surface and no approach barrier observed.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:					
Element Name:	Barrier	Width:					
Location:	NE, SE, NW & SW of Structure	Height:					
Material:	Steel	Count (items):					
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	m				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m						
Comments:	No approach barrier observed at time of inspection. A code compliant approach barrier should be installed when structure is replaced.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Approaches	Length:	60				
Element Name:	Wearing Surface	Width:	5				
Location:	East & West of Structure	Height:					
Material:	Gravel	Count (items):					
Element Type:	Gravel Wearing Surface	Total Quantity:	300.0 m ²				
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m ²		80.0	120.0	100.0	9 & 10	
Comments:	Generally approach wearing surface is in fair to poor condition. Severe settlement noted on wearing surface with moderate to severe tire rutting and potholes also noted on wearing surface.						
Recommended Work:		Rehab		Replace	Maintenance Needs: 18		
		1-5 years		6-10 years	Urgent	X 1 year 2 years	
					Regrade gravel wearing surface		

Element Group:	Culverts	Length:	13.7				
Element Name:	Barrels	Width:	4.6				
Location:	Below Roadway	Height:	2.7				
Material:	Corrugated Steel	Count (items):	1				
Element Type:	SPCSP Arch Culvert	Total Quantity:	292.80 m				
Environment:	Benign	Limited Inspection					
Protection System:	Hot Dip Galvanizing					Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	m		213.74	49.78	29.28		
Comments:	Mild to medium sag noted at the middle of the barrel. Light corrosion noted along springline with some cracks noted at bolted connections. Evidence of leakage and efflorescence noted at waterline on west wall. Missing bolts observed throughout barrel.						
Recommended Work:		Rehab	X	Replace	Maintenance Needs:		
		1-5 years	X	6-10 years	Urgent	1 year 2 years	

Element Group:	Coatings	Length:							
Element Name:	Structural Steel	Width:							
Location:	On Culvert Barrel	Height:							
Material:	Coating	Count (items):							
Element Type:	Coating - Hot Dip Galvanized	Total Quantity:	292.8	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		287.88	2.87	2.05				
Comments:	Minor coating loss noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Barrel	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW Side of Structure	Height:							
Material:	Native Material	Count (items):	4						
Element Type:	Embankment	Total Quantity:	Each						
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Embankments are moderately sloped, well vegetated and appear stable.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams				Length:				
Element Name:	Streams and Waterways				Width:				
Location:	Below Structure				Height:				
Material:	Native				Count (items):	All			
Element Type:	Stream				Total Quantity:	All N/A			
Environment:	Benign				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Moderate volume and flow from north to south with obstructions noted at the south side of structure.								
Recommended Work:		Rehab		Replace	Maintenance Needs:	18			
		1-5 years		6-10 years		Urgent	X	1 year	2 years
Clear obstruction									

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Culverts	Replace Structure	X			\$ 240,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 240,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification
<div></div>



Photo 1 Structure from East approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure



Photo 5 North elevation



Photo 6 South elevation



Photo 7 Severe settlement on east approach wearing surface



Photo 8 Interior of barrel from north side of structure



Photo 9 Light corrosion and missing bolt on east barrel wall



Photo 10 Cracks at bolt line at barrel wall



Photo 11 Evidence of leakage and efflorescence at bolt line on west barrel wall



Photo 12 Debris blocking south side of barrel

Structure Condition Summary Form

Structure Name Kerrs Ridge Rd Allowance & Castor Extension MD Culvert
Structure Number CUS005
Date of Inspection December 8, 2022
Consultant HP Engineering Inc.
Contract Number 22087 (HP)

					Element Qty. in excellent condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity									
Approaches	Wearing Surface	Sq.m	6.00	300.00	0.00	80.00	120.00	100.00	1800	648	36	9 & 10	18
Coatings	Structural steel	Sq.m	80.00	292.8	0	287.88	2.87	2.05	23424	17365	74	00	00
Culvert	Barrel	Sq.m	350.00	292.8	0	213.74	49.78	29.28	102480	63076	62	00	00
Embankments and Streams	Embankments	Each	0.00	4	0	4	0	0	0	0		00	00
	Streams and Waterways	All	0.00	1	0	1	0	0	0	0		00	18
									127704	81089			

Conditon Index 63.5

Inventory Data:

Structure Name	Spruit Rd & Castor Extension MD Culvert									
Main Hwy/Road #	Spruit Road		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.45km West of Riddell Rd									
Latitude	45.0795168			Longitude	-75.4313356					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	List/n.d. <input type="checkbox"/>			
					Desig./not list <input type="checkbox"/>	Desig. & List <input type="checkbox"/>				
MTO Region	40 - Eastern			Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>				
					Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>				
MTO District	42 - Ottawa			Posted Speed	50 km/h		No. of Lanes	2		
Old County	SDG			AADT	49		% Trucks	<input type="checkbox"/>		
Geographic Twp.	<input type="checkbox"/>			Inspection Route Sequence	<input type="checkbox"/>					
Structure Type	Structural Plate Corrugated Steel Pipe Arch Culvert			Interchange Number	<input type="checkbox"/>					
Total Deck Length	<input type="checkbox"/> m			Interchange Structure Number	<input type="checkbox"/>					
Overall Str. Width	<input type="checkbox"/> 3 m			Min. Vertical Clearance	<input type="checkbox"/> m					
Total Deck Area	<input type="checkbox"/> sq. m			Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>				
					School <input type="checkbox"/>	Bicycle <input type="checkbox"/>				
Culvert Length	<input type="checkbox"/> 13.7 m			Detour Length Around Bridge	<input type="checkbox"/> km					
Roadway Width	<input type="checkbox"/> 4.0 m			Direction of Structure	East/West					
Skew Angle	<input type="checkbox"/> Degrees			Fill on Structure	<input type="checkbox"/> 0.7 m					
No. of Spans	<input type="checkbox"/> 1									
Span Lengths	<input type="checkbox"/> 3 m									

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	November 2, 2020	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	63.37		
OSIM		2022	59.30		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 8, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Avasar Pradaliya, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	1° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			X		\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	X			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/>	None	<input type="checkbox"/>	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input checked="" type="checkbox"/> X Replace
Timing of Recommended Work:		<input checked="" type="checkbox"/> X	1 to 5 years			6 to 10 years	
Overall Comments:	Structure is in generally fair condition. No approach barrier observed at time of inspection. Severe corrosion, perforations and strcutre separation noted at springline. Some leaks and missing bolts at plate connections.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:						
Element Name:	Barrier	Width:						
Location:	NE, SE, NW & SW of Structure	Height:						
Material:	Steel	Count (items):						
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	m					
Environment:	Severe	Limited Inspection						
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m							
Comments:	No approach barrier observed at time of inspection. A code compliant approach barrier should be installed when structure is replaced.							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	4
Location:	East & West of Structure	Height:	
Material:	Gravel	Count (items):	
Element Type:	Gravel Wearing Surface	Total Quantity:	240.0 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		240
Comments:	Wearing surface is generally in good condition.		
Recommended Work:		Rehab	Replace
		1-5 years	6-10 years
			Urgent
			1 year
			2 years

Element Group:	Culverts	Length:	13.7
Element Name:	Barrels	Width:	3
Location:	Below Roadway	Height:	3
Material:	Corrugated Steel	Count (items):	1
Element Type:	SPCSP Arch Culvert	Total Quantity:	129.05 m
Environment:	Benign	Limited Inspection	
Protection System:	Hot Dip Galvanizing		
Condition Data:	Units	Exc.	Good
	m		89.55
Comments:	Medum to severe corrosion, perforations and structural separation at springline. Missing bolts at the connection of the structural plates noted. Minor sagging noted at mid span. Evidence of leakage ntoed at plate overlaps.		
Recommended Work:		Rehab	X
	X	1-5 years	6-10 years
			Urgent
			1 year
			2 years

Element Group:	Coatings	Length:								
Element Name:	Structural Steel	Width:								
Location:	On Culvert Barrel	Height:								
Material:	Coating	Count (items):								
Element Type:	Coating - Hot Dip Galvanized	Total Quantity:	129.05					m ²		
Environment:	Benign	Limited Inspection								
Protection System:	None								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		97.79	16.26	15.00					
Comments:	Medium to severe coating gloss noted throughout barrel.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year	2 years	

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Barrel	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW Side of Structure	Height:							
Material:	Native Material	Count (items):	4						
Element Type:	Embankment	Total Quantity:	Each						
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		2	2					
Comments:	Embankments are moderately sloped, and well vegetated. Washout noted at southwest embankment and erosion noted at stream bank at northwest embankment.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams			Length:					
Element Name:	Streams and Waterways			Width:					
Location:	Below Structure			Height:					
Material:	Native			Count (items):	All				
Element Type:	Stream			Total Quantity:	All N/A				
Environment:	Benign			Limited Inspection					
Protection System:	None							Perform.	
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	N/A				All	15			
Comments:	Medium volume and flow from south to north with no obstructions noted. Severe erosion noted at the northwest side of structure.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 13				
		1-5 years		6-10 years		Urgent	X	1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Culverts	Replace Structure		X		\$ 206,000.00
Approaches	Install Code Compliant approach barrier		X		\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 206,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification
<div></div>



Photo 1 Structure from east approach



Photo 2 Structure from west approach



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure



Photo 5 North elevation



Photo 6 South elevation



Photo 7 Typical view of west approach wearing surface



Photo 8 Interior of barrel from north end




Photo 9 Perforation and separation on west barrel wall of structure



Photo 10 Leaking and missing bolts at plate connections



Photo 11 Erosion at northwest embankment



Photo 12 Erosion and washout noted on southwest embankment

Structure Condition Summary Form

Structure Name Spruit Rd & Castor Extension MD Culvert
Structure Number CUS006
Date of Inspection December 8, 2022
Consultant HP Engineering Inc.
Contract Number 22087 (HP)

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in excellent condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	240.00	0.00	240.00	0.00	0.00	1440	1080	75	00	00
Coatings	Structural steel	Sq.m	80.00	129.05	0	97.79	16.26	15	10324	6388	62	00	00
Culvert	Barrel	Sq.m	350.00	129.05	0	89.55	19.75	19.75	45168	26272	58	01	00
Embankments and Streams	Embankments	Each	0.00	4	0	2	2	0	0	0		00	00
	Streams and Waterways	All	0.00	1	0	0	0	1	0	0		00	13
									56932	33740			

Conditon Index 59.3

Inventory Data:

Structure Name	Liscumb Rd & Tighe MD Culvert				
Main Hwy/Road #	Liscumb Rd	Services on structure:	Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/>	Non-Navig. Road <input checked="" type="checkbox"/> Ped. Other <input type="checkbox"/>	
	On Structure <input checked="" type="checkbox"/>				
	Under Structure <input type="checkbox"/>	Services under structure:	Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/>	Non-Navig. Road <input checked="" type="checkbox"/> Ped. Other <input type="checkbox"/>	
Structure Location	0.6km West of County Rd 3				
Latitude	45.1035524	Longitude	-75.3634268		
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input checked="" type="checkbox"/> Design./not list <input type="checkbox"/>	Cons/not App. Design. & List <input type="checkbox"/> List/n.d. <input type="checkbox"/>	
MTO Region	40 - Eastern	Road Class:	Freeway <input type="checkbox"/> Collector <input type="checkbox"/>	Arterial Local <input checked="" type="checkbox"/>	
MTO District	42 - Ottawa	Posted Speed	60 km/h	No. of Lanes	2
Old County	SDG	AADT	N/A	% Trucks	
Geographic Twp.		Inspection Route Sequence			
Structure Type	SPCSP Arch Culvert	Interchange Number			
Total Deck Length		Interchange Structure Number			
Overall Str. Width	4.5	Min. Vertical Clearance			
Total Deck Area		Special Routes:	Transit <input type="checkbox"/> School <input type="checkbox"/>	Truck Bicycle <input type="checkbox"/>	
Roadway Width	10.0	Detour Length Around Bridge			
Skew Angle	0	Direction of Structure	North/South		
No. of Spans	1	Fill on Structure	0.6		
Culvert Length	15.3				
Span Lengths	4.5				

Historical Data:

Year Built		Year of Last Major Rehab.	
Last OSIM Inspection		Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	70.33		
OSIM		2022	70.25		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 5,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:				
Recommended Work on	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:		<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years	
Overall Comments:	Structure is in generally good condition. No approach barrier present above structure - A code compliant barrier and end treatments should be installed above the structure. Corrosion along springline noted in barrel. Erosion of northeast embankment and washout of southeast embankment encroaching into stream.			
Date of Next Inspection:	2024			

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	60							
Element Name:	Wearing Surface	Width:	10							
Location:	Over Culvert	Height:								
Material:	Gravel	Count (items):								
Element Type:	Gravel Wearing Surface	Total Quantity:	600.0	m2						
Environment:	Severe	Limited Inspection								
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m2		600.00							
Comments:	The approach wearing surface is generally in good condition. No barriers present - A code compliant barrier and end-treatments should be installed above the structure									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Culverts	Length:	15.3							
Element Name:	Barrels	Width:	4.5							
Location:	Below Roadway	Height:	2							
Material:	Corrugated Steel	Count (items):	1							
Element Type:	SPCSP Arch Culvert	Total Quantity:	137.70	m2						
Environment:	Benign	Limited Inspection								
Protection System:	Hot Dip Galvanized							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m2		117.60	20.00	0.1					
Comments:	Moderate corrosion noted along the springlines of culvert with deformation at the southwest end. Barrel appears too short.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Coating	Length:								
Element Name:	Structural Steel	Width:								
Location:	On culvert barrel	Height:								
Material:	Other	Count (items):								
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	137.70	m2						
Environment:	Benign	Limited Inspection								
Protection System:	None							Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m2		125.20	7.50	5.00					
Comments:	Light to moderate coating loss noted along culvert side walls.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Foundations	Length:						
Element Name:	Foundation (below ground level)	Width:						
Location:	Below barrel	Height:						
Material:	unknown	Count (items):						
Element Type:	unknown	Total Quantity:	All	N/A				
Environment:	Benign	Limited Inspection		x				
Protection System:	Unknown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted at the time of inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SW & SE sides of structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Embankments	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	Vegetation						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		2.0	2.0				
Comments:	Embankments are moderately sloped. Moderate erosion at the northeast. Washout present at the southeast encroaching into stream.							
Recommended Work:		Rehab		Replace	Maintenance Needs:		13	
		1-5 years		6-10 years		Urgent	x	1 year
					Erosion control at embankments			

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope protection	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Slope protection	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		2	2				
Comments:	Generally in good condition - See embankment condition notes							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Embankments and Streams			Length:						
Element Name:	Streams and Waterways			Width:						
Location:	Under structure			Height:						
Material:	Native			Count (items):	All					
Element Type:	Stream			Total Quantity:	All					
Environment:	Benign			Limited Inspection				N/A		
Protection System:	None								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Medium volume and flow from west to east with no visible flow obstruction noted.									
Recommended Work:		Rehab		Replace	Maintenance Needs: 18					
		1-5 years		6-10 years		Urgent		1 year	x	2 years
					Clear vegetation					

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Barrier	Install barriers and end-treatments			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 48,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Tighe MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS008



Photo 1 Structure from north approach



Photo 2 Structure from south approach



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Tighe MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS008



Photo 5 East elevation



Photo 6 West elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Liscumb Rd & Tighe MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS008



Photo 7 View of channel west of structure (inlet)



Photo 8 View of channel east of structure (outlet)



Photo 9 View through pipe arch barrel from the west



Photo 10 Deformation at inlet on the southwest corner of structure



Photo 11 Erosion and encroachment into barrel at the northwest



Photo 12 Corrosion on pipe arch walls (typ.)

Structure Condition Summary Form

Structure Name Liscumb Rd Tighe MD Culvert
Structure Number CUS008
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	600.00		600.00			3600	2700	75	00	00
Culvert	Barrel	Sq.m	350.00	137.70		117.60	20.00	0.10	48195	33670	70	00	00
Coatings	Structural steel	Sq.m	80.00	137.70		125.20	7.50	5.00	11016	7752	70	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		2.00	2.00		0	0		00	13
Embankments and Streams	Slope Protection	Each	0.00	4.00		2.00	2.00		0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	18
									62811	44122			
Bridge Condition Index (BCI)	70.25												

Inventory Data:

Structure Name	Boyne Rd Kittle Creek MD Culvert									
Main Hwy/Road #	Boyne Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	1.2km East of Kittle Rd									
Latitude	45.1266729			Longitude	-75.261989					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
					Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>		
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>		
					Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>		
MTO District	42 - Ottawa			Posted Speed	60 km/h		No. of Lanes	2		
Old County	SDG			AADT	1000		% Trucks	<input type="checkbox"/>		
Geographic Twp.	<input type="text"/>			Inspection Route Sequence	<input type="text"/>					
Structure Type	2-cell CSP Round Culvert			Interchange Number	<input type="text"/>					
Total Deck Length	<input type="text"/> m			Interchange Structure Number	<input type="text"/>					
Overall Str. Width	3 m			Min. Vertical Clearance	<input type="text"/> m					
Total Deck Area	<input type="text"/> sq. m			Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>		
					School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>		
Roadway Width	18.3 m			Detour Length Around Bridge	<input type="text"/> km					
Skew Angle	8.4 Degrees			Direction of Structure	East/West					
No. of Spans	2			Fill on Structure	0.9 m					
Span Lengths	1.5, 1.5 m									

Historical Data:

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text"/>	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.71		
OSIM		2022	74.64		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy, Light rain				
Temperature:	6° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			x		\$ 5,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
Investigation Notes:	Rehabilitation Study for Approach Barriers Only				\$ 5,000.00

Overall Structure Notes:							
Recommended Work on	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years		<input type="checkbox"/> 6 to 10 years				
Overall Comments:	Structure is generally in good condition. Cracks noted in asphalt wearing surface above structure. Grade differential of +-50mm in granular shoulders. Deformation at midspan joint noted in east culvert with some light corrosion. Minor loss of rip rap noted at the south embankments. A code compliant barrier and end-treatments should be installed above the structure						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	60					
Element Name:	Wearing Surface	Width:	8.4					
Location:	Over Culvert	Height:						
Material:	Asphalt	Count (items):						
Element Type:	Asphalt Wearing Surface	Total Quantity:	504.0	m2				
Environment:	Severe	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units m2	Exc.	Good 491.96	Fair 8.00	Poor* 4.04			
Comments:	Severe transverse cracks above structure noted. Severe longitudinal edge crack noted at the Southwest. Grade difference of +/-50mm noted at shoulders. No barriers present above structure - A code compliant barrier and end-treatments should be installed							
Recommended Work:		Rehab	Replace	Maintenance Needs:				15, 18
		1-5 years	6-10 years		Urgent	1 year	x	2 years
				Rout and seal asphalt, regrade shoulders				

Element Group:	Culverts	Length:	18.3					
Element Name:	Barrels	Width:	1.5					
Location:	Below Roadway	Height:	1.5					
Material:	Corrugated Steel	Count (items):	2					
Element Type:	2-Cell CSP Round culverts	Total Quantity:	172.39	m2				
Environment:	Benign	Limited Inspection						
Protection System:	Hot Dip Galvanized						Perform. Deficiencies	
Condition Data:	Units m2	Exc.	Good 170.39	Fair 2.00	Poor*			
Comments:	Minor sag and light to medium corrosion noted along springline. Minor deformation at east barrel. Center joint o east barrel is slightly misaligned with light to medium corrosion present.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year		2 years

Element Group:	Coating	Length:						
Element Name:	Structural Steel	Width:						
Location:	On culvert barrel	Height:						
Material:	Other	Count (items):						
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	172.4	m2				
Environment:	Benign	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units m2	Exc.	Good 172.4	Fair	Poor*			
Comments:	Generally in good condition							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years		Urgent	1 year		2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (below ground level)	Width:							
Location:	Below barrel	Height:							
Material:	unknown	Count (items):							
Element Type:	unknown	Total Quantity:	All	N/A					
Environment:	Benign	Limited Inspection		x					
Protection System:	Unkown								Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	N/A		All						
Comments:	Foundations are rated for performance only and not material condition.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent	1 year	2 years		

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, NW, SW & SE sides of structure	Height:							
Material:	Vegetation	Count (items):	4						
Element Type:	Embankments	Total Quantity:	4	Each					
Environment:	Moderate	Limited Inspection							
Protection System:	Rip-Rap								Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	Each		2	2.0					
Comments:	Embankments are moderately sloped, well-vegetated, and stable. light erosion present at southwest.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent	1 year	2 years		

Element Group:	Embankments and Streams	Length:							
Element Name:	Slope protection	Width:							
Location:	NE, NW, SW & SE Side of Structure	Height:							
Material:	Rip-Rap	Count (items):	4						
Element Type:	Embankment	Total Quantity:		Each					
Environment:	Moderate	Limited Inspection							
Protection System:	None								Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies			
	Each		4						
Comments:	Generally in good condition with minor loss of rip-rap at the south.								
Recommended Work:		Rehab	Replace	Maintenance Needs:					
		1-5 years	6-10 years		Urgent	1 year	2 years		

Element Group:	Embankments and Streams			Length:	#REF!		
Element Name:	Streams and Waterways			Width:	#REF!		
Location:	Under structure			Height:	#REF!		
Material:	Native			Count (items):	All		
Element Type:	Stream			Total Quantity:	All N/A		
Environment:	Benign			Limited Inspection			
Protection System:	None						Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*		
	N/A		All				
Comments:	Low volume and low flow from north to south with no visible flow obstruction noted.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years		Urgent	1 year	2 years

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Boyne Rd Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS009



Photo 1 Structure from East approach



Photo 2 Structure from West approach

MUNICIPAL STRUCTURE INSPECTION FORM

Boyne Rd Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS009



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Boyne Rd Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS009



Photo 5 North Elevation



Photo 6 South Elevation



Photo 7 Transverse crack in asphalt approach wearing surface above structure



Photo 8 Longitudinal edge cracks and grade difference at shoulders



Photo 9 View through east barrel, looking south



Photo 10 Misalignment of joint in east barrel and localized corrosion



Photo 11 View through west barrel, looking north



Photo 12 Light loss of Rip Rap at southwest embankment

Structure Condition Summary Form

Structure Name Boyne Rd Kittle Creek MD Culvert
Structure Number CUS009
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	504.00		491.96	8.00	4.04	3024	2233	74	00	15
Culvert	Barrel	Sq.m	350.00	172.39		170.39	2.00		60337	45007	75	00	00
Coatings	Structural steel	Sq.m	80.00	172.40		172.40			13792	10344	75	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

Inventory Data:

Structure Name	Development Rd & CPR Railway Culvert									
Main Hwy/Road #	Development Road		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	1.0km South of County Rd 43, South of CPR Rail tracks									
Latitude	45.047765			Longitude	-75.45206					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	Desig./not list <input type="checkbox"/>	Desig. & List <input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
MTO Region	40 - Eastern			Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>	Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>		
MTO District	42 - Ottawa			Posted Speed	60 km/h		No. of Lanes	2		
Old County	SDG			AADT	88		% Trucks	<input type="checkbox"/>		
Geographic Twp.	<input type="text"/>			Inspection Route Sequence	<input type="text"/>					
Structure Type	3-Cell CSP Round Culvert			Interchange Number	<input type="text"/>					
Total Deck Length	<input type="text"/> m			Interchange Structure Number	<input type="text"/>					
Overall Str. Width	4.5 m			Min. Vertical Clearance	<input type="text"/> m					
Total Deck Area	20.4 sq. m			Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>	School <input type="checkbox"/>	Bicycle <input type="checkbox"/>		
Roadway Width	6.4 m			Detour Length Around Bridge	<input type="text"/> km					
Skew Angle	<input type="text"/> Degrees			Direction of Structure	North/South					
No. of Spans	3			Fill on Structure	1 m					
Span Lengths	1.5, 1.5, 1.5 m									

Historical Data:

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	November 2, 2020	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	48.75		
OSIM		2022	41		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	1 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study				<input checked="" type="checkbox"/>	\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:				
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>			
	Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>			
	Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>			
	Detailed Timber Investigation:	<input checked="" type="checkbox"/>			
	Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/>			
Underwater Investigation:		<input checked="" type="checkbox"/>			
Fatigue Investigation:		<input checked="" type="checkbox"/>			
Seismic Investigation:		<input checked="" type="checkbox"/>			
Structure Evaluation:		<input checked="" type="checkbox"/>			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:		<input checked="" type="checkbox"/>		\$ 2,500.00
	Monitoring Crack Widths:	<input checked="" type="checkbox"/>			
		Total Costs			\$ 22,500.00
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input checked="" type="checkbox"/> Replace			
Timing of Recommended Work:	<input checked="" type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years					
Overall Comments:	Structure is in generally poor condition and should be replaced. Severe corrosion and perforations noted on bottom and along spring line of barrel. Severe sag underroadway in top barrel. Separation at midspan of north barrel, with fill entering the barrel.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	

Maintenance Needs

01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:						
Element Name:	Barrier	Width:						
Location:	NE, SE, NW & SW of Structure	Height:						
Material:	Steel	Count (items):						
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	m					
Environment:	Severe	Limited Inspection						
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m					8		
Comments:	No approach barrier observed at time of inspection. A code compliant barrier should be installed during structure replacement.							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years

Element Group:	Approaches	Length:	60					
Element Name:	Wearing Surface	Width:	6.4					
Location:	Over Structure	Height:						
Material:	Asphalt	Count (items):						
Element Type:	Asphalt Surface Treatment	Total Quantity:	384.0 m ²					
Environment:	Severe	Limited Inspection						
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		337.92	30.72	15.36			
Comments:	Medum edge cracking, and potholes noted on wearing surface. Patched potholes noted and some minor settlement noted on both approaches.							
Recommended Work:	X	Rehab		Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years
					Repair asphalt surface treatment and patch pothole			

Element Group:	Culverts	Length:	20.4					
Element Name:	Barrels	Width:	1.5					
Location:	Below Roadway	Height:	1.5					
Material:	Other	Count (items):	3					
Element Type:	Expansion Joint Armouring	Total Quantity:	288.25 m ²					
Environment:	Severe	Limited Inspection	X					
Protection System:	None							Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	m ²		105.25	98	85.0	01 & 02 & 03		
Comments:	Severe corrosion and perforations noted along bottom and springline of culvert. Severe dent noted at east ends of barrel. Severe sag ntoed under roaeway. Limited inspection of top barrel. Separation and partial collapse at midspan of north barrel with fill .							
Recommended Work:		Rehab	X	Replace	Maintenance Needs:			
	X	1-5 years		6-10 years		Urgent	1 year	2 years
					Install supports.			

Element Group:	Coating	Length:								
Element Name:	Structural Steel	Width:								
Location:	On culvert Barrel	Height:								
Material:	Coating	Count (items):								
Element Type:	Hot Dip Galvanizing	Total Quantity:	288.25					m ²		
Environment:	Benign	Limited Inspection								
Protection System:	None								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		80.71	121.1	86.5					
Comments:	Severe coating loss noted throughout barrels.									
Recommended Work:		Rehab	X	Replace	Maintenance Needs:					
	X	1-5 years		6-10 years		Urgent		1 year	2 years	

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Abutment Walls and Wingwalls	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:								
Element Name:	Embankments	Width:								
Location:	NE, SE, NW & SW Side of Structure	Height:								
Material:	Native Material	Count (items):	4							
Element Type:	Embankment	Total Quantity:		Each						
Environment:	Moderate	Limited Inspection								
Protection System:	Vegetation								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each			4						
Comments:	Embankments are moderately sloped and well vegetated with erosion noted at all corners. Debris build-up noted at northeast embankment..									
Recommended Work:		Rehab		Replace	Maintenance Needs: 18 - Clear Debris					
		1-5 years		6-10 years		Urgent		1 year	X	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Below Structure	Height:							
Material:	Native	Count (items):	All						
Element Type:	Stream	Total Quantity:	All	N/A					
Environment:	Benign	Limited Inspection							

Protection System:	None								Perform. Deficiencies	
Condition Data:	Units		Exc.		Good	Fair		Poor*		
	N/A				All					
Comments:	Low volume and no flow with ice build-up noted in waterway.									
Recommended Work:			Rehab		Replace	Maintenance Needs:				
			1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Approaches	Install Approach Barrier			X	\$ -
Barrel	Replace Structure		X		\$ 367,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 367,000.00

Associated Work	Comments	Estimated Cost
Approaches		\$ 40,000.00
Detours		\$ 35,000.00
Traffic Control		
Utilities		\$ -
Right of Way		\$ -
Environmental Study		\$ 10,000.00
Other		\$ -
Contingencies		\$ -
Total cost:		\$ 85,000.00

Justification
<div></div>



Photo 1 Structure from north approach



Photo 2 Structure from south approach



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure



Photo 5 East elevation



Photo 6 West elevation



Photo 7 Wide pattern cracks, asphalt patches and potholes on south wearing surface



Photo 8 Severe corrosion and perforations in south barrel



Photo 9 Interior of south barrel from west end



Photo 10 Large dents in east end of south barrel



Photo 11 Interior of middle barrel from east end of structure



Photo 12 Separation and partial collapse of north barrel



Photo 13 Separation of seam in north barrel

Structure Condition Summary Form

Structure Name Development Rd CPR Railway Culvert
Structure Number CUS010
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	384.00	0.00	337.52	30.72	15.36	2304	1593	69	00	15
Culvert	Barrel	Sq.m	350.00	288.25	0.00	105.25	98.00	85.00	100888	41348	41	01,02	00
Coatings	Structural steel	Sq.m	80.00	288.25	0.00	80.71	121.10	86.50	23060	8718	38	00	00
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	0.00	4.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									126252	51658			

Bridge Condition Index (BCI)

41

Inventory Data:

Structure Name		<input type="text" value="Kittle Rd & Kittle Creek MD Culvert"/>							
Main Hwy/Road #	<input type="text" value="Kittle Rd"/>	Services on structure:	<i>Navig. Water</i>	<input type="text"/>	<i>Non-Navig.</i>	<input type="text"/>	<i>Ped.</i>	<input type="text"/>	
	On Structure		<input checked="" type="checkbox"/>	<i>Rail</i>	<input type="text"/>	<i>Road</i>	<input checked="" type="checkbox"/>	<i>Other</i>	<input type="text"/>
	Under Structure		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
		Services under structure:	<i>Navig. Water</i>	<input type="text"/>	<i>Non-Navig.</i>	<input checked="" type="checkbox"/>	<i>Ped.</i>	<input type="text"/>	
			<i>Rail</i>	<input type="text"/>	<i>Road</i>	<input type="text"/>	<i>Other</i>	<input type="text"/>	
Structure Location		<input type="text" value="1.3km West of County Rd 7"/>							
Latitude	<input type="text" value="45.11716"/>	Longitude	<input type="text" value="-75.25508"/>						
Owner(s)	<input type="text" value="Township of North Dundas"/>	Heritage Designation	<i>Not Consid: Desig./not list</i>	<input checked="" type="checkbox"/>	<i>Cons/not App. Desig. & List</i>	<input type="text"/>	<i>List/n.d.</i>	<input type="text"/>	
MTO Region	<input type="text" value="40 - Eastern"/>	Road Class:	<i>Freeway</i>	<input type="text"/>	<i>Arterial</i>	<input type="text"/>	<i>Local</i>	<input checked="" type="checkbox"/>	
MTO District	<input type="text" value="42 - Ottawa"/>	Posted Speed	<input type="text" value="60 km/h"/>		No. of Lanes	<input type="text" value="2"/>			
Old County	<input type="text" value="SDG"/>	AADT	<input type="text" value="68"/>		% Trucks	<input type="text"/>			
Geographic Twp.	<input type="text"/>	Inspection Route Sequence	<input type="text"/>						
Structure Type	<input type="text" value="2-cell CSP Round Culvert"/>	Interchange Number	<input type="text"/>						
Total Deck Length	<input type="text"/> m	Interchange Structure Number	<input type="text"/>						
Overall Str. Width	<input type="text" value="3"/> m	Min. Vertical Clearance	<input type="text"/> m						
Total Deck Area	<input type="text"/> sq. m	Special Routes:	<i>Transit</i>	<input type="text"/>	<i>Truck</i>	<input type="text"/>	<i>Bicycle</i>	<input type="text"/>	
Roadway Width	<input type="text" value="12.2"/> m	Detour Length Around Bridge	<input type="text"/> km						
Skew Angle	<input type="text" value="6"/> Degrees	Direction of Structure	<input type="text" value="East/West"/>						
No. of Spans	<input type="text" value="2"/>	Fill on Structure	<input type="text" value="0.9"/> m						
Span Lengths	<input type="text" value="1.5, 1.5"/> m								

Historical Data:

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text"/>	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.71		
OSIM		2022	69.48		

Appraisal Indices:	Comments:
Fatigue:	
Seismic:	
Scour:	
Flood:	
Geometrics:	
Barrier:	
Curb:	
Load Capacity:	
Key Aspects:	

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4°C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		<input checked="" type="checkbox"/>		\$ 5,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	<input checked="" type="checkbox"/>			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/>			
Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Coating Condition Survey:	<input checked="" type="checkbox"/>			
Detailed Timber Investigation:	<input checked="" type="checkbox"/>			
Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/>			
Underwater Investigation:	<input checked="" type="checkbox"/>			
Fatigue Investigation:	<input checked="" type="checkbox"/>			
Seismic Investigation:	<input checked="" type="checkbox"/>			
Structure Evaluation:	<input checked="" type="checkbox"/>			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/>			
Monitoring Crack Widths:	<input checked="" type="checkbox"/>			
Investigation Notes:				

Overall Structure Notes:				
Recommended Work on	<input checked="" type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace
Timing of Recommended Work:		<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years	
Overall Comments:	Structure is generally in good condition. Some debris noted within east pipe and east pipe inlet. Light corrosion noted along bottom third of pipe. Light scaling and potholes noted on the asphalt wearing surface. Debris and perforation noted in west barrel. No barrier present above structure - A code compliant barrier and end-treatments should be installed			
Date of Next Inspection:	2024			

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	6
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	360.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		349.20
			7.20
			3.60
Comments:	Potholes noted along center of roadway with some light scaling noted throughout. No barrier present above structure - A code compliant barrier and end-treatments should be installed above the structure		
Recommended Work:	Rehab	Replace	Maintenance Needs: 15
	1-5 years	6-10 years	Urgent 1 year x 2 years
	Rout and seal asphalt wearing surface		

Element Group:	Culverts	Length:	12.2
Element Name:	Barrels	Width:	1.5
Location:	Below Roadway	Height:	1.5
Material:	Corrugated Steel	Count (items):	2
Element Type:	2-Cell CSP Round culverts	Total Quantity:	114.92 m2
Environment:	Benign	Limited Inspection	
Protection System:	Hot Dip Galvanized		
Condition Data:	Units	Exc.	Good
	m2		91.94
			22.98
Comments:	Light to medium corrosion noted along springline. Deformation/perforation noted in west barrel. Debris buildup in east pipe. Limited inspection due to sedimentation		
Recommended Work:	Rehab	Replace	Maintenance Needs: 18
	1-5 years	6-10 years	Urgent X 1 year 2 years
	Remove debris in pipes		

Element Group:	Coating	Length:	
Element Name:	Structural Steel	Width:	
Location:	On culvert barrel	Height:	
Material:	Other	Count (items):	
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	114.92 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		114.92
Comments:	Generally in good condition with some light corrosion along the bottom third of pipe		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Foundations	Length:						
Element Name:	Foundation (below ground level)	Width:						
Location:	Below barrel	Height:						
Material:	unknown	Count (items):						
Element Type:	unknown	Total Quantity:	All	N/A				
Environment:	Benign	Limited Inspection		x				
Protection System:	Unknown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted at the time of inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SW & SE sides of structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Embankments	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	Rip-Rap						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4					
Comments:	Embankments are moderately sloped, well-vegetated, and stable.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope protection	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Rip-Rap	Count (items):	4					
Element Type:	Embankment	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4					
Comments:	Generally in good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams			Length:					
Element Name:	Streams and Waterways			Width:					
Location:	Under structure			Height:					
Material:	Native			Count (items):	All				
Element Type:	Stream			Total Quantity:	All				
Environment:	Benign			Limited Inspection				N/A	
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Low volume and low flow from north to south. Obstruction/debris noted at east inlet.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 18				
		1-5 years		6-10 years		Urgent	x	1 year	2 years
					Remove debris				

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Barriers	Install code compliant barrier and end-treatment			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ -

Associated Work	Comments	Estimated Cost
Approaches		\$ -
Detours		\$ -
Traffic Control		\$ -
Utilities		\$ -
Right of Way		\$ -
Environmental Study		\$ -
Other		\$ -
Contingencies		\$ -
Total cost:		\$ -

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Kittle Rd & Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS011



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Kittle Rd & Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS011



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Kittle Rd & Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS011



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Kittle Rd & Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS011



Photo 7 Small potholes forming on asphalt wearing surface above structure



Photo 8 Corrosion and debris within east barrel

MUNICIPAL STRUCTURE INSPECTION FORM

Kittle Rd & Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS011



Photo 9 Debris buildup at east barrel inlet

Structure Condition Summary Form

Structure Name Kittle Rd & Kittle Creek MD Culvert
Structure Number CUS011
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	360.00		349.20	7.20	3.60	2160	1589	74	00	15
Culvert	Barrel	Sq.m	350.00	114.92		91.94	22.98		40222	27351	68	00	00
Coatings	Structural steel	Sq.m	80.00	114.92		114.92			9194	6895	75	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

									51576	35835
Bridge Condition Index (BCI)	69.48									

Inventory Data:

Structure Name	Finch Winchester Boundary Rd & Stoney Creek MD Culvert									
Main Hwy/Road #	Finch Winchester Boundary Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>	
	Under Structure	<input type="checkbox"/>								
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.4 km South of County Rd 9									
Latitude	45.16392		Longitude	-75.19492						
Owner(s)	Township of North Dundas		Heritage Designation	Not Consid.	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
				Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern		Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
				Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa		Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG		AADT	49		% Trucks	<input type="checkbox"/>			
Geographic Twp.	<input type="text"/>		Inspection Route Sequence	<input type="text"/>						
Structure Type	CSP Round Culvert		Interchange Number	<input type="text"/>						
Total Deck Length	<input type="text"/> m		Interchange Structure Number	<input type="text"/>						
Overall Str. Width	3 m		Min. Vertical Clearance	<input type="text"/> m						
Total Deck Area	<input type="text"/> sq. m		Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
				School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	4.6 m		Detour Length Around Bridge	<input type="text"/> km						
Skew Angle	20 Degrees		Direction of Structure	North/South						
No. of Spans	1		Fill on Structure	0.4 m						
Span Lengths	3 m									

Historical Data:

Year Built	<input type="text"/>	Year of Last Major Rehab.	<input type="text"/>
Last OSIM Inspection	<input type="text"/>	Last Evaluation	<input type="text"/>
Last Enhanced OSIM Inspection	<input type="text"/>	Current Load Limit	<input type="text"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="text"/>	Load Limit By-Law #	<input type="text"/>
Last Underwater Inspection	<input type="text"/>	By-Law Expiry Date	<input type="text"/>
Last Condition Survey	<input type="text"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.57		
OSIM		2022	64.00		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy, Light rain				
Temperature:	3° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			x		\$ 5,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
Investigation Notes: Rehabilitation/Replacement Study for Approach Barrier Only					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input checked="" type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace			
Timing of Recommended Work:	<input type="checkbox"/> 1 to 5 years	<input checked="" type="checkbox"/> 6 to 10 years					
Overall Comments:	Structure is in generally fair condition. Repair culvert barrel in 1-5 years. Moderate corrosion noted along bottom of culvert barrel. Scour present at barrel ends. Cracks in barrel noted with some small perforations. No barriers present - A code compliant barrier and end-treatments should be installed.						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	60				
Element Name:	Wearing Surface	Width:	4.6				
Location:	Over Culvert	Height:					
Material:	Asphalt	Count (items):					
Element Type:	Asphalt Wearing Surface	Total Quantity:	276.0	m2			
Environment:	Severe	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m2	Exc.	Good 276	Fair	Poor*		
Comments:	Generally in good condition with light potholes forming. No barriers present above structure - A code compliant barrier and end treatments should be installed above the structure.						
Recommended Work:	x	Rehab		Replace	Maintenance Needs:		
	x	1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Culverts	Length:	18.3				
Element Name:	Barrels	Width:	3				
Location:	Below Roadway	Height:	3				
Material:	Corrugated Steel	Count (items):	1				
Element Type:	CSP Round Culvert	Total Quantity:	172.4	m2			
Environment:	Benign	Limited Inspection					
Protection System:	Hot Dip Galvanized					Perform. Deficiencies	
Condition Data:	Units m2	Exc.	Good 123.5	Fair 47.4	Poor* 1.5		
Comments:	Moderate with localized severe corrosion along waterline noted with small perforations below waterline. Two cracks in barrel wall noted.						
Recommended Work:		Rehab		Replace	Maintenance Needs: 7		
		1-5 years		6-10 years	Urgent	1 year x 2 years	

Element Group:	Coating	Length:					
Element Name:	Structural Steel	Width:					
Location:	On culvert barrel	Height:					
Material:	Other	Count (items):					
Element Type:	Hot dip galvanizing	Total Quantity:	172.4	m2			
Environment:	Benign	Limited Inspection					
Protection System:	None					Perform. Deficiencies	
Condition Data:	Units m2	Exc.	Good 120.7	Fair 28.7	Poor* 28.7		
Comments:	Generally in fair condition, with 1/3 of the pipe coating failing.						
Recommended Work:		Rehab		Replace	Maintenance Needs:		
		1-5 years		6-10 years	Urgent	1 year 2 years	

Element Group:	Foundations	Length:						
Element Name:	Foundation (below ground level)	Width:						
Location:	Below barrel	Height:						
Material:	unknown	Count (items):						
Element Type:	unknown	Total Quantity:	All	N/A				
Environment:	Benign	Limited Inspection		x				
Protection System:	Unkown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability was noted at the time of inspection							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SW & SE sides of structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Embankments	Total Quantity:	4	Each				
Environment:	Moderate	Limited Inspection	X					
Protection System:	Rip-Rap						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		3	1.0				
Comments:	Embankments are moderately sloped, well-vegetated, and stable. Evidence of overgrown vegetation was noted at the southwest embankment. Moderate erosion at southwest embankment							
Recommended Work:		Rehab	Replace	Maintenance Needs:			13	
		1-5 years	6-10 years	Urgent	1 year	x	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope protection	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Rip-Rap	Count (items):	4					
Element Type:	Embankment	Total Quantity:		Each				
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		3	1				
Comments:	Generally in good condition with some overgrowth at the southwest embankment noted.							
Recommended Work:		Rehab	Replace	Maintenance Needs:				
		1-5 years	6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams			Length:			
Element Name:	Streams and Waterways			Width:			
Location:	Under structure			Height:			
Material:	Native			Count (items):	All		
Element Type:	Stream			Total Quantity:	All N/A		
Environment:	Benign			Limited Inspection			
Protection System:	None						Perform.
Condition Data:	Units	Exc.	Good	Fair	Poor*	Deficiencies	
	N/A		All				
Comments:	Medium volume and moderate flow from west to east with no visible flow obstruction noted. Evidence of severe scour and erosion on stream bed was noted at both east and west side of battel.						
Recommended Work:		Rehab	Replace	Maintenance Needs:			
		1-5 years	6-10 years	Urgent:	X	1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Approach Barrier	Install Code Compliant Barrier and End Treatments			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 48,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification
<div></div>

MUNICIPAL STRUCTURE INSPECTION FORM

**Finch Winchester Boundary Rd
& Stoney Creek MD Culvert**

SITE PHOTOGRAPHS

Site No.: CUS012



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

**Finch Winchester Boundary Rd
& Stoney Creek MD Culvert**

SITE PHOTOGRAPHS

Site No.: CUS012



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

**Finch Winchester Boundary Rd
& Stoney Creek MD Culvert**

SITE PHOTOGRAPHS

Site No.: CUS012



Photo 5 East elevation



Photo 6 West elevation

MUNICIPAL STRUCTURE INSPECTION FORM

**Finch Winchester Boundary Rd
& Stoney Creek MD Culvert**

SITE PHOTOGRAPHS

Site No.: CUS012



Photo 7 View through pipe barrel from the West



Photo 8 Corrosion along bottom of pipe

MUNICIPAL STRUCTURE INSPECTION FORM

Finch Winchester Boundary Rd
& Stoney Creek MD Culvert

SITE PHOTOGRAPHS

Site No.: CUS012



Photo 9 Light deformation at east barrel end



Photo 10 Perforations on barrel wall

Structure Condition Summary Form

Structure Name

Finch Winchester Boundary Rd & Stoney Creek MD Culvert

Structure Number

CUS012

Date of Inspection

2022/11/25

Project No.

22087

Consultant

HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	276.00		275.00	1.00	0.00	1656	1240	75	00	00
Culvert	Barrel	Sq.m	350.00	173.89		125.00	47.39	1.50	60862	39447	65	00	07
Coatings	Structural steel	Sq.m	80.00	173.89		115.93	28.98	28.98	13911	7883	57	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		3.00	1.00		0	0		00	13
Embankments and Streams	Slope Protection	Each	0.00	4.00		3.00	1.00		0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00
									76429	48570			
Bridge Condition Index (BCI)	63.55												

Structure Condition Summary Form

Structure Name Van Camp Rd North Branch Soung Naiton River MD Culvert
Structure Number CUS013
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	169.50	0.00	169.50	0.00	0.00	0	0		00	00
	Wearing Surface	Sq.m	6.00	384.00	0.00	384.00	0.00	0.00	2304	1728	75	00	15
Culvert	Inlet Components	Sq.m	350.00	16.00	0.00	14.75	0.75	0.50	5600	3977	71	00	08
	Outlet Components	Sq.m	350.00	16.00	0.00	13.75	1.50	0.75	5600	3819	68	00	08
Coatings	Barrel	Sq.m	350.00	541.44	0.00	518.44	15.00	8.00	189504	138191	73	00	00
	Structural steel	Sq.m	80.00	541.40	0.00	519.78	10.83	10.83	43312	31533	73	00	00
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	0.00	1.00	0.00	0	0		00	18
									246320	179248			
Bridge Condition Index (BCI)	73												

Inventory Data:

Structure Name	Van Camp Rd North Branch South Nation River MD Culvert										
Main Hwy/Road #	Van Camp Rd	Services on Structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>			
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>		
	Under Structure		<input type="checkbox"/>	Services Under Structure:		Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>			
Structure Location	0.25km West of County Road 1										
Latitude	45.01981		Longitude	-75.48735							
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid:	<input type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>			
			Desig./not list	<input type="checkbox"/>	Desig. & List	<input type="checkbox"/>					
MTO Region	40 - Eastern	Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>					
			Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>					
MTO District	42 - Ottawa	Posted Speed	60 km/h		No. of Lanes	2					
Old County	SDG	AADT	49		% Trucks	<input type="checkbox"/>					
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>								
Structure Type	2-Cell SPCSP Culvert	Interchange Number	<input type="checkbox"/>								
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>								
Overall Str. Width	12.6 m	Min. Vertical Clearance	<input type="checkbox"/> m								
Total Deck Area	23.5 sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>					
			School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>					
Roadway Width	6.4 m	Detour Length Around Bridge	<input type="checkbox"/> km								
Skew Angle	30 Degrees	Direction of Structure	East/West								
No. of Spans	2	Fill on Structure	<input type="checkbox"/> m								
Span Lengths	5.4, 5.4 m										

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	73.59		
OSIM		2022	73		

Appraisal Indices:

Comments:

Fatigue:

Seismic:

Scour:

Flood:

Geometrics:

Barrier:

Curb:

Load Capacity:

Key Aspects:

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Sarah Vandergeest, P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy				
Temperature:	-2°C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study:					
Material Condition Survey					
	Detailed Deck Condition Survey:	<input checked="" type="checkbox"/> X			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/> x			
	Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/> x			
	Detailed Coating Condition Survey:	<input checked="" type="checkbox"/> x			
	Detailed Timber Investigation:	<input checked="" type="checkbox"/> x			
	Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/> x			
Underwater Investigation:		<input checked="" type="checkbox"/> x			
Fatigue Investigation:		<input checked="" type="checkbox"/> x			
Seismic Investigation:		<input checked="" type="checkbox"/> x			
Structure Evaluation:		<input checked="" type="checkbox"/> x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/> x			
	Monitoring Crack Widths:		<input checked="" type="checkbox"/> X		\$ 2,500.00
		Total Cost			\$ 2,500.00
Investigation Notes Rehabilitation/Replacement Study is for					

Overall Structure Notes:							
Recommended Work on Structure:	<input checked="" type="checkbox"/> X	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace		
Timing of Recommended Work:			<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years			
Overall Comments:	New steel beam guiderail installed since previous inspection. Tree blocking channel at both east and west barrels. Some moderate corrosion noted at waterline in both barrels. Evidence of water leaking observed, recommend monitoring structure.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Scaling (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:	169.5
Element Name:	Barrier	Width:	
Location:	NE, SE, NW & SW of Structure	Height:	
Material:	Steel	Count (items):	1
Element Type:	Steel Flex Beam on Steel Posts	Total Quantity:	169.5 m
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m		169.5
Comments:	Steel beam guiderail was installed since previous inspection. Barrier is generally in good condition.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	6.4
Location:	East and West of Surface	Height:	
Material:	Asphalt	Count (items):	1
Element Type:	Asphalt Wearing Surface	Total Quantity:	384.0 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		384
Comments:	Moderate tire rutting and some rippling noted. Gravel accumulation observed at edges of wearing surface.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Culverts	Length:	2.50
Element Name:	Inlet Components	Width:	0.40
Location:	South Side of Structure	Height:	1.70
Material:	Cast-In-Place Concrete	Count (items):	1
Element Type:	Reinforced Concrete Retaining Walls and Collar	Total Quantity:	16.00 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		14.75
Comments:	Spall noted at southeast corner and wide crack observed at southwest corner of inlet components.		
Recommended Work:	Rehab	Replace	Maintenance Needs: 08
	1-5 years	6-10 years	Urgent
			1 year
			X
			2 years

Element Group:	Culverts	Length:	23.50						
Element Name:	Barrels	Width:	5.40						
Location:	Below Roadway	Height:	3.20						
Material:	Cast-In-Place Concrete	Count (items):	2						
Element Type:	SPCSP Arch Culvert	Total Quantity:	541.44	m ²					
Environment:	Severe	Limited Inspection							
Protection System:	None						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		518.44	15.0	8.0				
Comments:	Evidence of leaking and salt stains noted at bolt lines in barrels. Light to moderate to corrosion with some flaking noted at waterline. Monitoring of barrels is recommended. Minor sag noted in west end of west barrel.								
Recommended Work:	X	Rehab		Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Culverts	Length:	2.50						
Element Name:	Outlet Components	Width:	0.40						
Location:	North Side of Structure	Height:	1.70						
Material:	Cast-In-Place Concrete	Count (items):	1						
Element Type:	Reinforced Concrete Retaining Walls and Collar	Total Quantity:	16.0	m ²					
Environment:	Severe	Limited Inspection							
Protection System:	None						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		13.75	1.50	0.75				
Comments:	Cracks noted around both barrels with heavy efflorescence staining also observed. Map cracks with efflorescence and damp stains noted.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 08				
		1-5 years		6-10 years		Urgent		1 year	X 2 years

Element Group:	Coatings	Length:							
Element Name:	Structural Steel	Width:							
Location:	On Culvert Barrel	Height:							
Material:	Coating	Count (items):							
Element Type:	Structural Steel Coating	Total Quantity:	541.4	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	None						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		519.78	10.83	10.83				
Comments:	Some coating loss noted throughout barrel								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	X 2 years

Element Group:	Foundation	Length:							
Element Name:	Foundation (below ground level)	Width:							
Location:	Below Barrels	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection	X						
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	All		100%						
Comments:	No evidence of foundation instability at time of inspection.								
Recommended Work:		Rehab		Replace	Maintenance Ne	0			
		1-5 years		6-10 years	Urgent		1 year		2 years

Element Group:	Embankments & Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW OF Structure	Height:							
Material:	Native Soil	Count (items):							
Element Type:	Embankment	Total Quantity:	4						
Environment:	Moderate	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4						
Comments:	Washout noted around barrier posts at various locations. Some erosion noted over barrels on both sides of structures.								
Recommended Work:		Rehab		Replace	Maintenance Needs:	13			
		1-5 years		6-10 years	Urgent	X	1 year		2 years

Element Group:	Embankments & Streams	Length:							
Element Name:	Streams & Waterways	Width:							
Location:	Under Structure	Height:							
Material:	Native	Count (items):							
Element Type:	Stream	Total Quantity:	All						
Environment:	Moderate	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	All			All					0
Comments:	Moderate to high volume with moderate flow from south to north at time of inspection. Trees blocking both inlet of east barrel and outlet of west barrel.								
Recommended Work:		Rehab		Replace	Maintenance Needs:	18			
		1-5 years		6-10 years	Urgent	X	1 year		2 years
Remove Channel Obstructions									

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Barrels	Culvert Barrel Repairs	x			\$ 18,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 18,000.00

Associated Work	Comments	Estimated Cost
Approaches		\$ -
Detours		\$ -
Traffic Control		\$ -
Utilities		\$ -
Right of Way		\$ -
Environmental Study		\$ -
Other		\$ -
Contingencies		\$ -
Total cost:		\$ -

Justification
<div></div>

SITE PHOTOGRAPHS

CULVERT

Van Camp Rd North Branch South Nation River MD Culvert

Site No.: CUS013



Photo 1 Structure from east approach



Photo 2 Structure from west approach

SITE PHOTOGRAPHS

CULVERT

Van Camp Rd North Branch South Nation River MD Culvert

Site No.: CUS013



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

SITE PHOTOGRAPHS

CULVERT

Van Camp Rd North Branch South Nation River MD Culvert

Site No.: CUS013



Photo 5 North elevation



Photo 6 South elevation

SITE PHOTOGRAPHS

CULVERT

Van Camp Rd North Branch South Nation River MD Culvert

Site No.: CUS013



Photo 7 Moderate tire rutting on east wearing surface



Photo 8 Typical view of south approach barrier

SITE PHOTOGRAPHS

CULVERT

Van Camp Rd North Branch South Nation River MD Culvert

Site No.: CUS013



Photo 9 Wide crack at southwest corner of south concrete wall



Photo 10 Spall on north concrete wall

SITE PHOTOGRAPHS

CULVERT

Van Camp Rd North Branch South Nation River MD Culvert

Site No.: CUS013



Photo 11 Interior of west barrel



Photo 12 Wet areas and evidence of leaking in west barrel

SITE PHOTOGRAPHS

CULVERT

Van Camp Rd North Branch South Nation River MD Culvert

Site No.: CUS013



Photo 13 Interior view of east barrel from north end of structure

Inventory Data:

Structure Name	River Rd & Kittle Creek MD Culvert				
Main Hwy/Road #	River Rd	Services on structure:	Navig. Water	Non-Navig.	Ped.
	On Structure <input checked="" type="checkbox"/>		Rail	Road <input checked="" type="checkbox"/>	Other
	Under Structure	Services under structure:	Navig. Water	Non-Navig.	Ped.
			Rail	Road <input checked="" type="checkbox"/>	Other
Structure Location	0.2km South of County Rd 43				
Latitude	45.100715	Longitude	-75.250827		
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	List/n.d. <input type="checkbox"/>
			Desig./not list <input type="checkbox"/>	Desig. & List <input type="checkbox"/>	
MTO Region	40 - Eastern	Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>	
			Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>	
MTO District	42 - Ottawa	Posted Speed	80 km/h	No. of Lanes	2
Old County	SDG	AADT	150	% Trucks	
Geographic Twp.		Inspection Route Sequence			
Structure Type	CSP Horizontal Ellipse Culvert	Interchange Number			
Total Deck Length		Interchange Structure Number			
Overall Str. Width	3.9 m	Min. Vertical Clearance			
Total Deck Area		Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>	
			School <input type="checkbox"/>	Bicycle <input type="checkbox"/>	
Roadway Width	25.3 m	Detour Length Around Bridge			
Skew Angle	6 Degrees	Direction of Structure	East/West		
No. of Spans	1	Fill on Structure	0.8 m		
Span Lengths	3.9 m				

Historical Data:

Year Built		Year of Last Major Rehab.	
Last OSIM Inspection		Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	61.93		
OSIM		2022	61.79		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM	<input type="checkbox"/> Enhanced OSIM	
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy, Light rain				
Temperature:	4 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			x		\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:		x		\$ 2,500.00
	Monitoring Crack Widths:	x			
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input checked="" type="checkbox"/> X	<input type="checkbox"/> Replace		
Timing of Recommended Work:	<input type="checkbox"/> X	<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years				
Overall Comments:	Structure is in generally fair condition. Barrel is deformed and a separation and piping was noted at the south (outlet) end of culvert. Flow observed under pipe with erosion at both ends of pipe. South end of pipe is also perched. A code-compliant barrier should be installed above the structure						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	6
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	360.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		287.00
			38.00
			35.00
Comments:	Moderate ravelling, moderate depression/settlement, and potholes noted. No barrier present - A code compliant barrier and end-treatment should be installed above the structure		
Recommended Work:	X	Rehab	Replace
	X	1-5 years	6-10 years
Maintenance Needs:		Urgent	1 year
			2 years
Regrade and repave roadway above structure			

Element Group:	Culverts	Length:	25.3
Element Name:	Barrels	Width:	3.9
Location:	Below Roadway	Height:	2.8
Material:	Corrugated Steel	Count (items):	1
Element Type:	2-Cell CSP Round culverts	Total Quantity:	170.00 m2
Environment:	Benign	Limited Inspection	
Protection System:	Hot Dip Galvanized		
Condition Data:	Units	Exc.	Good
	m2		109.80
			44.20
			16.0
Comments:	South segment of pipe is separated at the joint, causing infiltration and undermining below the culvert. South segment is also perched.		
Recommended Work:		Rehab	Replace
	X	1-5 years	6-10 years
Maintenance Needs:		Urgent	1 year
			2 years
Replace Structure			

Element Group:	Coating	Length:	
Element Name:	Structural Steel	Width:	
Location:	On culvert barrel	Height:	
Material:	Other	Count (items):	
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	170.00 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		168.00
			1.0
			1.0
Comments:	Generally in good condition with some light localized coating failure at joints		
Recommended Work:		Rehab	Replace
		1-5 years	6-10 years
Maintenance Needs:		Urgent	1 year
			2 years

Element Group:	Foundations	Length:						
Element Name:	Foundation (below ground level)	Width:						
Location:	Below barrel	Height:						
Material:	unknown	Count (items):						
Element Type:	unknown	Total Quantity:	All	N/A				
Environment:	Benign	Limited Inspection		x				
Protection System:	Unknown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted at the time of inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SW & SE sides of structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Embankments	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	Rip-Rap						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		1	3.0				
Comments:	Light to moderate erosion present at NW, SW, and SE embankments. Large fallen tree above structure at the North.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	X	1 year	2 years
					Remove tree			

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope protection	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Rip-Rap	Count (items):	4					
Element Type:	Embankment	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4					
Comments:	Generally in good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Streams and Waterways	Width:							
Location:	Under structure	Height:							
Material:	Native	Count (items):	All						
Element Type:	Stream	Total Quantity:	All N/A						
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A			All					
Comments:	Low volume and low flow from north to south. Scour of embankment around pipe ends present. Flow under south segment of pipe								
Recommended Work:		Rehab		Replace	Maintenance Needs: 13				
		1-5 years		6-10 years		Urgent	X	1 year	2 years
					Erosion control measures on stream bed				

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
	Replace Structure		X		\$ 395,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 395,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

River Rd & Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS014



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

River Rd & Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS014



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

River Rd & Kittle Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS014



Photo 5 North elevation



Photo 6 South elevation



Photo 7 Roadway depression above structure, potholes, and raveling



Photo 8 Typical scour / undermining of culvert (North inlet shown)



Photo 9 Deformation along top of pipe and light localized corrosion at joints



Photo 10 Separation of south barrel segment causing scour/piping



Photo 11 Undermining below south pipe segment



Photo 12 Corrosion along bottom of pipe and at joints

Structure Condition Summary Form

Structure Name River Rd & Kittle Creek MD Culvert
Structure Number CUS014
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	360.00		287.00	38.00	35.00	2160	1383	64	00	00
Culvert	Barrel	Sq.m	350.00	170.00		109.80	44.20	16.00	59500	35011	59	00	00
Coatings	Structural steel	Sq.m	80.00	170.00		168.00	1.00	1.00	13600	10112	74	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		1.00	3.00		0	0		00	18
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00			1.00		0	0		00	13

										75260	46505			
Bridge Condition Index (BCI)		61.79												

Inventory Data:

Structure Name	Guy Rd & Mullin MD Culvert				
Main Hwy/Road #	Guy Road	Services on structure:	<i>Navig. Water</i> <input type="checkbox"/> <i>Rail</i> <input type="checkbox"/>	<i>Non-Navig. Road</i> <input checked="" type="checkbox"/> <i>Ped. Other</i> <input type="checkbox"/>	
	On Structure <input checked="" type="checkbox"/>				
	Under Structure <input type="checkbox"/>	Services under structure:	<i>Navig. Water</i> <input type="checkbox"/> <i>Rail</i> <input type="checkbox"/>	<i>Non-Navig. Road</i> <input checked="" type="checkbox"/> <i>Ped. Other</i> <input type="checkbox"/>	
Structure Location	0.5km East of Browns Lane				
Latitude	45.0436194	Longitude	-75.3733288		
Owner(s)	Township of North Dundas	Heritage Designation	<i>Not Consid. Desig./not list</i> <input checked="" type="checkbox"/> <i>Cons/not App. Desig. & List</i> <input type="checkbox"/>	<i>List/n.d.</i> <input type="checkbox"/>	
MTO Region	40 - Eastern	Road Class:	<i>Freeway Collector</i> <input type="checkbox"/> <i>Arterial Local</i> <input checked="" type="checkbox"/>		
MTO District	42 - Ottawa	Posted Speed	60 km/h	No. of Lanes	2
Old County	SDG	AADT	152	% Trucks	<input type="checkbox"/>
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>		
Structure Type	SPCSP Arch Culvert	Interchange Number	<input type="checkbox"/>		
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>		
Overall Str. Width	3.30 m	Min. Vertical Clearance	<input type="checkbox"/> m		
Total Deck Area	<input type="checkbox"/> sq. m	Special Routes:	<i>Transit School</i> <input type="checkbox"/> <i>Truck Bicycle</i> <input type="checkbox"/>		
Culvert Length	16.8 m	Detour Length Around Bridge	<input type="checkbox"/> km		
Roadway Width	5.8 m	Direction of Structure	East/West		
Skew Angle	10 Degrees	Fill on Structure	0.8 m		
No. of Spans	1				
Span Lengths	3.3 m				

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	November 2, 2020	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	73.32		
OSIM		2022	73		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 8, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Sarah Vandergeest P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	2° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			x		\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
		Total Costs			\$ 20,000.00
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/>	None	<input type="checkbox"/>	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input checked="" type="checkbox"/> X Replace
Timing of Recommended Work:			<input checked="" type="checkbox"/> X	1 to 5 years		6 to 10 years	
Overall Comments:	No approach barrier noted at time of inspection and a code compliant approach barrier should be installed. Potholes, moderate ravelling, alligator cracks and asphalt patches on wearing surface. Moderate corrosion with localized perforations on barrel. Evidence of leakage noted on east side of barrel with some sag also noted.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	

Maintenance Needs

01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:							
Element Name:	Barrier	Width:							
Location:	NE, SE, NW & SW of Structure	Height:							
Material:	Steel	Count (items):							
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	m						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m					8			
Comments:	No approach barrier noted at time of inspection. A code compliant approach barrier should be installed.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	5.8
Location:	East and West Side of Structure	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Surface Treatment	Total Quantity:	348.0 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		327
Comments:	Potholes, alligator cracks, light to moderate ravelling and patched potholes noted on approach wearing surface.		
Recommended Work:		Rehab	
		1-5 years	
		6-10 years	
Maintenance Needs:		12	
		Urgent	
		1 year	X
		2 years	
		Repair asphalt surface treatment and patch pothole	

Element Group:	Culverts	Length:	16.8
Element Name:	Barrels	Width:	3.3
Location:	Below Roadway	Height:	2.2
Material:	Corrugated Steel	Count (items):	1
Element Type:	SPCSP Arch Culvert	Total Quantity:	157.89 m
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m		153.16
Comments:	Medium corrosion and localized perforations noted along bottom of culvert. Deformation at north end of barrel. Evidence of leakage noted on east side of barrel.		
Recommended Work:		Rehab	X
		1-5 years	X
		6-10 years	
Maintenance Needs:			
		Urgent	
		1 year	
		2 years	

Element Group:	Coating	Length:								
Element Name:	Structural Steels	Width:								
Location:	On Barrel	Height:								
Material:	Unknown	Count (items):								
Element Type:	Unknown	Total Quantity:	157.89					m ²		
Environment:	Benign	Limited Inspection								
Protection System:	Unknown								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m ²		149.99	3.95	3.95					
Comments:	Coating loss noted on culvert barrel.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year	2 years	

Element Group:	Foundations	Length:								
Element Name:	Foundation (Below Ground Level)	Width:								
Location:	Below Abutment Walls and Wingwalls	Height:								
Material:	Unknown	Count (items):								
Element Type:	Unknown	Total Quantity:	All							
Environment:	Benign	Limited Inspection			X					
Protection System:	Unknown								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All			0				
Comments:	No visible evidence of foundation instability was noted during the inspection.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year	2 years	

Element Group:	Embankments and Streams	Length:								
Element Name:	Embankments	Width:								
Location:	NE, SE, NW & SW Side of Structure	Height:								
Material:	Native Material	Count (items):	4							
Element Type:	Embankment	Total Quantity:	Each							
Environment:	Moderate	Limited Inspection								
Protection System:	Vegetation								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	Each		4.00							
Comments:	Embankments are moderately sloped, well vegetated, and appear to be stable. Some erosion noted above the barrel.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year	2 years	

Element Group:	Embankments and Streams				Length:				
Element Name:	Streams and Waterways				Width:				
Location:	Below Structure				Height:				
Material:	Native				Count (items):	All			
Element Type:	Stream				Total Quantity:	All N/A			
Environment:	Benign				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Medium volume and low flow with no obstructions noted at time of inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Approaches	Install code compliant approach barrier			X	\$ -
Culvert	Replace Barrels	X			\$ 222,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 222,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification



Photo 1 Structure from east approach



Photo 2 East approach from centre of structure



Photo 3 West approach from centre of structure



Photo 4 North elevation



Photo 5 South elevation



Photo 6 Potholes, and alligator cracks on edge of east wearing surface



Photo 7 Interior view of barrel



Photo 8 Perforations at north end of barrel



Photo 9 Evidence of leakage at east end of barrel

Structure Condition Summary Form

Structure Name Guy Rd & Mullin MD Culvert
Structure Number CUS015
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	348.00	0.00	327.00	15.00	6.00	2088	1508	72	00	12
Culvert	Barrel	Sq.m	350.00	157.89	0.00	153.15	3.16	1.58	55262	40644	74	00	00
Coatings	Structural steel	Sq.m	80.00	157.89	0.00	149.99	3.95	3.95	12631	9126	72	00	00
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									69981	51278			

Bridge Condition Index (BCI) 73

Inventory Data:

Structure Name	Pemberton Rd & Mulin MD Culvert									
Main Hwy/Road #	Pemberton Road		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure	X		Rail	<input type="checkbox"/>	Road	X	Other	<input type="checkbox"/>	
	Under Structure									
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	X	Ped.	<input type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.45km South of Hogaboam road									
Latitude	45.04404			Longitude	-75.3422					
Owner(s)	Township of North Dundas			Heritage Designation	Not Consid. Desig./not list	X	Cons/not App. Desig. & List	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>
MTO Region	40 - Eastern			Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>		
				Collector	<input type="checkbox"/>		Local	X		
MTO District	42 - Ottawa			Posted Speed	60 km/h		No. of Lanes	2		
Old County	SDG			AADT	115		% Trucks	<input type="checkbox"/>		
Geographic Twp.				Inspection Route Sequence	<input type="checkbox"/>					
Structure Type	SPCSP Arch Culvert			Interchange Number	<input type="checkbox"/>					
Total Deck Length	<input type="checkbox"/> m			Interchange Structure Number	<input type="checkbox"/>					
Overall Str. Width	4.80 m			Min. Vertical Clearance	<input type="checkbox"/> m					
Total Deck Area	<input type="checkbox"/> sq. m			Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>		
				School	<input type="checkbox"/>		Bicycle	<input type="checkbox"/>		
Culvert Length	17.5 m			Detour Length Around Bridge	<input type="checkbox"/> km					
Roadway Width	5.8 m			Direction of Structure	North/South					
Skew Angle	30 Degrees			Fill on Structure	0.8 m					
No. of Spans	1									
Span Lengths	3 m									

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	November 4, 2022	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	62.97		
OSIM		2022	63		

Appraisal Indices:

Comments:

Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	December 1, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Sarah Vandergeest P.Eng.				
Others in Party:	Adrian Hu				
Equipment Used:	Digital camera, flashlight, chest waders, and other equipment as required.				
Weather:	Sunny				
Temperature:	2° C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			X		\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	X			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:	x			
	Monitoring Crack Widths:	x			
		Total Costs			\$ 20,000.00
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/>	None	<input type="checkbox"/>	Minor Rehab.	<input type="checkbox"/>	Major Rehab.	<input checked="" type="checkbox"/> X Replace
Timing of Recommended Work:		<input checked="" type="checkbox"/> X	1 to 5 years			6 to 10 years	
Overall Comments:	No approach barrier noted at time of inspection. Code compliant barrier should be installed during replacement. Evidence of leaks noted at northwest corner of barrel. Minor sag noted in middle of barrel.						
Date of Next Inspection:	December 2024						

Suspected Performance Deficiencies

01 Load carrying capacity	06 Bearing not uniformly loaded/unstable	12 Slippery surfaces
02 Excessive deformations (deflections & rotations)	07 Jammed expansion joint	13 Flooding/channel blockage
03 Continuing settlement	08 Pedestrian/vehicular hazard	14 Undermining of foundation
04 Continuing movements	09 Rough riding surface	15 Unstable embankments
05 Seized bearings	10 Surface ponding	16 Other
	11 Deck drainage	
Maintenance Needs		
01 Lift and Swing Bridge Maintenance	07 Repair to Structural Steel	13 Erosion Control at Bridges
02 Bridge Cleaning	08 Repair of Bridge Concrete	14 Concrete Sealing
03 Bridge Handrail Maintenance	09 Repair of Bridge Timber	15 Rout and Seal
04 Painting Steel Bridge Structures	10 Bailey bridges - Maintenance	16 Bridge Deck Drainage
Rehab History: (Date / Description)	11 Animal/Pest Control	17 Sealing (Loose Concrete or ACR Steel)
06 Bridge Bearing Maintenance	12 Bridge Surface Repair	18 Other

Element Group:	Approaches	Length:							
Element Name:	Barrier	Width:							
Location:	NE, SE, NW & SW of Structure	Height:							
Material:	Steel	Count (items):							
Element Type:	Steel Flex Beam on Steel Posts (SBGR)	Total Quantity:	m						
Environment:	Severe	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m					8			
Comments:	No approach barrier noted at time of inspection. A code compliant approach barrier should be installed.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	5.8
Location:	North and South Side of Structure	Height:	
Material:	Gravel	Count (items):	
Element Type:	Gravel Wearing Surface	Total Quantity:	348.0 m ²
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m ²		338
Comments:	Small potholes forming, moderate tire rutting and some rippling noted on wearing surface.		
Recommended Work:		Rehab	
		1-5 years	
Replace	Maintenance Needs:		
		6-10 years	
		Urgent	
		1 year	
		2 years	

Element Group:	Culverts	Length:	17.5
Element Name:	Barrels	Width:	4.8
Location:	Below Roadway	Height:	3
Material:	Corrugated Steel	Count (items):	1
Element Type:	SPCSP Arch Culvert	Total Quantity:	199.15 m
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m		152.35
Comments:	Severe corrosion and perforations along springline noted in previous inspection, not observed. Severe corrosion and cracks noted at bolt lines. Minor sag note in middle of barrel. Missing bolts at southeast panels of barrel. Leaking noted at bolt line at northwest corner of barrel.		
Recommended Work:		Rehab	X
	X	1-5 years	
Replace	Maintenance Needs:		
		6-10 years	
		Urgent	
		1 year	
		2 years	

Element Group:	Coating	Length:							
Element Name:	Structural Steels	Width:							
Location:	On Barrel	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	199.15	m ²					
Environment:	Benign	Limited Inspection							
Protection System:	Unknown							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m ²		149.36	29.87	19.92				
Comments:	Moderate to severe coating loss noted on culvert barrel.								
Recommended Work:		Rehab	X	Replace	Maintenance Needs:				
	X	1-5 years		6-10 years		Urgent		1 year	

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Abutment Walls and Wingwalls	Height:							
Material:	Unknown	Count (items):							
Element Type:	Unknown	Total Quantity:	All						
Environment:	Benign	Limited Inspection			X				
Protection System:	Unknown							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All			0			
Comments:	No visible evidence of foundation instability was noted during the inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, SE, NW & SW Side of Structure	Height:							
Material:	Native Material	Count (items):	4						
Element Type:	Embankment	Total Quantity:		Each					
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4.00						
Comments:	Embankments are steeply sloped, well vegetated, and appear to be stable.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	

Element Group:	Embankments and Streams	Length:									
Element Name:	Streams and Waterways	Width:									
Location:	Below Structure	Height:									
Material:	Native	Count (items):		All							
Element Type:	Stream	Total Quantity:		All N/A							
Environment:	Benign	Limited Inspection									
Protection System:	None								Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*						
	N/A		All								
Comments:	Medium volume and low flow from east to west with no obstructions noted at time of inspection.										
Recommended Work:		Rehab		Replace	Maintenance Needs:						
		1-5 years		6-10 years		Urgent		1 year		2 years	

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Approaches	Install code compliant approach barrier			X	\$ -
Culvert	Replace Barrels		X		\$ 336,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 336,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification



Photo 1 Structure from south approach



Photo 2 North approach from centre of structure



Photo 3 South approach from centre of structure



Photo 4 East elevation



Photo 5 West elevation



Photo 6 Potholes forming on south wearing surface



Photo 7 Interior of barrel from west end



Photo 8 Evidence of leakage from bolt lines at northwest corner of barrel



Photo 9 Light corrosion and evidence of leakage on barrel wall



Photo 10 Some fill loss around barrel

Structure Condition Summary Form

Structure Name Pemberton Rd & Mulin MS Culvert
Structure Number CUS016
Date of Inspection December 1, 2022
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	348.00	0.00	338.00	10.00	0.00	2088	1545	74	00	15
Culvert	Barrel	Sq.m	350.00	199.15	0.00	152.35	26.89	19.92	69703	43756	63	00	00
Coatings	Structural steel	Sq.m	80.00	199.15	0.00	149.35	29.87	19.92	15932	9917	62	00	00
Embankments and Streams	Embankments	Each	0.00	4.00	0.00	4.00	0.00	0.00	0	0		00	00
	Streams and Waterways	All	0.00	1.00	0.00	1.00	0.00	0.00	0	0		00	00
									87723	55218			

Bridge Condition Index (BCI)

63

Inventory Data:

Structure Name				Nation Valley Rd and Dillabough Creek MD Culvert				
Main Hwy/Road #	Nation Valley Rd		Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	
	On Structure	<input checked="" type="checkbox"/>		Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	
	Under Structure	<input type="checkbox"/>						
			Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	
				Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	
Structure Location								2.4km West of County Rd 43
Latitude		45.0818683		Longitude		-75.2464547		
Owner(s)	Township of North Dundas		Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	
				Design./not list	<input type="checkbox"/>	Design. & List	<input type="checkbox"/>	
MTO Region	40 - Eastern		Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>	
				Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>	
MTO District	42 - Ottawa		Posted Speed	60 km/h		No. of Lanes	2	
Old County	SDG		AADT	117		% Trucks	<input type="checkbox"/>	
Geographic Twp.			Inspection Route Sequence		<input type="checkbox"/>			
Structure Type	SPCSP Arch Culvert		Interchange Number		<input type="checkbox"/>			
Total Deck Length	<input type="checkbox"/> m		Interchange Structure Number		<input type="checkbox"/>			
Overall Str. Width	3.3 m		Min. Vertical Clearance		<input type="checkbox"/> m			
Total Deck Area	<input type="checkbox"/> sq. m		Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>	
				School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>	
Roadway Width	6.4 m		Detour Length Around Bridge		<input type="checkbox"/> km			
Skew Angle	5 Degrees		Direction of Structure		East/West			
No. of Spans	1		Fill on Structure		0.4 m			
Culvert Length	17.4 m							
Span Lengths	3.3 m							

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	28.13		
OSIM		2022	75		Structure Replaced

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy, Light rain				
Temperature:	4 °C				

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 5,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:						
Recommended Work on	<input checked="" type="checkbox"/> x	None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace	
Timing of Recommended Work:			1 to 5 years	6 to 10 years		
Overall Comments:	Structure has been replaced since last inspection with 3.3m wide x 2.3m high horizontal ellipsoid culvert, and is in generally good condition. Erosion noted at the northwest embankment, encroaching into culvert. Structure elements and quantities should be updated. A code compliant barrier and end-treatments should be installed above the structure					
Date of Next Inspection:	2024					

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	6.4
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	384.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		384.00
Comments:	Asphalt wearing surface appears to have been replaced since last inspection and is in generally good condition. No barrier present - A code compliant barrier and end-treatment should be installed above the structure.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Culverts	Length:	17.4
Element Name:	Barrels	Width:	3.3
Location:	Below Roadway	Height:	2.1
Material:	Corrugated Steel	Count (items):	1
Element Type:	SPCSP Arch Culvert	Total Quantity:	91.87 m2
Environment:	Benign	Limited Inspection	
Protection System:	Hot Dip Galvanized		
Condition Data:	Units	Exc.	Good
	m2		91.87
Comments:	Structure appears to have been replaced since last inspection and is in generally good condition. Structure data and geometry should be updated.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Coating	Length:	
Element Name:	Structural Steel	Width:	
Location:	On culvert barrel	Height:	
Material:	Other	Count (items):	
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	91.87 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		91.87
Comments:	Structure appears to have been replaced since last inspection and is in generally good condition. Structure data and geometry should be updated.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent 1 year 2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (below ground level)	Width:							
Location:	Below barrel	Height:							
Material:	unknown	Count (items):							
Element Type:	unknown	Total Quantity:	All	N/A					
Environment:	Benign	Limited Inspection		x					
Protection System:	Unknown							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted at the time of inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, NW, SW & SE sides of structure	Height:							
Material:	Vegetation	Count (items):	4						
Element Type:	Embankments	Total Quantity:	4	Each					
Environment:	Moderate	Limited Inspection							
Protection System:	Rip-Rap							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each	3		1.0					
Comments:	Embankments are moderately sloped, well vegetated, and stable. Washout noted at northwest embankment encroaching into barrel.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams	Length:							
Element Name:	Slope protection	Width:							
Location:	NE, NW, SW & SE Side of Structure	Height:							
Material:	Rip-Rap	Count (items):	4						
Element Type:	Embankment	Total Quantity:	4	Each					
Environment:	Moderate	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each	3		1					
Comments:	Generally in good condition. Washout noted at northwest embankment encroaching into barrel.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams	Length:								
Element Name:	Streams and Waterways	Width:								
Location:	Under structure	Height:								
Material:	Native	Count (items):	All							
Element Type:	Stream	Total Quantity:	All							
Environment:	Benign	Limited Inspection								
Protection System:	None									Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Low volume and low flow from south to north with no visible obstructions noted.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Barriers	Install code compliant barrier and end-treat			X	\$ 48,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 48,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd & Dillabough Creek MD Culvert SITE PHOTOGRAPHS

Site No.:CUS017



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd & Dillabough Creek MD Culvert SITE PHOTOGRAPHS

Site No.:CUS017



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd & Dillabough Creek MD Culvert SITE PHOTOGRAPHS

Site No.:CUS017



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Nation Valley Rd & Dillabough Creek MD Culvert SITE PHOTOGRAPHS

Site No.:CUS017



Photo 7 Typical view through culvert from the North



Photo 8 South culvert barrel end and encroachment of washout (inlet)

Structure Condition Summary Form

Structure Name

Nation Valley Rd & Dillabough Creek MD Culvert

Structure Number

CUS017

Date of Inspection

2022/11/25

Project No.

22087

Consultant

HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	384.00		384.00			2304	1728	75	00	15
Culvert	Barrel	Sq.m	350.00	91.87		91.87			32155	24116	75	00	00
Coatings	Structural steel	Sq.m	80.00	91.87		91.87			7350	5512	75	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00	3.00		1.00		0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00	3.00		1.00		0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00
									41808	31356			
Bridge Condition Index (BCI)	75.00												

Inventory Data:

Structure Name	Webb Rd & Whittaker MD Culvert				
Main Hwy/Road #	Webb Rd	Services on structure:	Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/>	Non-Navig. <input type="checkbox"/> Road <input checked="" type="checkbox"/>	Ped. <input type="checkbox"/> Other <input type="checkbox"/>
	On Structure <input checked="" type="checkbox"/>				
	Under Structure <input type="checkbox"/>	Services under structure:	Navig. Water <input type="checkbox"/> Rail <input type="checkbox"/>	Non-Navig. <input checked="" type="checkbox"/> Road <input type="checkbox"/>	Ped. <input type="checkbox"/> Other <input type="checkbox"/>
Structure Location	1.1 km North of Nesbitt Rd				
Latitude	45.05621	Longitude	-75.2979		
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input checked="" type="checkbox"/> Desig./not list <input type="checkbox"/>	Cons/not App. <input type="checkbox"/> Desig. & List <input type="checkbox"/>	List/n.d. <input type="checkbox"/>
MTO Region	40 - Eastern	Road Class:	Freeway <input type="checkbox"/> Collector <input type="checkbox"/>	Arterial <input type="checkbox"/> Local <input checked="" type="checkbox"/>	
MTO District	42 - Ottawa	Posted Speed	60 km/h	No. of Lanes	2
Old County	SDG	AADT	49	% Trucks	
Geographic Twp.		Inspection Route Sequence			
Structure Type	4-cell CSP Round culvert	Interchange Number			
Total Deck Length		Interchange Structure Number			
Overall Str. Width	3.2	Min. Vertical Clearance			
Total Deck Area		Special Routes:	Transit <input type="checkbox"/> School <input type="checkbox"/>	Truck <input type="checkbox"/> Bicycle <input type="checkbox"/>	
Roadway Width	5.5	Detour Length Around Bridge			
Skew Angle	20	Direction of Structure	North/South		
No. of Spans	4	Fill on Structure			
Culvert Length	7				
Span Lengths	0.8				

Historical Data:

Year Built		Year of Last Major Rehab.	
Last OSIM Inspection		Last Evaluation	
Last Enhanced OSIM Inspection		Current Load Limit	
Enhanced Access Equipment (ladder, boat, lift, etc.)		Load Limit By-Law #	
Last Underwater Inspection		By-Law Expiry Date	
Last Condition Survey			

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.66		
OSIM		2022	47.15		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 20,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:		x		\$ 2,500.00
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:						
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input checked="" type="checkbox"/> X	<input type="checkbox"/> Replace	
Timing of Recommended Work:	<input type="checkbox"/> X	<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years			
Overall Comments:	Replace structure as soon as possible - Barrel ends heavily damaged and torn from impact at the west. Severe undermining and loss of fill throughout structure. Scaling and honeycombing present throughout concrete deck. No barrier present - A code compliant barrier and end treatments should be installed above the structure.					
Date of Next Inspection:	2024					

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	8
Element Name:	Wearing Surface	Width:	5.5
Location:	Over Culvert	Height:	
Material:	Cast-in-place concrete	Count (items):	
Element Type:	Concrete riding surface	Total Quantity:	44.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		11.00
Comments:	Light to medium scaling noted with void below north slab and extreme undermining. No barrier present - A code compliant barrier end end treatments should be installed above structure		
Recommended Work:	Rehab	X	Replace
	X	1-5 years	6-10 years
Urgent replacement of structure			

Element Group:	Culverts	Length:	7
Element Name:	Barrels	Width:	0.8
Location:	Below Roadway	Height:	0.8
Material:	Corrugated Steel	Count (items):	4
Element Type:	CSP round culvert	Total Quantity:	70.34 m2
Environment:	Benign	Limited Inspection	
Protection System:	Hot Dip Galvanized		
Condition Data:	Units	Exc.	Good
	m2		27.34
Comments:	Localized rust and dent at the north was noted. Severe deformations noted at the west end. No fill is present for at least 50% of the width below deck.		
Recommended Work:	Rehab	X	Replace
	X	1-5 years	6-10 years
Urgent replacement of structure			

Element Group:	Coating	Length:	
Element Name:	Structural Steel	Width:	
Location:	On culvert barrel	Height:	
Material:	Other	Count (items):	
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	70.34 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		50.34
Comments:	Generally in good condition with light corrosion		
Recommended Work:	Rehab		Replace
		1-5 years	6-10 years
Urgent replacement of structure			

Element Group:	Foundations	Length:						
Element Name:	Foundation (below ground level)	Width:						
Location:	Below barrel	Height:						
Material:	unknown	Count (items):						
Element Type:	unknown	Total Quantity:	All	N/A				
Environment:	Benign	Limited Inspection		x				
Protection System:	Unknown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted at the time of inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SW & SE sides of structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Embankments	Total Quantity:	4	Each				
Environment:	Moderate	Limited Inspection						
Protection System:	Rip-Rap						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4					
Comments:	Embankments are moderately sloped, well vegetated, and stable.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope protection	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Rip-Rap	Count (items):	4					
Element Type:	Embankment	Total Quantity:	4	Each				
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4					
Comments:	Generally in good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:								
Element Name:	Streams and Waterways	Width:								
Location:	Under structure	Height:								
Material:	Native	Count (items):	All							
Element Type:	Stream	Total Quantity:	All							
Environment:	Benign	Limited Inspection								N/A
Protection System:	None									Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Moderate volume and low flow from west to east, with no visible obstructions noted.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Structure	Replace		X		\$ 167,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 167,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Webb Rd & Whittaker MD culvert

SITE PHOTOGRAPHS

Site No.:CUS018



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

Webb Rd & Whittaker MD culvert

SITE PHOTOGRAPHS

Site No.:CUS018



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Webb Rd & Whittaker MD culvert

SITE PHOTOGRAPHS

Site No.:CUS018



Photo 5 East elevation



Photo 6 West elevation



Photo 7 Severe undermining and loss of fill at North approach slab (1)



Photo 8 Severe undermining and loss of fill at North approach slab (2)

MUNICIPAL STRUCTURE INSPECTION FORM

Webb Rd & Whittaker MD culvert

SITE PHOTOGRAPHS

Site No.:CUS018



Photo 9 View of East barrel ends



Photo 10 Severe deformations on west ends of barrels, and scaling on concrete deck



Photo 11 Separation of barrels and voids in slab around barrels on west side



Photo 12 Severe scaling of concrete wingwalls and slab (typical)



Photo 13 Scaling along top of exposed concrete deck

Structure Condition Summary Form

Structure Name Webb Rd & Whittaker MD Culvert
Structure Number CUS018
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	44.00		11.00		33.00	264	50	19	00	15
Culvert	Barrel	Sq.m	350.00	70.34		27.34	25.00	18.00	24619	10677	43	00	00
Coatings	Structural steel	Sq.m	80.00	70.34		50.34	20.00		5627	3660	65	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

									30510	14387
Bridge Condition Index (BCI)	47.15									

Inventory Data:

Structure Name	Hollister Rd & Moffat Creek Culvert								
Main Hwy/Road #	County Rd 31	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
On Structure	X		Rail	<input type="checkbox"/>	Road	X	Other	<input type="checkbox"/>	
Under Structure			Services under structure:		Navig. Water	<input type="checkbox"/>	Non-Navig.	X	Ped.
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location	0.5 km South of River Rd								
Latitude	45.047427	Longitude	-75.31713						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input type="checkbox"/>	X	Cons/not App. <input type="checkbox"/>	List/n.d.	<input type="checkbox"/>		
			Design./not list	<input type="checkbox"/>	Design. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern	Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
			Collector	<input type="checkbox"/>	Local	X			
MTO District	42 - Ottawa	Posted Speed	80 km/h	No. of Lanes	2				
Old County	SDG	AADT	N/A	% Trucks	<input type="checkbox"/>				
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	2-Cell CSP Culvert	Interchange Number	<input type="checkbox"/>						
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	3 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	<input type="checkbox"/> sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
			School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	10.7 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	0 Degrees	Direction of Structure	North/South						
No. of Spans	2	Fill on Structure	0.9 m						
Culvert Length	26.5 m								
Span Lengths	1.2, 1.8 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	61.04		
OSIM		2022	59.58		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 20,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input checked="" type="checkbox"/> X	<input type="checkbox"/> Replace		
Timing of Recommended Work:	<input type="checkbox"/> X	<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years				
Overall Comments:	Replace structure in 1 to 5 years - Structure is generally in fair to poor condition. No barrier present on west side of structure- A code compliant barrier and end treatments should be installed above the structure. Sag and perforations noted in barrel, with cracks along boltlines. Heavy sediment build up noted in both culverts						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Accessories (Attachments and signs)				Length:					
Element Name:	Signs				Width:					
Location:	NE & SE Side of structure				Height:					
Material:	Steel				Count (items):	2				
Element Type:	Hazard Markers				Total Quantity:	2.0 m2				
Environment:	Severe				Limited Inspection					
Protection System:	None								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m2		2.00							
Comments:	Generally in good condition									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Approaches				Length:	61				
Element Name:	Barriers				Width:					
Location:	East side of structure				Height:					
Material:	Steel				Count (items):	1				
Element Type:	Steel flex beam on steel posts (SBGR)				Total Quantity:	61.0 m2				
Environment:	Severe				Limited Inspection					
Protection System:	Hot Dip Galvanizing								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m2		61.00							
Comments:	Generally in good condition - No barrier present on the west side of structure - A code compliant barrier and end-treatments should be installed on the west side									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Approaches				Length:	60				
Element Name:	Wearing Surface				Width:	10.7				
Location:	Over Culvert				Height:					
Material:	Asphalt				Count (items):					
Element Type:	Asphalt Wearing Surface				Total Quantity:	642.0 m2				
Environment:	Severe				Limited Inspection					
Protection System:	None								Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	m2		642.00							
Comments:	Generally in good condition									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Element Group:	Culverts	Length:	26.5						
Element Name:	Barrels	Width:	1.8 (N), 1.2 (S)						
Location:	Below Roadway	Height:	1.8 (N), 1.2 (S)						
Material:	Corrugated Steel	Count (items):	2						
Element Type:	CSP Round Culvert	Total Quantity:	233.00 m2						
Environment:	Benign	Limited Inspection							
Protection System:	Hot Dip Galvanized							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m2		158.00	50.00	25.0				
Comments:	Minor to moderate sag and corrosion noted. Perforations in noted in both culverts along the waterline. Heavy sedimentation present in both barrels. Rust noted on the exterior of both barrel ends								
Recommended Work:		Rehab	x	Replace	Maintenance Needs:				
	x	1-5 years		6-10 years		Urgent	1 year	2 years	
Replace Structure									

Element Group:	Coating	Length:							
Element Name:	Structural Steel	Width:							
Location:	On culvert barrel	Height:							
Material:	Other	Count (items):							
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	233.00 m2						
Environment:	Benign	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m2		153.00	45.00	35.00				
Comments:	Medium to severe coating loss noted along culvert side walls.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent	1 year	2 years	

Element Group:	Foundations	Length:							
Element Name:	Foundation (below ground level)	Width:							
Location:	Below barrel	Height:							
Material:	unknown	Count (items):							
Element Type:	unknown	Total Quantity:	All N/A						
Environment:	Benign	Limited Inspection						x	
Protection System:	Unknown							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted at the time of inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent	1 year	2 years	

Element Group:	Embankments and Streams			Length:					
Element Name:	Embankments			Width:					
Location:	NE, NW, SW & SE sides of structure			Height:					
Material:	Vegetation			Count (items):	4				
Element Type:	Embankments			Total Quantity:	4				
Environment:	Moderate			Limited Inspection					
Protection System:	Rip-Rap						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4						
Comments:	Embankments are moderately sloped, well vegetated, and stable.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams			Length:					
Element Name:	Slope protection			Width:					
Location:	NE, NW, SW & SE Side of Structure			Height:					
Material:	Rip-Rap			Count (items):	4				
Element Type:	Embankment			Total Quantity:	4				
Environment:	Moderate			Limited Inspection					
Protection System:	None						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4						
Comments:	Generally in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams			Length:					
Element Name:	Streams and Waterways			Width:					
Location:	Under structure			Height:					
Material:	Native			Count (items):	All				
Element Type:	Stream			Total Quantity:	All				
Environment:	Benign			Limited Inspection					
Protection System:	None						Perform. Deficiencies		
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Low volume and flow from west to east with no flow obstructions noted. Evidence of overgrown vegetation was noted at the east side of the barrels								
Recommended Work:		Rehab		Replace	Maintenance Needs: 18				
		1-5 years		6-10 years	Urgent	1 year	x 2 years		
					Clear vegetation				

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Pipe Arch	Repair		X		\$ 278,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 278,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Hollister Rd Moffat & Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS019



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

Hollister Rd Moffat & Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS019



Photo 3 East elevation



Photo 4 West elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Hollister Rd Moffat & Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS019



Photo 5 View of east end of barrels from roadway



Photo 6 View of west end of barrels from the Southwest embankment

MUNICIPAL STRUCTURE INSPECTION FORM

Hollister Rd Moffat & Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS019



Photo 7 View through south barrel, looking west



Photo 8 View through north barrel, looking east

MUNICIPAL STRUCTURE INSPECTION FORM

Hollister Rd Moffat & Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS019



Photo 9 Perforation, corrosion, and sedimentation at midspan of South barrel



Photo 10 Perforations and corrosion at waterline in North barrel

Structure Condition Summary Form

Structure Name Hollister Rd & Moffat Creek MD Culvert
Structure Number CUS019
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	61.00		61.00			0	0		00	00
	Wearing Surface	Sq.m	6.00	642.00		642.00			3852	2889	75	00	15
Accessories	Signs	Each	0.00	2.00		2.00			0	0		00	00
Culvert	Barrel	Sq.m	350.00	233.00		158.00	50.00	25.00	81550	48475	59	00	00
Coatings	Structural steel	Sq.m	80.00	233.00		153.00	45.00	35.00	18640	10620	57	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00
									104042	61984			

Bridge Condition Index (BCI) 59.58

Inventory Data:

Structure Name		Hollister Rd Equalizer Culvert							
Main Hwy/Road #	County Rd 31	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		0.9 km South of River Rd							
Latitude	45.0456418	Longitude	-75.3137318						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid:	<input checked="" type="checkbox"/>	Cons/not App.	<input type="checkbox"/>	List/n.d.	<input type="checkbox"/>	
			Design./not list	<input type="checkbox"/>	Design. & List	<input type="checkbox"/>			
MTO Region	40 - Eastern	Road Class:	Freeway	<input type="checkbox"/>	Arterial	<input type="checkbox"/>			
			Collector	<input type="checkbox"/>	Local	<input checked="" type="checkbox"/>			
MTO District	42 - Ottawa	Posted Speed	80 km/h		No. of Lanes	2			
Old County	SDG	AADT	N/A		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	2-Cell CSP Round Culvert	Interchange Number	<input type="checkbox"/>						
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	3.2 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	<input type="checkbox"/> sq. m	Special Routes:	Transit	<input type="checkbox"/>	Truck	<input type="checkbox"/>			
			School	<input type="checkbox"/>	Bicycle	<input type="checkbox"/>			
Roadway Width	10.7 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	20 Degrees	Direction of Structure	North/South						
No. of Spans	2	Fill on Structure	1 m						
Culvert Length	26.5 m								
Span Lengths	1.6, 1.6 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	59.57		
OSIM		2022	59.15		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:			
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> OSIM <input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.		
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.		
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.		
Weather:	Cloudy, Light rain		
Temperature:	4 °C		

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study		x		\$ 20,000.00
Material Condition Survey				
Detailed Deck Condition Survey:	x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
Concrete Substructure Condition Survey:	x			
Detailed Coating Condition Survey:	x			
Detailed Timber Investigation:	x			
Post-Tensioned Strand Investigation:	x			
Underwater Investigation:	x			
Fatigue Investigation:	x			
Seismic Investigation:	x			
Structure Evaluation:	x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	x			
Monitoring Crack Widths:	x			
Investigation Notes:				

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input checked="" type="checkbox"/> X	<input type="checkbox"/> Replace		
Timing of Recommended Work:	<input checked="" type="checkbox"/> X	<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years				
Overall Comments:	Repair structure in 1-5 years. Structure is in generally fair to poor condition with perforations along both barrels and medium to severe corrosion throughout. Minor sag visible through both barrels No barrier present - A code compliant barrier and end-treatments should be installed above the structure.						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	10.7
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	642.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		642.00
Comments:	Generally in good condition - No barrier present - A code compliant barrier and end-treatments should be installed above the structure.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Culverts	Length:	26.5
Element Name:	Barrels	Width:	1.6 (S), 1.6 (N)
Location:	Below Roadway	Height:	1.6 (S), 1.6 (N)
Material:	Corrugated Steel	Count (items):	2
Element Type:	SPCSP Arch Culvert	Total Quantity:	266.30 m2
Environment:	Benign	Limited Inspection	
Protection System:	Hot Dip Galvanized		
Condition Data:	Units	Exc.	Good
	m2		175.30
Comments:	Medium rust and localized dent was noted on exposed surface of the barrels. Medium to severe corrosion and perforations were noted along springline within both barrels. Minor sag visible from within barrels		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	x	1-5 years	Urgent
		6-10 years	1 year
			2 years

Element Group:	Coating	Length:	
Element Name:	Structural Steel	Width:	
Location:	On culvert barrel	Height:	
Material:	Other	Count (items):	
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	266.30 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		188.30
Comments:	Medium to severe coating loss noted along culvert side walls.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (below ground level)	Width:							
Location:	Below barrel	Height:							
Material:	unknown	Count (items):							
Element Type:	unknown	Total Quantity:	All	N/A					
Environment:	Benign	Limited Inspection		x					
Protection System:	Unknown							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted at the time of inspection.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, NW, SW & SE sides of structure	Height:							
Material:	Vegetation	Count (items):	4						
Element Type:	Embankments	Total Quantity:	4	Each					
Environment:	Moderate	Limited Inspection							
Protection System:	Rip-Rap							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4						
Comments:	Embankments are moderately sloped, well vegetated, and stable.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams	Length:							
Element Name:	Slope protection	Width:							
Location:	NE, NW, SW & SE Side of Structure	Height:							
Material:	Rip-Rap	Count (items):	4						
Element Type:	Embankment	Total Quantity:	4	Each					
Environment:	Moderate	Limited Inspection							
Protection System:	None							Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4						
Comments:	Generally in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years	Urgent	1 year	2 years		

Element Group:	Embankments and Streams	Length:								
Element Name:	Streams and Waterways	Width:								
Location:	Under structure	Height:								
Material:	Native	Count (items):	All							
Element Type:	Stream	Total Quantity:	All							
Environment:	Benign	Limited Inspection								N/A
Protection System:	None									Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*					
	N/A		All							
Comments:	Low volume and flow from west to east with no obstructions noted.									
Recommended Work:		Rehab		Replace	Maintenance Needs:					
		1-5 years		6-10 years		Urgent		1 year		2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Barrel	Replace		x		\$ 297,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 297,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Hollister Rd Equalizer Culvert

SITE PHOTOGRAPHS

Site No.:CUS020



Photo 1 Structure from north approach



Photo 2 Structure from south approach

MUNICIPAL STRUCTURE INSPECTION FORM

Hollister Rd Equalizer Culvert

SITE PHOTOGRAPHS

Site No.:CUS020



Photo 3 North approach from centre of structure



Photo 4 South approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Hollister Rd Equalizer Culvert

SITE PHOTOGRAPHS

Site No.:CUS020



Photo 5 East elevation



Photo 6 West elevation



Photo 7 View over culverts towards the East



Photo 8 Severe corrosion and perforation at waterline within South barrel (typ.)



Photo 9 View through south culvert barrel, looking West



Photo 10 View through north culvert barrel, looking East

Structure Condition Summary Form

Structure Name Hollister Rd Equalizer Culvert
Structure Number CUS020
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	642.00		642.00			3852	2889	75	00	15
Culvert	Barrel	Sq.m	350.00	266.30		175.30	60.00	31.00	93205	54416	58	00	00
Coatings	Structural steel	Sq.m	80.00	266.30		188.30	44.00	34.00	21304	12706	60	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

									118361	70011
Bridge Condition Index (BCI)	59.15									

Inventory Data:

Structure Name		Nesbitt Rd & Whittaker MD Culvert							
Main Hwy/Road #	Nesbitt Rd	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		0.6 km East of County Rd 31							
Latitude	45.04451	Longitude	-75.2987						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	List/n.d. <input type="checkbox"/>				
			Design./not list <input type="checkbox"/>	Design. & List <input type="checkbox"/>					
MTO Region	40 - Eastern	Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>					
			Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>					
MTO District	42 - Ottawa	Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG	AADT	153		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	Super Cor Culvert	Interchange Number	<input type="checkbox"/>						
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	10 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	<input type="checkbox"/> sq. m	Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>					
			School <input type="checkbox"/>	Bicycle <input type="checkbox"/>					
Roadway Width	8.5 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	<input type="checkbox"/> Degrees	Direction of Structure	East/West						
No. of Spans	1	Fill on Structure	0.8 m						
Culvert Length	13 m								
Span Lengths	10 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:					
Year	Contract	WP Number	Category	Funding	Comments

Investigation History:					
Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	74.98		
OSIM		2022	74.50		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy, Light rain				
Temperature:	4 °C				

Additional Investigations Required:	Priority			Estimated Cost
	None	Normal	Urgent	
Rehabilitation/Replacement Study	<input checked="" type="checkbox"/> x			
Material Condition Survey				
Detailed Deck Condition Survey:	<input checked="" type="checkbox"/> x			
Non-Destructive Delamination Survey of Asphalt-Covered Deck:	<input checked="" type="checkbox"/> x			
Concrete Substructure Condition Survey:	<input checked="" type="checkbox"/> x			
Detailed Coating Condition Survey:	<input checked="" type="checkbox"/> x			
Detailed Timber Investigation:	<input checked="" type="checkbox"/> x			
Post-Tensioned Strand Investigation:	<input checked="" type="checkbox"/> x			
Underwater Investigation:	<input checked="" type="checkbox"/> x			
Fatigue Investigation:	<input checked="" type="checkbox"/> x			
Seismic Investigation:	<input checked="" type="checkbox"/> x			
Structure Evaluation:	<input checked="" type="checkbox"/> x			
Monitoring				
Monitoring of Deformations, Settlements and Movements:	<input checked="" type="checkbox"/> x			
Monitoring Crack Widths:	<input checked="" type="checkbox"/> x			
Investigation Notes:				

Overall Structure Notes:						
Recommended Work on	<input checked="" type="checkbox"/> x	None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input type="checkbox"/> Replace	
Timing of Recommended Work:			1 to 5 years	6 to 10 years		
Overall Comments:	Structure is in generally good condition with recently replaced barrier and end treatments above structure. Sedimentation buildup of sediment on stream bed within culvert possibly due to culvert misalignment with stream. Wide cracks noted in wearing surface above structure. Light corrosion and coating failure on east culvert wall along stip footing					
Date of Next Inspection:	2024					

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Accessories (attachments and signs)				Length:				
Element Name:	Signs				Width:				
Location:	NE, NW, SW, & SE Side of Structure				Height:				
Material:	Steel				Count (items):	4			
Element Type:	Hazard Markers				Total Quantity:	4.0 Each			
Environment:	Severe				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		2.00	2.00					
Comments:	Generally in good condition. 2x missing delineators								
Recommended Work:		Rehab		Replace	Maintenance Needs: 18				
		1-5 years		6-10 years		Urgent	x	1 year	2 years
					Install missing delineators				

Element Group:	Approaches				Length:	35			
Element Name:	Barriers				Width:				
Location:	NE, NW, SW, & SE Side of Structure				Height:				
Material:	Steel				Count (items):	4			
Element Type:	Steel Flex Beam on Steel Posts (SBGR)				Total Quantity:	140.0 m			
Environment:	Severe				Limited Inspection				
Protection System:	Hot Dip Galvanized								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m		140.00						
Comments:	SBGR has been replaced and is in generally good condition								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Approaches				Length:	60			
Element Name:	Wearing Surface				Width:	8.5			
Location:	Over Culvert				Height:				
Material:	Asphalt				Count (items):				
Element Type:	Asphalt Wearing Surface				Total Quantity:	510.00 m2			
Environment:	Severe				Limited Inspection				
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	m2		503.61	3.29	3.1				
Comments:	Wide transverse and longitudinal cracks noted in approach wearing surface.								
Recommended Work:		Rehab		Replace	Maintenance Needs: 15				
		1-5 years		6-10 years		Urgent	x	1 year	2 years
					Rout and seal cracks				

Element Group:	Barriers	Length:	10
Element Name:	Railing Systems	Width:	
Location:	North and South side of structure	Height:	
Material:	Steel	Count (items):	2
Element Type:	Steel Thrie beam on Steel Posts	Total Quantity:	20.00 m
Environment:	Severe	Limited Inspection	
Protection System:	Hot dip Galvanizing		
Condition Data:	Units	Exc.	Good
	m		20.00
Comments:	Generally in good condition		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Culverts	Length:	25.0
Element Name:	Barrels	Width:	3.4
Location:	Below barrel	Height:	2.1
Material:	Corrugated Steel	Count (items):	1
Element Type:	Super Cor Culvert	Total Quantity:	167.3 m2
Environment:	Benign	Limited Inspection	
Protection System:	Hot Dip Galvanizing		
Condition Data:	Units	Exc.	Good
	m2		167.30
Comments:	Light corrosion noted along springline		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Coating	Length:	
Element Name:	Structural Steel	Width:	
Location:	On culvert Barrel	Height:	
Material:	Coating	Count (items):	
Element Type:	Hot Dip Galvanizing	Total Quantity:	167.3 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		152.3
Comments:	Generally in good condition - light corrosion and coating loss noted on east wall along strip footing.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Coating	Length:							
Element Name:	Railing Systems/Hand Railings	Width:							
Location:	On Railing Systems	Height:							
Material:	Coating	Count (items):							
Element Type:	Hot Dip Galvanizing	Total Quantity:	20	Each					
Environment:	Benign	Limited Inspection							
Protection System:	None								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		20						
Comments:	Generally in good condition.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Foundations	Length:							
Element Name:	Foundation (Below Ground Level)	Width:							
Location:	Below Barrel	Height:							
Material:	Unknown	Count (items):	All						
Element Type:	Unknown	Total Quantity:	All	N/A					
Environment:	Benign	Limited Inspection		x					
Protection System:	Unknown								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	N/A		All						
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability observed at the time of inspection. A wide vertical crack was noted on exposed footing.								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams	Length:							
Element Name:	Embankments	Width:							
Location:	NE, NW, SW, & SE Side of Structure	Height:							
Material:	Rip-Rap	Count (items):	4						
Element Type:	Embankments	Total Quantity:	4	Each					
Environment:	Moderate	Limited Inspection							
Protection System:	Vegetation								Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*				
	Each		4						
Comments:	Embankments are moderately sloped, well vegetated, and stable								
Recommended Work:		Rehab		Replace	Maintenance Needs:				
		1-5 years		6-10 years		Urgent		1 year	2 years

Element Group:	Embankments and Streams		Length:			
Element Name:	Slope Protection		Width:			
Location:	NE, NW, SW, & SE Side of Structure		Height:			
Material:	Vegetation		Count (items):		4	
Element Type:	Slope Protection		Total Quantity:		4 Each	
Environment:	Moderate		Limited Inspection			
Protection System:	None				Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	Each		4			
Comments:	Generally in good condition.					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Element Group:	Embankments and Streams		Length:			
Element Name:	Streams and Waterways		Width:			
Location:	Under Structure		Height:			
Material:	Native		Count (items):		All	
Element Type:	Streams		Total Quantity:		All N/A	
Environment:	Benign		Limited Inspection			
Protection System:	None				Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	N/A		All			
Comments:	Evidence of misalignment with stream is present - sediment accumulation noted along stream bed.					
Recommended Work:		Rehab		Replace	Maintenance Needs: 18	
		1-5 years		6-10 years	Urgent	1 year x 2 years
						Remove sediment from stream bed and implement erosion control measures at stream banks

Element Group:	Retaining Walls		Length:			
Element Name:	Walls		Width:			
Location:	North and South sides of structure		Height:			
Material:	Wire Mesh		Count (items):			
Element Type:	Wire Mesh MSE Retaining Walls		Total Quantity:		40 m2	
Environment:	Moderate		Limited Inspection		x	
Protection System:	None				Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	m2		All			
Comments:	MSE walls are in generally good condition					
Recommended Work:		Rehab		Replace	Maintenance Needs:	
		1-5 years		6-10 years	Urgent	1 year 2 years

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ -

Associated Work		Comments	Estimated Cost
Approaches			\$ -
Detours			\$ -
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ -
Other			\$ -
Contingencies			\$ -
Total cost:			\$ -

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Nesbitt Rd & Whittaker MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS021



Photo 1 Structure from east approach



Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Nesbitt Rd & Whittaker MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS021



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Nesbitt Rd & Whittaker MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS021



Photo 5 North elevation



Photo 6 South elevation

MUNICIPAL STRUCTURE INSPECTION FORM

Nesbitt Rd & Whittaker MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS021



Photo 7 New approach guide rail and end treatments above structure (typ.)



Photo 8 Wide transverse crack in asphalt wearing surface above structure

MUNICIPAL STRUCTURE INSPECTION FORM

Nesbitt Rd & Whittaker MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS021



Photo 9 Medium longitudinal crack and raveling in asphalt wearing surface



Photo 10 Coating failure within culvert along east strip footing



Photo 11 Sediment buildup within culvert along stream bed

Structure Condition Summary Form

Structure Name Nesbitt Rd & Whittaker MD Culvert
Structure Number CUS021
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Barrier	m	0.00	140.00		140.00			0	0		00	00
	Wearing Surface	Sq.m	6.00	510.00		503.61	3.29	3.10	3060	2274	74	00	15
Accessories	Signs	Each	0.00	4.00		2.00	2.00		0	0		00	00
Barriers	Railing Systems	m	200.00	20.00		20.00			4000	3000	75	00	00
Culvert	Barrel	Sq.m	350.00	167.30		167.30			58555	43916	75	00	00
	Railing Systems/ Hand Railing	Sq.m	125.00	20.00		20.00			2500	1875	75	00	00
Coatings	Structural steel	Sq.m	80.00	167.30		152.30	15.00		13384	9618	72	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
Retaining Walls	Walls	Sq.m	350.00	20.00		20.00			7000	5250	75	00	18
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

									88499	65933	
--	--	--	--	--	--	--	--	--	-------	-------	--

Bridge Condition Index (BCI) 74.50

Inventory Data:

Structure Name		Nesbitt Rd & Barkley Creek MD Culvert							
Main Hwy/Road #	Nesbitt Rd	Services on structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input type="checkbox"/>	Ped.	<input type="checkbox"/>	
	On Structure		<input checked="" type="checkbox"/>	Rail	<input type="checkbox"/>	Road	<input checked="" type="checkbox"/>	Other	<input type="checkbox"/>
	Under Structure		<input type="checkbox"/>						
		Services under structure:	Navig. Water	<input type="checkbox"/>	Non-Navig.	<input checked="" type="checkbox"/>	Ped.	<input type="checkbox"/>	
			Rail	<input type="checkbox"/>	Road	<input type="checkbox"/>	Other	<input type="checkbox"/>	
Structure Location		0.3 km West of Shay Rd							
Latitude	45.05131	Longitude	-75.28076						
Owner(s)	Township of North Dundas	Heritage Designation	Not Consid: <input checked="" type="checkbox"/>	Cons/not App. <input type="checkbox"/>	Design./not list <input type="checkbox"/>	Cons/not App. <input type="checkbox"/>	Design. & List <input type="checkbox"/>	List/n.d. <input type="checkbox"/>	
MTO Region	40 - Eastern	Road Class:	Freeway <input type="checkbox"/>	Arterial <input type="checkbox"/>	Collector <input type="checkbox"/>	Local <input checked="" type="checkbox"/>			
MTO District	42 - Ottawa	Posted Speed	60 km/h		No. of Lanes	2			
Old County	SDG	AADT	150		% Trucks	<input type="checkbox"/>			
Geographic Twp.		Inspection Route Sequence	<input type="checkbox"/>						
Structure Type	SPCSP Arch Culvert	Interchange Number	<input type="checkbox"/>						
Total Deck Length	<input type="checkbox"/> m	Interchange Structure Number	<input type="checkbox"/>						
Overall Str. Width	5.5 m	Min. Vertical Clearance	<input type="checkbox"/> m						
Total Deck Area	<input type="checkbox"/> sq. m	Special Routes:	Transit <input type="checkbox"/>	Truck <input type="checkbox"/>	School <input type="checkbox"/>	Bicycle <input type="checkbox"/>			
Roadway Width	7.0 m	Detour Length Around Bridge	<input type="checkbox"/> km						
Skew Angle	20 Degrees	Direction of Structure	East/West						
No. of Spans	1	Fill on Structure	0.6 m						
Culvert Length	21 m								
Span Lengths	5.5 m								

Historical Data:

Year Built	<input type="checkbox"/>	Year of Last Major Rehab.	<input type="checkbox"/>
Last OSIM Inspection	<input type="checkbox"/>	Last Evaluation	<input type="checkbox"/>
Last Enhanced OSIM Inspection	<input type="checkbox"/>	Current Load Limit	<input type="checkbox"/> tonnes
Enhanced Access Equipment (ladder, boat, lift, etc.)	<input type="checkbox"/>	Load Limit By-Law #	<input type="checkbox"/>
Last Underwater Inspection	<input type="checkbox"/>	By-Law Expiry Date	<input type="checkbox"/>
Last Condition Survey	<input type="checkbox"/>		

Rehab History: (Date / Description):

Work History:

Year	Contract	WP Number	Category	Funding	Comments

Investigation History:

Type	BM Used	Date	BCI	Special Notes	BCI Justification
OSIM		2020	65.91		
OSIM		2022	65.37		

Appraisal Indices:		Comments:
Fatigue:		
Seismic:		
Scour:		
Flood:		
Geometrics:		
Barrier:		
Curb:		
Load Capacity:		
Key Aspects:		

Field Inspection Information:					
Date of Inspection:	November 25, 2022	Type of Inspection:	<input checked="" type="checkbox"/> X	OSIM	<input type="checkbox"/> Enhanced OSIM
Inspector:	Tashi Dwivedi, P.Eng.				
Others in Party:	Adrian Hu, B.Eng., Nicholas Brown, B.Eng.				
Equipment Used:	Digital camera, chipping hammer, chain, measuring tape, caliper, chalk, marker, flashlight, chest waders, and other equipment as required.				
Weather:	Cloudy, Light rain				
Temperature:	4 °C				

Additional Investigations Required:		Priority			Estimated Cost
		None	Normal	Urgent	
Rehabilitation/Replacement Study			x		\$ 20,000.00
Material Condition Survey					
	Detailed Deck Condition Survey:	x			
	Non-Destructive Delamination Survey of Asphalt-Covered Deck:	x			
	Concrete Substructure Condition Survey:	x			
	Detailed Coating Condition Survey:	x			
	Detailed Timber Investigation:	x			
	Post-Tensioned Strand Investigation:	x			
Underwater Investigation:		x			
Fatigue Investigation:		x			
Seismic Investigation:		x			
Structure Evaluation:		x			
Monitoring					
	Monitoring of Deformations, Settlements and Movements:		x		\$ 2,500.00
	Monitoring Crack Widths:		x		\$ 2,500.00
Investigation Notes:					

Overall Structure Notes:							
Recommended Work on	<input type="checkbox"/> None	<input type="checkbox"/> Minor Rehab.	<input type="checkbox"/> Major Rehab.	<input checked="" type="checkbox"/> X	<input type="checkbox"/> Replace		
Timing of Recommended Work:	<input type="checkbox"/> X	<input type="checkbox"/> 1 to 5 years	<input type="checkbox"/> 6 to 10 years				
Overall Comments:	Monitor Crracks and Replace structure in 1 to 5 years - Structure is generally in fair condition. No barrier present - A code compliant barrier and end treatments should be installed above the structure. Sag and perforations noted in barrel, with cracks along boltlines.						
Date of Next Inspection:	2024						

Suspected Performance Deficiencies

- | | | |
|---|--|------------------------------|
| 01 Load carrying capacity | 06 Bearing not uniformly loaded/unstable | 12 Slippery surfaces |
| 02 Excessive deformations (deflections & rotations) | 07 Jammed expansion joint | 13 Flooding/channel blockage |
| 03 Continuing settlement | 08 Pedestrian/vehicular hazard | 14 Undermining of foundation |
| 04 Continuing movements | 09 Rough riding surface | 15 Unstable embankments |
| 05 Seized bearings | 10 Surface ponding | 16 Other |
| | 11 Deck drainage | |

Maintenance Needs

- | | | |
|--------------------------------------|---------------------------------|--|
| 01 Lift and Swing Bridge Maintenance | 07 Repair to Structural Steel | 13 Erosion Control at Bridges |
| 02 Bridge Cleaning | 08 Repair of Bridge Concrete | 14 Concrete Sealing |
| 03 Bridge Handrail Maintenance | 09 Repair of Bridge Timber | 15 Rout and Seal |
| 04 Painting Steel Bridge Structures | 10 Bailey bridges - Maintenance | 16 Bridge Deck Drainage |
| Rehab History: (Date / Description) | 11 Animal/Pest Control | 17 Scaling (Loose Concrete or ACR Steel) |
| 06 Bridge Bearing Maintenance | 12 Bridge Surface Repair | 18 Other |

Element Group:	Approaches	Length:	60
Element Name:	Wearing Surface	Width:	7
Location:	Over Culvert	Height:	
Material:	Asphalt	Count (items):	
Element Type:	Asphalt Wearing Surface	Total Quantity:	420.0 m2
Environment:	Severe	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		420.00
Comments:	Asphalt wearing surface appears to have been repaved since last inspection and is in generally good condition. No barrier present - A code compliant barrier and end-treatment should be installed above the structure.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Culverts	Length:	21
Element Name:	Barrels	Width:	5.5
Location:	Below Roadway	Height:	3.2
Material:	Corrugated Steel	Count (items):	1
Element Type:	SPCSP Arch Culvert	Total Quantity:	317.10 m2
Environment:	Benign	Limited Inspection	
Protection System:	Hot Dip Galvanized		
Condition Data:	Units	Exc.	Good
	m2		260.93
Comments:	Minor to moderate sag and corrosion noted. Perforations noted in barrel and splits at boltline and waterline noted at the east (across 24 bolt holes) - Crack monitoring recommended.		
Recommended Work:	Rehab	x	Replace
	x	1-5 years	6-10 years
			Urgent
			1 year
			2 years

Element Group:	Coating	Length:	
Element Name:	Structural Steel	Width:	
Location:	On culvert barrel	Height:	
Material:	Other	Count (items):	
Element Type:	Coating - Hot dip galvanizing	Total Quantity:	317.10 m2
Environment:	Benign	Limited Inspection	
Protection System:	None		
Condition Data:	Units	Exc.	Good
	m2		242.58
Comments:	Medium to severe coating loss noted along culvert side walls.		
Recommended Work:	Rehab	Replace	Maintenance Needs:
	1-5 years	6-10 years	Urgent
			1 year
			2 years

Element Group:	Foundations	Length:						
Element Name:	Foundation (below ground level)	Width:						
Location:	Below barrel	Height:						
Material:	unknown	Count (items):						
Element Type:	unknown	Total Quantity:	All	N/A				
Environment:	Benign	Limited Inspection		x				
Protection System:	Unkown						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	N/A		All					
Comments:	Foundations are rated for performance only and not material condition. No visible evidence of foundation instability noted at the time of inspection.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Embankments	Width:						
Location:	NE, NW, SW & SE sides of structure	Height:						
Material:	Vegetation	Count (items):	4					
Element Type:	Embankments	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	Rip-Rap						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4					
Comments:	Embankments are moderately sloped, well vegetated, and stable.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams	Length:						
Element Name:	Slope protection	Width:						
Location:	NE, NW, SW & SE Side of Structure	Height:						
Material:	Rip-Rap	Count (items):	4					
Element Type:	Embankment	Total Quantity:	4 Each					
Environment:	Moderate	Limited Inspection						
Protection System:	None						Perform. Deficiencies	
Condition Data:	Units	Exc.	Good	Fair	Poor*			
	Each		4					
Comments:	Generally in good condition.							
Recommended Work:		Rehab		Replace	Maintenance Needs:			
		1-5 years		6-10 years	Urgent	1 year	2 years	

Element Group:	Embankments and Streams		Length:			
Element Name:	Streams and Waterways		Width:			
Location:	Under structure		Height:			
Material:	Native		Count (items):		All	
Element Type:	Stream		Total Quantity:		All	
Environment:	Benign		Limited Inspection		N/A	
Protection System:	None					Perform. Deficiencies
Condition Data:	Units	Exc.	Good	Fair	Poor*	
	N/A		All			
Comments:	Low volume and flow from south to north. Vegetation encroaching at South (inlet)					
Recommended Work:		Rehab		Replace	Maintenance Needs: 18	
		1-5 years		6-10 years	Urgent	1 year x 2 years
					Clear vegetation	

Repair and Rehabilitation Required:		Priority			Estimated Cost
Element	Repair and Rehabilitation Required	6-10 Years	1-5 Years	< 1 Year	
Pipe Arch	Replace		X		\$ 462,000.00
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
					\$ -
Total Cost:					\$ 462,000.00

Associated Work		Comments	Estimated Cost
Approaches			\$ 40,000.00
Detours			\$ 35,000.00
Traffic Control			\$ -
Utilities			\$ -
Right of Way			\$ -
Environmental Study			\$ 10,000.00
Other			\$ -
Contingencies			\$ -
Total cost:			\$ 85,000.00

Justification

MUNICIPAL STRUCTURE INSPECTION FORM

Nesbitt Rd & Barkley Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS022



Photo 1 Structure from east approach




Photo 2 Structure from west approach

MUNICIPAL STRUCTURE INSPECTION FORM

Nesbitt Rd & Barkley Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS022



Photo 3 East approach from centre of structure



Photo 4 West approach from centre of structure

MUNICIPAL STRUCTURE INSPECTION FORM

Nesbitt Rd & Barkley Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS022



Photo 5 North elevation



Photo 6 South elevation



Photo 7 View of culvert sag from the North side



Photo 8 Section crack/splitting along boltline at East barrel wall, with coating loss

MUNICIPAL STRUCTURE INSPECTION FORM

Nesbitt Rd & Barkley Creek MD Culvert

SITE PHOTOGRAPHS

Site No.:CUS022



Photo 9 Corrosion and coating loss (typ.)

Structure Condition Summary Form

Structure Name Nesbitt Rd and Barkley Creek MD Culvert
Structure Number CUS022
Date of Inspection 2022/11/25
Project No. 22087
Consultant HP Engineering Inc.

Element Group	Element Name	Unit (Qty.)	Unit Price (MTO)	Total Element Quantity	Element Qty. in Excellent Condition (1.00)	Element Quantity in Good Condition (0.75)	Element Quantity in Fair Condition (0.4)	Element Quantity in Poor Condition (0)	Total Replacement Value (TRV)	Current Element Value (CEV)	Element Condition Index	Performance Deficiency	Maintenance Need
Approaches	Wearing Surface	Sq.m	6.00	420.00		420.00			2520	1890	75	00	15
Culvert	Barrel	Sq.m	350.00	317.10		260.93	31.97	24.20	110985	72970	66	00	00
Coatings	Structural steel	Sq.m	80.00	317.10		242.58	42.81	31.71	25368	15925	63	00	00
Foundations	Foundations (below ground level)	N/A	0.00	1.00		1.00			0	0		00	00
	Embankments	Each	0.00	4.00		4.00			0	0		00	00
Embankments and Streams	Slope Protection	Each	0.00	4.00		4.00			0	0		00	00
	Streams and Waterways	All	0.00	1.00		1.00			0	0		00	00

										138873	90785			
Bridge Condition Index (BCI)	65.37													